

22/03/2002

ASS. REC. BY:

REF: CS3/A1919008192/VCD302

Special Instruction:

Surveyor: marcusASSIGNMENT (Office)From (Person): Chin Lee Yingof A19Date/Time: 9 May 2019 9:08 a.m

Estimated Cost:

Bill to:

~~OD~~ ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKJ 3116YInsured: SKU 3613Xat Workshop m/s ZOOM Auto workTel: 9450 7920of B15 Caki Bukit Road 4 A 01-53

Policy No:

Claim No: 1621326718SG

Sum Insured:

Excess:

Make of Veh:

D.O.A. 6 May 2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9 May 19 10:30 a.mPerson Contacted: ErlinVehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SKJ 3116Y - X</u>
	<u>SKU 3613X - X</u>
	<u>Dismantle: 10/5/2019</u>
	<u>After repair: 13/5/2019</u>

REF: A19

DRS

ASSIGNMENT

From: Date: 9.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKJ 3116 Y
at Workshop m/s: Zoom Autoworks
of B15 Eki Bukit Road 4 #01-53

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup" 4402J

Vehicle: IN / OUT

Date: Person Contacted: 31-8-2019

Veh No: SKJ 3116 Y Yr Regn: 8/09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen C4 SX c.c. 1598

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 158115 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55-216

R: Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 6/5/19

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 9/5/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

no settlement, LTA 9722 3rd.
4 dy.

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair: 4

1)

☐: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)☐: Weekend (\$)

Survey Fee: 180

Transportation:

S + RS, SI

Photos

Others

TOTAL

191

Report Format: DAR

Lump Sum / I.B.I. (\$))

Your password will expire in 2 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 5/9/2019 9:08:04 AM
Attachments:  PRI-SKJ3116Y-ZAW.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16

MANHATTAN HOUSE

SINGAPORE 169876

TEL : (65) 6532 2455

FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg

Our Ref : TCMG/SKJ3116Y/0519/ZAW

Your Ref : SKU 3613 X

7 May 2019

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

BY E-MAIL ONLY
(shengyang.lim@aig.com)

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Quah Wei Jun Wilson**, the owner and/or driver of motor vehicle no. **SKJ 3116 Y**, which was involved in an accident along West Coast Grove on 6 May 2019 at 08:20 hours.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SKU 3613 X** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Zoom Autowerks, (B/15 Kaki Bukit Road 4 #01-53, Bartley Biz Centre S(417808), Elin Cai @ 94507920).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,



MR LING LEONG HUI

cc. M/s Zoom Autowerks
(Yref: SKJ3116Y)

enc

BY E-MAIL ONLY

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4402J
Vehicle Details	
Vehicle No.:	SKJ3116Y
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	CITROEN
Vehicle Model:	C4 SX 1.6L VTI AT ABS D/AB P-SR 5DR 2WD
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	10FHBV0566666
Chassis No.:	VF7LC5FWF9Y544598
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,682.00
Original Registration Date:	01 Sep 2009
First Registration Date:	01 Sep 2009
Transfer Count:	3
Actual ARF Paid:	\$18,682.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Aug 2019
PARF Rebate Amount:	\$9,341.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$381.00
Total Rebate Amount:	\$9,722.00

The information contained herein is correct as at 14 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/05/2019 15:02
Date Of Accident	06/05/2019 08:20
Exact Location Of Accident	WEST COAST GROVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ3116Y
Insured/Policyholder	
Name Of Registered Owner	QUAH WEI JUN WILSON
NRIC No	S9124402J
Email Address	AKSTONE307@GMAIL.COM
Mobile Phone No	(LOCAL) +65-85526856
Alternative Phone No	OFFICE-85526856

Vehicle Particulars

Manufacturer	CITROEN
Model	C4
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5107236112
Cover Note Number	

Driver

Name of Driver	SUNILJIT SINGH
NRIC No	S8240037J
Date Of Birth	22/11/1982
Occupation	OUTDOOR
Date Of Driving Pass	14/02/2019
Driving Experience	0 YEAR AND 2 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-85334382
Fax Number	
Contact Number	
EMail Address	AKSTONE307@GMAIL.COM

Address	BLK 747 YISHUN STREET 72 #02-110
Postcode	760747
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU3613X
Vehicle Make/Model/Colour	MAZDA 6 /SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG WAI LING (HUANG HUILING)
NRIC/Passport Number	S7711122J
Contact Number	98452545
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


06 MAY 2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

NG WING KIN JAMES
admin.vac@vicom.com.sg



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on a one lane ~~RA~~ Road came from the back and bang to the side of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

06 MAY 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel Signature

Name: NG WING KIN JAMES

NRIC/PIN No.: admin.vac@vicom.com.sg



SKJ 31167

Load bumper D.S. —

Del bumper fog lamp NLS CR

Del bumper fog lamp cover NLS greasy

Del bumper protector NLS CR

headlamp NLS SCR

Del bumper side holder NLS cracked

Del Lender NLS Repair X

Del spot L.N. NLS Bent —

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 May 2019 Edit Reg		09 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	WONG WAI LING , ID: S7711122J								
Main Claimant:	QUAN WEI JUM WILSON								
Vehicle Reg. No.:	SKJ3116Y	Date of Loss:	06/05/2019 00:00 - :59 [116 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1621326718SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 21/07/2018 - 20/07/2019						
Vehicle Reg. No. (Insured):	SKU3613X	Policy No. (Claimant):							
		Excess:							
Repairer:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53, 417808 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (10/05/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKJ3116Y (1621326718SG)
[SKU3613X]
TP
QUAN WEI JUM WILSON
May 6 2019 12:00AM
[WONG WAI LING]
Zoom Autowerks Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Video										1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail		Print	
1	26/05/19 14:06	Video - Accident From:OD - Reg. No: SKU3613X, Claimant: WONG WAI LING										Load AVI	
										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	09/05/19 17:26	Odometer Reading										Load JPG	
2	09/05/19 17:26	Chassis Number										Load JPG	
3	09/05/19 17:26	General View										Load JPG	
4	09/05/19 17:26	General View										Load JPG	
5	09/05/19 17:26	General View										Load JPG	
6	09/05/19 17:26	General View										Load JPG	
7	09/05/19 17:26	General View										Load JPG	
8	09/05/19 17:26	General View										Load JPG	
9	09/05/19 17:26	General View										Load JPG	
10	09/05/19 17:26	General View										Load JPG	
11	09/05/19 17:26	General View										Load JPG	
12	09/05/19 17:26	General View										Load JPG	
13	09/05/19 17:26	General View										Load JPG	
14	09/05/19 17:26	General View										Load JPG	
15	09/05/19 17:26	General View										Load JPG	
16	09/05/19 17:26	General View										Load JPG	
17	09/05/19 17:26	General View										Load JPG	
18	09/05/19 17:26	General View										Load JPG	
19	09/05/19 17:26	General View										Load JPG	
20	09/05/19 17:26	General View										Load JPG	
21	09/05/19 17:26	General View										Load JPG	
22	09/05/19 17:26	General View										Load JPG	
23	09/05/19 17:26	General View										Load JPG	
24	09/05/19 17:26	General View										Load JPG	
25	09/05/19 17:26	General View										Load JPG	
26	09/05/19 17:26	General View										Load JPG	
27	09/05/19 17:26	General View										Load JPG	
28	09/05/19 17:26	General View										Load JPG	
29	09/05/19 17:26	General View										Load JPG	
30	09/05/19 17:26	General View										Load JPG	
31	09/05/19 17:26	General View										Load JPG	
32	09/05/19 17:26	General View										Load JPG	
33	09/05/19 17:26	General View										Load JPG	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
34	09/05/19 17:26	General View		Load JPG <input checked="" type="checkbox"/>
35	09/05/19 17:26	General View		Load JPG <input checked="" type="checkbox"/>
36	09/05/19 17:26	General View		Load JPG <input checked="" type="checkbox"/>
37	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
38	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
39	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
40	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
41	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
42	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
43	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
44	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
45	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
46	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
47	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
48	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
49	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
50	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
51	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
52	14/05/19 16:13	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
53	14/05/19 16:13	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
54	14/05/19 16:13	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
55	14/05/19 16:13	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
56	14/05/19 16:13	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
57	14/05/19 16:13	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
58	14/05/19 16:13	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
59	14/05/19 16:13	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
60	14/05/19 16:13	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	09/05/19 15:07	EMAIL FROM AIG DD 09.05.19		Load PDF
2	09/05/19 15:07	NOTIFICATION FROM LAWYER		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	10/05/19 10:11	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19008192/UCD3E2

Date: 12/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKJ3116Y

Insured Vehicle No : SKU3613X

Date of Loss: 06/05/2019

Nature of Claim: TP

Claim No: 1621326718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ3116Y**

Make & Model: CITROEN C4, 1.6 SX (A)

Engine No: 10FHBV0566666

Reg. Date: 01/09/2009 (Man. Year: 2009)

Chassis No: VF7LC5FWF9Y544598

Colour: Red

Odometer: 158115 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Continental 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/05/2019

Date Inspected: 09/05/2019 Inspected At:

Zoom Autowerks Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-53
Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	0.00 F	*- F
2	1		*FRONT BUMPER FOG LAMP N/S	Cracked	0.00 F	*- F
3	1		*FRONT BUMPER FOG LAMP COVER N/S	Grazed	0.00 F	*- F
4	1		*FRONT BUMPER PROTECTOR N/S	Cut	0.00 F	*- F
5	1		*HEADLAMP N/S	Scratched	0.00 F	*- F
6	1		*FRONT BUMPER SIDE HOLDER N/S	Cracked	0.00 F	*- F
7	1		*FRONT FENDER N/S	Repair	0.00 F	*- F
8	1		*FRONT SPORT RIM N/S	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >