

12/04/2012

ASS. REC. BY:

REF:

CS3 / AIG 19008198 / Rld B

Special Instruction:

SMV/Veh:

Rasul

ASSIGNMENT (Office)

From (Person):

chun lee ying

of

AIG

Date/Time:

9/5/19 @ 10:32am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKW 376P

Insured:

8KR 8701H

at Workshop m/s

MJE Motor

Tel:

6454 2203

of

Blk 7 Sin Ming Sec. C # 01-94

Policy No:

2100405311

Claim No:

47386439778G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.Q.A.

06/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:43pm @ 9/5/19

Person Contacted:

JO

Vehicle:

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SKW 376P - X

8KR 8701H - X

Demantle: 10/5/2019

After repair: 13/5/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 May 2019 Edit Reg		09 May 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Phua Cheng Kiat, ID: S0680547G		
Main Claimant:	CHEW WENG YEW, ID: S8002326Z		
Vehicle Reg. No.:	SKW376P	Date of Loss:	06/05/2019 13:00 - :59
Claim Type:	TP / 4738643977SG	Policy/Cover Note No.:	2100405311
Vehicle Reg. No. (Insured):	SKR8701H	Policy No. (Claimant):	
		Excess:	
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/05/2019]		
Claimant's Solicitor:	CHEONGHOH LAW CORPORATION - Tel: 63378700		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (14/05/2019): Request To Upload TP GIA Report
- AIG_SG (14/05/2019): No OI GIA Report
- AIG_SG (10/05/2019): Request To Upload TP GIA Report
- AIG_SG (10/05/2019): No Policy Found

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Your password will expire in 4 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 5/9/2019 10:32:43 AM
Attachments:  3585_001.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Thursday, May 09, 2019 9:36 AM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur

Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKR8701H AND SKW376P ON 06/05/2019 (Oref: LCH.lg/SJEM-90354.19)

This message is from an external sender; be cautious with links and attachments.

* Please quote our reference number when replying

Dear Sirs,

We refer to the above matter and your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid letter.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) Lee Kok Weng
- (2) Nicky Seah
- (3) Ang Guea Kiang
- (4) How Andrew
- (5) Chang Fuh Keong
- (6) Philip Foo
- (7) Ong Ah Keng, Kent
- (8) Ong Poh Meng
- (9) Ng Soon Aik Francis

(10) Ng Soon Chuan Louis

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre- repair survey of SKW 376 P and contact our client's workshop, MJE Motor , Blk 7 Sin Ming Sector C #01-94 Singapore 575642 for the said survey.

Contact Person : Y Y / Jo
9225 1391 / 6454 2203

Please proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number

Our Ref: LCH.lg/SJEM-90354.19

08.05.19

BY FAX NO. 68357416 AND BY HAND
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

BY CERTIFICATE OF POSTING
Phua Cheng Kiat
1 Marymount Terrace
#10-04
Singapore 574036

BY CERTIFICATE OF POSTING

Dear Sirs

We are instructed by Chew Weng Yew to notify you of a road traffic accident on 06.05.19 at about 1:20 pm at Scotts Road Towards Newton involving our client's vehicle registration number SKW 376 P and vehicle registration number SKR 8701 H driven by your insured driver/you/your driver at the material time. A copy of the Singapore accident statement filed is available.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For the avoidance of doubt, our client will be claiming for compensation for loss of use/rental of a replacement vehicle in the instances enumerated in the State Courts Practice Direction Amendment No. 1 of 2016 paragraphs 7.1 and 7.2 of the Appendix C of the Pre-action Protocol for Non-Injury Motor Accident Cases which compensation is additional to any other claim for loss of use/rental of a replacement vehicle which our client may make against your insured and/or your insured's driver and or you/your driver.

Yours faithfully

Cheonghoh Law Corporation

encs:

This is a computer-generated document and requires no signature

cc: client (via e-mail/fax only) - SKW 376 P

Enquire Vehicle & Owner Information (Vehicle No. SKR8701H As At 06 May 2019 / 13:20:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SJEM-90354.19/LG

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S0680547G

Owner Name: PHUA CHENG KIAT

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House
No.: 1

Registered Street Name: MARYMOUNT TERRACE

Registered Unit No.: # 10 - 04

Registered Building Name: -

Registered Postal Code: 574036

Current Vehicle Details

Vehicle No.: SKR8701H

Make Description/Model: NISSAN / SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR

Insurance Company Name:AIG ASIA PACIFIC INSURANCE PTE. LTD.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2326Z
Vehicle Details	
Vehicle No.:	SKW376P
Vehicle to be Exported:	No
Intended Deregistration Date:	31 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	MR20734282B
Chassis No.:	JN1JANT32Z0000850
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,934.00
Original Registration Date:	14 Oct 2015
First Registration Date:	14 Oct 2015
Transfer Count:	1
Actual ARF Paid:	\$22,708.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2025
PARF Rebate Amount:	\$17,031.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,190.00
COE Rebate Amount:	\$37,057.00
Total Rebate Amount:	\$54,088.00

The information contained herein is correct as at 31 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/05/2019 17:26
Date Of Accident	06/05/2019 13:20
Exact Location Of Accident	SCOTTS ROAD TOWARDS NEWTON
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW376P
Insured/Policyholder	
Name Of Registered Owner	CHEW WENG YEW
NRIC No	S8002326Z
Email Address	CHRIS@WATERMARKINTL.BIZ
Mobile Phone No	(LOCAL) +65-92705658
Alternative Phone No	OFFICE-92705658

Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA461811/1
Cover Note Number	

Driver

Name of Driver	CHEW WENG YEW
NRIC No	S8002326Z
Date Of Birth	24/01/1980
Occupation	INDOOR
Date Of Driving Pass	10/11/2006
Driving Experience	12 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92705658
Fax Number	
Contact Number	OFFICE-92705658
Email Address	CHRIS@WATERMARKINTL.BIZ

Address	BLK 451 TAMPINES STREET 42, #07-220
Postcode	520451
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR8701H
Vehicle Make/Model/Colour	NISSAN SYLPHY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PHUA CHENG KIAT
NRIC/Passport Number	S0680547G
Contact Number	97569006
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CHEW WENG YEW
Approximate Age	
Injuries Sustain	NECK
Injured person in which vehicle?	SKW376P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 451 TAMPINES ST 42, #07-220
Postcode	520451

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




Sketch Plan Pg. 2

SKETCH PLAN

VEHICLE A
- SKW 376P

VEHICLE B
- SKR 8701 H

SCOTTS ROAD TOWARD NEWTON



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG SCOTTS ROAD TOWARD NEWTON RD DIRECTION, I WAS ON THE MIDDLE LANE 2ND LANE.

WHILE SOMEWHERE NEAR TO LAMP POST 37, SUDDENLY THE VEHICLE INFRONT OF ME BRAKE TO COMPLETE STOP, AND SO I TOO APPLIED BRAKE AND CAME INTO A COMPLETE STOP. WHICH SUDDENLY I FELT A IMPACT FROM THE REAR OF MY VEHICLE.

ALIGHTED FROM MY VEHICLE AND REALIZED IT WAS A VEHICLE WITH LICENCE PLATE NUMBER (SKR 8701 H) THAT COLLIDED TO THE REAR OF MY VEHICLE.

* Repair other workshop *

VEHICLE A - SKW 376P
VEHICLE B - SKR 8701 H

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

7/5/19 @
3pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:



MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: **SKW376P**

NAC	INC	Item	CON	AC	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI




































CLAIM SUBFOLDER TRACKING




































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 May 2019 Edit Reg		09 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Phua Cheng Kiat , ID: S0680547G								
Main Claimant:	CHEW WENG YEW , ID: S8002326Z								
Vehicle Reg. No.:	SKW376P	Date of Loss:	06/05/2019 13:00 - :59 [42 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4738643977SG	Policy/Cover Note No.:	2100405311						
Vehicle Reg. No. (Insured):	SKR8701H	Policy No. (Claimant):							
		Excess:							
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/05/2019]								
Claimant's Solicitor:	CHEONGHOH LAW CORPORATION - Tel: 63378700								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (14/05/2019): Request To Upload TP GIA Report AIG_SG (14/05/2019): No OI GIA Report AIG_SG (10/05/2019): Request To Upload TP GIA Report AIG_SG (10/05/2019): No Policy Found 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW376P (4738643977SG)
[SKR8701H]
TP
CHEW WENG YEW
May 6 2019 1:00PM
[Phua Cheng Kiat]
Mje Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
2	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
3	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
4	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
5	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
6	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
7	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
8	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
9	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
10	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
11	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
12	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
13	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
14	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
15	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
16	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
17	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
18	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
19	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
20	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
21	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
22	31/05/19 11:52	General View															Load JPG		<input checked="" type="checkbox"/>	
23	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
24	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
25	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
26	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
27	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
28	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
29	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
30	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
31	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
32	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
33	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
34	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
35	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
36	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	
37	31/05/19 11:53	Photographs of Damaged Parts															Load JPG		<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	31/05/19 11:53	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	31/05/19 11:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19008198/R1CD3E2

Date: 01/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100405311

Claimant Vehicle No : SKW376P

Insured Vehicle No : SKR8701H

Date of Loss: 06/05/2019

Nature of Claim: TP

Claim No: 4738643977SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW376P

Make & Model: NISSAN X-TRAIL, 2.0 (A)

Engine No: MR20734282B

Reg. Date: 14/10/2015 (Man. Year: 2015)

Chassis No: JN1JANT32Z0000850

Colour: Red

Odometer: 50132 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/05/2019

Date Inspected: 09/05/2019 Inspected At:

Mje Motor (HQ)
BLK 7 SIN MING IND EST SEC C
#01-96 SINGAPORE 575642

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*BOOTLID	Repair	0.00 F	*- F
7	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >