





PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC19008202/Evd3e2		
300 BEACH ROAD		Date: 24-05-2019		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLF 2011G	Veh. Inspected	FBM 7929H	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/021734	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	09/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA SNIPER T150	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MH3UG0740J0093934	Colour	GREEN	
Odometer	27395 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/80-17	CORSA	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/80-17	CORSA	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information				
Accident Date	30/04/2019	Inspect Date / Time	10/05/2019 ( 10:21 AM )	
Survey held at	464 MACPHERSON ROAD			
Repairer	ONE MOTOR PERFORMANCE [9756 6117]			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC19008202/Evd3e2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.