

ASS. REC. BY:

REF: CS3/CI19008204/EC d327

Special Instruction:

Survivor:

Starz

ASSIGNMENT (Office)

From (Person): (Hong) Buon Sen

of CTZ

Date/Time: 9.5.19 1.03pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 9138G

Insured: SJK 3744R

at Workshop m/s Shung Li Lai

Tel: 68420302

of 2 Keri Bukit Ave 2 #01-36

Policy No:

Claim No: SNM/K1202044

Sum Insured:

Excess:

Make of Vch:

D.O.A. 8.5.2019

(Client's Record)

10.5.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 9.5.19 3.15pm

Person Contacted: Shung Li Lai

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SKC 9138G - NH/TIME 1900 9/28/24 DOA - 08/09/2019
	SJK 3744R - NH/TIME 1900 8/28/24 DOA - 08/09/2019
	Dismantle: 13/5/2019
	After repair: 23/5/2019

PRS

ASSIGNMENT

From: _____ Date: 10-9-2019

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No: SKC 91386

at Workshop n/s Sheng Li Lai

of 2 Kaki Bukit Ave 2 #01-36 Autohub

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS "w/p"

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKC 91386 Yr Began: 8/13/99

Type: ☒ A.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐

Truck / Trailer or _____

Make: Lexus 15250 C.C. 2500

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 7434FS T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHBK 26212293671

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or _____

Tyre Size: F: 245/45R17 R: 4


BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front	Rear
R/Bal. 7 mm	R/Bal. 7 mm
L/Bal. 7 mm	L/Bal. 7 mm
D.O.A. 8/5/19	D.O.A. 10/5/19

Survey held at Sheng Li Lai

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ W/C / ☐ Rooftop or _____

The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MR MR-66K Repair range - 2K-3K Days - 4 days
	
	14/5/2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ Site Insp (\$)

Transportation:

☐ Interview (\$)

3 * RS. 50

☐ Tech. Invs (\$)

Photos

☐ Weekend (\$)

Others

Report Format: PRS

Lump Sum / I.B.I. (\$)

TOTAL

150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		13 May 2019 14:49 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	LIEW CHAT SOON
Vehicle Reg. No.:	SKC9138G
Date of Loss:	08/05/2019 00:00 - :59
Claim Type:	TP / SNM19D202044C02
Policy/Cover Note No.:	DMPCSN30711818000
Vehicle Reg. No. (Insured):	SJK3744R
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 23/05/2019]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 9 May 2019 1:03 PM
To: Ong & Shan LLC
Cc: Sheng Li Lai; assignments
Subject: RE: ACCIDENT INVOLVING SKC 9138G & SJK 3744R ON 08.05.2019 ALONG AYE @ 0840 HRS (OUR REF: SRSTP.3630.19.SL) / OUR REF: SNM19D202044

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Ong & Shan LLC [mailto:ongshanllc@gmail.com]

Sent: Thursday, 9 May, 2019 9:55 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: Sheng Li Lai <slshenglilai@gmail.com>

Subject: Re: ACCIDENT INVOLVING SKC 9138G & SJK 3744R ON 08.05.2019 ALONG AYE @ 0840 HRS (OUR REF: SRSTP.3630.19.SL) / OUR REF: SNM19D202044

Dear Boon Sen,

We refer to your email of even date.

We regret to inform you that our client is not agreeable to your proposed list of motor surveyors. Henceforth, we propose that you choose a surveyor from our list of surveyors as appended below:

List of Surveyor firms	
Appraisal VP Pte Ltd	Victor Png
Appraisal VP Pte Ltd	Jaclyn Loh
Allied Auto Appraisal	H C Ng
Pro-Options Services	Liaw Leong San
Pal's Appraisal Pte Ltd	
Auto Performance Appraisal	Lek Boon Hwee
SK Auto Consultants	Kumar
Precision Appraisal	Philip Foo
Hoh Andrew	Prominent Appraisal

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume that you have no objections to our list of motor surveyors and you will be deemed to have agreed to any of the above motor surveyors as a "single joint expert".

Should you object to our list of surveyors, we will inform the claimant accordingly to instruct his choice of motor surveyors to conduct the pre-repair survey.

Also, please be informed that our client do not have any estimated Costs of Repairs.

Warmest Regards,

Evelyn Tan
M/s Ong & Shan LLC
Block 184 Toa Payoh Central
#02-364 Singapore 310184

Tel: 6224 9847 Fax : 6254 7261
Email: ongshanllc@gmail.com

On Thu, May 9, 2019 at 9:09 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG

LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, 9 May, 2019 9:02 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; ongshanllc@gmail.com

Cc: Angie Foo <angie.foo@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: FW: ACCIDENT INVOLVING SKC 9138G & SJK 3744R ON 08.05.2019 ALONG AYE @ 0840 HRS (OUR REF: [SRSTP.3630.19.SL](#))

Dear Boon Sen,

Please conduct PRS – TP: SKC9138G (SNM19D202044) soonest possible.

File with OIC – Boon Sen - 63896171

From: Ong & Shan LLC [<mailto:ongshanllc@gmail.com>]

Sent: Wednesday, 8 May 2019 5:52 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: ACCIDENT INVOLVING SKC 9138G & SJK 3744R ON 08.05.2019 ALONG AYE @ 0840 HRS (OUR REF: SRSTP.3630.19.SL)

Dear Sirs,

Please see attached our Notice which was faxed to you earlier today. Kindly let us have your reply.

Warmest Regards,

Evelyn Tan

M/s Ong & Shan LLC

Block 184 Toa Payoh Central

#02-364 Singapore 310184

Tel: 6224 9847 Fax : 6254 7261

Email: ongshanllc@gmail.com

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2543D
Vehicle Details	
Vehicle No.:	SKC9138G
Vehicle to be Exported:	No
Intended Deregistration Date:	13 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250 AUTO LUX FL
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	4GR0554658
Chassis No.:	JTHBK262102093671
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$41,697.00
Original Registration Date:	31 Mar 2009
First Registration Date:	31 Mar 2009
Transfer Count:	1
Actual ARF Paid:	\$41,697.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2029
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$30,442.00
Total Rebate Amount:	\$30,442.00

The information contained herein is correct as at 13 May 2019

OK

500+ dealers
competed to
buy my car!



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years Renewal Coe Toyota Wish



2.08% P.A. 60 Admin Fee @ COV
Finance 2 Years Warranty \$3800
Down Monthly from \$288
GV Credit Pte Ltd. Starke



VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

view our cars

Browse by Category

Sort by Date Posted

20 results/page

14 vehicles

Lexus IS250

Advanced Search



Search Selection

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Lexus IS250		Any	Any	> 10 year(s) old	Any	Any	Any	Available



Lexus IS250 (COE till 04/2026)

\$61,800

\$8,930 /yr

12-Apr-2006

2,500 cc

133,000 km

Luxury

Available

Sheltered Parked, Immaculate Condition And Drives Like New! Bone Dry Undercarriage! Underwent Major Preventive Wear And Tear Replacement Recently: Alternator/Starter Motor/Brakes And Suspension System...

Posted: 28-Mar-2019

Tags: 2006 Lexus IS250, 2006 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus

DIRECT OWN



Lexus IS250 (COE till 05/2021)

\$18,500

\$9,050 /yr

29-May-2006

2,500 cc

210,000 km

Luxury

Available

Car In Good Condition. Family Upsizing. Price Is Somewhat Firm.

Posted: 26-Apr-2019

Tags: 2006 Lexus IS250, 2006 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus

DIRECT OWN



Lexus IS250 Luxury (COE till 06/2021)

\$20,800

\$9,750 /yr

19-Jul-2006

2,500 cc

143,000 km

Luxury

Available

"One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Accident Free, STA Or VICOM Are Welcome, Wear And Tear Replaced, Purchase Comes With Official Warranty Ce...

Carway

Posted: 09-May-2019

Tags: 2006 Lexus IS250, 2006 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus

DIRECT OWN



Lexus IS250 (COE till 07/2021)

\$20,800

\$9,370 /yr

31-Aug-2006

2,500 cc

Luxury

Available

Always Wanted A Luxury Yet Powerful Sedan? Here Comes An Opportunity For You! Luxurious Sedan That Is Powerful With A Smooth Drive, At An Affordable Price And Low Commitment. Evaluated By Our In-house...

Posted: 24-Apr-2019

Tags: 2006 Lexus IS250, 2006 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus

DIRECT OWN

GET YOUR
COE
RENEWAL
LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Lexus IS250 (COE till 10/2027)

\$70,000

\$8,320 /yr

11-Oct-2007

2,500 cc

257,000 km

Luxury

Available

Over \$25K Of Accessories, Super Reluctant Sales. High Mileage But New Gearbox Under Warranty. V6 Engine. Serviced Every 6-8K Mileage. 19" Ori Vertini Rims, F Sport 6 Big BBK, Tesla Audio, V Vision Bod...

Posted: 07-May-2019

Tags: 2007 Lexus IS250, 2007 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus

DIRECT OWN

Compare



Lexus IS250 (COE till 01/2028)

\$52,800

\$6,050 /yr

31-Jan-2008

2,500 cc

137,000 km

Luxury

Availabl

Well Maintained! Interior And Exterior All Well Maintained And In Excellent Condition. Comes With 3 Free Servicing Packages. 100% Accident Free. 90% In House And Bank Loan Available. Trade In Welcome....

Performance Carz Pte Ltd

Posted: 08-May-2019 Tags: 2008 Lexus IS250, 2008 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 Luxury (COE till 01/2023)

\$35,888

\$9,640 /yr

01-Feb-2008

2,500 cc

107,028 km

Luxury

Availabl

We Are The COE Specialist. No Gimmicks, Honest Dealing, Low Mileage Clocked, Car In Superb Condition. Full Loan Available, 100% Approval. Trade In Welcome, Bank Loan Available. Call Us For An Appointment...

Posted: 12-Apr-2019 Tags: 2008 Lexus IS250, 2008 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 (New 5-yr COE)

\$58,800

\$11,750 /yr

14-Nov-2008

2,500 cc

125,945 km

Luxury

Availabl

Options To Renew COE 10 Years At \$65800! Own A Luxury Car At A Affordable Price, Well Maintained, Low Mileage! Reliable And Smooth Drive. Flexible Bank/ In House Loan Package With Attractive Interest ...

Posted: 18-Apr-2019 Tags: 2008 Lexus IS250, 2008 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 Luxury (COE till 01/2029)

\$76,999

\$7,960 /yr

12-Jan-2009

2,500 cc

64,000 km

Luxury

Availabl

New F Sport Face Lift Fitted, New 4 Nos Shock Absorption, Aircon Cooling Coil, Alternator, Receipt Prove Mileage Only 63000 Km! Luxury Model, Neat/Clean/Stock Condition, Engine And Gearbox Tip Top Condit...

Posted: 07-Apr-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 Luxury (COE till 01/2029)

\$63,977

\$6,580 /yr

30-Jan-2009

2,500 cc

115,000 km

Luxury

Availabl

Loan Available, Full Specifications Luxury Model, \$800 For Monthly Installment, New Paintwork, New Rims, Low Mileage, Low Depreciation, Excellent Maintained Condition, No Repairs Needed And Comes With...

Posted: 30-Mar-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Free Valuation by sgCarMart Quotz

Trading-in your Car? Make a better informed decision by getting your Car accurately valued with Quotz, based on SG's largest car database, sgCarMart. Get notified via Phone, SMS, Email. Sell your Car for more - Get your Free Valuation Today.

Find out more!



Lexus IS250 (COE till 02/2029)

\$60,800

\$6,230 /yr

12-Feb-2009

2,500 cc

135,000 km

Luxury

Availabl

Very Well Maintained. Full Service Done 1 Month Ago Including Transmission Oil (ATF) Change, New Tires, Brake Pads, Brake Master Pump, Aircon Filters, Spark Plugs

Posted: 07-May-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 (COE till 03/2029)

\$66,800

\$6,770 /yr

23-Mar-2009

2,500 cc

106,164 km

Luxury

Availabl

Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With Confidence! Call Us Now To Make An Appoin...

Posted: 03-May-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 (New 10-yr COE)

\$68,800

\$6,870 /yr

24-Apr-2009

2,500 cc

144,736 km

Luxury

Availabl

(100% Quality Buy!) Drive With Confidence From CaseTrust Accredited Dealer. Vehicle Fully Done Up In Showroom Condition With Premium Grooming And Brand New Paint Coat. Purchase Comes With 6 Months Eng...

Sincere Motoring

Posted: 12-May-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus



Lexus IS250 (New 10-yr COE)

\$64,800

\$6,470 /yr

13-May-2009

2,500 cc

-

Luxury

Availabl

Drive With Pleasure When You Lay Your Hands On A Full Carbon Fiber Steering Wheels With Paddle-shifters Worth \$2800. Upgraded Software & Exhaust For Optimum Power Gain Of 30bhp, Down 30%, Monthly Only...

Allmotoring.sg

Posted: 07-May-2019 Tags: 2009 Lexus IS250, 2009 lexus is250, Lexus IS250, lexus is250, Lexus, IS250, is250, Used Lexus

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/05/2019 13:39
Date Of Accident	08/05/2019 08:40
Exact Location Of Accident	AYE (MCE) BEFORE EXIT 10B
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC9138G
Insured/Policyholder	
Name Of Registered Owner	MR LIEW CHAT SOON
NRIC No	S1272543D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97455591
Alternative Phone No	OFFICE-97455591

Vehicle Particulars

Manufacturer	TOYOTA
Model	LEXUS IS250 AUTO LUX FL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MC014122-R07
Cover Note Number	

Driver

Name of Driver	LIEW CHAT SOON
NRIC No	S1272543D
Date Of Birth	13/02/1957
Occupation	INDOOR
Date Of Driving Pass	08/08/1978
Driving Experience	40 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97455591
Fax Number	
Contact Number	OFFICE-97455591
EMail Address	NOEMAIL

Address	23 JALAN RAJA UDANG #28-07
Postcode	329216
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG THE STATED VENUE. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK3744R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PRITHIVAN
NRIC/Passport Number	S8814664F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.


[The remaining lines of the form are empty, with a diagonal line drawn across the middle section.]

DECLARATION

(We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:






































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		13 May 2019 14:49 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ~ Co. Reg. No.: -									
Main Claimant: LIEW CHAT SOON									
Vehicle Reg. No.: SKC9138G		Date of Loss: 08/05/2019 00:00 - :59 [121 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D202044C02		Policy/Cover Note No.: DMPCSN30711818000							
Vehicle Reg. No. (Insured): SJK3744R		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 23/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKC9138G (SNM19D202044C02)
[SJK3744R]
TP
LIEW CHAT SOON
May 8 2019 12:00AM
[-]
Sheng Li Lai

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print		
1	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
2	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
3	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
4	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
5	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
6	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
7	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
8	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
9	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
10	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
11	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
12	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
13	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
14	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
15	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
16	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
17	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
18	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
19	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
20	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
21	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
22	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
23	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
24	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
25	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
26	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
27	04/06/19 19:20	General View				 Load JPG	<input checked="" type="checkbox"/>		
28	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		
29	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		
30	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		
31	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		
32	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		
33	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		
34	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		
35	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		
36	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		
37	04/06/19 19:20	Photographs of Damaged Parts				 Load JPG	<input checked="" type="checkbox"/>		

Photos/Images				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
39	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
40	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
41	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
42	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
43	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
44	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
45	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
46	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
47	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
48	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
49	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
50	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
51	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
52	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
53	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
54	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
55	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
56	04/06/19 19:20	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
57	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
58	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
59	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
60	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
61	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
62	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
63	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
64	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
65	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
66	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
67	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
68	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
69	04/06/19 19:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/05/19 14:50	PRI CONTACT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19008204/ECD3E2

Date: 20/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30711818000

Claimant Vehicle
No: SKC9138GInsured Vehicle
No: SJK3744R

Date of Loss: 08/05/2019

Nature of Claim: TP

Claim
No: SNM19D202044C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC9138G

Make & Model: LEXUS IS250, 2.5 Luxury FL (A)

Engine No: 4GR0554658

Reg. Date: 31/03/2009 (Man. Year: 2009)

Chassis No: JTHBK262102093671

Colour: Black

Odometer: 243485 km

Engine Capacity: 2500 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/05/2019

Date Inspected: 10/05/2019 Inspected At:

Sheng Li Lai (KAKI BUKIT)
NO. 2 KAKI BUKIT AVE 2, # 01-36
AUTOHUB KAKI BUKIT
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2019)
Parts:	143	LEXUS IS250 2.5 Luxury FL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC9138G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >