

2/6/2009

ASS. REC. BY:

REF:

08/11/19008220/Bed30b

Special Instruction:

SURVEYOR  
M. Kim

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

9/5/19 @ 9:34 am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKT9024L

Insured:

S/N 66077

at Workshop n/s

Tampines Auto

Tel:

6786 2884

of

Blk 9002 Tampines 84-93 # 01-36 Ind. park A

Policy No:

1700050388

Claim No:

145615567486

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

7/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:09pm @ 9/5/19

Person Contacted:

Ms. Linda

Vehicle:

IN OUT

Date/Time

Action/Instruction (X) Estimate

S KT9024L-X

S/N 66077-X

Dismantle: 10/5/2019

Bedore paint: 13/5/2019

Barry

## ASSIGNMENT

PRS

From:

Date: 9/5/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKT 9024L

at Workshop m/s

Tampines Auto

of

Blk 9002 Tampines St. 93 #01-36

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>lup</sup>

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKT 9024L Yr Regn: 25/6/2015

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 5 2.0L

C.C. 1998

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

87891

T/Radio: Insured / Std / NI / NA

Eng/No:

PE10230880

C/No:

JM6CW 1071F0121854

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55/16

R: 205/55/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

7/5/2019

D.O.I.

9/5/2019

Survey held at

Tampines Auto

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV 69,000/2  
 PV 52,827/2  
 NV 16,173/2

Tamim bin  
 13/5/2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format:

DAR

Lump Sum / I.B.I: (\$ )


180

11

191

Your password will expire in 4 days. [Click here to change it.](#)

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 5/9/2019 9:34:43 AM  
Attachments:  tmpAD45.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Joycelyn [mailto:joycelyn@legaloptions.biz]

**Sent:** Wednesday, May 08, 2019 4:19 PM

**To:** Hor, Yinrul

**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJN6607T AND SKT9024L ON 07/05/2019

**This message is from an external sender; be cautious with links and attachments.**

Dear Sir/Mdm,

We refer to your email dated 16/04/2019.

Our client rejected your list of surveyors.

We provide you herewith our client's surveyors:-

	CONTACT PERSON
1	HOW ANDREW
2	LEE KOK WENG
3	SEAH KWANG BOON

Your said surveyor may liaise directly with our client's repairer,  
Ms Linda at 6786 2884 for  
the pre-repair inspection to be carried out.

The workshop is located at M/s Tampines Auto Services, Block 9002 Tampines Street 93, #01-36 Tampines Industrial Park A,  
Singapore 528836.

\*  
If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor  
appointed by our clients shall be our single joint expert for this matter.

Thanks n regards,

*Joycelyn Sim*

Legal Secretary

**LEGAL OPTIONS LLC**

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2807 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**LEGAL OPTIONS LLC**ADVOCATES & SOLICITORS  
Mediators - Commissioners for Oaths - Notary Public**法商律师事务所***Motor Accident & Personal Injuries*

Tel: (65) 6513 2800 Fax: (65) 6438 8275

*Commercial, Litigation, Property, Trust & Estate, Family*

Tel: (65) 6438 8039 Fax: (65) 6734 8230

*We do not accept service of Court Documents by fax*

Your Ref : SJN 6607T  
Our Ref : 19-A21-10336-VL.ts.js

8<sup>th</sup> May 2019**M/S AIG ASIA PACIFIC INSURANCE PTE LTD**

78 Shenton Way #07-16

AIG Building

Singapore 079120

(Attn: Motor Claims Department)

Dear Sirs,

**CLAIMANT : ROSKHAIDER BIN MOHAMED SAAT**  
**ACCIDENT INVOLVING SKT 9024L AND SJN 6607T ALONG JURONG WEST ON 07/05/2019**

We are instructed by **MR ROSKHAIDER BIN MOHAMED SAAT** to notify you of a road traffic accident on **7<sup>TH</sup> MAY 2019** at about **07:30 HOURS ALONG JURONG WEST EXITING INTO JALAN BAHAR** involving our client's vehicle registration number **SKT 9024L** and vehicle registration number **SJN 6607T** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



Cc: Client (SKT 9024L)

**Directors**

Joan Lim Pheok Hoon LL.B (Hons)

Victor Leong Wai Meng LL.B (Hons)

Teo Lip Hua Benedict LL.B (Hons) LL.M

Junior Secretary's DID: 6513 2807

Direct Fax: 6438 8275

(Email: [joycelyn@legoptions.biz](mailto:joycelyn@legoptions.biz))

Mailing Address for Accident Claims

Documents Support:

23 Kaki Bukit Avenue 4 #01-01 South Wing,  
Singapore 415933**IMMEDIATE ATTENTION***By Fax: 6415 3727/Post*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle


<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7244E
<b>Vehicle Details</b>	
Vehicle No.:	SKT9024L
Vehicle to be Exported:	No
Intended Deregistration Date:	13 May 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	PE10230880
Chassis No.:	JM6CW1071F0121854
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,145.00
Original Registration Date:	25 Jun 2015
First Registration Date:	25 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$12,145.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2025
PARF Rebate Amount:	\$9,108.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Jun 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,509.00
COE Rebate Amount:	\$43,719.00
<b>Total Rebate Amount:</b>	<b>\$52,827.00</b>

The information contained herein is correct as at 13 May 2019

OK

Dep 10,500/yr

MV 69,000/2  
PV 52,827/2  
NV 16,173/2

TG Lim   
13/5/19



**Mazda 5 2.0A Sunroof** \$70,800 \$10,520 /yr 30-Jun-2015 1,998 cc 38,896 km MPV Available

A Family Car With Generous Cabin Space And Relatively Fuel Efficient Family Transportation! Financing Packages Available! Trade In Welcome! Buy With Confidence From Mazda/Eurokars Pre-Owned Centre! Hi...

Posted: 08-May-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Mazda 5 2.0A Sunroof** - N.A 19-Aug-2015 1,998 cc - MPV **SOLD**

Direct Seller, 1 Owner, Low Mileage Of At 44K, Regular Servicing, With Road Tax Renewed To Aug 2019. A Family Car With Generous Boot Space. Urgent Sale. Interested Buyers, Please Email Mezzo3 At Gmai...

**DIRECT OWNER**

Posted: 08-Mar-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Mazda 5 2.0A Sunroof** - N.A 31-Aug-2015 1,998 cc - MPV **SOLD**

Beautiful Sunroof Unit Original Condition! Well Maintained, Almost Brand New Condition. Spacious 7 Seater With Extremely Low Fuel Consumption! Strictly By Appointment Only. Call Now!

Cosmo Automobiles

Posted: 16-Mar-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Insurance renewal at cheaper price!**

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



**Mazda 5 2.0A Sunroof** - N.A 31-Aug-2015 1,998 cc - MPV **SOLD**

Full Loan Available At \$1k+/ Month We Can Help To Conver To Z10 Usage If Needed. In House Loan / Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart ...

88 Motor Trading

Posted: 08-Mar-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Mazda 5 2.0A Sunroof** - N.A 22-Sep-2015 1,998 cc - MPV **SOLD**

100% Loan Available, 1 Owner, Serviced By Agent, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.

Faster Auto Trading

Posted: 02-Mar-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Mazda 5 2.0A Sunroof** - N.A 23-Sep-2015 1,998 cc - MPV **SOLD**

Full Loan Available With Our Flexible In-House Loan Options! 1 Year Warranty By Jack Cars Service Center. Free Jack Cars Servicing Vouchers And Free Concierge Service. Midnight Blue With Black Leather...

Jack Cars Enterprise Pte Ltd

Posted: 17-Mar-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Mazda 5 2.0A Sunroof** - N.A 23-Sep-2015 1,998 cc - MPV **SOLD**

Elegant Silver MPV, One Owner Only, With Sunroof, Low Maintenance Cost, Very Well Maintained, With Warranty, Flexible In-house Loan Packages Available.

Posted: 22-Feb-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Mazda 5 2.0A Sunroof** - N.A 25-Sep-2015 1,998 cc - MPV **SOLD**

Low Interest Rate From 1.99% For Limited Period Only! In House Loan Available. 1 Owner Only! Super Well Maintained/Tip Top Condition With Sunroof. Extended Warranty Provided, Buy It From Us With A Pea...

Dickson Automobile

Posted: 20-Feb-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Mazda 5 2.0A Sunroof** - N.A 19-Oct-2015 1,998 cc - MPV **SOLD**

Rare Mazda 5 With Low Depreciation Yet Negotiable! Road Tax Till Oct 19. Amazing Low Mileage Done Of 40519km! Agent Serviced With Proof. 1 Owner. Nice And New Car Number. 100% Accident Free. Call Now!

**PREMIUM AD**

Lake View Credit Pte Ltd

Posted: 09-Mar-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Mazda 5 2.0A Sunroof** - N.A 16-Nov-2015 1,998 cc - MPV **SOLD**

Serviced At Eurokars With Proof, Last On Oct 18. Amazing Low Mileage Done 62725km. Excellent Condition, 1 Fussy Lady Owner. Nice And New Car Number. Road Tax Till May 19. 100% Accident Free. Call Now!

**PREMIUM AD**

Lake View Credit Pte Ltd

Posted: 16-Mar-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda



**Mazda 5 2.0A Sunroof** - N.A 20-Nov-2015 1,998 cc - MPV **SOLD**

Beautiful Metallic Silver, 1 Careful Owner, Fully Service By Agent, Under Warranty. Well Maintained, Seldom Used. Per Year 14800 KM Only, Accident Free, Elite Highest Spec Model, Just Serviced, Undergone...

**PREMIUM AD**

Jia Leong Trading Enterprise

Posted: 05-Apr-2019 Tags: 2015 Mazda 5, 2015 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/05/2019 16:43
Date Of Accident	07/05/2019 07:30
Exact Location Of Accident	JURONG WEST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT9024L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ROSKHAIDER BIN MOHAMED SAAT
NRIC No	S1817244E
Email Address	ROSKHAIDER@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96209323
Alternative Phone No	OTHERS-96209323

### Vehicle Particulars

Manufacturer	MAZDA
Model	5 2.0

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00301385
Cover Note Number	

### Driver

Name of Driver	ROSKHAIDER BIN MOHAMED SAAT
NRIC No	S1817244E
Date Of Birth	09/05/1967
Occupation	INDOOR
Date Of Driving Pass	04/08/1985
Driving Experience	33 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96209323
Fax Number	
Contact Number	OTHERS-96209323
Email Address	ROSKHAIDER@GMAIL.COM



Address	BLK 330 TAMPINES ST 32 #03-444
Postcode	520330
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FRONT & WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN6607T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the police for investigation.
6. The report will be forwarded by the Insurers of the RIA Records Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of the report will for a fee be made available upon application to interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the lodging of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIAS") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (at insurance) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers". The Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claim;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, medical reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the package well as putting my external mail in envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my personal data about the "Purposes".
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIAS to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management to prevent and settle claims;
- (e) the information as collected under (a) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that are involved in evaluating, investigating, handling or managing fraud and regulations, law enforcement and government agencies as reasonable required for the purposes set out, or;
  - (ii) for complying with requirements under any relevant law, law or court order;

Policyholder's Signature

Date & Time: 2/5/2019

16:40 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name:

HRG/RN No.:

## Sketch Plan #2

### SKETCH PLAN

	<p><u>Vehicle</u></p> <p>A -</p> <p>B -</p> <p><u>Legend</u></p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">               Vehicle         </div> <div style="text-align: center;">               Motorcycle         </div> </div>
---	---

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7 May 2019 at 7:30 am at Jurong West, exiting into Jalan Bahar. My car A was hit from behind by car B. Car A attained extensive damage due to hit by car B.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.  
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against your policy must be made within the stipulated time frame from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time: 9/5/2019  
 16:40 pm

Driver's Signature

(If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature

Name:  
 NRIC/FIN No.:

.SKT 9024L

[illegible]

### ...CLAIM SUBFOLDER...(Pending for Survey Report)


































PRI



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 May 2019 <a href="#">Edit Reg</a>		09 May 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	KENNETH GOH THIAM HOCK WU, ID: S7812814C								
Main Claimant:	NA								
Vehicle Reg. No.:	SKT9024L	Date of Loss:	07/05/2019 00:00 - :59 [46 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5609360116SG	Policy/Cover Note No.:	1700050388 (Comprehensive) Coverage: 10/08/2018 - 09/08/2019						
Vehicle Reg. No. (Insured):	SJN6607T	Policy No. (Claimant):							
		Excess:							
Repairer:	Tampines Auto Services (HQ) BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A, 528836 Tampines - Tel: 67862884								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 21/05/2019]								
Claimant's Solicitor:	LEGAL OPTIONS LLC - Tel: 64388039								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (10/05/2019): Request To Upload TP GIA Report</li> <li>AIG_SG (10/05/2019): Conflicting DOA</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

















































## Claim Documents

**\*SKT9024L (5609360116SG)**  
**[SJN6607T]**  
**TP**  
**NA**  
**May 7 2019 12:00AM**  
**[KENNETH GOH THIAM HOCK WU]**  
**Tampines Auto Services**


Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View In Browser	
Photos/Images										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print		
1	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
2	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
3	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
4	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
5	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
6	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
7	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
8	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
9	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
10	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
11	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
12	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
13	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
14	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
15	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
16	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
17	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
18	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
19	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
20	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
21	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
22	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
23	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
24	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
25	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
26	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
27	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
28	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
29	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
30	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
31	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
32	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
33	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
34	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
35	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
36	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	
37	31/05/19 12:21	General View									Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
39	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
40	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
41	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
46	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
47	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
48	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
49	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
50	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
51	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
52	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
53	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
54	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
55	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
56	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
57	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
58	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
59	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
60	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
61	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
62	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
63	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
64	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
65	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
66	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
67	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
68	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
69	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
70	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
71	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
72	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
73	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
74	31/05/19 12:21	General View	 Load JPG	<input checked="" type="checkbox"/>
75	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	31/05/19 12:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	31/05/19 12:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/05/19 11:02	OI GIA report	 Load PDF	



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19008220/BCD3E2

Date: 27/06/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700050388  
**Claimant Vehicle No :** SKT9024L **Insured Vehicle No :** SJN6607T  
 Date of Loss: 07/05/2019 Nature of Claim: TP Claim No: 5609360116SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT9024L**  
 Make & Model: MAZDA MAZDA5, 2.0 5-DOOR WAGON 2.0L SP.6EAT SUNR (A) Engine No: PE10230880  
 Reg. Date: 25/06/2015 (Man. Year: 2015) Chassis No: JM6CW1071F0121854  
 Colour: Red Odometer: 87891 km  
 Engine Capacity: 1998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm  
 Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 09/05/2019  
 Date Inspected: 09/05/2019 Inspected At: Tampines Auto Services (HQ)  
 BLK 9002 TAMPINES ST 93, #01-34/36  
 INDUSTRIAL PARK A  
 Singapore 528836  
 Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE GARNISH	Bent	0.00 F	*- F
3	1		*REAR NUMBER PLATE LAMP	Dislodged	0.00 F	*- F
4	1		*REAR BUMPER	Dented	0.00 F	*- F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
8	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
9	2		*REAR BUMPER REFLECTOR	Dislodged	0.00 F	*- F
10	1		*REVERSE SENSOR	Dislodged	0.00 F	*- F
11	1		*REAR END PANEL	Dented	0.00 F	*- F
12	1		*REAR END PANEL TOP GARNISH	Dislodged	0.00 F	*- F
13	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
14	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
15	1		*TAILGATE	Dented	0.00 F	*- F
16	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
17	1		*TAILGATE GARNISH	Cracked	0.00 F	*- F
18	2		*TAILGATE LAMP	Broken	0.00 F	*- F
19	1		*TAILGATE PROTECTOR	Bent	0.00 F	*- F
20	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
21	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
22	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
23	1		*TAILGATE RUBBER	Distorted	0.00 F	*- F
24	1		*TAILGATE INNER BOARD	Distorted	0.00 F	*- F
25	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
26	1		*REVERSE CAMERA	* Check	0.00 F	*- F
27	1		*EXHAUST PIPE / SILENCER	Bent	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >