

FINALIZATION		Date/Time: _____	Confirm with: _____	Confirm by: _____
Repair Cost: 46	\$S 700.00	() days	Reduction: 34 %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time: 01/08/19	Confirm with: WTS	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	\$S 100	(Agreed / Assessed)	E.O.L.A S/N No.: 15	If NO or B 28, Ass. Lia: _____
Repair Cost: (46/690)	\$S 719.00			COI CHARGED LANE
Loss of Rental (LOR):	\$S _____	() days		
Loss of Use (LOU):	\$S 280.00	(280 x 1 days)		
Loss of Income (LOI):	\$S _____	(S x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]		
Global TA Search	\$S 2.00			
Medical:	\$S _____			1) Claim status: Normal/Reject/Private Settle
Disbursement:	\$S _____	(e.g. Tow/Independent)		2) Report format: _____
Legal Costs:	\$S _____			3) Survey fee: 4320.00
Total:	\$S 1,001.00	Global Sum \$S:	1,000.00	
FINAL PAYMENT		Date/Time: _____	Confirm with: _____	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$S 1,000.00	Name 1:	WTS ENGINEERING PTE LTD	
Payee 2: (Strike if N.A.)	\$S _____	Name 2:	_____	
Payee 3: (Strike if N.A.)	\$S _____	Name 3:	_____	



WTS Engineering Pte Ltd
8 Gul Circle, Singapore 629664 Tel: 65588964 Fax: 65622163
Company Registration Number: 200505706E

Quotation

DATE: 07/05/19
VEHICLE NO: PA8671Z
DRIVER: ZHU CHEN SHENG
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q19/05/1015
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 02/05/19
REF No: JW-0519-308

S/N	Description	Qty	Cost per Unit	Amount S\$
Spares Parts				
1	FRONT PASSENGER DOOR RUBBER MUDGUARD	1	320	320.00
Labour Costs				
1	TO REMOVE AND REPLACE FRONT PASSENGER DOOR RUBBER MUDGUARD	1	400	400.00
Spray Paint				
1	Spray Painting TO SPRAY PAINTING FRONT BUMPER.	1	350	350.00
TOTAL:				1,070.00
Total Amount				SGD 1,070.00

15% - 272

852

4/5/19 700 x
01 day

Remarks:

Signature of Workshop Opt

Signature of Department Head

Signature of Claim Department

Surveyor Sign: [Signature]
Surveyor Name: Tan Jia
Date: 10/5/19 8:45pm

Tan Jia 93415749
'nd'
6/5/19 8:45pm
Resing after painting
01 day
tan jia e (handwritten)
LKK

N.V. = 142
68411972

Look Again Carefully before really
the Repairs of the following:
• To respray/replace/repair spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairs

Signature:

Date:

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 07/05/19
VEHICLE NO: PA98712
DRIVER: ZHU CHEN SHENG
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q19/05/1015
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 02/05/19
REF No: JW-0519-308


S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	FRONT PASSENGER DOOR RUBBER MUDGUARD	1	320	320.00
Labour Costs				
1	TO REMOVE AND REPLACE FRONT PASSENGER DOOR RUBBER MUDGUARD	1	400	400.00
Spray Paint				
1	Spray Painting TO SPRAY PAINTING FRONT BUMPER.	1	350	350.00
TOTAL:				1,070.00
Total Amount				SGD 1,070.00

Remarks:

Signature of Workshop Dpt

Signature of Department Head

Signature of Claim Department

Surveyor Sign: 
Surveyor Name: Tanphir
Date: 14/5/19 @ 945pm

Tanphir 97495749
14/5/19 @ 945pm
Resurvey after painting
01 day
tanphir @ 14/5/19
LKK

N.V. 7th
68411972

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

1 / 1

Acknowledged by Repairer
Signature:
Date:



Your password will expire in 5 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION REQUEST – PA9871Z vs SMG5942H (OI) on D.O.A.: 02/05/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 5/8/2019 11:13:09 AM
Attachments: GIA.PDF, PRI.pdf, QUOTATION.pdf, GIA.PDF, PRI.PDF, QUOTATION.PDF

Hi,

Please refer to the enclosed request from **Woodlands Transport Service Pte Ltd.**

Claim no : 7443170647SG003
Case Owner : KIAN MENG CHAN

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Mohamad Taufikh** as Single Joint Expert as requested.*

Thanks & Regards,

Yin Rut, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOL Claims Operations – Auto
Yinrut.Hor@aig.com | [+65 6559 8988](tel:+6565598988)

12.04pm @ 8/5/19
person @ Mr. Chen
vehicle not in.

From: kenjilee@woodlandtransport.com.sg [mailto:kenjilee@woodlandtransport.com.sg]
Sent: Tuesday, May 07, 2019 5:34 PM
To: Hor, Yinrul; Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Cc: goo@woodlandtransport.com.sg; sichan@woodlandtransport.com.sg
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG5942H AND PA9871Z ON 02/05/2019

This message is from an external sender; be cautious with links and attachments.

Dear All,

We choose Mr Mohamad Taufikh (LKK Auto Consultants Pte Ltd) as the single joint expert for this PRI

Thank you.

Thanks and Regards,

Kenji Lee

Claims Department

Woodlands Transport Service Pte Ltd
8, Gul Circle, Singapore 629564
Main Line : +65 6559 8988 Fax : +65 6898 2394
Direct Line : +65 6559 8954
www.woodlandtransport.com.sg

6559 8984

Group of Companies:

From: Hor, Yinrul <Yinrul.Hor@aig.com>
Sent: Tuesday, 7 May 2019 4:30 PM
To: kenjilee@woodlandtransport.com.sg
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG5942H AND PA9871Z ON 02/05/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-05-14 16:30 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com

To: kenjilee@woodlandstransport.com.sg

Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariessa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG5942H AND PA9871Z ON 02/05/2019

Date: Tue, 7 May 2019 08:30:07 +0000

Without Prejudice

Your Reference : JW/0519/308

Our Reference : 7443170647SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

✱

Yin Rul, Hor (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations ✱ C Auto

Yinrul.Hor@aig.com | www.aig.sg

From: kenjilee@woodlandstransport.com.sg [mailto:kenjilee@woodlandstransport.com.sg]

Sent: Tuesday, May 07, 2019 4:15 PM

To: Hor, Yinrul

Cc: goo@woodlandstransport.com.sg; slchan@woodlandstransport.com.sg

Subject: [EXTERNAL] PRI PA9871Z VS SMG5942H DOA 02/05/19

This message is from an external sender; be cautious with links and attachments.

Dear Sir

ACCIDENT INVOLVING SMG5942H WITH OUR VEHICLE NO PA9871Z ON 02/05/2019

We refer to the above accident and understand that you are the insurer of SMG5942H

Our vehicle sustained damages in the above accident.

Please send your surveyor to our premises at **No. 8 Gul Circle, Singapore 629564**.

Please contact **Mr Chan at Tel: 6559 8984 / 9299 4122** for an appointment to view the vehicle.

Attached is the repair estimate for your perusal.

For your immediate attention and action, please.

Thank you.

Thanks and Regards,

Kenji Lee

Claims Department

Woodlands Transport Service Pte Ltd

8, Gul Circle, Singapore 629564

Main Line : +65 6559 8988 Fax : +65 6898 2394

Direct Line : +65 6559 8954

www.woodlandstransport.com.sg

Group of Companies:



WTS Engineering Pte Ltd

(Joy)

YOUR REF : SMG5942H
OUR REF : JW/0519/308

19 June 2019

AIG Asia Pacific Insurance Pte Ltd C/O

LKK Auto Consultants Pte Ltd

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25

Singapore (408933)

Attention : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING SMG5942H WITH OUR VEHICLE PA9871Z ON 02/05/2019

We refer to the above accident and understand that you are the insurer appointed surveyor of SMG5942H.

From our investigation, we are of opinion that the accident arose as a result of your insured's negligent driving.

Our loss in this connection comprises the following:

1. Cost Of Repair	\$	749.00
2. 1 Day Loss Of Use	\$	350.00
3. Search Fees	\$	2.00

Total	\$	1,101.00
-------	----	-----------------

Please let us know whether you are prepared to admit liability and reimburse our loss in full within the next two weeks on receipt of this letter otherwise we will proceed the matters legally which we will recourse the costs incurred to you.

Please acknowledge receipt of this Letter of Demand

Thank you.

Yours faithfully,

Kenji Lee

Claims Department

Direct Line : (65) 6559 8954

Facsimile : (65) 6898 2394

Email : kenjilee@woodlandstransport.com.sg

WTS Engineering Pte Ltd

8, Gul Circle, Singapore 629564. Tel: 6 559 8988 Fax: 6 898 2394

URL www.woodlandstransport.com.sg

Company Registration Number : 200505706E



bizSAFE₃





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

18 JULY 2019

LIU LILI
BLOCK 34 JURONG EAST STREET 32
#07-229
SINGAPORE 600314

By Post & By Email

Dear Sir/Madam,

OUR REF : CC4/AIG19008221/T1hb3
YOUR REF : SMG 5942H
ACCIDENT INVOLVING SMG 5942H AND PA 9871Z ALONG 6 BOON LAY AVENUE
ON 02.05.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of PA 9871Z against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle PA 9871Z. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2096 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

lliusq@yahoo.com.sg
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Thursday, 18 July, 2019 2:46 PM
To: lliusg@yahoo.com.sg
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SMG 5942H_ACCIDENT INVOLVING SMG 5942H AND PA 9871Z ALONG 6 BOON LAY AVENUE ON 02.05.2019



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

18 JULY 2019

LIU LILI
BLOCK 34 JURONG EAST STREET 32
#07-229
SINGAPORE 600314

By Post & By Email

Dear Sir/Madam,

OUR REF : CC4/AIG19008221/T1hb3
YOUR REF : SMG 5942H
ACCIDENT INVOLVING SMG 5942H AND PA 9871Z ALONG 6 BOON LAY AVENUE ON 02.05.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of PA 9871Z against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle PA 9871Z. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2096 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



Your ref : CC4/ALG19008221/Tihb3
Our ref : JW10519/308

Date: 06/08/2019

ALG Asia Pacific Insurance Pte Ltd C/O
LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park, Ubi Ave1, # 02-25
Singapore 408733

WITHOUT PREJUDICE

Dear Sirs,

ACCIDENT INVOLVING 3MG5742H AND OUR VEHICLE NO PA9871Z ON 02/05/19

We, **Woodlands Transport Service Pte Ltd**, owner of Motor Vehicle Registration No.

PA9871Z do hereby authorize **WTS Engineering Pte Ltd** as my agent and representative to correspond in, negotiate and settle on my behalf, my claim against the parties involved in the above-mentioned accident.

Yours faithfully,

Lim Eng Kwong
Group Managing Director



Woodlands Transport Service Pte Ltd

B, Gul Circle, Singapore 629564
T: 6 559 8988 F: 6 898 2394
www.woodlandstransport.com.sg
UEN: 198102721M



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **WTS ENGINEERING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,000.00** (Global Sum – all in) for vehicle no. **PA 9871Z** that was damaged pursuant to the accident which occurred on **02/05/2019** (date) along **6 BOON LAY AVENUE** (location) involving vehicle no/s **SMG 5942H**. This is pursuant to the inspection conducted on **10/05/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **WOODLANDS TRANSPORT SERVICE PTE LTD** ("the third party claimant") of vehicle no. **PA 9871Z** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **PA 9871Z** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 1st (day) of August (month) **2019** (year)



WTF

Signed by appointed surveyor

A handwritten signature in black ink, appearing to be a stylized "P" or similar character.

Signed by "the workshop" (with chop)



WTS Engineering Pte Ltd

From : Workshop Department

M/S : Woodlands Transport Service Pte Ltd

No 8 Gul Circle

Singapore 629564

Date : 19-Jun-19

No: 0619/1028

S/n	Description	Unit	Amount
	Repair cost of PA9871Z		
	Accident Date: 02/05/19		
	Repair works took 1 day		
	Lumpsum repair inclusive of labour charges and spray painting		\$ 700.00
	Add 7% GST		\$ 49.00
	SGD: Seven Hundred Forty Nine Only		
		Total	\$ 749.00

Authorised Signature

WTS Engineering Pte Ltd

8, Gul Circle, Singapore 629564 Tel: 6 559 8988 Fax: 6 898 2394

URL: www.woodlandtransport.com.sg

Company Registration Number : 200505706E



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-069276
Date of Request: 03/05/2019

Your Ref No: Online Purchase

Woodlands Transport Service Pte Ltd
8 Gul Circle
Singapore 629564

Dear Sir/Madam,

Enquiry Date: 03/05/2019
Enquiry By: Goo Lee Ping
TP Vehicle No: SMG5942H
Accident Date: 02/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2019 Edit Reg		08 May 2019 00:00 Edit Adj Rpt	S\$700.00 Edit Estimates	S\$700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIU LILI, ID: 57080800E								
Main Claimant:	WOODLANDS TRANSPORT SERVICE PTE LTD, Co. Reg. No.: 198102721M								
Vehicle Reg. No.:	PA9871Z	Date of Loss:	02/05/2019 07:00 - :59 [101 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7443170647SG	Policy/Cover Note No.:	1900007212 (Comprehensive) Coverage: 26/12/2018 - 25/12/2020						
Vehicle Reg. No. (Insured):	SMG5942H	Policy No. (Claimant):	SD18V07061						
		Excess:							
Repairer:	Wts Engineering Pte Ltd (HQ) 8 Gul Circle, 629564 Tuas - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221-8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PA9871Z (7443170647SG)
[SMG5942H]
TP
WOODLANDS TRANSPORT SERVICE PTE LTD
May 2 2019 7:00AM
[LIU LILI]
Wts Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Photos/Images			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/19 14:51	Odometer Reading		<input checked="" type="checkbox"/>
2	18/07/19 14:51	Chassis Number		<input checked="" type="checkbox"/>
3	18/07/19 14:51	General View		<input checked="" type="checkbox"/>
4	18/07/19 14:51	General View		<input checked="" type="checkbox"/>
5	18/07/19 14:51	General View		<input checked="" type="checkbox"/>
6	18/07/19 14:51	General View		<input checked="" type="checkbox"/>
7	18/07/19 14:51	General View		<input checked="" type="checkbox"/>
8	18/07/19 14:51	General View		<input checked="" type="checkbox"/>
9	18/07/19 14:51	General View		<input checked="" type="checkbox"/>
10	18/07/19 14:51	General View		<input checked="" type="checkbox"/>
11	18/07/19 14:51	General View		<input checked="" type="checkbox"/>
12	18/07/19 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
13	18/07/19 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
14	18/07/19 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/05/19 16:26	EMAIL FROM AIG DD 08052019		<input type="checkbox"/>
2	09/05/19 16:26	TP ESTIMATE		<input type="checkbox"/>
3	09/05/19 16:26	TP GIA REPORT		<input type="checkbox"/>
4	13/05/19 18:51	TP ESTIMATE- MARKED		<input type="checkbox"/>
5	18/07/19 14:48	EMAIL TO OI		<input type="checkbox"/>
6	19/07/19 17:57	LETTER TO OI		<input type="checkbox"/>
7	08/08/19 10:10	AUTHORIZATION LETTER		<input type="checkbox"/>
8	13/08/19 09:19	WORKSHOP INVOICE		<input type="checkbox"/>
9	13/08/19 09:19	Release Voucher		<input type="checkbox"/>
10	13/08/19 09:19	GIA SEARCH		<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/05/19 10:38	OI GIA report		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMG5942H (Insd veh)	Model:	ISUZU LT134P 7.8 D (A)
	PA9871Z (TP veh)		
Date of Accident:	02/05/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		1,144.90
Final Repair Cost	:	\$		1,000.00
Loss of Use	:	\$		1.00 days at \$250.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		1,000.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	WTS Engineering Pte Ltd	: \$	1,000.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

13 Aug
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19008221/T1HB3Q2

Date: 13/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900007212
Claimant Vehicle PA9871Z **Insured Vehicle No :** SMG5942H
 No :
 Date of Loss: 02/05/2019 Nature of Claim: TP Claim No: 7443170647SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PA9871Z**
 Make & Model: ISUZU LT134P, 7.8 D (A) Engine No: 6HK1488755
 Reg. Date: 18/11/2010 (Man. Year: 2009) Chassis No: JALLT134PA7000040
 Colour: White Odometer: 444322 km
 Engine Capacity: 7790 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5 (D)
 Front Left Side: Distance 8 mm Rear Left Side: Distance 8/8 mm
 Front Right Side: Distance 8 mm Rear Right Side: Distance 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	320.00	272.00	48.00	15.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	580.00	170.00	22.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,070.00	852.00	218.00	20.37
Approved Total (Overridden) (S\$)		700.00		
(S\$)	1,070.00	700.00	370.00	34.58
+ GST 7.00/7.00% (S\$)	74.90	49.00	25.90	34.58
Nett Amount (S\$)	1,144.90	749.00	395.90	34.58
+ Loss of Use (1.0 x S\$250.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,001.00		
Global Sum Settlement (S\$)		1,000.00		

INSPECTION

Date of Assignment: 08/05/2019
 Date Inspected: 10/05/2019 Inspected At:

Wts Engineering Pte Ltd (HQ)
8 Gul Circle
Singapore 629564

Estimated Period of Repair: 1.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PASSENGER DOOR RUBBER MUDGUARD	Torn	320.00 F	*320.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					320.00	320.00
- List Item Discount on L Items 0.00/15.00% (\$\$)					0.00	48.00
Total Parts (\$\$)					320.00	272.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE FRONT PASSENGER DOOR RUBBER MUDGUARD	New	400.00	300.00
2	TO SPRAY PAINTING FRONT BUMPER	New	350.00	280.00
Gross Labour Cost (S\$)			750.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >