

ASS. REC. BY:

REF:

CS/ASM19008229 / d3

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Kitty teo

of

ASM (AXA)

Date/Time:

9/5/2019

Estimated Cost:

Bill to:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDP 2122L

Insured:

at Workshop m/s

Tel:

of

Policy No:

Claim No:

S8M017F8

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

19/12/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

Desktop Survey

SDP 2122L-X

5/6/2020

AXA has closed the case in SMART claim. Celine 5/6/2020



Service Request Details

Claim

S8M017F8

Reference

None 

Loss Date

December 19, 2018

Report Date

Dec 20, 2018 6:54:00 PM

Request Date

May 9, 2019

Due Date

May 16, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Desktop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDP2122L

MODEL
PANAMERA

Service Address

27A Tanjong Penjuru, , , 609042

Primary Contact/Insured

ANG KENG BOON
1 NEWTON ROAD, #27-01, 307943, Singapore

WILLIAM_ANG@XTRA.COM.SG

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

NAME

Accident Statement

TYPE

Reports & Statement

SUB-TYPE

AUTHOR

Merimen

DATE UPLOADED

NAME

Seek 2nd opinion on consistency of damages.pdf

TYPE

Letters and Correspondence

SUB-TYPE

Intermediaries

DATE UPLOADED

May 9, 2019

NAME

 SDP2122L.pdf

TYPE

Evidence

SUB-TYPE

Photos

AUTHOR

MATTHEW NG (AXA)

DATE UPLOADED

December 27, 2018