

DATE

ASS. REC. BY:

REF: C/TPD19008250/P

Special Instructions:

SURVEYOR

ASSIGNMENT (Office)

From (Person): Kamaliah Kamie of SPF Date/Time: 29/4/2019

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: JIG 4808 Insured:

at Workshop m/s Tel:

of

Policy No: MHASPP06000017235 Claim No: TP/1P/12567/2019

Sum Insured: Excess:

Make of Veh: D.O.A. 11/3/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	JIG 4808 -X

4201/9

- ff) Case IAFP-IB-20190416 - Mechanical Inspection of Motorcycle, JIG7808R (TP/IP/12567/2019)
- gg) Case IAFP-IB-20190416 - Mechanical Inspection of Motor Car, SGU3335X (TP/IP/12567/2019)
- hh) Case IAFP-IB-20190416 - Mechanical Inspection of Motor Taxi, SHD6208M (TP/IP/12567/2019)
- ii) Case IAFP-IB-20190416 - Mechanical Inspection of Motor taxi, SHC5238M (TP/IP/12567/2019)
- jj) Case IAFP-IB-20190416 - Mechanical Inspection of Motor taxi, SJG5245Y (TP/IP/12567/2019)

On 4 March 2019 (Monday) at about 1.53 a.m., the Deceased was riding his motorcycle alone along BKE(PIE) when the 1st Defendant side swiped against his motorcycle. Due to the impact, the Deceased landed on lane 3 while his motorcycle landed on lane 2. After the collision, the 1st Defendant stopped his motorcar along the road shoulder. About 28 seconds after the accident, the 2nd Defendant was travelling on lane 3 of BKE(PIE) when he ran over the Deceased, who was lying on lane 3. Sometime later, the 3rd Defendant was travelling either on lane 2 or lane 3 of BKE(PIE) when he was unable to avoid the Deceased and his motorcycle and collided onto them. Due to the accident, the Deceased sustained multiple injuries and was pronounced dead at the scene by paramedic Sgt Siddiq at 2.08 a.m.

Vehicles to be inspected: JIG7808R (Rider - Deceased)
SGU3335X (1st Defendant)
SHD6208M (2nd Defendant)
SHC5238M (3rd Defendant)
SJG5245Y (4th Defendant)

IO In-Charge: SIO Clarence Lim

Error in vehicle number

Clarence LIM (SPF) <Clarence_LIM@spf.gov.sg>

Wed 19/6/2019 2:46 PM

To: Naz (LKKAUTO) <Naz@lkkauto.com>;

Cc: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>;

Sir,

As spoken, there was a typo error to the motorcycle number that was given. It should be JJG 4808 instead of JJG 7808.

2. For the investigation of a fatal accident (Reference TP/IP/12567/2019), a mechanical inspection of a motorcycle, JJG 4808 is required because of the following reason/s: On 4 March 2019 (Monday) at about 1.53 a.m., the Deceased was riding his motorcycle alone along BKE(PIE) when the 1st Defendant side swiped against his motorcycle. Due to the impact, the Deceased landed on lane 3 while his motorcycle landed on lane 2. After the collision, the 1st Defendant stopped his motorcar along the road shoulder. About 28 seconds after the accident, the 2nd Defendant was travelling on lane 3 of BKE(PIE) when he ran over the Deceased, who was lying on lane 3. Sometime later, the 3rd Defendant was travelling either on lane 2 or lane 3 of BKE(PIE) when he was unable to avoid the Deceased and his motorcycle and collided onto them. Due to the accident, the Deceased sustained multiple injuries and was pronounced dead at the scene by paramedic Sgt Siddiq at 2.08 a.m.

Thank you

Clarence Lim
Investigation Officer
Fatal Accident Investigation Team
Traffic Police
Singapore Police Force
CID: (65) 6547 6195 | FAX: (65) 6547 6352



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."