

(REV 1/98)
 ASS. REC. BY: _____ REF: CI/TPD19008257/PC Special Instruction: _____
 Surveyor: _____ **ASSIGNMENT (Office)**
 From (Person): Kamaliyah Kamie of SPF Date/Time: 3/11/2019
 Estimated Cost: _____ Bill to: _____
OD/TP+WS+TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: XD 1356 L Insured: _____
 at Workshop m/s _____ Tel: _____
 of _____
 Policy No: MHNSPFC0000017235 Claim No: TP/IP/22757/2019
 Sum Insured: _____ Excess: _____
 Make of Vch: _____ D.O.A. 3/11/2019
 (Client's Award)
 CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____
 Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	<u>XD1356L-X</u>

BY _____
 (Signature)
 (Stamp)

kk) Case IAFP-IB-20190416 - Mechanical Inspection of Garbage Truck, XD1356L (TP/IP/22757/2019)

On 3 April 2019 (Wednesday) at about 6.21 p.m., the Accused (Garbage truck) was travelling on the extreme left lane of 3-lanes along Tuas South Avenue 3 towards Tuas West Road. Approaching the signalised cross junction of Tuas West Drive, traffic light was green in Accused's favour. When the Accused was driving at the yellow box of the said junction, the Deceased (Cyclist) was seen cycling across the signalised pedestrian crossing from Accused's right to left view ahead of the Accused. The Accused applied brake to avoid colliding onto the Deceased. However, the front right portion of Accused's vehicle collided onto the Deceased. Due to the collision, the Deceased sustained serious head injury. The Deceased was conveyed in an unconscious state by an ambulance to Ng Teng Fong General Hospital (NTFGH). However, on the same day at 8.18 pm, the Deceased succumbed to his injuries and was pronounced dead by Doctor Jun Kai at Ng Teng Fong General Hospital, A & E Department.

Vehicles to be inspected: XD1356L (Potential Defendant)

IO In-Charge: SIO Dzul Hairie

ll) Case IAFP-IB-20190416 - Mechanical Inspection of Motor Lorry, GBE3186C (TP/IP/22701/2019)

On 3 April 2019 at 6.33 am, along Tampines Avenue 1 towards Avenue 2, motor lorry was driving on lane 1 of 3 lanes road when it collided with a pedestrian who was crossing from the motor lorry's right to left.. The pedestrian was sent to Changi General Hospital and Succumbed to his injuries on 5th April 2019.

Vehicles to be inspected: GBE3186C (Potential Defendant)

IO In-Charge: SIO Yazid

mm) Case IAFP-IB-20190416 - Mechanical Inspection of Motor Taxi, SHC4495T (TP/IP/19355/2019)

On 22 March 2019 at 7.04 pm At the junction of Alexandra Road and Jalan Bukit Merah, motor taxi SHC 4495 T made a right turn at the junction and collided onto 2 pedestrians that were crossing along the pedestrian crossings. Both pedestrians as well as the taxi driver was sent to National University Hospital (NUH) however one of the pedestrian, female aged 66 years old succumbed to her injuries and was pronounced dead in NUH on the same day.

Vehicles to be inspected: SHC4495T (Potential Defendant)

IO In-Charge: SIO Yazid