

DATE

ASS. REC. BY:

REF:

9/TPD19008275/PC

Special Instruction:

SURVAYOR

ASSIGNMENT (Office)

From (Person):

Kamalah Kamle

of

SPF

Date/Time:

29/4/2019

Estimated Cost:

Bill to:

OD+TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP2064Y

Insured:

at Workshop no/s

Tel:

of

Policy No:

MHA-SPF-060000FF235

Claim No:

TP/IP/13815/2019

Such Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

2/8/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction ()

Estimate

YP2064Y-X

Can

do

BT

Driver Tech
needed

- (FAIT)
- m) Case IAFP-IB-20190405 - Mechanical Inspection of Motor Lorry, YP2064Y (TP/IP/13815/2019)
n) Case IAFP-IB-20190405 - Mechanical Inspection of Motorcycle, FBE7418H (TP/IP/13815/2019)

On 8 March 2019 at about 6.02 p.m., the Accused (B1 – YP2064Y) was driving on the right of the 2 lanes of Senoko South Road towards Senoko Road. As he was approaching Unit: 23 Senoko South Road, the Accused was intending to make a right turn into the said unit. While in the midst of making the right turn, the Deceased (A1 – FBE7418H) who was travelling straight from the opposite direction, on the right lane of Senoko South Road towards Woodlands Avenue 8, collided onto the left front passenger cabin of the lorry. As a result of the accident, the Deceased sustained serious head and chest injury. The Deceased succumbed to his injuries and was pronounced dead at scene by SCDF paramedic Zaidil at 6.18 p.m

Vehicle to be inspected: YP2064Y (Potential Defendant)
FBE7418H (Deceased)

IO In-Charge: SIO Dzul Hairie

- o) Case IAFP-IB-20190405 - Mechanical Inspection of Motorcycle, FBB1250D (TP/IP/15371/2019)

On 15.03.2019 at about 9.26 am, the deceased was riding his motorcycle, FBB1250D, along KJE towards PIE when he lost control of his vehicle for unknown reason and skidded. The Deceased was pronounced dead at scene at 9.46 a.m. by SCDF Paramedic Sgt Fatimah. As a result of the accident, it had caused other vehicles to be involved as well (1 motorcycle, 1 motor car and 1 Malaysian trailer).

Vehicle to be inspected: FBB1250D (Deceased)

IO In-Charge: SIO Dzul Hairie

- p) Case IAFP-IB-20190405 - Mechanical Inspection of Motorcycle, FW4724B (TP/IP/17453/2019)

On 20 March 2019 at about 2.40 am, the deceased was riding his motorcycle along the left lane of 2-lanes along Tampines South flyover when he lost control of his vehicle veering to the left and hit onto the left guard railing. Due to the impact, the deceased flung above the left guard railing and landed along PIE towards Changi Airport. The deceased was pronounced dead at scene.

Vehicle to be inspected: FW4724B (Deceased)

IO In-Charge: SIO Dzul Hairie