

ASS. REC. FY:

REF: CS/CT119008308 / AV d3 n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping of CT1

Date/Time: 10.5.19 105 a.m

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJP 4649A

Insured: YN 8687X

at Workshop m/s 96 Motorsports

Tel: 67026996

of 62 Kaki Bukit Ave 6

Policy No: DMCVSN/164917/8022

Claim No: SNM 19D 20 2042 C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.5.2019

(Client's Record)

14.5.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.5.19 11.15 a.m

Person Contacted: RuyS

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJP 4649A -X
	YN 8687X -X
27/8/19	Adrian confirmed LS \$2300 (Red 11,244, 8370)

Adrian

REF: CTI

# ASSIGNMENT

From: Date: 14.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJP 4649A

at Workshop n/s 96 motorsport

of 62 Lgri Bukit Ave 6

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Moring

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

"wp"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJP 4649A. Yr Regn: 2009, March.

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda Rx8 C.C. 1308

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 192697. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SE3P301106

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18.

R: 245/40R18.

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. ob mm R/Bal. ob mm

L/Bal. ob mm L/Bal. ob mm

D.O.A. D.O.I. 14/05/19

Survey held at 96 Motorsport.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

COE Expiry: 24/03/29.

RECEIVED 28 AUG 2019

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

1)

Date/Time, File Return to?

2) 21/8 - typist

Report Format: merimen

Lump Sum / I.B.I. (\$) 2300/-

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 May 2019		10 May 2019 10:51				<b>New Assignment</b>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	CHEN SING (S) PTE LTD, Co. Reg. No.: 199404158H								
Main Claimant:	PRAKASH S/O JOTHENATHAN, ID: S8217233E								
Vehicle Reg. No.:	SJP4649A	Date of Loss:	07/05/2019 10:00 - :59 [121 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202042C02	Policy/Cover Note No.:	DMCVSN16491718022 (Comprehensive)						
Vehicle Reg. No. (Insured):	YN8687X	Policy No. (Claimant):	PNPV2019-00003386						
		Excess:	S\$0.00						
Repairer:	96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB, 417893 Kaki Bukit - Tel: 6702 6996								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/05/2019]								
Driver/Custodian (Insured):	NG YORK HWI (48 / Male), NRIC: S7040042A Email:								
Adj Asg. Remarks:	kindly assign Mr Adrian Ling for SJE. thank you!								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All Search Tasks Create New Task Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/05/2019 17:11
Date Of Accident	07/05/2019 10:10
Exact Location Of Accident	3 KALLANG PUDDING CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP4649A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PRAKASH S/O JOTHENATHAN
NRIC No	S8217233E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87484977
Alternative Phone No	OFFICE-87484977

### Vehicle Particulars

Manufacturer	MAZDA
Model	RX 8
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	PNPV2019-00003386
Cover Note Number	

### Driver

Name of Driver	MAX CHOO SHI-CE
NRIC No	S8025968I
Date Of Birth	29/08/1980
Occupation	INDOOR
Date Of Driving Pass	15/03/2009
Driving Experience	10 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87484977
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	106 THOMSON RIDGE
Postcode	574688
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN8687X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:




Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN

3 KALLANG PUDDING CARPARK



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED DATE AND TIME, I,

VEHICLE 'A' WAS STATIONARY PARKED AT THE

STATED VENUE. THEN VEHICLE 'B' BANG ONTO

MY VEHICLE REAR PORTION.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time:

*[Signature]* / MAY 2010

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





## 96 MOTORSPORTS PTE LTD

64 Kaki Bukit Ave 6 Singapore (417893)

Email: estimator@96motorsports.com

Tel: 67026996/83118211

VEHICLE NUM:

SJP 4649 A

MAKE & MODEL:

M.RX-8

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

SE3P-301106

TP China

Veron

ATTN:						
NO.	DESCRIPTION - PARTS			QTY	PRICE	ADJUSTED PRICE
1	REAR BOOT	Reps	x.	1	873.10	
2	REAR BOOT HINGE L+R	3 pieces	x	2	194.10	
3	REAR BOOT ABSORBER L+R		x	2	181.70	
4	REAR BOOT EMBLEM ( MAZDA )	3 pieces	✓	1	53	✓
5	REAR BOOT EMBLEM ( RX-8 )		✓	1	63	✓
6	REAR TAIL LAMP LH	original	✓	1	<del>1303.50</del>	446.80
7	REAR TAIL LAMP BRACKET LH	new	x	1	125	
8	REAR BUMPER	Reps	x	1	972.50	
9	REAR BUMPER RETIANER LH	new new	x	1	47.60	
10	REAR EXHAUST	2 pieces	x	1	2007.20	
11	REAR EXHAUST GSK	1 piece	x	1	35.20	
12	REAR EXHAUST MOUNTING		x	1	38.10	
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						

562.80

450.32





## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19008308/AVD3N2

Date: 02/09/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN16491718022	
Claimant Vehicle No :	SJP4649A	Insured Vehicle No :	YN8687X	
Date of Loss:	07/05/2019	Nature of Claim:	TP	Claim No: SNM19D202042C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJP4649A	Engine No:	13B542618
Make & Model:	MAZDA RX-8, 1.3 (A)	Chassis No:	SE3P301106
Reg. Date:	25/03/2009 (Man. Year: 2008)	Odometer:	192697 km
Colour:	Red		
Engine Capacity:	1308 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,244.00	1,950.32	9,293.68	82.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	950.00	1,350.00	58.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,544.00</b>	<b>2,900.32</b>	<b>10,643.68</b>	<b>78.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>		
<b>(S\$)</b>	<b>13,544.00</b>	<b>2,300.00</b>	<b>11,244.00</b>	<b>83.02</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>948.08</b>	<b>161.00</b>	<b>787.08</b>	<b>83.02</b>
<b>Nett Amount (S\$)</b>	<b>14,492.08</b>	<b>2,461.00</b>	<b>12,031.08</b>	<b>83.02</b>

## INSPECTION

Date of Assignment:	10/05/2019	
Date Inspected:	14/05/2019	Inspected At: 96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB Singapore 417893
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2019)
<b>Parts:</b>	M1-COUPE	MAZDA RX-8 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJP4649A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Repair	873.10 F	*- FL
2	2		*REAR BOOT HINGE L + R	Not Necessary	194.10 F	*- FL
3	2		*REAR BOOT ABSORBER L + R	Not Necessary	181.70 F	*- FL
4	1		*REAR BOOT EMBLEM (MAZDA)	Necessary	53.00 F	*53.00 FL
5	1		*REAR BOOT EMBLEM (RX-8)	Necessary	63.00 F	*63.00 FL
6	1		*REAR TAIL LAMP LH	Cracked	1,303.50 F	*446.90 FL
7	1		*REAR TAIL LAMP BRACKET LH	Not Necessary	125.00 F	*- FL
8	1		*REAR BUMPER	Repair	972.50 F	*- FL
9	1		*REAR BUMPER RETAINER LH	Not Necessary	47.60 F	*- FL
10	1		*REAR EXHAUST	Not Necessary	2,007.20 F	*- FL
11	1		*REAR EXHAUST GSK	Not Necessary	35.20 F	*- FL
12	1		*REAR EXHAUST MOUNTING	Not Necessary	38.10 F	*- FL
13	1		*REAR BUMPER DIFFUSER	Not Necessary	2,000.00 FS	*- FS
14	1		*REAR BOOT SPOILER	Cracked	2,500.00 FS	*1,500.00 FS
15	1		*REAR BOOT SPOILER BRACKET	Not Necessary	600.00 FS	*- FS
16	1		*REAR SENSOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,244.00</b>	<b>2,062.90</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>112.58</b>
<b>Total Parts (\$\$)</b>	<b>11,244.00</b>	<b>1,950.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	300.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	800.00	600.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	60.00	0.00
4	TO CHECK BOOT MECH	New	120.00	0.00
5	TO R,R RR LUGGAGE COMPARTMENT	New	120.00	0.00
6	TO R,R REVERSE SENSOR & CHECK FUNCTION	New	80.00	50.00
7	TO R,R RR EXHAUST PIPE SYSTEM	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,300.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >