

ASS. REC. BY:

REP: CS3/LPC19008316/Evd3ⁿ² Special Instruction:

Surveyor:

Steve

ASSIGNMENT (Office)

From (Person):

ong hi

of

lpc

Date/Time:

9/6/19 @ 5:25pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EYA / INV / MY / CS

To Inspect Vehicle No:

GBD 2894D

Insured:

XD 6994L

at Workshop n/s

N-SI Automotive

Tel:

6842 0051

of

2 Kaki Bukit Ave 2 #01-18

Policy No:

Claim No:

19/19/19/VCS/021748

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

02/05/2019

CA / REV 1 / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

9/6/19 @ 10/5/19

Person Contacted:

ziting

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

GBD 2894D - X

XD 6994L - CS-H2GII 7016298 / G gbn 2

DVA: 2/18/2017

22/5/19

Submit PRS report

ACCOUNT *Steve*

REF:

ASSIGNMENT

From _____ Date: _____
Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s: _____
at _____
Insured _____
Policy No _____
Claims No _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

N/S	O/S

Veh No *G8028940* Yt Regn. *22/8/14*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: *Nissan Cabstar* c.c. *2953*
Colour *White* A/C Insured / Std / NI / N/
Sp. Reading *180392* T/Radio: Insured / Std / NI / N/
Eng/No: _____
Ci/No: *JM 15C 2F 242 0856245*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Broke: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim. STD A/Rim or
Tyre Size: F: *175 R15C*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. *5* mm R/Bal. *5* mm
L/Bal. *5* mm L/Bal. *5* mm
D.O.A. *2/5/19* D.O.A. *10/5/19*
Survey held at *N-51* *1.56*
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision

Date / Time : _____ Action / Instruction
MV-35K

RECEIVED 22 MAY 2019

Date/Time, File Pass to: ☐ : Procl. Report
4) ☐ : Final Report
Date/Time, File Return to?

Days Of Repair:
Resurvey No. of Trip:

2) *20/5- typst*

Report Format :
Lump Sum / I.B. I. (3)

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech Invs (\$
☐ : Weekend (\$

Survey Fee:
Transportation

☐ : S + R. 54
☐ : Photos
☐ : Fuel
☐ : ...

450

Nivitha (LKK Auto)


From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 9 May 2019 5:25 PM
To: Chio Ziting; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG
Subject: RE: GBD2894D & XD6994L - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 19/19/19/VC05/021748 [External General]
Attachments: 2894-0001.pdf

Lonpac External - General

Dear Nivitha

Please see attached.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.


From: Chio Ziting [mailto:ziting@n51.com.sg]
Sent: Thursday, 9 May, 2019 5:14 PM
To: ONG LI LI
Subject: Re: GBD2894D & XD6994L - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 19/19/19/VC05/021748 [External General]

Dear Sir / Madam,

Please see attachment.

Thank you

Regards,
Zi Ting
N-51 Automotive Pte Ltd
Office: 6842 0051
Fax: 6741 0510
www.n51.com.sg



On Thu, May 9, 2019 at 4:50 PM ONG LI LI <long@lonpac.com> wrote:

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We are not agreeable with your list of proposed surveyor, we shall appoint LKK Auto Consultants Pte Ltd to conduct survey.

Dear Nivitha

Please arrange.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Chio Ziting [mailto:ziting@n51.com.sg]

Sent: Thursday, 9 May, 2019 4:37 PM

To: ONG LI LI

Subject: Re: GBD2894D & XD6994L - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS Our Ref: 19/19/19/VC05/021748 [External General]

Dear Sir / Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you.

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



On Thu, May 9, 2019 at 2:43 PM ONG LI LI <llong@lonpac.com> wrote:

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	<input type="checkbox"/>
2	Xing Guo Qiang	<input type="checkbox"/>
3	Mohamad Taufikh	<input type="checkbox"/>
4	Bryan Ang	<input type="checkbox"/>
5	Adrian Ling	<input type="checkbox"/>
6	Mohammed Rasul	<input type="checkbox"/>
7	Marcus Chua	<input type="checkbox"/>
8	Kenneth Kong	<input type="checkbox"/>
9	Muhammad Nazril Bin Abdullah	<input type="checkbox"/>
10	Ong Hwee jie/Steve Chen	<input type="checkbox"/>

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Chio Ziting [mailto:ziting@n51.com.sg]

Sent: Thursday, 9 May, 2019 1:10 PM

To: MT_Claim_SG

Subject: GBD2894D & XD6994L - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors

Thank you.

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?

Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Renewal Coe Toyota Wish



2.50TNP, A 50 Admin Fees (HGV)
Finance 2 Traders Warranty, 3800
Down Monthly From \$758
GV Credit Pte Ltd - Siond












Browse by Category

Sort by Date Posted 20 results/page

18 vehicles

Nissan Cabstar

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Cabstar		Any	Any	2014	Any	Any	Any	Available
	Nissan Cabstar		\$33,800	\$7,250 /yr	09-Jan-2014	2,953 cc	74,476 km	Truck	Available
Fuel Type: Diesel Rare Nissan Cabstar With Super Low Mileage At 74476 Km, Excellent Condition, Powerful Engine, Low Fuel Consumption. This Lorry Come With Full Canopy, Means That You Can Carry 13 Pax Man Power For Your... ABWIN Bus Pte Ltd Posted: 11-May-2019 Tags: 2014 Nissan Cabstar, 2014 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$32,500	\$6,790 /yr	24-Feb-2014	2,953 cc	147,000 km	Truck	Available
Fuel Type: Diesel Posted: 22-Apr-2019 Tags: 2014 Nissan Cabstar, 2014 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$37,800	\$7,890 /yr	25-Feb-2014	2,953 cc	-	Truck	Available
Fuel Type: Diesel Excellent Condition, New Paintwork. 100% Loan Available. Call Now For More Info! QFai Auto Pte Ltd Posted: 20-Mar-2019 Tags: 2014 Nissan Cabstar, 2014 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$34,800	\$7,140 /yr	27-Mar-2014	2,953 cc	-	Truck	Available
Fuel Type: Diesel Previous Owner Outsource Sub-con For Small Project. Trade-in This Truck To Get 14FT Truck For Bigger Project. 100% No Big Issue For The Next 5 Years. Trade-in Back For Newer Vehicle Is Acceptable When... ABWIN Bus Pte Ltd Posted: 07-May-2019 Tags: 2014 Nissan Cabstar, 2014 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	COE Bidding Results Find out more about the latest results of our Certificate of Entitlement (COE). Find out more!								
	Nissan Cabstar		\$35,800	\$7,090 /yr	30-May-2014	2,953 cc	-	Truck	Available
Fuel Type: Diesel Cheapest In Market! Super Nice Carplate Number. 10 Feet Lorry, Excellent Condition, New Paintwork, No Repairs Required. Flexible In-House Loan, Call Now For Doorstep Viewing! ABWIN (1994) Pte Ltd Posted: 06-May-2019 Tags: 2014 Nissan Cabstar, 2014 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$38,500	\$7,620 /yr	30-May-2014	2,953 cc	-	Truck	Available
Fuel Type: Diesel Please Call To Arrange For Viewing, Thanks. Posted: 31-Mar-2019 Tags: 2014 Nissan Cabstar, 2014 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$37,800	\$7,470 /yr	02-Jun-2014	2,953 cc	102,580 km	Truck	Available
Fuel Type: Diesel 1 Owner, Original Paint Work, 100% Accident Free, 100% Loan Available. Posted: 13-Mar-2019 Tags: 2014 Nissan Cabstar, 2014 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
	Nissan Cabstar		\$33,800	\$6,650 /yr	12-Jun-2014	2,953 cc	-	Truck	Available
Fuel Type: Diesel Vehicle Selling At It Is! No Repair Needed! Call Our Sales Now! KSL Automotive Pte Ltd Posted: 04-May-2019 Tags: 2014 Nissan Cabstar, 2014 nissan cabstar, Nissan Cabstar, nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan									
Compare:	Nissan Cabstar		-	N.A	25-Jun-2014	2,953 cc	-	Truck	Available

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1772R
Vehicle Details	
Vehicle No.:	GBD2894D
Vehicle to be Exported:	No
Intended Deregistration Date:	13 May 2019
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	ZD30341145K
Chassis No.:	JN1SC2F24Z0856245
Maximum Power Output:	-
Open Market Value:	\$25,386.00
Original Registration Date:	22 Aug 2014
First Registration Date:	22 Aug 2014
Transfer Count:	1
Actual ARF Paid:	\$1,270.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$35,966.00
COE Rebate Amount:	\$18,959.00
Total Rebate Amount:	\$18,959.00

The information contained herein is correct as at 13 May 2019

OK

MSME19056719 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 02/05/2019 16:12
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/05/2019 16:12
Date Of Accident	02/05/2019 09:45
Exact Location Of Accident	JURONG PIER ROAD (NEAR PASS OFFICE OPPOSITE OF LA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD2894D
Insured/Policyholder	
Name Of Registered Owner	CHH CONSTRUCTION SYSTEM PTE LTD
Co Reg No	199101772R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97843858
Vehicle Particulars	
Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1712317
Cover Note Number	

Driver

Name of Driver	AHMED SHAHEEN
NRIC No	G7057952P
Date Of Birth	31/08/1978
Occupation	INDOOR
Date Of Driving Pass	13/02/2018
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98878064
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address -

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : UNKNOWN

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY WAITING TO PROCEED TO GO INTO THE PASS OFFICE. DUE TO THE BIG TRUCK AHEAD OF ME BLOCKING MY WAY IN. WHILE WAITING, SUDDENLY, THE BIG TRUCK IN FRONT OF ME START TO REVERSE TO MY DIRECTION. AND SO, I QUICKLY PRESS ON MY HORN AND WARN THE DRIVER OF THE TRUCK. BUT NEVERTHELESS, THE VEHICLE DIDN'T STOP AND EVENTUALLY HIT ONTO THE FRONT OF MY VEHICLE. HENCE, HE ALIGHTED FROM HIS VEHICLE AND I TOO ALIGHTED FROM MY VEHICLE. AND WHICH WE EXCHANGED OUR PARTICULARS AND I REALISED IT WAS THE VEHICLE WITH LICENCE PLATE (XD6994L) THAT REVERSED AND COLLIDED ONTO MY VEHICLE WHEN HE DOESNT HAVE ENOUGH SPACE AT THE ROUNDABOUT TO COMPLETE THE TURN. AND HE REVERSED WITHOUT NOTICING I'M BEHIND HIS VEHICLE AND WHICH CAUSED THE COLLISION TO THE FRONT OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD6994L

Vehicle Make/Model/Colour

Details Of Properties VEHICLE B

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN


VEHICLE A
- GBD 2894D

VEHICLE B
- XD 6994 L

SURONH
POWER
STATION

LAMP
POST 4

JUNONH PORT
WEST GATE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS STATIONARY WAITING TO PROCEED ON TO GO INTO THE PASS OFFICE, DUE TO THE BIG TRUCK OR ME WAS BLOCKING MY WAY IN.

WHILE WAITING, SUDDENLY THE BIG TRUCK INFRONT OF ME START TO REVERSE TO MY DIRECTION, AND SO I QUICKLY PRESS ON MY HORN AND WARN THE DRIVER OF THE TRUCK. BUT NEVERTHELESS, THE VEHICLE DIDNIT STOPPED AND EVENTUALLY HIT ONTO THE FRONT OF MY VEHICLE.

HENCE, HE ALIGHTED FROM HIS VEHICLE AND I TOO ALIGHTED FROM MY VEHICLE AND WHICH WE EXCHANGED OUR PARTICULAR AND I REALIZED, IT WAS THE VEHICLE WITH LICENCE PLATE NUMBER (XD 6994 L) THAT REVERSE AND COLLIDED TO MY VEHICLE, WHEN HE DOESNIT HAVE ENOUGH SPACE AT THE ROUND ABOUT TO COMPLETE THE TURN. AND SO HE REVERSE WITHOUT NOTICING I'M BEHIND HIS VEHICLE AND WHICH CAUSING THE COLLISION TO THE FRONT OF MY VEHICLE.

VEHICLE A - GBD 2894D

VEHICLE B - XD 6994 L.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

LONPAC INSURANCE BHD

Ref: CS3/LPC19008316/Evd3n2

300 BEACH ROAD

Date: 24-05-2019

#17-04/07 THE CONCOURSESINGAPORE 199555



Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XD 6994L	Veh. Inspected	GBD 2894D
Policy No.		Coverage (\$)	0.00
Claim No.	19/19/19/VC05/021748	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	09/05/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JN1SC2F24Z0856245	Colour	WHITE
Odometer	180392 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175 R15C	BRIDGESTONE	5 mm
L/H Front Tyre	175 R15C	BRIDGESTONE	5 mm
R/H Rear Tyre	175 R15C	BRIDGESTONE	5 mm
L/H Rear Tyre	175 R15C	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.	
---	--

5. General Information

Accident Date	02/05/2019	Inspect Date / Time	10/05/2019 (01:56 PM)
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No. CS3/LPC19008316/Evd3n2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.