

ASS. REC. BY:

REF:

CS/SPF/19008317 / R1430

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Francie they

of

SPF

Date/Time:

9/5/20/9

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 9180Z

Insured:

at Workshop m/s

Gold Bell

Tel:

9755 7336

of

8 tuas Ave 18

Policy No:

Claim No:

AEMD/105/009/2019/059

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

CA / REV / REP. / REV 24 HRS

14/5/19 @ 12pm - 3pm

H.O.D. Endorsement:

Date/Time: 09/05/19

Person Contacted:

Brian

Vehicle IN (OUT)

Date/Time

Action/Instruction

Estimate

✓

YP 9180Z - X

Submit preli report pending
Liability

Do Not Finalise

Paul

ASSIGNMENT

From:

Date: 14/5

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

YP 9180Z

at Workshop m/s

GOLDMILL

97557336

of 8 Puss Ave 18

Brian Eng

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

14/5/2019 12pm - 3pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

YP 9180Z

Yr Regn: 2018 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI CANTER PER21 C.C 2998

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

47968

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PER21E A25 237

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/85R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

04/05/19

D.O.I.

14/05/19

Survey held at

GOLDMILL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 11 JUL 2019

Date/Time, File Pass to?

☒ : Preli. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

220
220

Report Format :

Lump Sum / I.B.I: (\$)

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Thursday, 9 May 2019 5:20 PM
To: Veron Chen (LKKAuto); assignments
Cc: Abdul Rahman MOHAMAD SALIM (SPF); Hafizul Farhan RAHMAT (SPF)
Subject: RE : Pre-Repair Inspection for vehicle YP 9180Z

Your reference: YP 9180Z

Our reference: AEMD/105/009/2019/059

Veron,

Please conduct a Pre-Repair Inspection for vehicle YP 9180 Z at the address and date/Time listed below:

Date:14/05/2019

Time :12pm-3pm (Owner waiting)

Venue: 8 Tuas Ave 18, S638892

You may contact Mr Brian Eng Kwok Long at 65 9755 7336 for more details.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Nivitha (LKK Auto)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 10 May 2019 11:36 AM
To: 'Frankie THAY (SPF)'; assignments; Olivia Lau (LKKAuto)
Cc: 'Abdul Rahman MOHAMAD SALIM (SPF)'; 'Hafizul Farhan RAHMAT (SPF)'; SUR
Subject: RE: Pre-Repair Inspection for vehicle YP 9180Z

Dear Frankie,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 14/05/2019.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Frankie THAY (SPF) [mailto:Frankie_THAY@spf.gov.sg]
Sent: Thursday, 9 May 2019 5:20 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Abdul Rahman MOHAMAD SALIM (SPF) <Abdul_Rahman_Mohamad_Salim@spf.gov.sg>; Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Subject: RE : Pre-Repair Inspection for vehicle YP 9180Z

Your reference: YP 9180Z

Our reference: AEMD/105/009/2019/059

Veron,

Please conduct a Pre-Repair Inspection for vehicle YP 9180 Z at the address and date/Time listed below:

Date:14/05/2019

Time :12pm-3pm (Owner waiting)

Venue: 8 Tuas Ave 18, S638892

You may contact Mr **Brian Eng Kwok Long** at 65 9755 7336 for more details.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/05/2019 10:43
Date Of Accident	04/05/2019 09:00
Exact Location Of Accident	SLE TOWARDS BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP9180Z
Insured/Policyholder	
Name Of Registered Owner	LIENHON ENGINEERING PTE LTD
Co Reg No	199904636M
Email Address	INFO@LIENHON.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-67563433

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER FEB21ER4SDEN (CBU)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1824311800
Cover Note Number	2/8/18-1/9/19

Driver

Name of Driver	MOHAMMAD AZIZIUR RAHMAN MOHAMMAD HASEN ALI
Passport No/FIN	G8335242L
Date Of Birth	27/11/1983
Occupation	OUTDOOR
Date Of Driving Pass	25/05/2015
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86499617
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address CO LIENHON ENG.PL

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name SEMBANWANG NPC

Police Station Address ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT ATTACHED : T/20190504/2052

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: SD CARD WITH TRAFFIC POLICE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number QX501T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category GOVERNMENT

Name of Driver WU SHANG ZHEN

NRIC/Passport Number S9726381G

Contact Number 85021296

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

VEHICLE NO.: YP9180Z
INSURER: China
DATE & TIME: 4/5/19
9am

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: YS
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Diagram illustrating a road layout with a shoulder lane and a main lane. The shoulder lane is labeled "Shoulder lane" and contains a vehicle labeled "A". The main lane is labeled "SLE towards BKK" and contains a vehicle labeled "B". Arrows indicate the direction of travel for both lanes.

A - YP91802
 B = QX501T
 Wu Shang zhen
 997263816
 hp: 85021296

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report: 7/20190504/2052

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *G. G. G.* *YS*
NRIC/FIN No.:

GLPAC Search Program V3: () Claim Own Policy () Claim Third Party () Reporting Only
() Claim OOTP at other workshop ()

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20190504/2052

1 of 3

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

Report No. T/20190504/2052

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/05/2019 11:48	Vide Report No.: I/20190504/0081	Station Diary No.: 39
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: RAHMAN MOHAMMAD AZIZUR	Address:
ID Type / ID No.: FIN NO / G8335242L	Contact No.: Home/Office: Mobile: 88499617
Nationality: BANGLADESHI	Email:
Sex: Male Age: 35 Date of Birth: 27/11/1983	Type of Informant: Driver
Race: Indian	Language: Institution / School Name:
Occupation: Lorry driver	Driving Licence Information: Class: 3 Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 04/05/2019 09:00	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY SLE towards BKE Lampost Lamp Post Number: 475				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX501T	Car				Slightly Damaged	1
YP9180Z	Lorry				Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
YP9180Z	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMGVSN18243118 00	02/08/2018	01/08/2019

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20190504/2052

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

2 of 3

Report No. T/20190504/2052

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Wu Shang Zhen	ID No.	S9726381G
Related Vehicle	QX501T (Car)	Contact No.	85021296
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	RAHMAN MOHAMMAD AZIZUR	ID No.	G8335242L
Related Vehicle	YP9180Z (Lorry)	Contact No.	86499617
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 04/05/2019 at about 0900hrs, I was driving my company lorry, YP9180Z, a white Mitsubishi lorry along SLE towards before Exit 9 (Woodlands Avenue 12). I was driving on the 3rd lane when a police car (QX501T) hit the rear of my company lorry which resulted in a dent on both my left rear signal light and rear bumper. Immediately after that, I stopped my lorry and got down. Traffic police was at scene and the driver of the police car wrote down his particulars and passed it to me. I was instructed by the traffic police to lodge a report. I nor any of the police officers was not injured.

Sketch Plan #5



**SINGAPORE
POLICE FORCE**



T/20190504/2052

Police Station Of Origin:
Sembawang N.P.C.
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 3

Report No. T/20190504/2052

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
L/
Staff Sgt MOHAMED ROSLI BIN MOHAMED

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
04/05/2019 11:48

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Classification Of Case:

Authentication Stamp
NP188

Sketch Plan #6

WORK PERMIT
Employment of Foreign Manpower Act (Chapter 81A)
Republic of Singapore

Employer
LEHCHEN ENGINEERING PTE LTD

Sector: **CONSTRUCTION**

Name
RAHMAT MOHAMMAD AZIZUR

Occupation
CONSTRUCTION WORKER-CUM DRIVER

Work Permit No.
0 62875401

Date of Expiry
16-09-2017

Special Pass
08-09-2017

Date of Entry
27-08-2012

LE315494

REPUBLIC OF SINGAPORE DRIVING LICENCE

98335242L

MUHAMMAD AZIZUR RAHMAT
MUHAMMAD HASEN ALI

Date of Birth: **27 Nov 1983**
Valid From: **25 May 2015**
Valid Till: **24-05-2020**

002431965K

VISIT PASS
Immigration Regulations

Name
RAHMAT MOHAMMAD AZIZUR

Date of Birth: **27-11-1983** Sex: **M** Nationality: **BANGLADESHI**

File No: **08335242L** Date of Issue: **08-09-2017** Date of Expiry: **27-08-2019**

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg **25 May 2015**

SP 43267





GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg. No.: 168003983G

Page 1 / 2

ESTIMATE

Date	: 07/05/2019	Reg No	: YP9180Z
To	: SINGAPORE POLICE FORCE	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA25237
Office / Mobile	:	Engine No	: 4P10D20460
Email Address	:	Quotation No.	: 86937
		Ref. No.	: GBE/SVC/SALES-4866/190507
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/05/2019
Attn.	: ENGWOKLONG	Policy No.	:
Office / Mobile	: +65 6864 0637	Claim Type	: TP CLAIM - SINGAPORE POLICE FORCE
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1	MK580765	LAMP,RR COMB <i>SCA</i>	1	182.34	-25	136.76	136.76
2	MX915946	LICENSE PLATE LAMP / 12V <i>CCA</i>	1	105.84	-25	79.38	79.38
PARTS TOTAL :							216.14

SPECIAL NETT ITEMS

1	NUMBER PLATE <i>SCA</i>	1	20.00
2	REAR DESK STEP BRACKET <i>repair</i>	1	450.00
3	REAR DESK SAFETY BAR <i>bd</i>	1	680.00
4	REAR DESK SAFETY BAR BRACKET <i>repair</i>	1	380.00
5	BOLT & NUT SET <i>bd</i>	1	125.00
PARTS TOTAL:			1655.00

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	<i>300</i>	350.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	<i>400</i>	450.00
LABOUR TOTAL :			800.00

Hp 900/100/68
 SUB-TOTAL : 2,671.14
 GST @ 7% for \$ 2,671.14 186.98
GRAND TOTAL (S\$) : 2,858.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 days
P/P
14/05/19 @ 1420
Ready after repair





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19008317/R1td3e2		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN : FRANKIE THAY		Date : 25-07-2019		
		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 501T	Veh. Inspected	YP 9180Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/059	Excess (\$)	0.00	
Assign From	FRANKIE THAY	Assign Date	09/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER FEB21	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	FEB21EA25237	Colour	WHITE	
Odometer	47968	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	DUNLOP	6 mm	
L/H Front Tyre	195/85 R15	DUNLOP	6 mm	
R/H Rear Tyre	195/85 R15	DUNLOP	6 mm	
L/H Rear Tyre	195/85 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/05/2019	Inspection Date	14/05/2019	
Survey held at	8 TUAS AVE 18			
Repairer	GOLDBELL ENGINEERING PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 9180Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LAMP,RR COMB	SCRATCHED	182.34	182.34
1	LICENSE PLATE LAMP/12V	CRACKED	105.84	105.84
	LESS 25% DISCOUNT		-72.05	-72.05
			216.13	216.13
SPECIAL NETT ITEMS				
1	NUMBER PLATE (SN)	SCRATCHED	20.00	20.00
1	REAR DESK STEP BRACKET (SN)	TO REPAIR SEE LABOUR	450.00	-
1	REAR DESK SAFETY BAR (SN)	BENT	680.00	680.00
1	REAR DESK SAFETY BAR BRACKET (SN)	TO REPAIR SEE LABOUR	380.00	-
1	SET BOLT & NUT (SN)	BENT	125.00	125.00
			1,655.00	825.00
LABOUR				
	TO REMOVE AND REFIX DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN ETC.INCLUSIVE OF THE REPAIR OF REAR DESK STEP BRACKET AND REAR DESK SAFETY BAR BRACKET .		350.00	300.00
	TO PUTTY,CLEAN,SPRAY PAINT AND POLISH,ETC.		450.00	400.00
			800.00	700.00
GRAND TOTAL			2,671.13	1,741.13
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				1,741.13

Report Ref No. CS/SPF19008317/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.