

ASS. REC. BY:

REF: CS3/LPC 170083181 BT d387

Special Instruction:

Surveyor: Mr hm

ASSIGNMENT (Office)

From (Person): Ong Li Li of LPC Date/Time: 10.5.19 12.19 pm

Estimated Cost: Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV 1910H Insured: GZ 2026T

at Workshop m/s Hiap Lek Automobile Tel: 64531743

of 160 Sin Ming Drvl #05-17

Policy No: Claim No: 18/19/19/VL05/021780

Sum Insured: Excess:

Make of Veh: D.O.A. 9.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10.5.19 1.29 pm Person Contacted: Xin Shui

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJV 1910H - X
	GZ 2026T - CC4/AXA 1K005497 / m1u43u2 DOA 20/03/2014
25/6-	Receive file on 25/6/2019.

REF: LPC

ASSIGNMENT

Colene

Front:

Date: 10-5-2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJV 1910H

at Workshop m/s Hiap Lek Automobile
of 160 Sin ming Drive #05-17

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No. SJV 1910H

Yr Regn. Jan, 2010

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis

c.c. 1598

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 147900

T/Radio: Insured / Std / NI / NA

Eng/No: 3ZZEE

C/No: MR053ZEE106164567

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TCYO / YOKO or FIRENZA

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 9/5/19

D.O.I. 10.5.19 3.33pm

Survey held at Hiap Lek Automobile

Des. of Damages: Frt / Rear / O/S / M/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Submit PRS report

RECEIVED 25 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip: 3

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format :

TP-PRS

Lump Sum / I.B.I. (\$)

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 10 May 2019 12:19 PM
To: Oracle Law Corp; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG
Subject: RE: Our Ref: SB/PO/Acc/2019-8983 Your Ref: 18/19/19/VC05/021780 [External General]

Lonpac External - General

Without Prejudice
Save as to Costs


Dear Alvin

We are not agreeable with your list of proposed surveyors and we shall appoint LKK Auto Consultants Pte Ltd to conduct the survey. Please advise the location of your client's vehicle.

Dear Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Oracle Law Corp [mailto:mail@oraclelaw.sg]
Sent: Friday, 10 May, 2019 12:17 PM
To: ONG LI LI
Subject: RE: Our Ref: SB/PO/Acc/2019-8983 Your Ref: 18/19/19/VC05/021780 [External General]

Dear Miss Ong,

PRE-REPAIR INSPECTION
ACCIDENT INVOLVING SJV 1910H & GZ 2026T ALONG THE ROAD BETWEEN CARPENTER STREET & HONGKONG STREET ON 09-05-2019 @ 3.15 P.M.

Kindly refer to attachment the contents of which are self-explanatory for your kind attention and immediate action.

Regards

Alvin Ong

Oracle Law Corporation

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Friday, 10 May 2019 12:03 PM
To: Oracle Law Corp <mail@oraclelaw.sg>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: Your Ref: SB/PO/Acc/2019-8983 Our Ref: 18/19/19/VC05/021780 [External General]

Lonpac External - General

Without Prejudice
Save as to Costs

Dear Sir/Mdm

We refer to your fax today.


We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Ong Hwee jie/Steve Chen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

Nivitha (LKK Auto)


From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 10 May 2019 12:36 PM
To: Oracle Law Corp; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG
Subject: RE: Our Ref: SB/PO/Acc/2019-8983 Your Ref: 18/19/19/VC05/021780 [External General]
Attachments: 21780 prs.pdf

Lonpac External - General

Dear Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Oracle Law Corp [mailto:mail@oraclelaw.sg]
Sent: Friday, 10 May, 2019 12:25 PM
To: ONG LI LI
Subject: RE: Our Ref: SB/PO/Acc/2019-8983 Your Ref: 18/19/19/VC05/021780 [External General]

Dear Miss Ong,

Workshop details already stated in our PRI letter as:

Details of Repairers

Hiap Lek Automobile Trading
160 Sin Ming Drive
#05-17 Sin Ming Autocity S(575722)
Tel No.: 6453-1743 Fax No.: 6457-6181

Regards

Alvin Ong

 **Oracle Law Corporation**

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860



• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcler, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oraclelaw.sg

18/19/19/VC05/02780

FACSIMILE TRANSMISSION

To	: Lonpac Insurance Berhad	Date	: 10 th May 2019
Attention	: Motor Claims	From	: Mr Stanley Bay / Miss Pauline Ong
Your Ref.	: Insurer of GZ 2026T	Our Ref.	: SB/PO/Acc/2019-8983
Fax No.	: 6296-2706 / 6296-3767	No. of Pages	: 3 (including this page)

IMMEDIATE ATTENTION

Dear Sirs

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING SJV 1910H & GZ 2026T ALONG THE ROAD BETWEEN CARPENTER STREET & HONGKONG STREET ON 09-05-2019 @ 3.15 P.M.

We act for the owners of vehicle registration no. SJV 1910H.

We are instructed by our clients to notify you of the above accident involving our clients' said vehicle and your insured's vehicle registration no. GZ 2026T. A copy of our clients' motor accident report is enclosed herein.

As a result of the above accident, our clients' said vehicle was damaged. Before our clients proceed to repair their damaged vehicle, please let us know within the next (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair their said vehicle without further reference to you.

Please note that this notification does not in any way prejudice our clients' right nor shall it be deemed as a waiver of any of their rights, as such our clients' rights are expressly reserved.

Yours faithfully

Mr Stanley Bay / Miss Pauline Ong

Enc

Details of Repairers

Hiap Lek Automobile Trading
160 Sin Ming Drive
#05-17 Sin Ming Autocity S(575722)
Tel No.: 6453-1743 Fax No.: 6457-6181

Date of Accident : 09/05/19 Accident Time: 3:15pm (24-HR-FORMAT)
Accident Place : road between carpenter st towards Hong Kong st
Vehicle Reg. No (Car plate No.) : SJV 1910H
Vehicle Make/Model : Toyota Altis
Insurance Company : NTac Income Policy No. _____
Owner or Company Names /IC NO: motor maxx pte ltd
Owner or Company Contact No. : _____ Owner's HP _____ Company Tel _____
DRIVER'S Name & IC no. : Wong Chen Hong / 58783894 C.
DRIVER'S Date of Birth : 09/10/1987 DRIVER'S License Pass Date 06 sep 2012
Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
DRIVER'S Address : 41 Happy Ave East (S) 369849
DRIVER'S Contact No./ Alt No. : 1) 8833 8911 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (eg. working inside or outside of an ofc) self employed
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Ins
Number of Passengers (including Driver): 1
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Other Party Driver's Particulars (if any)

Vehicle Reg No: 47 2026T
Vehicle Make/Model: Mitsubishi Fuso
Name DRIVER: Abdul Rahman Bin Saini
IC No. DRIVER: 51496776A
DRIVER'S Contact & add: _____

Vehicle Reg No: _____
Vehicle Make/Model: _____
Name DRIVER: _____
IC NO. DRIVER: _____
DRIVER'S Contact & add: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

(A) 5 JV 1910H
(B) GZ 2026T

South Bridge Rd.

Hong Kong St



open car door

carpenter St



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 09/05/19 @ about 3:15pm, I am travelling Carpenter St towards Hong Kong street. when I had turn right into the street between Carpenter St and Hong Kong St, my vehicle is already in the lane going straight, I saw a stationary car (A) parked along the roadside. The lane is big enough for 2 vehicle to pass. when I had passed the stationary vehicle, I suddenly felt an impact on my left portion. when I got down, I then realised that the driver of GZ 2026T was in the car and he opens the driver's door and the door hit onto my left portion. I do not have enough time to think or react when I had passed the GZ 2026T. As the door open too suddenly.

DECLARATION

I declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4556D
Vehicle Details	
Vehicle No.:	SJV1910H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	3ZZ4962527
Chassis No.:	MR053ZEE106164567
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	14 Jan 2010
First Registration Date:	14 Jan 2010
Transfer Count:	2
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2020
PARF Rebate Amount:	\$8,926.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jan 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,502.00
COE Rebate Amount:	\$1,019.00
Total Rebate Amount:	\$9,945.00

The information contained herein is correct as at 25 Jun 2019

OK



PRE-REPAIR INSPECTION REPORT			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC19008318/Btd3s2 Date: 25-06-2019 Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GZ 2026T	Veh. Inspected	SJV 1910H
Policy No.		Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021780	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	10/05/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MR053ZEE106164567	Colour	BLACK
Odometer	147900 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65R15	FIRENZA	6 mm
L/H Front Tyre	195/65R15	FIRENZA	6 mm
R/H Rear Tyre	195/65R15	FIRENZA	6 mm
L/H Rear Tyre	195/65R15	FIRENZA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information			
Accident Date	09/05/2019	Inspect Date / Time	10/05/2019 (03:33 PM)
Survey held at	HIAP LEK AUTOMOBILE TRADING BLK 14 #01-19 SECTOR B SIN MING INDUSTRIAL ESTATE . SINGAPORE 575658.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC19008318/Btd3s2

Inspected By



LIM TEOW GUAN

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.