

Surveyor

REF: CS/LAW/19008342/J+ d302

Special Instruction:

1/s: \$ 13,650.00

From (Person): Michelle Hiew of TWOP Date/Time: 7/5/2019

ASSIGNMENT (Office)

Third Parties:

Estimated Cos: Bill to:

Claimant:

Surveyor: Priority Services

OD/TP Reinspection Evaluation

Workshop: Eng Soon Painting

To Inspect Vehicle No: SKJ 4500P Insured: SJM 561K

at Workshop m/s Eng Soon Painting Tel: 6260 6271

of BIK 4, Yew Tee Ind. Est 393-J

SJE

Policy No: Claim No: TWK/AR/233.18/iii/ml/PD

Sum Insured: Excess:

Make of Veh: D.O.A. 17/07/2018

(Client's Record)

16/05/2019 @ 10am

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red S 1%; Original 3 days)

Date/Time: 30/5/19 Submit Final Fig 3950/-, 3 days (Red S 9100, 71%; Original 3 days)

Date/Time	Action/Instruction
	SKJ 4500P - CSB/AR/1702 0953/R/1602
	SJM 561K - CSB/CAT/1014316/1chy392
	Insp: BIK 52 Tuas Crescent, 628731
	call Ms. Nancy @ 8623848
	Don: 31/10/17
	Don: 9/10/14
	<i>[Signature]</i>
	28/5/2019

Do Not Finalise

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 30 MAY 2019

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:

Basic & Add Transport Photos Others Total

Date:

1000
1000

1) Date/Time 30/5/2019 File Pass to Typist

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

ASSIGNMENT

From \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV \_\_\_\_\_  
 To inspect Vehicle No. \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

Veh No: SKJ 4500P Yr Regr: 1 Apr 2013  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mercedes S300 C.C. 2997  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 145292 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WDD221542A516631  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 255/45R18  
 R: \_\_\_\_\_

(Policy Condition) \_\_\_\_\_  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 17/7/18 D.O.I. 16/5/19  
 Survey held at S2 Tuag Crescent  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS \_\_\_\_\_  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-895000</u>

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to? \_\_\_\_\_  
 \_\_\_\_\_

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)

Survey Fee:	
Transportation	
G + RES. SI	
Photos	
Others	
TOTAL	

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I. (\$) \_\_\_\_\_

## Nivitha (LKK Auto)

---

**From:** Michelle Liew on behalf of Angeline Rajoo <michelleliew@tkqp.com.sg>  
**Sent:** Tuesday, 7 May 2019 5:54 PM  
**To:** LKK (assignments@lkkauto.com); 'LKK (sur@lkkauto.com)'  
**Cc:** Angeline Rajoo; 'bonnie kwok (litigation@bonniekwok.com)'  
**Subject:** SJE - MC Suit No. 19245/2018 - LKK Ref: TBA || TKQP Ref: TWK/AR/2133.18/iii/ml/PD || Bonnie Kwok LLC Ref: BK.18718.18.st  
**Attachments:** OI GIA report 2133.18.PDF; Plt GIA 2133.18.PDF; 20190507144255424.pdf; 20190507144300128.pdf

**Importance:** High

**M/s LKK Auto Consultants Pte Ltd**

Ref: New matter

Dear Sirs

**MC SUIT NO. 19245 OF 2018 – CLAIMANT: YUM FONG TRADING COMPANY PTE LTD  
ACCIDENT INVOLVING SKJ 4500P & SJM 561K ON 17.07.18 ALONG PIE**

We act for India International Insurance Pte Ltd, the insurers of motor vehicle no. SJM 561K. The Plaintiff's is represented by M/s Bonnie Kwok LLC, of motor vehicle no. SKJ 4500P.

Both our clients and the Plaintiff have jointly agreed to appoint **Mr Ong Hwee Jie** of LKK Auto Consultants Pte Ltd as our Single Joint Expert to conduct a fresh physical re-inspection of the Plaintiff's motor vehicle no. SKJ 4500P.

For purposes of SJE report, please note that you are appointed on behalf of both parties and please advise what your charges are for the inspection and we shall take instructions on bearing the charges equally with the Plaintiff.

We enclose a copy of the relevant documents for your attention:-

- 1) Plaintiff GIA report with photos of damage
- 2) Defendant's GIA report with photos of damage
- 3) Final repair bill from Eng Soon Painting Services
- 4) Paper survey report from Priority Services

Would M/s Bonnie Kwok LLC reading in copy please forward the Plaintiff's **survey report together with colour photos** to LKK Auto Consultants Pte Ltd, as our file copy is unclear.

Kindly liaise with M/s Bonnie Kwok LLC for a date to conduct physical re-inspection of the Plaintiff's vehicle.

We look forward to receiving the SJE report soonest possible.

Best Regards

Michelle Liew  
Secretary  
For and on behalf of Ms Angeline Rajoo

---

# TKQP

Tan Kok Quan Partnership  
Advocates & Solicitors, Singapore  
1 Wallich Street #07-02 Guoco Tower Singapore 078881  
T (65) 6225 9333  
D (65) 6496 9569

F (65) 6225 0111

E [michelleliew@tkpp.com.sg](mailto:michelleliew@tkpp.com.sg)

W [www.tkpp.com.sg](http://www.tkpp.com.sg)

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

## Nivitha (LKK Auto)

---

**From:** bonnie kwok <litigation@bonniekwok.com>  
**Sent:** Thursday, 9 May 2019 11:58 AM  
**To:** Michelle Liew on behalf of Angeline Rajoo; LKK (sur@lkkauto.com); LKK (assignments@lkkauto.com)  
**Cc:** Angeline Rajoo  
**Subject:** Re: SJE - MC Suit No. 19245/2018 - LKK Ref: TBA || TKQP Ref: TWK/AR/2133.18/iii/ml/PD || Bonnie Kwok LLC Ref: BK.18718.18.Acc Inv: SKJ 4500 P & SJM 561 K ON 17 JULY 2018  
**Attachments:** 18718.18.survey report.pdf; 18718.18.photo.pdf

Dear Sir,

We refer to M/s Tan Kok Quan's email dated 7 May 2019.

Kindly arrange Mr. Ong Hwee Jie of LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the inspection at Blk 52 Tuas Crescent Singapore 638731 on 16 May 2019 at 10.00 a.m. for the re-survey of our client's vehicle. You may contact Ms Nancy at 8623848.

As requested, we forward the Plaintiff's survey report together with the colour photographs for your attention.

Kindly ensure that your surveyor attends punctually.

Please let us have your offer of settlement as soon as possible.

Regards,  
June

On Tue, 7 May 2019 at 17:54, Michelle Liew on behalf of Angeline Rajoo <[michelleliew@tkqp.com.sg](mailto:michelleliew@tkqp.com.sg)> wrote:

M/s LKK Auto Consultants Pte Ltd  
Ref: New matter

Dear Sirs

mc suit no. 19245 of 2018 - Claimant: Yum Fong Trading Company Pte Ltd  
Accident involving SKJ 4500P & SJM 561K on 17.07.18 along PIE

We act for India International Insurance Pte Ltd, the insurers of motor vehicle no. SJM 561K. The Plaintiff's is represented by M/s Bonnie Kwok LLC, of motor vehicle no. SKJ 4500P.

Both our clients and the Plaintiff have jointly agreed to appoint Mr Ong Hwee Jie of LKK Auto Consultants Pte Ltd as our Single Joint Expert to conduct a fresh physical re-inspection of the Plaintiff's motor vehicle no. SKJ 4500P.

For purposes of SJE report, please note that you are appointed on behalf of both parties and please advise what your charges are for the inspection and we shall take instructions on bearing the charges equally with the Plaintiff.

We enclose a copy of the relevant documents for your attention:-

- 1) Plaintiff GIA report with photos of damage
- 2) Defendant's GIA report with photos of damage
- 3) Final repair bill from Eng Soon Painting Services
- 4) Paper survey report from Priority Services

Would M/s Bonnie Kwok LLC reading in copy please forward the Plaintiff's survey report together with colour photos to LKK Auto Consultants Pte Ltd, as our file copy is unclear.

Kindly liaise with M/s Bonnie Kwok LLC for a date to conduct physical re-inspection of the Plaintiff's vehicle.

We look forward to receiving the SJE report soonest possible.

Best Regards

Michelle Liew  
Secretary  
For and on behalf of Ms Angeline Rajoo

---

[tkqp\_logo.jpg]  
Tan Kok Quan Partnership  
Advocates & Solicitors, Singapore  
1 Wallich Street #07-02 Guoco Tower Singapore 078881  
T (65) 6225 9333  
D (65) 6496 9569  
F (65) 6225 0111  
E [michelleliew@tkqp.com.sg](mailto:michelleliew@tkqp.com.sg)<mailto:michelleliew@tkqp.com.sg>  
W [www.tkqp.com.sg](http://www.tkqp.com.sg)<http://www.tkqp.com.sg/>

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

--

**BONNIE KWOK LLC**

Advocates & Solicitors  
101A Upper Cross Street  
#08-12 People's Park Centre  
Singapore 058358  
TEL: 6536 6026  
FAX: 6536 2279

email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)  
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



## PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers  
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779  
Tel: 62934822 Fax: 62963283  
E-mail: admin@priorityservices.sg

Date: 16 October 2018

Your Ref: MPC2018D0000016

Our Ref: TP-0070/10/18

Motor Claims Department  
M/s. India International Insurance Pte Ltd  
64 Cecil Street #04-05  
IOB Building  
Singapore 049711

Attention: Mr. Meka

Dear Sir,

Inspection of 2013 Mercedes Benz S300L (A)  
Registration No.: SKJ 4500 P  
Odometer Reading: 126449 km  
Chassis No.: WDD2211542A516631

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 23-07-2018, followed by inspection of dismantled parts on the same day and resurvey after repairs on 26-07-2018.

The following documents were received: -

- 1) Copy of survey report by M/s. Automax Survey
- 2) 32 copies of photos depicting damages sustained by SKJ 4500 P and 5 photos showing resurvey after repair
- 3) Accident reports by drivers of SKJ 4500 P and SJM 561 K

The vehicle sustained rear damages during an accident on 17-07-2018.

Repair cost submitted was \$13,650.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>		<u>Revised Amount</u>	<u>Our Recommendation</u>
1pc.	Boot lid – slightly bent/repairable	\$ 1,928.00	\$ -
16pcs.	Boot lid inner trim clips – not necessary	80.00	-
1pc.	Boot lid rubber – no evidence of damage	164.80	-
2pcs.	Boot lid lamp – no evidence of damage	880.00	-

1pc.	Boot lid MERCEDES logo	\$ 74.00	\$ 74.00
1pc.	Boot lid emblem SL350	92.50	92.50
1pc.	Boot lid emblem AMG	75.00	75.00
1pc.	Boot lid emblem C&C logo	55.00	55.00
1pc.	Boot lid chrome moulding – no evidence of damage	148.80	-
1pc.	Boot lid lock – no evidence of damage	285.80	-
1pc.	Boot lid lock striker – not necessary	65.00	-
1pc.	Rear bumper fascia – dented/cut	1,450.00	1,450.00
1pc.	Rear bumper absorber bracket	327.80	327.80
1pc.	Rear bumper reinforcement – no evidence of damage	595.00	-
2pcs.	Rear bumper side retainer	82.00	82.00
2pcs.	Rear bumper side attachment	96.00	96.00
6pcs.	Rear bumper side retainer rivets	22.80	22.80
10pcs.	Rear bumper clips	38.00	38.00
1pc.	Rear bumper inner centre pad garnish – no evidence of damage	204.00	-
1pc.	Rear bumper sponge – no evidence of damage	162.00	-
1pc.	Rear bumper lower trim (black)	730.00	730.00
1pc.	Rear bumper chrome (center)	171.00	171.00
1pc.	Rear boot inner board cover – no evidence of damage	280.00	-
1pc.	Rear end panel – no evidence of damage	691.00	-
1pc.	Rear end panel garnish – no evidence of damage	192.00	-
2pcs.	Tail lamp – no evidence of damage	1,760.50	-
		<u>\$ 10,651.00</u>	<u>\$ 3,214.10</u>
	Less 10%	<u>1,065.10</u>	<u>321.41</u>
		<u>\$ 9,585.90</u>	<u>\$ 2,892.69</u>

Special Nett Items:-

1set	Reverse sensor with control unit	\$ 628.00	\$ 628.00
1set	Reverse sensor wiring – no evidence of damage	228.30	-
2pcs.	Rear bumper chrome tail pipe – no evidence of damage	1,297.80	-
1set	Reverse camera with control unit – no evidence of damage	825.00	-
	Total For Parts:-	<u>\$ 12,565.00</u>	<u>\$ 3,520.69</u>

Labour Charges:-

To tuff coat affected areas.	\$ 150.00	\$ 30.00
To remove and refix interior upholstery.	150.00	-
To check wiring system.	180.00	30.00
To remove and replace reverse sensor and test function.	260.00	60.00

To reprogram electrical module system.	\$ 550.00	\$ 200.00
To respray affected areas.	1,400.00	500.00
To renew damaged parts, straighten and repair rear chassis member, rear floor panel, rear wheel housing panel and aligned all parts.	1,800.00	500.00
<b>Total:-</b>	<u>\$ 17,055.00</u>	<u>\$ 4,840.69</u>
Lump-sum repairs:	\$ 13,650.00	\$ 3,850.00

Estimated period of repairs: 3 working days

1) Damages consistent to Singapore Accident Statement report.


Pre-accident Market Value : About \$ 125,000.00  
 PARF/COE rebate : \$ 103,484.00


Vehicle within economical limit to repair.

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully  
**PRIORITY SERVICES**

  
**JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA**  
 Motor Appraiser

Surveyed-by:  
  
**JEFFREY ONG**  
 Motor Appraiser

# ENG SOON PAINTING SERVICES

Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677978  
Tel: 6760 6271

---

M/s Yum Fong Trading Company Pte Ltd  
c/o M/s Eng Soon Painting Services  
Block 4 Yew Tee Ind Est 393-J  
Woodlands Road  
Singapore 677969

Date: 7 September 2018

Dear Sir,

Date of accident : 17/07/2018  
Final repair bill to SKJ 4500 P

To Supply,

Lump Sum repairs recommended By the surveyor .....	\$13,650.00
<b>Total</b>	<b>\$13,650.00</b>

**Dollars : THIRTEEN THOUSAND SIX HUNDRED AND FIFTY ONLY**

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110  
Mobile : 9655 6879      Email : automaxsurvey@gmail.com  
Registration No. 53110062J

Billing To: Yum Fong Trading Company Pte Ltd  
C/o Eng Soon Painting SVC  
Blk 4 Yew Tee Ind Est 393 - J  
Woodlands Road  
Singapore 677969

Invoice no.: TP18070030  
Date: 07 SEPT 2018

Vehicle no: SKJ 4500 P

Model : MERCEDES BENZ S300L

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 23 July 2018 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 920.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 920.00

**Notes :**

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.





# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110  
Mobile : 9855 6879      Email : automaxsurvey@gmail.com  
Registration No. 53110062J

## 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair :    7 working days to complete
  
5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
  
6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SKJ 4500 P

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<i>List Items</i>				
1 pc	Boot lid <i>Repair X</i>	bent	\$ 1,928.00	\$ 1,928.00
16 pcs	Boot lid inner trim clips <i>nnx</i>	necessary	\$ 80.00	\$ 80.00
1 pc	Boot lid rubber <i>nnx</i>	deformed	\$ 164.80	\$ 164.80
2 pcs	Boot lid lamp <i>nnx</i>	electronically shocked	\$ 880.00	\$ 880.00
1 pc	Boot lid mercedes logo	necessary	\$ 74.00	\$ 74.00 ✓
1 pc	Boot Lid Emblum "SL350"	necessary	\$ 92.50	\$ 92.50 ✓
1 pc	Boot Lid Emblum "AMG"	necessary	\$ 75.00	\$ 75.00 ✓
1 pc	Boot Lid Emblum "C & C LOGO"	necessary	\$ 55.00	\$ 55.00 ✓
1 pc	Boolid chrome moulding <i>nnx</i>	bent/distorted	\$ 148.80	\$ 148.80
1 pc	Boot Lid Lock <i>SVC X</i>	dent/distorted	\$ 285.80	\$ 285.80
1 pc	Boot Lid Lock Striker <i>nnx</i>	dent/distorted	\$ 65.00	\$ 65.00
1 pc	Rear bumper fascia	bent	\$ 1,450.00	\$ 1,450.00 ✓
1 pc	Rear bumper absorber bracket	Bent/deformed	\$ 327.80	\$ 327.80 ✓
1 pc	Rear bumper reinforcement <i>nnx</i>	dent/distorted	\$ 595.00	\$ 595.00
2 pcs	Rear bumper side retainer	bent	\$ 82.00	\$ 82.00 ✓
2 pcs	Rear bumper side attachment	bent	\$ 96.00	\$ 96.00 ✓
6 pcs	Rear bumper side retainer riverts	necessary	\$ 22.80	\$ 22.80 ✓
10 pcs	Rear bumper clips	necessary	\$ 38.00	\$ 38.00 ✓
1 pc	Rear bumper inner center pad gamish <i>nnx</i>	deformed	\$ 204.00	\$ 204.00
1 pc	Rear bumper sponge <i>nnx</i>	deformed	\$ 162.00	\$ 162.00
1 pc	Rear bumper lower trim (black)	distorted	\$ 730.00	\$ 730.00 ✓
1 pc	Rear bumper chrome ( center )	damaged	\$ 171.00	\$ 171.00 ✓
1 pc	Rear boot inner board cover <i>nnx</i>	deformed	\$ 280.00	\$ 280.00
1 pc	Rear end panel <i>nnx</i>	bent/distorted	\$ 691.00	\$ 691.00
1 pc	Rear end panel garnish <i>nnx</i>	deformed	\$ 192.00	\$ 192.00
1 set	Rear exhaust pipe <i>nnx</i>	bent - repair	\$ 2,877.00	\$ -
2 pcs	Tail lamp <i>nnx</i>	electronically shocked	\$ 1,760.50	\$ 1,760.50
		Parts Sub-Total	\$ 13,528.00	\$ 10,651.00
	Discount	10.00%	\$ 1,352.80	\$ 1,065.10
			\$ 12,175.20	\$ 9,585.90

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (\$)	Our Revised Estimation (\$)
<i>Special Nett Items</i>				
1set	Reverse sensor with control unit	electronically shocked	\$ 628.00	\$ 628.00 ✓
1 set	Reverse sensor wiring <i>nnx</i>	necessary	\$ 228.30	\$ 228.30
2 pcs	Rear bumper chrome tail pipe <i>nnx</i>	deformed	\$ 1,297.80	\$ 1,297.80
1set	Reverse camera with control unit <i>nnx</i>	electronically shocked	\$ 825.00	\$ 825.00
		Special Nett Sub-Total	\$ 2,979.10	\$ 2,979.10
		Spare Parts Total	\$ 15,154.30	\$ 12,585.00


LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
------	------------------	---------------------------	------------------------------

	Spare Parts Total c/f	\$ 15,154.30	\$ 12,585.00
1	To tuff coat affected areas	\$ 180.00	\$ 150.00 x
2	To remove and refix interior upholstery	\$ 180.00	\$ 150.00 x 60
3	To Check Wiring System.	\$ 200.00	\$ 180.00 30
4	To remove and replace reverse sensor & camera and test function	\$ 280.00	\$ 260.00 30
5	To reprogram electrical module system	\$ 600.00	\$ 550.00 120
6	To respray affected areas	\$ 1,600.00	\$ 1,400.00 600
7	To renew damaged parts, straightener and repair rear chassis member, rear floor panel, rear wheel housing panel & aligned all parts.	\$ 2,000.00	\$ 1,800.00 600
Total		\$ 20,194.30	\$ 17,055.00

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 13,650.00

  
Fong Kok Heng  
Qualified Appraiser



L/S \$3750/- 3 days  
4 days

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/07/2018 08:33
Date Of Accident	17/07/2018 07:35
Exact Location Of Accident	KJE TOWARDS TUAS AFTER CHANGI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKJ4500P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YUM FONG TRADING COMPANY PTE LTD
Co Reg No	NA 200704916W
Email Address	YUMFONG@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-98317783
Alternative Phone No	OFFICE-63641180

Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	S300
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088606183-01
Cover Note Number	

Driver	
Name of Driver	CHONG YUM FONG
NRIC No	S2197533H
Date Of Birth	01/01/1961
Occupation	OUTDOOR
Date Of Driving Pass	20/03/1979
Driving Experience	39 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98317783
Fax Number	
Contact Number	OFFICE-63641180
Email Address	YUMFONG@SINGNET.COM.SG

Address	NO : 52 TUAS CRESCENT
Postcode	638731
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NANCY SOH GENDER: : FEMALE
Passenger 2	NAME: : MAID - NAME UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NPC
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED AND POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM561K
Vehicle Make/Model/Colour	HYUNDAI - RED COLOR
Details Of Properties	FRONT PORTION DAMAGED
Vehicle Category	PRIVATE CAR
Name of Driver	TAN KIM KIAT


NRIC/Passport Number	S8025438E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	CHONG YUM FONG
Approximate Age	58
Injuries Sustain	REFER REPORT
Injured person in which vehicle?	SKJ4500P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 788C WOODLANDS CRESCENT #11-176
Postcode	733788

Sketch Plan

SKETCH PLAN



- (A) My vehicle = SKJ4500P
- (B) TP vehicle = SM561K.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on the 1<sup>st</sup> lane, traffic was heavy and slow, suddenly I felt a hard "Bing" from my vehicle rear.

I came out and checked & saw a Red car (vehicle 'B') had "hit back" my vehicle rear.

Damages on both vehicles. I will seek medical attention as I did not feel well.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Driver's Signature

Reporting Officer/Inspector/Stationer

*[Signature]*  
18/7/2018

## Sketch Plan #2

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claim, including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (b) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Person's Signature  
NAME:  
NRIC/IN ID:



**SINGAPORE  
POLICE FORCE**



T/20180718/2111

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649618  
Tel No: 1800-2689999

1 of 3

Report No. T/20180718/2111

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 18/07/2018 18:48		Vide Report No.:		Station Diary No.: 140	
<b>Informant's Particulars</b>					
Name of Informant: CHONG YUM FONG			Address: APT BLK 788C WOODLANDS CRESCENT #11-176 SINGAPORE 733788		
ID Type / ID No.: NRIC NO / S2197533H			Contact No.: Home/Office:                      Mobile: 98317783		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 57	Date of Birth: 01/01/1961	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: director			Driving Licence Information: Class: 2B,2A,4,5		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/07/2018 07:35	Type of Location: Straight Road
Location:  KRANJI EXPRESSWAY  Towards Tuas.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SJM581K	Car	PERODUA	VIVA SXI MT	Green	Slightly Damaged	0
SKJ4500P	Car	MERCEDES BENZ	S 300L (HID SR DRL)	Grey	Slightly Damaged	2

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999



T/20180718/2111

2 of 3

Report No. T/20180718/2111

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	CHONG YUM FONG		ID No. S2197533H
Related Vehicle	NIL		Contact No. 98317783
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,2A,4,5 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
<b>Driver</b>			
Name	TAN KIM KIAT		ID No. S8025438E
Related Vehicle	NIL		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

**Brief Details.**

On 17/7/2018 at around 0735hrs, I was driving my car(SKJ4500P) along KJE towards Tuas. During that period of time the traffic was heavy packed thus, my car is moving slowing along the flow. During that time suddenly, a car(SJM561K) came from the back rear and hit onto the back rear of my car. After the accident I then came out from my car to make a check and discovered that my car sustained damages. After that, we then exchange particulars of our driving license details.

After that I then report the matter to IZ and also went to Khoo Teck Phua Hospital to make a check. I was given 05 days of medical leave from 17/7/2018 to 21/7/2018 with Ref. KHANE181395747.



**SINGAPORE  
POLICE FORCE**



T/20180718/2111

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

3 of 3  
Report No. T/20180718/2111

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
J/  
Sgt 2 NIGEL LIM NIAN

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
18/07/2018 16:48

Officer In Charge Of Case:  
TP / AEIT /  
SSI KASMAWATI BTE SAMIAN  
Contact No: 65476179

Classification Of Case:

Authentication Stamp  
NP158

Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/07/2018 11:59
Date Of Accident	17/07/2018 07:30
Exact Location Of Accident	PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM561K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN KIM KIAT
NRIC No	S8025438E
Email Address	KIM_KIAT25@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91819959
Alternative Phone No	OFFICE-91819959

### Vehicle Particulars

Manufacturer	PERODUA
Model	VIVA-1.0 EZ (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	18MPC00016203
Cover Note Number	

### Driver

Name of Driver	TAN KIM KIAT
NRIC No	S8025438E
Date Of Birth	25/08/1980
Occupation	OUTDOOR
Date Of Driving Pass	08/08/2000
Driving Experience	17 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91819959
Fax Number	
Contact Number	OFFICE-91819959
Email Address	KIM_KIAT25@YAHOO.COM.SG

Address	BLK 692A CHOA CHU KANG CRESCENT #07-06
Postcode	681692
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ4500P
Vehicle Make/Model/Colour	MERCEDES
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHONG YUM FONG
NRIC/Passport Number	S2197533H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 18/07/2018


Driver's Signature  
(If driver is not the policyholder)  
Date & Time

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

PIE (THRS)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 17/07/2018 AT 7:30AM, I WAS TRAVELLING FROM CHIA CHU KANG TOWARDS PIONEER ALONG PIE (THRS). I WAS TRYING TO SWITCH FROM LANE 1 TO LANE 2 WITH SK34500P IN FRONT OF ME ~~BUT I WAS~~ <sup>AS I WAS TRYING TO PASS</sup> FOCUSING ON LANE 2 VEHICLES TO SWITCH LANE FOR SLIGHTLY LONGER TIME.

AS I AM TRYING TO EXIT AT THE SECOND EXIT AT PIONEER <sup>ROAD</sup> NORTH, I WAS FOCUSING ON LANE 2 VEHICLES TO SWITCH LANE <sup>AT</sup> BUT SPENT A ~~++~~ SLIGHTLY LONGER TIME TO CHECK AND WHEN I CHECK MY FRONT I SAW THAT MY CAR WAS ABOUT A METRE FROM SK34500P AND I JAMMED MY BRAKE BUT STILL KNOCK ON THE BACK OF SK34500P. DAMAGES ARE SHOWN ON THE IMAGES ATTACHED

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 18/07/2018

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: *Palm Heng*  
NRIC/FIN No.:



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 1907817225 (SSE Reg. No. M2-0078100-8)  
 61 Cecil Street #03-005 #03-02 | Raffles Building | Singapore 049711  
 Office (65) 63476100 Email insurance@iia.com.sg  
 Fax (65) 62241174 Website www.iia.com.sg


**CERTIFICATE OF INSURANCE**

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1987 ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1988 (MALAYSIA)

All Accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

CERTIFICATE NO. : 18MPC00016203		COVER: Third Party Only
1. Index Mark and Registration Number of Vehicle Chassis No	:	SJM561K PM2L251S002043669
2. Name of Policyholder	:	TAN KIM KIAT
3. Effective date of Insurance	:	16/06/2018
4. Expiry date of Insurance	:	15/06/2019
5. Person or Classes of Persons entitled to drive*		
(a) The Policyholder		The Policyholder may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her employer or his/her partner.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.		Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
<b>Limitations as to use*</b>		
Use only for social, domestic and pleasure purposes and for the Policyholder's business.		
<b>The Policy does not cover</b>		
a) Use for hire or reward.		
b) Use for racing, pace-making, reliability trial, speed-testing.		
c) Use for the carriage of goods other than samples in connection with any trade or business.		
d) Use for any purpose in connection with the Motor Trade.		
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		
We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).		
Agent/Broker : CUSTOMER-Customer		
Date of issue : 16/06/2018 06:47:21		
MX1		

Signed for and on behalf of the Company

  
 \_\_\_\_\_  
 Authorised Signatory



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 3 Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg	08 Aug 2000

NP 42BA



5333792



NRC No S8025438E



Date of Issue  
28-07-2014

Address

APT BLK 692A CHOA CHU KANG CRESCENT  
#07-06  
SINGAPORE 681692

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TAN KOK QUAN PARTNERSHIP

Ref : CS/LAW19008342/Jtd3e2

1 WALLICH STREET #07-02  
GUOCO TOWERSINGAPORE 078881

Date : 30-05-2019



Code : L021

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SJM 561K	Veh. Inspected	SKJ 4500P
Policy No.		Coverage (\$)	0.00
Claim No.	TWK/AR/2133.1B/iii/ml/PD	Excess (\$)	0.00
Assign From	MICHELLE LIEW	Assign Date	07/05/2019

### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ S 300L	c.c	2997
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2211542A516631	Colour	SILVER
Odometer	145292	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/45 R18	CONTINENTAL	6 mm
L/H Front Tyre	255/45 R18	CONTINENTAL	6 mm
R/H Rear Tyre	255/45 R18	CONTINENTAL	6 mm
L/H Rear Tyre	255/45 R18	CONTINENTAL	6 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.  
REPAIR CONDITION SEE DETAILS.

### 5. General Information

Accident Date	17/07/2018	Inspection Date	16/05/2019
Survey held at	BLK 52 TUAS CRESCENT		
Repairer	ENG SOON PAINTING SVC		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 4500P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOT LID	REPAIRED SEE LABOUR	1,928.00	-
16	BOOT LID INNER TRIM CLIPS	NOT NECESSARY	80.00	-
1	BOOT LID RUBBER	NOT NECESSARY	164.80	-
2	BOOT LID LAMP	NOT NECESSARY	880.00	-
1	BOOT LID MERCEDES LOGO	REPLACED	74.00	74.00
1	BOOT LID EMBLUM "SL350"	REPLACED	92.50	92.50
1	BOOT LID EMBLUM "AMG"	REPLACED	75.00	75.00
1	BOOT LID EMBLUM "C & C LOGO"	REPLACED	55.00	55.00
1	BOOT LID CHROME MOULDING	NOT NECESSARY	148.80	-
1	BOOT LID LOCK	SERVICEABLE	285.80	-
1	BOOT LID LOCK STRIKER	NOT NECESSARY	65.00	-
1	REAR BUMPER FASCIA	REPLACED	1,450.00	1,450.00
1	REAR BUMPER ABSORBER BRACKET	REPLACED	327.80	327.80
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	595.00	-
2	REAR BUMPER SIDE RETAINER	REPLACED	82.00	82.00
2	REAR BUMPER SIDE ATTACHMENT	REPLACED	96.00	96.00
6	REAR BUMPER SIDE RETAINER RIVERTS	REPLACED	22.80	22.80
10	REAR BUMPER CLIPS	REPLACED	38.00	38.00
1	REAR BUMPER INNER CENTER PAD GARNISH	NOT NECESSARY	204.00	-
1	REAR BUMPER SPONGE	NOT NECESSARY	162.00	-
1	REAR BUMPER LOWER TRIM (BLACK)	REPLACED	730.00	730.00
1	REAR BUMPER CHROME (CENTER)	REPLACED	171.00	171.00
1	REAR BOOT INNER BOARD COVER	NOT NECESSARY	280.00	-
1	REAR END PANEL	NOT NECESSARY	691.00	-
1	REAR END PANEL GARNISH	NOT NECESSARY	192.00	-
1	SET REAR EXHAUST PIPE	NOT NECESSARY	2,877.00	-
2	TAIL LAMP	NOT NECESSARY	1,760.50	-
	LESS 10% DISCOUNT		-1,352.80	-321.41
			<b>12,175.20</b>	<b>2,892.69</b>

Report Ref No. CS/LAW19008342/Jtd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>SPECIAL NETT ITEMS</b>				
1	SET REVERSE SENSOR WITH CONTROL UNIT (SN)	REPLACED	628.00	628.00
1	SET REVERSE SENSOR WIRING (SN)	NOT NECESSARY	228.30	-
2	REAR BUMPER CHROME TAIL PIPE (SN)	NOT NECESSARY	1,297.80	-
1	SET REVERSE CAMERA WITH CONTROL UNIT (SN)	NOT NECESSARY	825.00	-
			2,979.10	628.00
<b>LABOUR</b>				
TO TUFF COAT AFFECTED AREAS.		NOT NECESSARY	180.00	-
TO REMOVE AND REFIX INTERIOR UPHOLSTERY.			180.00	60.00
TO CHECK WIRING SYSTEM.			200.00	30.00
TO REMOVE AND REPLACE REVERSE SENSOR & CAMERA AND TEST FUNCTION.			280.00	30.00
TO REPROGRAM ELECTRICAL MODULE SYSTEM.			600.00	120.00
TO RESPRAY AFFECTED AREAS.			1,600.00	600.00
TO RENEW DAMAGED PARTS, STRAIGHTENER AND REPAIR REAR CHASSIS MEMBER, REAR FLOOR PANEL, REAR WHEEL HOUSING PANEL & ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF BOOT LID.			2,000.00	600.00
			5,040.00	1,440.00
<b>GRAND TOTAL</b>			<b>20,194.30</b>	<b>4,960.69</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,950.00</b>

Report Ref No. CS/LAW19008342/Jtd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.