

ASS. REC. BY:

REF: CS3 / MSG19068353 / Ecd

Special Instruction:

Surveyor: SteveASSIGNMENT (Office)From (Person): Irma Tak Gelang of MSG Date/Time: 10.5.19 16:58pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLA 5695P Insured: SMF 2900Dat Workshop m/s Wing Fatt Motor Tel: 96187858of BK 100t Bukit merah line 3 #01-15Policy No: A291036140M7 Claim No: 592975

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 8.5.19(Client's Record) _____ 13.5.2019

CA / REV / REP. / REV 24 HRS _____ H.O.D. Endorsement: _____

Date/Time: 10.5.19 5:04pm Person Contacted: URGENT Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate	
	SLA 5695P - NDA / INC 1900811314	D.O.A - 08/05/2019
	SMF 2900D - NDA / INC 1900811314	D.O.A - 08/05/2019
	Dismantle: 14/5/2019	
	After repair: 22/5/2019	

ASSIGNMENT

From: 13-5-2019
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: LA 569SP
 at Workshop info: Wing Fatt
 of BIK 1004 Bukit Merah line 3 # 01-15
 Insured:
 Policy No:
 Claims No:
 Sum Insured:
 (Client's Record)
 Make of Veh:



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Rpt: Consistent? Yes or No
 GIA / PR Seen: Consistent? Yes or No
 Est. Repairs: days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: LA 569SP
 Yr Regn: 7/03/16
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota A/His
 Colour: White
 Sp. Reading: 87401
 Eng/No:
 C/No: MROS3REH104S36199
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim, or
 Tyre Size: F: 205/55R16
 R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: R/Bal. 6 mm L/Bal. 6 mm D.O.A. 8/5/19
 Rear: R/Bal. 6 mm L/Bal. 6 mm D.O.I. 13/5/19
 Survey held at: Wing Fatt
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MR-67K
	Repair range - 4K-5K
	Days - 6 days
	14/5/2019

Date/Time, File Pass to:

☐ : Profi. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Date/Time, File Return to:

2)

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format: PRO

Lump Sum / I.B.I. (\$)

Survey Fee:

Transportation:

3) S + RES. TR

4) Photos

5) Others

6)

TOTAL

120
11
131

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 May 2019 09:12		10 May 2019 16:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ONG ENG CHIANG, ID: S2166902D								
Main Claimant:	CHEN YEW PING, ID: S1063970J								
Vehicle Reg. No.:	SLA5695P	Date of Loss:	08/05/2019 10:00 - :59 [38 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 592975	Policy/Cover Note No.:	A29103614QMY (Comprehensive) Coverage: 31/10/2018 - 30/10/2019						
Vehicle Reg. No. (Insured):	SMF2900D	Policy No. (Claimant):							
		Excess:	S\$700.00						
Repairer:	Weng Fatt Motor Engineering (HQ) Blk 1004 Bukit Merah Lane 3, #01-15, 159720 Bukit Merah - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/05/2019]								
Driver/Custodian (Insured):	ONG ENG CHIANG (), NRIC: S2166902D Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: VINCENT NG 9618 7858								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3970J
Vehicle Details	
Vehicle No.:	SLA5695P
Vehicle to be Exported:	No
Intended Deregistration Date:	13 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1ZRY194593
Chassis No.:	MR053REH104536199
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,804.00
Original Registration Date:	07 Mar 2016
First Registration Date:	07 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$17,804.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Mar 2026
PARF Rebate Amount:	\$13,353.00
Intended COE Rebate Details	
COE Expiry Date:	06 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$29,286.00
Total Rebate Amount:	\$42,639.00

The information contained herein is correct as at 13 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/05/2019 16:00
Date Of Accident	08/05/2019 10:00
Exact Location Of Accident	TRAFFIC JUNCTION OF SWISS CLUB ROAD/DUNEARN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA5695P
Insured/Policyholder	
Name Of Registered Owner	CHEN YEW PING
NRIC No	S1063970J
Email Address	INFO@WENGFATT.SG
Mobile Phone No	(LOCAL) +65-96215317
Alternative Phone No	OTHERS-96215317

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107954222
Cover Note Number	

Driver

Name of Driver	CHEN YEW PING
NRIC No	S1063970J
Date Of Birth	05/01/1946
Occupation	INDOOR
Date Of Driving Pass	08/07/1964
Driving Experience	54 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96215317
Fax Number	
Contact Number	OTHERS-96215317
Email Address	INFO@WENGFATT.SG

Address	985 BUKIT TIMAH ROAD #03-21
Postcode	589627
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMF2900D
Vehicle Make/Model/Colour	MAZDA CX-3
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG ENG CHIANG
NRIC/Passport Number	S2166902D
Contact Number	96888807
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN



A: SLA569CD
B: SMF2900D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary at traffic light when
vehicle (B) hit me from the rear
My vehicle is vehicle (A)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NR/CEN No:

Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 May 2019 09:12		10 May 2019 16:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ONG ENG CHIANG , ID: S2166902D									
Main Claimant: CHEN YEW PING , ID: S1063970J									
Vehicle Reg. No.: SLA5695P		Date of Loss: 08/05/2019 10:00 - :59 [38 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 592975		Policy/Cover Note No.: A29103614QMY (Comprehensive) Coverage: 31/10/2018 - 30/10/2019							
Vehicle Reg. No. (Insured): SMF2900D		Policy No. (Claimant):							
		Excess: S\$700.00							
Repairer: Weng Fatt Motor Engineering (HQ) Blk 1004 Bukit Merah Lane 3, #01-15, 159720 Bukit Merah - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Imm.Advice due 11/05/2019]									
Driver/Custodian (Insured): ONG ENG CHIANG () , NRIC: S2166902D Email:									
Adj Asg. Remarks: SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: VINCENT NG 9618 7858									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLA5695P (592975)**
[SMF2900D]
TP
CHEN YEW PING
May 8 2019 10:00AM
[ONG ENG CHIANG]
Weng Fatt Motor Engineering

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/05/19 20:04	General View	 Load JPG	☒
2	13/05/19 20:04	General View	 Load JPG	☒
3	13/05/19 20:04	General View	 Load JPG	☒
4	13/05/19 20:04	General View	 Load JPG	☒
5	13/05/19 20:04	Odometer Reading	 Load JPG	☒
6	13/05/19 20:04	Chassis Number	 Load JPG	☒
7	13/05/19 20:04	General View	 Load JPG	☒
8	13/05/19 20:04	General View	 Load JPG	☒
9	13/05/19 20:04	General View	 Load JPG	☒
10	13/05/19 20:04	General View	 Load JPG	☒
11	13/05/19 20:04	General View	 Load JPG	☒
12	13/05/19 20:04	General View	 Load JPG	☒
13	13/05/19 20:04	General View	 Load JPG	☒
14	13/05/19 20:04	General View	 Load JPG	☒
15	13/05/19 20:04	General View	 Load JPG	☒
16	13/05/19 20:04	General View	 Load JPG	☒
17	13/05/19 20:04	General View	 Load JPG	☒
18	13/05/19 20:04	General View	 Load JPG	☒
19	13/05/19 20:04	General View	 Load JPG	☒
20	13/05/19 20:04	General View	 Load JPG	☒
21	13/05/19 20:04	General View	 Load JPG	☒
22	13/05/19 20:04	General View	 Load JPG	☒
23	13/05/19 20:04	General View	 Load JPG	☒
24	13/05/19 20:04	General View	 Load JPG	☒
25	13/05/19 20:04	General View	 Load JPG	☒
26	13/05/19 20:04	General View	 Load JPG	☒
27	13/05/19 20:04	General View	 Load JPG	☒
28	13/05/19 20:04	General View	 Load JPG	☒
29	13/05/19 20:04	General View	 Load JPG	☒
30	13/05/19 20:04	General View	 Load JPG	☒
31	13/05/19 20:04	General View	 Load JPG	☒
32	13/05/19 20:04	General View	 Load JPG	☒
33	13/05/19 20:04	General View	 Load JPG	☒
34	13/05/19 20:04	General View	 Load JPG	☒
35	13/05/19 20:04	General View	 Load JPG	☒
36	13/05/19 20:04	General View	 Load JPG	☒
37	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
39	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
40	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
41	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
42	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
43	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
44	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
45	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
46	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
47	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
48	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
49	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
50	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
51	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
52	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
53	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
54	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
55	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
56	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
57	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
58	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
59	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
60	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
61	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
62	14/05/19 19:58	Photographs of Damaged Parts	 Load JPG	☒
63	22/05/19 19:28	Photo After Spray	 Load JPG	☒
64	22/05/19 19:28	Photo After Spray	 Load JPG	☒
65	22/05/19 19:28	Photo After Spray	 Load JPG	☒
66	22/05/19 19:28	Photo After Spray	 Load JPG	☒
67	22/05/19 19:28	Photo After Spray	 Load JPG	☒
68	22/05/19 19:28	Photo After Spray	 Load JPG	☒
69	22/05/19 19:28	Photo After Spray	 Load JPG	☒
70	22/05/19 19:28	Photo After Spray	 Load JPG	☒
71	22/05/19 19:28	Photo After Spray	 Load JPG	☒
72	22/05/19 19:28	Photo After Spray	 Load JPG	☒
73	22/05/19 19:28	Photo After Spray	 Load JPG	☒
74	22/05/19 19:28	Photo After Spray	 Load JPG	☒
75	22/05/19 19:28	Photo After Spray	 Load JPG	☒
76	22/05/19 19:28	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/05/19 09:13	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	
2	10/05/19 09:13	SLA5695P GIA Rpt	 Load PDF	
3	10/05/19 09:14	SMF2900D GIA Rpt	 Load PDF	
4	10/05/19 09:55	FAX FROM TP ON WORKSHOP DETAIL	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19008353/ECD3E2

Date: 10/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29103614QMY

Claimant Vehicle
No : SLA5695P

Insured Vehicle No : SMF2900D

Date of Loss: 08/05/2019

Nature of Claim: TP

Claim No: 592975

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA5695P

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)

Engine No: 1ZRY194593

Reg. Date: 07/03/2016 (Man. Year: 2015)

Chassis No: MR053REH104536199

Colour: White

Odometer: 87401 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/05/2019

Date Inspected: 13/05/2019 Inspected At:

Weng Fatt Motor Engineering (HQ)
Blk 1004 Bukit Merah Lane 3, #01-15
Singapore 159720

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 10 Jun 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA5695P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >