

NATIONAL Assessment Centre Services.

Part 1 Jan 2003

MNA 119061464

Date In: 13/5/19 09:31	Job description	Date & Time Completed	Done by
Ref No: NA/INC 19008372164	SAS e-filing		
Veh No: GBC 1794X	E-mail (within 3hrs, AIC 2hrs)		
DUA: 10/5/19 12:50	I-Motor Claim Form	MT/1044135- ⁰⁰²	13/5/19 17:08
☒ TP / Reporting Only	I-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	I-Photo Uploaded		
	Assessment/Survey Report		
TP Insurer:	Ass't Report by Fax / Hand to Owner/Whsn		

Preferred Wksp / INC Assign Wksp / QW: ()

Tel: ()

Fax: ()

TP Particulars:	Veh No: GW 25202	INC () / Non-INC ()
Owner / Driver: ()	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: ()	Date: ()	Time: ()
Insured/Driver Liability: ()	% [Note-Est. Status (WO): N: 0-20%; P: 21-79%; P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:
() Walk-In Customer: Customer's Information strictly Confidential & Strictly NO refer of repaler.
() Total Loss Case: to e-mail Insurer URGENTLY.
Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks:	INC 110011670	Damage Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: ()

Date/Time	Actions

NA 1903505	Invoice for ()	Am ()	PAID ()
Client's Particulars:	1) AIR: Accident Reporting (\$30);	30.00	
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$50)	80.00	
Contact No:	3) TP: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
QC Checked by (Engr-In-Charge):	5) FT: Follow-Through Survey (Resurvey) \$30		
Auditors' Comments:	For claiming against INC Only (ver 10 Jan 2003)		
Ref 1:	6) TR: Re-Inspection \$75		
Ref 2/3:	7) NI: Idao DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	ON:		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10	10.00	
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (Nil): TP (on INC) against INC \$20		
	9) N12: Idao Mobile \$0		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/05/2019 09:31
Date Of Accident	10/05/2019 12:50
Exact Location Of Accident	T JUNC OF HOUGANG AVE 2 AND AVE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC1794X
Insured/Policyholder	
Name Of Registered Owner	BORE PRECISION PTE LTD
Co Reg No	201433846N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81822148

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091947282-01
Cover Note Number	-

Driver

Name of Driver	TAN WAH HUI
NRIC No	S1233663B
Date Of Birth	24/08/1957
Occupation	OUTDOOR
Date Of Driving Pass	09/07/1979
Driving Experience	39 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81822148
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 617 WOODLANDS AVE 4 #11-555
Postcode	730617
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW2520Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	JUYEL MIA MAMIN MIA
NRIC/Passport Number	G8394308X
Contact Number	94732587
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN WAH HUI
------	-------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

BODY

GBC1794X

YES

NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

11/5/2019
1045 a.m.




Driver's Signature
(If driver is not the policyholder)
Date & Time:

11/5/2019
1045 a.m.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10th May 2019 at around 12.50 a.m. while travelling along Hougang Ave 2. My vehicle GBC 1794X (A) hit against vehicle GW 2520Z (B).

The reason being there is a sudden stop for GW 2520Z. As I was not in time step the brake. My vehicle hit vehicle (B).

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

11/5/19
1045 a.m



Driver's Signature
(If driver is not the policyholder)
Date & Time:

11/5/19
1045 a.m

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ACCIDENT STATEMENT

ACCIDENT DATE: (10 / 05 / 2019) (DD/MM/YYYY), TIME: (12 : 50) (HH:MM)

LOCATION: T JUNCTION OF HOUEANG AVE 2 AND AVE 8

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: GBC 1794 X
b) INSURANCE COMPANY: NTUC
c) POLICY NUMBER: 5091947282-01
d) POLICY TYPE: ☒ COMPREHENSIVE / ☐ THIRD PARTY / ☐ THIRD PARTY FIRE & THEFT
e) MAKE & MODEL: NISSAN / NV 200
f) TYPE: (SALOON / COUPE / MPV / ☒ VAN / ☐ LORRY / ☐ MOTORCYCLE / OTHERS)
g) VEHICLE CATEGORY: (PRIVATE / ☒ COMMERCIAL / ☐ MOTORCYCLE)
h) PURPOSE OF USING AT ACCIDENT TIME: WORKING
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES / NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- a) NAME: Bore Precision Pte Ltd. (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: CONTACT:
c) ADDRESS:

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: TAN WAH HUI (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: S1233663/R CONTACT: 81822148
c) ADDRESS: Blk 617 Woodland Ave 4 #11-555

* d) DATE OF BIRTH: (24 / 08 / 1957) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) DATE OF DRIVING PASS 1979

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)

IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED:

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)

b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION:

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: GW 2520Z MODEL: TOYOTA
b) DRIVER'S NAME: JUYEL MIA MAMIN MIA
c) NRIC/FIN/PASSPORT: G 8394308 X CONTACT: 94732587

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: MODEL:
e) DRIVER'S NAME:
f) NRIC/FIN/PASSPORT: CONTACT:

* No of passenger
(including driver)
(1)

* No of passenger
(including driver)
()

* No of passenger
(including driver)
()

email = ALBTAN17@yahoo.com

VIDEO

ALBTAN17@yahoo.com

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. S1233663B



Name
 TAN WAH HUI

陳 华 辉

Race
 CHINESE

Date of birth
 24-08-1957

Sex
 M

Country of birth
 SINGAPORE



IDENTITY CARD NO. S1233663B

TAN WAH HUI

Birth Date: 24 Aug 1957

Valid Date: 15 Sep 2003




4882940



NRIC No. S1233663B



Date of issue
 12-09-2012

Address
 APT BLK 617 WOODLANDS AVENUE 4
 #11-555
 SINGAPORE 730617

ANY LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

89/07/1979

NP 426A

License No. S1233



THE SCHEDULE

Commercial Vehicle Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Insured named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.
GST Reg No. M4-0003030-8

Policy Number	: 5091947282-01
The Policyholder	: BORE PRECISION PTE LTD 5 YISHUN INDUSTRIAL STREET 1 #02-03 NORTH SPRING BIZHUB SINGAPORE 768161

Period of Insurance	: 13 Jul 2018 To 12 Jul 2019
Sum Insured	: Market Value of Insured Vehicle at Time of Loss
Premium (inclusive GST)	: S\$1,368.49

Interest Insured

Cover Type	: Comprehensive	Number of Seater	: 2
Make/Model	: NISSAN/NV200	Registration Date	: 13 Jul 2011
Capacity	: 0.70 ton(s)	Insure with COE	: Yes
Registration Number	: GBC1794X	NCD Entitlement	: 10%
Chassis Number	: VSKYBAM20U0022979		
Excess (Section 1)	: S\$600		
Excess (Section 2)	: N/A		
Hire Purchase Company	: ETHOZ CAPITAL LTD		

Memo A : N/A


Endorsement Operative : N/A

Agency	: DING FENG PTE. LTD. (00000615356)
Date of Issue	: 04 Jul 2018 10:29 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive

Claim Handling

Accident MT/1044135

Policy No.	5091947282-01	Vehicle No.	GBC1794X	GST Registration No.	20143
Certificate No.					
Policyholder Name	BORE PRECISION PTE LTD			Policyholder NRIC	20143
Product Code	COMMERCIAL VEHICLE INSURAN	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	NA	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	10	Private Hire	No

▼ Accident Details

Report Date	13/05/2019 11:34	Accident Report Within 24 hrs	Yes	Accident Type	Collision
Date of Accident	10/05/2019	Time of Accident hh:mm	12:50	Country of Accident	Singap
Reporting Centre		Orange Force		ICM No.	
Accident Location	T JUNC OF HOUGANG AVE 2 AND AVE 8				

▼ Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

▼ Benefits

▼ GST Registered Information

GST Registered	Yes	GST Registration Date	18/05/2015
GST Registration No.	201433846N	GST Status Verified	Yes
Modification History			

▼ Policyholder Mailing Address

Address 1	5 YISHUN INDUSTRIAL STREET	Address 2	#02-03 NORTH SPRING BIZHUB	Address 3	SINGA
Address 4		Address Type	Singapore address	Post Code	76816
Unit No.	02-03	Related Policy Number	5092585928-01		

▼ OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	TAN WAH HUI	Driver NRIC	S1233663B	Driver DOB	24/08/
Register Date of Driver License	09/07/1979	Driver Age	61	Driving Experience	39
Contact No.(Mobile)	81822148	Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 617 #11-555	Address 2	WOODLANDS AVENUE 4	Address 3	SINGA
Address 4		Address Type	Singapore address	Post Code	73061
Unit No.	11-555				
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☒ Yes ☐ No
-------------------------------------	------	-------------	---

Modification History

Claim 002 **New**

Claim Type *	OD-MD	Insured Name	BORE PRECISION PTE LTD
Contact No.(Mobile)		Contact No. (Home)	
Email Address		OI Vehicle Number	GBC1794X
Claim Description	GBC1794X / GW2520Z ON 10 May 2019		
Preferred Workshop	0	Insured Liability	Fully at Fault
Repair No.	Yes	Preferred Repair Option	Income to assign workshop
Finalisation		GIA report	Received
Date Registered		Claim Close Date	13/05/2019 17:07
Report Taken By			LIEW SHAN HUI
☒ Print AK letter			

Save Submit

Attachment

Accident No.	MT/1044135	Claim No.	002
--------------	------------	-----------	-----

Last Doc. Received

☒ Yes ☐ No

Upload Date

13/05/2019 17:08

Path *

[Choose File](#) No file chosen[Choose File](#) No file chosen[Choose File](#) No file chosen[Choose File](#) No file chosen[Choose File](#) No file chosen[Choose File](#) No file chosen[Message Read](#)[Clear](#)

Category *

[Please Select](#)

Confidential

[NO](#)

Urgency *

[Normal](#)[Clear](#)[Please Select](#)[NO](#)[Normal](#)[Clear](#)[Please Select](#)[NO](#)[Normal](#)[Clear](#)[Please Select](#)[NO](#)[Normal](#)[Clear](#)[Please Select](#)[NO](#)[Normal](#)[Clear](#)[Please Select](#)[NO](#)[Normal](#)[Clear](#)[Please Select](#)[NO](#)[Normal](#)

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:08	NRIC/ Driving License	Normal	NRIC/ Driving License 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:08	SAS	Normal	SAS 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:08	Photos	Normal	Photos 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:08	Photos	Normal	Photos 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:08	Photos	Normal	Photos 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:07	Photos	Normal	Photos 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:07	Photos	Normal	Photos 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:07	Photos	Normal	Photos 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:07	Photos	Normal	Photos 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:07	Photos	Normal	Photos 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:07	Photos	Normal	Photos 2019-5-13
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 13 May 2019 17:07	Photos	Normal	Photos 2019-5-13

Video List

Uploaded By/Date	Folder Date	File Name	Source
------------------	-------------	-----------	--------

[Display in New Window](#)[Scan and uploading](#)

ASSIGNMENT (IDAC)By CSO- Nature of Accident:

- 1) Vehicle hit Vehicle: 2) Vehicle hit ??
- a) Motorcar () a) Pedestrian ()
- b) M/cycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govn Property () b) Road Work Object ()
(Eg: signboard, barrier, tree etc)
- c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other, _____
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case
- a) Stolen () b) Damage found ()
when recovered.
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal informationRemarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: GBC1794X Yr Regn: 13JUL 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / MPV
/ Truck / Trailer or

Make & Model: Nissan NV200 1.5L c.c 1461

Colour: Gray Transmission Type: Auto / Manual

Eng/No: _____ Sp. Reading: 259009

C/No: VSKYBAM2040022979

Gen. Cond: Good Fair Poor / Burnt or

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70 R14 - Citikan
R: YOKO

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or As above

Front	Rear
R/Bal. <u>4</u> mm	R/Bal. <u>7</u> mm
L/Bal. <u>4</u> mm	L/Bal. <u>7</u> mm

Parallel Import: Yes / No

Repair Type: LS / I.B.I

No of Repair Days: 10

D.O.I. 13/5/2019

Towed-In: Yes / No

Towing Required: Yes / No

Vehicle in Idac: Yes / No

Time: 10.40am

By Assessor- 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govn Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()

3) Vehicle does not seem damaged as a result of:

- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

Condition (CON)

(09)Blend (10)Dented (11)Distorted (12)Cracked (13)Cut (14)Scratched (15)Deformed (16)Shuffled (17)Buckled (18)Bent (19)Necessary (20)Missing (21)Torn (22)Unconfirmed (23)Not Working

VAN / LORRY (Frt)

ACTION (AC)

(1)Replace (✓) (2)Repair (X) (3)Check (C) (4)Not Consistent (NC)

Aug 2005

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	MIS		
1002	991887	Frt Number Plate Base	CRA		
1004	991300	Frt Bumper	DD		
2001	991477	Frt Bumper Lower Clips	DD		8
2002	991387	Frt Bumper Lower Sponge	DD		
2003	991449	Frt Bumper Side Cover	CRA		
2004	991443	Frt Bumper Side Retainer	CRA		2
1006	991325	Frt Bumper Bracket Lower Ge Grrr	CUT		
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CRA		
1022	991328	Frt Grille Emblem	CRA		
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel Apron L & R DIS			2
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish	L & R		2
1024	991222	Frt Apron Panel	L & R		2
1012	991527	Frt Corner Panel			
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy	BR		
1030	991821	Frt RH Headlamp Assy	BR		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish	BT		
1114	992093	Frt Windscreen Washer Pump	DD		
1115	992097	Frt Windscreen Washer Tank	DD		
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Insulator			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Unit Hose			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990273	Battery Bracket			

No of Items:

Assessor:

Vehicle No: GBC 1794X

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Fuse Box Assy			
2028	991501	F			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag	BUS		
1128	994485	Steering Wheel Airbag Sensor	NEC		
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy	JM		
1135	995182	Frt LH Seat Belt Assy	JM		
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender	BUC		
1097	995072	Frt LH Fender Inner Panel	DD		
1100	991740	Frt LH Fender Inner Shield	CRA		
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BUC		
1106	991739	Frt RH Fender Inner Panel	DD		
1109	991740	Frt RH Fender Inner Shield	CRA		
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door	DD		
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door	DD		
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
		Turbo Inter Cooler	NEC		2
		Alternator Assy			
		Engine Timing Chain Cover	CRA		

Claim Handling

▼ Accident MT/1044135

Task Transfer Exit

LOS SAL SUB

Policy No.	5091947282-01	Vehicle No.	GBC1794X	GST Registration No.	201433846N
Certificate No.					
Policyholder Name	BORE PRECISION PTE LTD			Policyholder NRIC	201433846N
Product Code	COMMERCIAL VEHICLE INSURAN	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	NA	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No ▼
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	10	Private Hire	No

▼ Accident Details

Report Date	13/05/2019 11:34	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	10/05/2019	Time of Accident hh:mm	12:50	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	T JUNC OF HOUGANG AVE 2 AND AVE 8				

▼ Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

▼ Benefits

▼ GST Registered Information

GST Registered	Yes	GST Registration Date	18/05/2015
GST Registration No.	201433846N	GST Status Verified	Yes
Modification History			

▼ Policyholder Mailing Address

Address 1	5 YISHUN INDUSTRIAL STREET	Address 2	#02-03 NORTH SPRING BIZHUB	Address 3	SINGAPORE 768161
Address 4		Address Type	Singapore address	Post Code	768161
Unit No.	02-03	Related Policy Number	5092585928-01		

▼ DI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	TAN WAH HUI	Driver NRIC	S1233663B	Driver DOB	24/08/1957
Register Date of Driver License	09/07/1979	Driver Age	61	Driving Experience	39
Contact No.(Mobile)	81822148	Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 617 #11-555	Address 2	WOODLANDS AVENUE 4	Address 3	SINGAPORE 730617
Address 4		Address Type	Singapore address	Post Code	730617
Unit No.	11-555				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

▼ Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

▼ Investigation

Claim 002 OD-MD

▼ Claim Case Officer Yap Chee Ling

LOS SAL SUB

Claim Type	OD-MD	Insured Name	BORE PRECISION PTE LTD	Insured NRIC	201433846N
Contact No.(Mobile)		Contact No. (Home)		Contact No. (Office)	65113025
Email Address		OI Vehicle Number	GBC1794X	TP Vehicle Number	GW25202
Claim Description	GBC1794X / GW25202 ON 10 May 2019			Name of Preferred Workshop	0
Preferred Workshop	0	Preferred Repair Option	Income to assign workshop	Insured Capability report	Fully at resolved
Date Registered	13/05/2019 17:10	Claim Close Date		Date Received	14/05/2019 09:58
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

Modification History

▼ Special Claim Creation Approval

Approval	Reason
----------	--------

Remarks

damage assessment Attachment

Vehicle Info

Vehicle Make	NISSAN	Vehicle Model	NV200	Engine Capacity	0.70
Date of Registration	13/07/2011	Classis No.	VSKYBAM20U0022979		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	

REMARK: NO OF REPAIR DAY: 10 DAYS, 2X FRT GARNISH LEFT & RIGHT - REPLACE, 1X FRT WINDSCREEN WASHER PUMP - UNCONFIRM, 1X FRT WINDSCREEN WASHER TANK - REPLACE, 2X AIRCON LIQUID PIPE - REPLACE, 2X AIRCON HOSE - UNCONFIRM, 1X AIRDUCT - UNCONFIRM, 2X STICKER - REPLACE, 1X TURBO INTERCOOLER - UNCONFIRM, 1X ENGINE TIMING CHAIN COVER - REPLACE,

Remark

Remark for Supplementary

Damage Listing

No.	Part No.	Description	Qty *	Repair Code *	
1	32200101	NUMBER PLATE (FRONT)	1	Replace	X
2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace	X
3	16000101	BUMPER (FRONT)	1	Replace	X
4	16002401	BUMPER CLIPS (FRONT)	8	Replace	X
5	16005901	BUMPER SPONGE (FRONT)	1	Replace	X
6	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
7	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
8	16006701	BUMPER TOWING COVER (FRONT)	1	Replace	X
9	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm	X
10	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm	X
11	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm	X
12	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Unconfirm	X
13	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm	X
14	27100101	GRILLE (FRONT)	1	Replace	X
15	27100801	GRILLE EMBLEM (FRONT)	1	Replace	X
16	12900301	APRON PANEL (FRONT)	2	Replace	X
17	27700101	HEAD LAMP (LEFT)	1	Replace	X
18	27700102	HEAD LAMP (RIGHT)	1	Replace	X
19	454009	WIPER PANEL GARNISH	1	Replace	X
20	41300101	SUPPORT PANEL (FRONT)	1	Replace	X
21	149001	BONNET	1	Replace	X
22	14903401	BONNET LOCK (LOWER)	1	Replace	X
23	14902201	BONNET HINGE (LEFT)	1	Replace	X
24	14902202	BONNET HINGE (RIGHT)	1	Replace	X
25	149029	BONNET INSULATOR	1	Replace	X
26	112023	AIR CON CONDENSER	1	Replace	X
27	112060	AIR CON FAN	1	Replace	X
28	344001	RADIATOR	1	Replace	X
29	344005	RADIATOR COWLING	1	Replace	X
30	344008	RADIATOR FAN	1	Unconfirm	X
31	34402802	RADIATOR HOSE (TOP)	1	Replace	X
32	344007	RADIATOR EXPANSION TANK	1	Replace	X
33	323001	OIL COOLER	1	Unconfirm	X
34	141001	BATTERY	1	Unconfirm	X
35	24301906	ENGINE MOUNTING (RIGHT)	1	Unconfirm	X
36	401001	STEERING AIR BAG	1	Replace	X
37	401005	STEERING AIR BAG SENSOR	1	Replace	X
38	106007	AIR BAG CONTROL UNIT	1	Unconfirm	X
39	36300102	SEAT BELT (FRONT RIGHT)	1	Replace	X
40	36300101	SEAT BELT (FRONT LEFT)	1	Replace	X
41	25400102	FENDER (FRONT LEFT)	1	Replace	X
42	25400103	FENDER (FRONT RIGHT)	1	Replace	X
43	25400801	FENDER INNER PANEL (FRONT LEFT)	1	Repair	X

Find a Part

root

Not Applicable

ABS

ABSORBER

ACCELERATOR

ACTUATOR

ADVERTISEMENT STICKER

AIR BAG

AIR BLOWER

AIR BOX

AIR CHAMBER BOX

AIR CLEANER

AIR COMPRESSOR

AIR CON

AIR CON (VAN)

AIR COOLER

AIR DISTRIBUTOR

AIR FILTER

AIR FLOW

AIR GRILLE

AIR HORN

AIR INTAKE

AIR RESONATOR BOX

AIR THROTTLE BODY AND SENSOR

ALARM

ALTERNATOR

ALUMINIUM PANEL - SIDE

AMPLIFIER

ANTENNA

ANTI ROLL

APRON

ARCH

ARM REST

ASH TRAY

AUTO CLUTCH

AUTO COOLER PIPE

AUTO CRUISE MOTOR

AUTO TRANSMISSION

AXLE

BACK REST (M/C)

BACK SEAT

BALANCER

BATTERY

BEADING (M/C)

BELT COVER (M/C)

BELT TENSIONER

BODY

BODY (M/C)

BOLT CAP (M/C)

BOLT HEAD COVER (M/C)

BONNET

BOOT

BOX (M/C)

BOX BRACKET (M/C)

BOX CARRIER (M/C)

BOX DOOR

BOX STICKER (M/C)

BRACE PANEL

BRAKE

BRAKE - ABS

BRAKE (M/C)

BUMPER

CABIN

CAMBER

CAMSHAFT

CAR AUDIO SYSTEM

44	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Repair	X
45	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	X
46	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
47	23300201	DOOR (FRONT LEFT)	1	Repair	X
48	23300202	DOOR (FRONT RIGHT)	1	Repair	X
49	124001	ALTERNATOR	1	Unconfirm	X
50	26600101	FUSE BOX (BOTTOM)	1	Unconfirm	X
51	26600102	FUSE BOX (CENTRE)	1	Unconfirm	X
52	26600103	FUSE BOX (TOP)	1	Unconfirm	X

Save Submit



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: GBC 1794X Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: HOER WAH MOTOR WORKSHOP

Collection Date: 14/5/2019 Time: 1755 with Keys: Yes / No

Tow Truck No: YH 138P L Tow Man: Chy Ezy Bong NRIC: S7048447A

Signature: [Signature]

For office use

Attended by: _____

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Yap Chee Ling <CheeLing.Yap@income.com.sg>
Sent: Tuesday, 14 May 2019 5:10 PM
To: LKK Paya Ubi; Hock Wah Motor Pte Ltd
Subject: GBC1794X | MT/1044135 (Awarding Letter to Hock Wah)

Importance: High

Hi IDAC and Hock Wah,

Vehicle is currently in IDAC.

Excess of \$600 is applicable.

Please liaise with the driver – Mr TAN WAH HUI at tel: 8182 2148 on the necessary.

**** STRICTLY NO SUPPLEMENTARY ALLOWED**

Thank you.

Yap Chee Ling (Ms)
Executive
Motor Insurance
T +65 6430 7893
www.income.com.sg



At Income, we are "In with You" on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers



Our Ref: MT/CA/OD/051/1044135-002/YCL

14 May 2019

HOCK WAH MOTOR WORKSHOP PTE LTD
BLK 3011 BEDOK NORTH AVE 4 #01-2008/10/12
BEDOK INDUSTRIAL PARK E
SINGAPORE 489977

Dear Sir

CLAIM NUMBER: MT/1044135-002
REPAIR OF VEHICLE NUMBER: GBC1794X

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 14 May 2019

Make: NISSAN

Model: NV200

Estimated Repair Days: 7

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits: Not applicable

Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Yap Chee Ling at 6430-7893 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.