#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.	sent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	13/05/2019 10:26
Date Of Accident	11/05/2019 14:40
Exact Location Of Accident	ANG MO KIO CENTRAL BLK 703
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	PA7738P
Insured/Policyholder	
Name Of Registered Owner	ACE BUS CHARTER & SERVICES
Co Reg No	53366110B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91454034
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	AFTER LUNCH LEAVING THE CARPARK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5092620977-01
Cover Note Number	
Driver	
	No No and No

Name of Driver

NG HOCK LAI

NRIC No

S8335597B

Date Of Birth

21/11/1983

Occupation

OUTDOOR

Date Of Driving Pass

25/08/2017

Driving Experience 1 YEAR AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91454034

Fax Number

Contact Number

EMail Address NOEMAIL

Address BLK 612A PUNGGOL DRIVE

#15-807

Postcode 821612

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

-

2

NO

**General Information of the Accident** 

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR
Road Surface DRY

**Other Information** 

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by NO

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

**Details of Police Action** 

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE

ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY:

Police Station Address SINGAPORE

Police Station Contact **TEL NO**: 1800-4519999 - **FAX NO**: 65535679

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident** 

PLS REFER TO THE POLICE REPORT:T/20190511/2099

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number FD4373E

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Page 2 of 16

Nature Of Damage

No. Of Passenger (Including Driver)

#### **Accident Sketch Plan**

#### SKETCH PLAN

## **IMPORTANT NOTICE**

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wliful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name

NRIC/FIN No.:

## **Accident Sketch Plan**

THOOP IT	ekans 988	MACRIMACD.		GMO KIO CAMI DPA 7738 P
	I A		0	3) FD 4373E
				GANTRY
ESCRIBE CIRCUMSTA	INCES OF THE ACCIDEN			1
PLS REFER		REPORT - T/2019	0511 (2099.	
ARATION decision the forestoing pa	erticulars are true in every n	#Spect.		
	erticulars are true in every n		Lym	13/05/19

#### **Individual Statement**





Police Station Of Origin: Ang Mo Kio South N.P.C 81 Ang Mo Kio Avenue 3 SINGAPORE 569929 2 of 3 Report No. T/20190511/2093

Tel No: 1800-4519999

CONTINUATION OF REPORT

Driver				H21-41	1000	
Name	NG HOCK LAI			ID No		\$8335597B
Related Vehicle	PA7738P (Bus/Coach/Minibus)			Conta	ict No.	97355791
Hospital/Clinic	NIL			Class Drivin Licen Expin	g	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL Date Dis			charge	NIL	
No. of Days granted Medical Leave NIL			Degree o		NIL	

### Brief Details.

On 11/05/2019, at about 1440hrs, I was driving my vehicle (PA7738P) along the service road of carpark behind Blk 705 Ang Mo Kio. As I travelling on the one lane service road, a motorcycle (FD4373E) reversed out of the motorcycle lot and hit onto the rear left side of my vehicle. We both stopped our vehicle, and as the place only have one lane, I told him to move to out of the carpark and exchange details there as it has 2 lanes which he acknowledged.

I then drove out of the carpark first, and when I make a check, I spotted his motorcycle doing a u-turn and driving off towards the opposite direction. I do not have any in-car camera. The rear left side of vehicle has a dent and a scratch along the left side of the vehicle.

The rider of the motorcycle is Caucasian, in his 30-40s.















## Police Report





1 01 3 Report No. T/20190511/2099

Police Station Of Origin: Ang Ma Kio South N.P.C 81 And Mo Kio Avenue 3 SINGAPORE 569929

Tel No: 1800-4519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/Q5/2019 15:54		Vide Report No.: Station Diary No. 115			
Informa	nt's Partic	ulars			
Name of Informant NG HOCK LAI			Address: APT BLK 612A PUNGGOL DRIVE #15-807 SINGAPORE 821612		
ID Type / ID No.: NRIC NO / S8335597B			Contact No.: Home/Office	Mobile: 97355791	
National SINGAP	ny. ORE CITIZ	EN	Email		
Sex: Male	Age: 35	Date of Birth. 21/11/1983	Type of informant: Driver		
Race: Chinese		Language	Institution / School Name:		
Occupation: SELF-EMPLOYED		Driving Licence Inform Class 2B,2A,2.3	ation: Date of Expiry:		

Type of Accident:	Non-Injury Hit and Run	Drink Drive No	Date/Time of Accident: 11/05/2019 14:40	Type of Location Car Park
	CENTRAL 1  MK Ctrl 1, behind block	c 703 AMK		
Weather		Road Surface.	R	oad Speed Limit:
Clear		SLOY CONTRACTOR		
Clear Traffic Flow: One Way		Dry Traffic Control: Not Controlled	110	raffic Volume: eavy

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenge
FD4373E	Matercycle	VESPA		Maroon		0
PA7738P	Bus/Coach/Mi	TOYOTA		Silver		0

Details of Person Involved	
Any Pedestrian Involved No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

### **Police Report**



7/20190511/2099

Police Station Of Origin: Ang Mo Kio South N.P.C 81 Ang Mo Kio Avenus 3 SINGAPORE 589929 2 of 3 Report No. T/20190611/2000

Tel No. 1800-4519999

CONTINUATION OF REPORT

Driver		OF THE PARTY.		Water III	
Name	NG HOCK LAI			ID No.	\$83355978
Related Vehicle	PA7738P (Bus/Coach/Minibus)			Contact No.	97355791
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL		Date Disc	charge NR.	
No. of Days granted Medical Leave NIL			Degree o		

#### Brief Details.

On 11/05/2019, at about 1440hrs, I was driving my vehicle (PA7738P) along the service road of carpani behind Blk 705 Ang Mc Kio. As I travelling on the one lane service road, a motorcycle (FD4373E) reversed out of the motorcycle lot and hit onto the rear left side of my vehicle. We both stopped our vehicle, and as the place only have one lane, I told him to move to out of the carpank and exchange details there as it has 2 lanes which he acknowledged.

I then drove out of the carpark first, and when I make a check, I spotted his motorcycle doing a u-turn and driving off towards the opposite direction. I do not have any in-car camera. The rear left side of vehicle has a dent and a scratch along the left side of the vehicle.

The rider of the motorcycle is Caucasian, in his 30-40s.

### **Police Report**





3 of 3

Police Station Of Origin: Ang Mo Kio South N.P.C 81 Ang Mo Kio Avenue 3 SINGAPORE 569929 Tel No. 1800-4519999 Report No. T/20190511/2009

CONTINUATION OF REPORT.

## Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Record F / Sgt 3 SWEE WEI ERN	ing The Report:	Signature Of Informant:	
Signature Of Interpreter Not applicable		Date/Time: 11/05/2019 15:54	
Officer In Charge Of Case TP / HRT / Sr Staff Sgt ESTHER CHOI	vG	Classification Of Case:	
Contact No. 65476368	100	BN GRE	
Authentication Stamp	1 1 to		
		and the second	
*	Day to F	orce	