

ASS. REC. BY:

REF: (CS3) FC119008399/ Jcd3^{SR}

Special Instruction:

Surveyor: HWA Jie

ASSIGNMENT (Office)

From (Person): Sithara

of

FC1

Date/Time: 13.5.19 11.43 AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JSM 8536

Insured:

SHB 32634

at Workshop m/s

Sincere Lead

Tel:

of 38 woodlands Industrial Park E1 #05-13

Policy No:

Claim No: D19003107MFS4

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time:

13.5.2019 1.12pm

Person Contacted:

Raymond

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	JSM 8536 - (CS3/FC118017829/ R/cd3s2 D.O.A - 29/09/2018
	SHB 32634 - (CS3/ALG/2017279/ H192924 D.O.A - 01/01/2012

REF: FCI

Hwee Jie

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: ± S\$1,500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. JSM 8536 Yr Regn: 9 Jun 2016Type: Car / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Yamaha c.c. 150Colour: White A/C: Insured / Std / NI / NASp. Reading: 31254 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PMYRG341060005967Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 90/80 R17R: 120/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 8/5/19 D.O.I. 13/5/19Survey held at Sincere leadDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS

MV-RM4500 X (record purpose)

Date/Time. File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time. File Return to?

2)

Report Format: PR

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

) \$ + PS. \$ _____

) Photos _____

) Others _____

TOTAL

MOTOR SURVEY ASSIGNMENT

Date	10-05-2019	Our Ref No. D19003102MFSH
Accident Date	08-05-2019	Claim Type. Third Party
Insured Vehicle	SHB3263H	Third Party Vehicle. JSM8536
Survey Location	38 WOODLANDS INDUSTRIAL PARK E1 #05-13	
Contact Person.	MR RAYMOND	
Contact No.	98158858/ 98158858	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SINCERE LEAD	Attention. NIL
Cc : TP Solicitor	ROY & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



**SINGAPORE
POLICE FORCE**



T/20190508/2157

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

1 of 3

Report No. T/20190508/2157

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/05/2019 16:35	Vide Report No.:	Station Diary No.: 659
--	------------------	---------------------------

Informant's Particulars			
Name of Informant: LIM CHEE POH		Address:	
ID Type / ID No.: FIN NO / G6882200P		Contact No.: Home/Office: Mobile: 97792877	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 31	Date of Birth: 16/03/1988	Type of Informant: Rider
Race: Chinese		Language:	Institution / School Name:
Occupation: CONSTRUCTION WORKER		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 08/05/2019 13:30	Type of Location: T-Junction
Location: Along Road 1 YISHUN AVENUE 7				
Along Yishun Avenue 7 turning left to Yishun Industrial Park A.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
JSM8536	Motorcycle	YAMAHA		White	Slightly Damaged	0
SHB3263H	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	Yellow	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190508/2157

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

2 of 3

Report No. T/20190508/2157

CONTINUATION OF REPORT

Rider			
Name	LIM CHEE POH	ID No.	G6882200P
Related Vehicle	JSM8536 (Motorcycle)	Contact No.	97792877
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 08/05/2019 at about 1330hrs, while riding my personal motorcycle (JSM8536) on the left lane of a 3 lane road along Yishun Avenue 7. While I was approaching a left turn to Yishun Industrial Park A, a vehicle (SHB3263H) on the same lane suddenly turn left while I was traveling straight and collided onto my right side and I fell onto my right side as well. The driver did not signal while making the left turn.

After collision, I checked with the driver and he informed that he did not see from his left side mirror therefore proceeded to change lane to the left side and collided onto me. My motorcycle suffered minor scratches and dent on the right side of it and the alignment of the motorcycle was off. No government property was involved. I then parked my motorcycle at the roadside and informed my friend to engage towing service to tow my motorcycle as it is not safe to ride with the alignment off.

Whilst lodging report, I felt pain on my right side due to the fall related to the accident which occurred earlier. I will be proceeding to consult doctor about the injury later on. In additional, the driver did gave me his contact number - 92716822 and his NRIC number - S1815237A.



**SINGAPORE
POLICE FORCE**



T/20190508/2157

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

3 of 3

Report No. T/20190508/2157

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Sgt 2 LEE JIAN HAO

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Signature Of Informant:

Date/Time:

08/05/2019 16:35

Classification Of Case:

Authentication Stamp

NP168

Singapore Police Force



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

VKR741DC

No. Pendaftaran	: JSM8536
No. IS	: 880316235059
Nama Pemunya Berdaftar	: LIM CHEE POH
Alamat	: NO. 22 JALAN JELATANG 7 TAMAN MEGAH RIA 81750 MASAI JOHOR
No. Chasis/No. Enjin	: PMYR034100005967 / G39EE-0005966
Buatan/Nama Model	: PMYR034100005967 / G39EE-0005966
Keupayaan Enjin	: YAMAHA / FZ150I (S)
Behan Bakar	: 150
Status Asal	: PETROL
Kelas Kegunaan	: PEMASANGAN TEMPATAN
Jenis Badan/Tahun Dibuat	: MOTOSIKAL
Tarikh Pendaftaran	: MOTOSIKAL / 2016
B. D. M/B. G. K/BIM	: 09/06/2016
Syarat Pendaftaran 1	: -
Syarat Pendaftaran 2	: -
Syarat Pendaftaran 3	: -

See All Ads (<https://www.mudah.my/malaysia/for-sale>)Favourites (<https://www.mudah.my/favourites>)PRO Niaga (<https://www.mudah.my/pro-niaga>)(<https://www.mudah.my/>)(https://www2.mudah.my/useraccount.html?signin=1&goto_page=chat)(<https://www2.mudah.my/useraccount.html?signin=1>)Home (/) > Penang (<https://www.mudah.my/Penang/for-sale>) > Motorcycles (<https://www.mudah.my/Penang/Motorcycles-for-sale-1040>) > 2016 Yamaha FZ150iBack to Results (<https://www.mudah.my/Malaysia/2016+yamaha+fz150i-for-sale?fs=1&lst=0&so=1&q=2016+yamaha+fz150i>) | Next Ad: (https://www.mudah.my/2016+Yamaha+FZ150i-74501390.htm?w=3&st=s&cg=0&q=2016+yamaha+fz150i&lst=0&fs=1&w=3&cg=0&q=2016+yamaha+fz150i&so=1&st=s&ca=3_s&next=1)

2016 2016 Yamaha FZ150i

List-ID: 74501390

18 Apr 2019



Click on the heart to add this to your Favourite list.



Seller Says Specifications

- Yamaha FZ150i Cash&Carry;
- 18xxx milages
- RM4800 nego
- one owner only
- penang area only

Kindly whatsapp any interested buyer

[Show contact number YJ](#)Price **RM 4 800**Location **Penang - Georgetown**Condition **Used**

Interested in this Ad? Contact the Seller!

yj

Private Seller

(https://www.mudah.my/u/bakanoob_010566812)

CHAT WITH SELLER

(https://www2.mudah.my/useraccount.html?signin=1&list_id=74501390&view=1&user_id=10566812)012 **CLICK TO VIEW PHONE NUMBER****CLICK TO EMAIL SELLER****ADD TO FAVOURITES**

Share this Ad

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS3/FCI19008399/Jcd3s2

Date: 10-06-2019



Code: FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHB 3263H	Veh. Inspected	JSM 6536
Policy No.		Coverage (\$)	0.00
Claim No.	D19003102MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	13/05/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA	c.c	150
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	PMYRG3410G0005967	Colour	WHITE
Odometer	31254 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80 R17	MAXXIS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70 R17	MAXXIS	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

**5. General Information**

Accident Date	08/05/2019	Inspect Date / Time	13/05/2019 (01:46 PM)
Survey held at	SINCERE LEAD AUTOMOTIVE 280 WOODLANDS INDUSTRIAL PARK E5 #02-10 SINGAPORE 757322		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) MARKET VALUE: \$1,500.00

Report Ref No. CS3/FCI19008399/Jcd3s2

Inspected By

ONG HWEI JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.