

12/15/2012

ASS. REC. BY:

REF:

023/AIG19008403/Ged302

Special Instruction:

Urgent!

SURVEYOR:

GG

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

13/5/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STR 8943M

Insured:

SGK 83268

at Workshop m/s

Sze Kang

Tel:

64812712

of

10 AMK #03-09

Policy No:

Claim No:

4856128749.SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

13/5

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction ( X )	Estimate
	STR 8943M - X	
	SGK 83268 - X	
	Dismantle: 13/5/2019	

PRS

REF:

AIG.

83228

(-2019)

## ASSIGNMENT

From

Date

Estimated Cost:

OD / TP / WS / TP RES / OD RES / LVA / INV / MV

To inspect Vehicle No. SJR 8943 M

at Workshop n/s Sze Kang

of 10 AMIC #03-09

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No.

SJR8943 M

Yt Regn

20 Jan 2009

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki Swift 1.6 cc 1586

Colour

yellow

A/C: Insured / Std / NI / NA

Sp. Reading

144697

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JSAE8 C31 S0020 4335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/45 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.A.

Bros -19

Survey held at

w/s

3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

~~\$1000~~ \$2000

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

DAR

Lump Sum / I.B.I. (\$)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

180

11

191

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 May 2019 <a href="#">Edit Reg</a>		14 May 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	SIM HEE CHONG, ID: S1431138F			
Main Claimant:	-			
Vehicle Reg. No.:	SJR8943M	Date of Loss:	08/05/2019 00:00 - :59	
Claim Type:	TP / 4856128749SG	Policy/Cover Note No.:	(Comprehensive)	
Vehicle Reg. No. (Insured):	SGK8326S	Policy No. (Claimant):		
		Excess:		
Repairer:	Sze Kang Automobile Spraying Services (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-17, 568047 Ang Mo Kio - Tel: 64812712			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/05/2019]			

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (15/05/2019): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Yours ref: 4856128749SG003 Our ref: YSY/19.021980 - PRE-REPAIR INSPE...

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 5/13/2019 10:59:29 AM  
Attachments:  tmpFC9F.TIF

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Veh In.

XGQ

# Ascentsia

Law Corporation

A Law Corporation with limited liability  
(Company Registration No. 200204598E)  
Commissioner for Oaths  
Notary Public

Your Ref:

Our Ref: YSY/19.021980/ec

9 May 2019

10 Anson Road  
#03-22 International Plaza  
Singapore 079903  
Tel : (65) 6534 3552  
Fax : (65) 6535 9920

Email: [enquiry@ascentsialawcorp.com](mailto:enquiry@ascentsialawcorp.com)  
Website: [www.ascentsialawcorp.com](http://www.ascentsialawcorp.com)  
(Service of Court documents by fax not accepted)

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 Shenton Way #07-16  
AIG Building  
Singapore 079120

**BY FAX & POST**  
(Fax No. 6835 7417)

Attn: Motor Claims Department

Dear Sirs

**ACCIDENT INVOLVING SJR 8943M & SGK 8326S ALONG AIRPORT ROAD ON 8 MAY 2019**

We act for Mr Goh Chin Tiam, who is the registered owner and driver of motor vehicle no. SJR 8943M at the material time.

Our client was involved in an accident on 8 May 2019 with your insured's motor vehicle no. SGK 8326S and has suffered damages, loss and expenses.

In accordance to the NIMA Protocol, we hereby give you 2 working days notice for you to conduct a pre-repair inspection of our client's motor vehicle at the following workshop:

**Sze Kang Automobile Spraying Services**  
10 Ang Mo Kio Industrial Park 2A  
#03-09/17  
Singapore 568047  
Tel: 6481 2712/8201 9979

Kindly make the necessary arrangements with the abovementioned workshop for your surveyor to conduct a pre-repair inspection (if required).

If we do not receive a response by 13 May 2019, we will proceed on the basis that you have waived your rights to a pre-repair inspection.

Yours faithfully,

  
Yip Shee Yin

cc client

*Velu lu*  
*XGQ*

Directors Kenny Khoo • Leong Why Kong • Yip Shee Yin Legal Consultant Thomas Au  
Associates Chiang Wan Ting • Clarisse Khoo • Ong Li Ling • Tan Choon Hiang

Confidentiality note: The contents herein are strictly meant for the addressee only and may contain privileged communications. If you are not the intended recipient, please either immediately return this document to us at our costs or destroy this document.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	322Z
<b>Vehicle Details</b>	
Vehicle No.:	SJR8943M
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.6 MT
Primary Colour:	Yellow
Manufacturing Year:	2009
Engine No.:	M16A1468016
Chassis No.:	JSAEZC31S00204335
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$14,542.00
Original Registration Date:	20 Jul 2009
First Registration Date:	20 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$14,542.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 May 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$27,886.00
COE Rebate Amount:	\$27,458.00
<b>Total Rebate Amount:</b>	<b>\$27,458.00</b>

The information contained herein is correct as at 26 Jul 2019

OK

## ▶ swift 1.6 Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
<b>Suzuki Swift Sport 1.6M</b>	<b>\$14,500</b>	\$11,880 /yr	16-Dec-2009	1,586 cc	160,000 km		<b>Availal</b>
Coilovers, Servicing Just Done, Good For Renewing COE. Come And Have A Look, Call Me For Viewing. Can Renew COE And Sell You At \$410 Price Is Negotiable. Dealers Are Welcome.							
Office No. - - Ja Tan - 96204800   Yi Yi - 93359533							
<b>Suzuki Swift Sport 1.6M (New 5-yr COE)</b>	<b>\$25,800</b>	\$5,150 /yr	24-Feb-2009	1,586 cc	150,636 km	Kruise Auto	<b>Availal</b>
90% Loan Amount. 100% Loan Available.Cheapest In The Market! Hurry Catch This Beast! New 5 Years COE, Very Smooth Engine And Gear With No Accident Record. Flexible Loan Package With Attractive Loan...							
Office No. - 65471511 Colin - 96487189   Jo - 96571525   Anthony - 91894920   Des - 81867412							
<b>Suzuki Swift Sport 1.6A (New \$27,800 5-yr COE)</b>		\$5,550 /yr	22-Apr-2009	1,586 cc	140,000 km	88 Motor Trading	<b>Availal</b>
Full Loan Available At \$700+ Monthly We Can Help To Conver To Z10 Usage If Needed. In House Loan/Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart ...							
Office No. - 62911187 Ben - 90913551   Jeremy - 97625070   Mr Ho - 96811390   Adrian - 98555551							
<b>Suzuki Swift Sport 1.6M (New 5-yr COE)</b>	<b>\$28,800</b>	\$5,750 /yr	25-Nov-2009	1,586 cc	-	Ocean Motoring	<b>Availal</b>
Pearl White With Carbon Fire Bonnet. Sunline Sports Grill. Apexi RSM. Well Maintain. Low Deposit. Bank Or-In House Loan Available. Test Dr Available.							
Office No. - - Jason - 90489293   Chan - 90021531							
<b>Suzuki Swift Sport 1.6M (New 5-yr COE)</b>	<b>\$29,000</b>	\$5,790 /yr	17-Mar-2009	1,586 cc	163,982 km	Inchcape Pre-Owned	<b>Availal</b>
Original Yellow Signature Swift Sports With Stock Condition Without Messy Mods. Paid Road Tax Till Sept 2019. Repairs Done. Call Our Sales Consultants For A Viewing Now!							
Office No. - 63036303 Chris Tang - 81683557   JJ Chua - 90037428   Kelvin Kee - 98719789   Jason Tan - 98882000							
<b>Suzuki Swift Sport 1.6M (New 5-yr COE)</b>	<b>\$29,800</b>	\$5,950 /yr	12-Nov-2009	1,586 cc	-	Gen Y Automobile	<b>Availal</b>
Loan High Approval, In House Finance Packages, We Provide 6 Months Warranty On Engine And Gearbox, Free Grooming. Loan Available! Optional For 5 Or 10 Years COE Renewal. 6 Months Extended Engine And G...							
Office No. - - Scott - 91894999   Win - 98968688							
<b>Suzuki Swift Sport 1.6A (New \$29,800 5-yr COE)</b>		\$5,950 /yr	13-Nov-2009	1,586 cc	138,000 km	Takashima Auto Enterprise	<b>Availal</b>
Like New, Low Mileage Done, New Sport Rims, New Tyres, New Road Tax, Pearl White Paintwork, Low Depreciation, Loan Available, Trade I Welcome.							
Office No. - 64658772 Johnny - 81138285							
<b>Suzuki Swift Sport 1.6M (New 5-yr COE)</b>	<b>\$29,800</b>	\$5,950 /yr	27-Apr-2009	1,586 cc	-	Gen Y Automobile	<b>Availal</b>
Loan High Approval, In House Finance Packages, We Provide 6 Months Warranty On Engine And Gearbox, Free Grooming. Loan Available! Optional For 5 Or 10 Years COE Renewal. 6 Months Extended Engine And G...							
Office No. - - Scott - 91894999   Win - 98968688							
<b>Suzuki Swift Sport 1.6M (COE \$29,800</b>		\$6,120 /yr	27-Mar-2009	1,586 cc	149,000 km		<b>Availal</b>

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/05/2019 14:45
Date Of Accident	08/05/2019 18:45
Exact Location Of Accident	AIRPORT ROAD ENTRANCE TO KPE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJR8943M
Insured/Policyholder	
Name Of Registered Owner	GOH CHIN TIAM
NRIC No	S7725322Z
Email Address	KENGOH8943@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97536974
Alternative Phone No	OTHERS-97536974
Vehicle Particulars	
Manufacturer	SUZUKI
Model	SWIFT 1.6 MT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MPC0000591
Cover Note Number	20/07/2018 - 19/07/2019
Driver	
Name of Driver	GOH CHIN TIAM
NRIC No	S7725322Z
Date Of Birth	02/09/1977
Occupation	INDOOR
Date Of Driving Pass	06/03/1997
Driving Experience	22 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97536974
Fax Number	
Contact Number	OTHERS-97536974
EMail Address	KENGOH8943@GMAIL.COM



Address	BLK 148 YISHUN STREET 11 #03-121
Postcode	760148
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGK8326S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SIM HEE CHONG
NRIC/Passport Number	S1431138F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

Date of accident: 8/5/19 Time: 6.45 PM Location: Airport road entrance to KPE  
 My Vehicle A: SSR 8943 M Vehicle B: SGK 8326 S Vehicle C: —

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I have just entered the tunnel (KPE) along Airport Rd. It was a single lane road and the car in front braked. I braked and slowed down but the car behind (SGK 8326 S) collided onto my rear.

Veh B: Sim Hec Chong / R143 1138 P

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address: ken90h8443@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

AH LIM MOTOR COMPANY

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary  
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

## MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (C)  
(4) Not Consistent (NC)

### Rear Portion

Vehicle No:

STR 8943 M

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	PT	/	
1138	993627	Rear Number Plate Base	cut	/	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	de	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	MC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper <del>Beam</del> Lamp RH	de	/	
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper <del>Damper</del> Grille	cut	/	
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper <del>Pad</del> Grille			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	Repair	X	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items:

Assessor:

02/01/2019

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 May 2019 <a href="#">Edit Reg</a>		13 May 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>SIM HEE CHONG</b> , ID: S1431138F								
Main Claimant:	<b>GOH CHIN TIAM</b> , ID: S7725322Z								
Vehicle Reg. No.:	<b>SJR8943M</b>	Date of Loss:	08/05/2019 00:00 - :59 [117 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4856128749SG</b>	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SGK8326S</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Sze Kang Automobile Spraying Services (HQ)</b> BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-17, 568047 Ang Mo Kio - Tel: 64812712								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 24/05/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (15/05/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJR8943M (4856128749SG)

[SGK8326S]






































TP





























GOH CHIN TIAM

May 8 2019 12:00AM

[SIM HEE CHONG]

Sze Kang Automobile Spraying Services

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
2	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
3	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
4	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
5	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
6	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
7	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
8	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
9	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
10	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
11	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
12	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
13	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
14	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
15	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
16	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
17	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
18	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
19	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
20	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
21	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
22	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
23	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
24	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
25	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
26	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
27	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
28	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
29	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
30	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
31	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
32	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
33	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
34	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
35	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
36	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	
37	19/06/19 12:34	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	19/06/19 12:34	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/06/19 12:34	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/06/19 12:34	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/06/19 12:34	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/06/19 12:34	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/06/19 12:34	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/06/19 12:34	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 12:34	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	19/06/19 12:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/05/19 11:05	OI GIA REPORT	 Load PDF	
2	04/07/19 14:40	SJR8943M - GIA Report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19008403/GCD3E2

Date: 29/07/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJR8943M

Insured Vehicle No : SGK8326S

Date of Loss: 08/05/2019

Nature of Claim: TP

Claim No: 4856128749SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJR8943M

Make &amp; Model: SUZUKI SWIFT, 1.6 MT (M)

Engine No: M16A1468016

Reg. Date: 20/07/2009 (Man. Year: 2009)

Chassis No: JSAEZC31S00204335

Colour: Yellow

Odometer: 144697 km

Engine Capacity: 1586 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/45 R16

Rear Tyre Size: 205/45 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 13/05/2019

Date Inspected: 13/05/2019 Inspected At:

10 Ang Mo Kio #03-09

Repairer : Sze Kang Automobile Spraying Services (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Cut	0.00 F	*- F
3	1		*REAR BUMPER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER LAMP RH	Deformed	0.00 F	*- F
6	1		*REAR BUMPER GRILLE	Cut	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >