



Your Ref: D18/6758/GB/JS

Date: 08th July 2019

Our Ref: CS1/FCI19008416/Dqd3s2

M/s Ms First Capital Insurance Ltd

36 Robinson Road
#16-01 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: TR 4081H
INSURED VEHICLE: XD 5022Z ACCIDENT DATE: 11/09/2018**

We thank you for your instruction on 10/05/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of TR 4081H from M/s L H Teo Appraisal Services.
- b) Final Repair Bill of TR 4081H from M/s Ryder Auto Pte Ltd.
- c) Colour damaged vehicle photographs of TR 4081H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -
Registration Number : TR 4081H
Make & Model : Fabricated For Special Purpose TRAILER
2. We recommend that the repairs of the entire damage require about 14 (Fourteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.