

ASS. REC. BY:

Surveyor: Taufiqh

ASSIGNMENT (Office)

Date/Time: 13.5.19 1.44 p.m

minimum

From (Person): Chin Lu Ying

of AIG

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SJH 4648U

To Inspect Vehicle No: SMD 6875C

Tel: 9455-7994

at Workshop n/s William Lu Car Air Con

of No 2 Kaki Bukit Ave 2 #01-33

Policy No: 2100412055-04

Claim No: 688117276286

Sum Insured:

Excess:

D.O.A 7.5.2019

Make of Veh: (Client's Record)

"up"

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 13.5.19 4.15 p.m

Person Contacted: William Lu

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SMD 6875C - X
	SJH 4648U - (CS/AIG 1600 3840 / Arbn 2) D.O.A 24/02/2016
	Demantle: 14/5/2019
	After repair: 17/5/2019


Customer

Tanfer

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To inspect Vehicle No: _____
 at Workshop in/s of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR 3-ten: _____ Consistent? : Yes or No
 Est. Repairs: **4** days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SMD6875C** in Reg: **Aug 18**
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Mazda CXB** CC: **1998**
 Colour: **Red** AC: Insured / Std / NI / NA
 Sp. Reading: **8466** T/W: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JM6DK2W7AK0406280**
 Gen. Cond: **G** / Good / Fair / Poor / Burnt
 Steering: **G** / Inorder / Jammed / Leaked / Burnt or
 Brake: **G** / Inorder / Jammed / Leaked / Burnt or
 Modi: **G** / Nil / STD / R/A / STD A/Rim or **504g**
 Tyre Size: F: **215 / 50 R18**
 R: **215 / 50 R18**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
G / TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.L: _____ D.O.L: **13/5/19C 450m**
 Survey held at: **William Lee**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No GUA

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: **4**
 Resurvey No. of Trip: **2**

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee:	
Transportation	
3 + 0.25 x 23	
Phone	
Other	
TOTAL	

Report Format: **DAR**
 Lump Sum / L.B.R: (\$)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 May 2019 Edit Reg		14 May 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

[Show All](#)

Main
Reference
Claim Details
Documents

[Created by adjuster]

CLAIM SUBFOLDER DETAILS

Insured:	Manogaran s/o Suppiah , ID: S2534907E		
Main Claimant:	EDWARD LEE YAO WEI , ID: S9017010D		
Vehicle Reg. No.:	SMD6875C	Date of Loss:	07/05/2019 15:00 - :59
Claim Type:	TP / 6881172762SG	Policy/Cover Note No.:	2100412055-04 (Comprehensive)
Vehicle Reg. No. (Insured):	SJH4648U	Policy No. (Claimant):	
Repairer:	William Lee Car Air Con () KAKI BUKIT AUTOHUB , #02-17, 417921 Kaki Bukit - Tel: 94557994		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/05/2019]		

[View All](#) [Compose Case Mail](#)

- #### ASSOCIATED MAIL RECEIVED
- AIG_SG (15/05/2019): Request To Upload TP GIA Report
 - AIG_SG (15/05/2019): No OI GIA Report

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 5/13/2019 1:44:58 PM
Attachments:  William Lee - Pre-Repair Notice (AIG)(SMD6875C).pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

X Est
Taufiqh

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.WL (SMD6875C)
Your Ref: SJH4648U

13 May 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

BY FAX: 6835 7416 & EMAIL

URGENT

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: EDWARD LEE YAO WEI
TRAFFIC ACCIDENT ON 07 MAY 2019 AT 15:00 HRS ALONG BUKIT TIMAH ROAD
BEFORE TAN KAH KEE MRT INVOLVING VEHICLES NO. SMD6875C & SJH4648U

We are instructed by Edward Lee Yao Wei to notify you of a road accident on 07 May 2019 at about 15:00 hrs along Bukit Timah Road before Tan Kah Kee MRT involving our client's vehicle registration number SMD6875C and vehicle registration number SJH4648U driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: William Lee Car Air Con Engineering
Address: No 2 Kaki Bukit Avenue 2
#01-33
Singapore 417921
Contact: William Lee (9455 7994)

Please liaise with the above workshop directly.

Yours faithfully

CrossBorders LLC
Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com
encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/05/2019 15:18
Date Of Accident	07/05/2019 15:00
Exact Location Of Accident	ALONG BUKIT TIMAH ROAD BEFORE TAN KAH KEE MRT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD6875C
Insured/Policyholder	
Name Of Registered Owner	EDWARD LEE YAO WEI
NRIC No	S9017010D
Email Address	EDWARDLEEYW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98899593
Alternative Phone No	OTHERS-98899593
Vehicle Particulars	
Manufacturer	MAZDA
Model	CX-3 2.0 SKYACTIV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800109614
Cover Note Number	
Driver	
Name of Driver	EDWARD LEE YAO WEI
NRIC No	S9017010D
Date Of Birth	21/05/1990
Occupation	INDOOR
Date Of Driving Pass	16/01/2010
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98899593
Fax Number	
Contact Number	OTHERS-98899593
EEmail Address	EDWARDLEEYW@GMAIL.COM

Address BLK 671 HOUGANG AVENUE 8
 #06-691
 Postcode 5306
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : LIOW YING RU
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4519999 - FAX NO: 65535679
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20190508/2113.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: VIDEO - WILLIAM LEE CAR AIRCON ENGRG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJH4648U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIOW YING RU

Approximate Age

Injuries Sustain

Injured person in which vehicle? SMD6875C

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name EDWARD LEE YAO WEI

Approximate Age 28

Injuries Sustain

Injured person in which vehicle? SMD6875C

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

- 8 MAY 2019

15:18hrs

GIA/ICE Secretariat 06-7711 1111

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature

Name: **Ph Kwee Choo**

NRIC/FIN No.: **S6840583A**

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report : T/20190508/2113.

Repair at workshop : William Lee Car Aircon Engng

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Edward
Policyholder's Signature

Date & Time:
- 8 MAY 2019

Driver's Signature
(If driver is not the policyholder)

Date & Time:

[Signature]
Reporting Centre Personnel's Signature

Name: P. Awee Choo
NRIC/FIN No.: S6840583A



**SINGAPORE
POLICE FORCE**



T/20190508/2113

1 of 4

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
669929
Tel No: 1800-4519999

Report No. T/20190508/2113

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/05/2019 14:38	Vide Report No.:	Station Diary No.: 88
--	------------------	--------------------------

Informant's Particulars

Name of Informant: EDWARD LEE YAO WEI		Address: APT BLK 671 HOUGANG AVENUE 8 #06-691 SINGAPORE 530671	
ID Type / ID No.: NRIC NO / S9017010D		Contact No.:	Mobile: 98899593
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 28	Date of Birth: 21/05/1990	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Commercial airline pilot		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/05/2019 15:00	Type of Location:
Location: Along Road 1 BUKIT TIMAH ROAD Along Bukit Timah Road just before Tan Kah Kee MRT station				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision:			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJH4648U	Car					0
SMD6875C	Car	MAZDA	CX-3 2.0 AT DELUXE 2WD	Red		1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date

POLICE REPORT Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190508/2113

2 of 4

Report No. T/20190508/2113

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SMD6875C	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800109614	30/08/2018	29/08/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	MANOGARAN S/O SUPPIAH		ID No.	S2534907E
Related Vehicle	SJH4648U (Car)		Contact No.	98339757
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	EDWARD LEE YAO WEI		ID No.	S9017010D
Related Vehicle	SMD6875C (Car)		Contact No.	98899593
Hospital/Clinic	ANG MO KIO POLYCLINIC		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	08/05/2019		Date Discharge	08/05/2019
No. of Days granted Medical Leave	02		Degree of Injury	NIL
Passenger				
Name	LIOW YING RU		ID No.	S9015062F
Related Vehicle	SMD6875C (Car)		Contact No.	97487928
Hospital/Clinic	ANG MO KIO POLYCLINIC		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	08/05/2019		Date Discharge	08/05/2019
No. of Days granted Medical Leave	03		Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190508/2113

3 of 4

Report No. T/20190508/2113

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Brief Details.

On the 07/05/2019 at about 1500hrs, I was driving my car SMD6875C at along Bukit Timah Road just before Tan Kah Kee MRT. The weather was clear and dry. The traffic was moderate. I was driving at the 2nd lane. I had one passenger seated at the front. As I was driving straight the car in front of me braked. Thus I braked and came to a stop and suddenly another car from rear collided from rear and caused our body to jerk forward.

I then came down and enquired with the rear driver what happened and he informed the he was unable to stop in time. Due to the accident my car's rear bumper is dented. I exchanged particulars and left. Both my passenger and I had some strain on our neck.

On the 08/05/2019, both my passenger and I decided to consult doctor at Ang Mo Kio Polyclinic and I obtained 2 days of MC and my passenger 3 obtained 3 days of MC.



**SINGAPORE
POLICE FORCE**



T/20190508/2113

4 of 4

Report No. T/20190508/2113

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Staff Sgt RAHUMATHULLA AZIMAL ALI

Signature Of Informant:
[Handwritten Signature]

Signature Of Interpreter:
Not applicable

Date/Time:
08/05/2019 14:38

Officer In Charge Of Case:
TP / AEIT /
SI ANG YI TING, STEPHANIE
Contact No.: 65476414

Classification Of Case:
SN 085

Authentication Stamp
NP168

 Signature: *[Handwritten Signature]*
Singapore Police Force

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7010D
Vehicle Details	
Vehicle No.:	SMD6875C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2019
Vehicle Make:	MAZDA
Vehicle Model:	CX-3 2.0 AT DELUXE 2WD
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	PE31271709
Chassis No.:	JM6DK2W7AK0406250
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$21,436.00
Original Registration Date:	30 Aug 2018
First Registration Date:	30 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$22,011.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2028
PARF Rebate Amount:	\$16,508.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,551.00
COE Rebate Amount:	\$29,689.00
Total Rebate Amount:	\$46,197.00

The information contained herein is correct as at 15 Jul 2019

OK

(1) Replaced (✓) (2) Replaced (3) Checked (4) Not Checked (5) Broken (6) Necessary
 (7) Missing (8) Torn (9) Unconfirmed (10) Not Working

MOTORCAR (Rear)


(1) Replaced (✓) (2) Replaced (3) Checked (4) Not Checked (5) Broken (6) Necessary
 (7) Missing (8) Torn (9) Unconfirmed (10) Not Working

Vehicle No: **SM D 6875 C**

Rear Portion

NAC	INC	Item	CON	AC	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	6
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	D/S	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	DD	✓	R
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	SPR	✓	R
1182	991328	Tailgate Emblem	NEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
990247	990247	Sticker			


 12/11/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	
Main	14 May 2019 Edit Reg		13 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
[Created by adjuster]									
CLAIM SUBFOLDER DETAILS									
Insured:	Manogaran s/o Suppiah , ID: S2534907E								
Main Claimant:	EDWARD LEE YAO WEI , ID: S9017010D								
Vehicle Reg. No.:	SMD6875C	Date of Loss:	07/05/2019 15:00 - :59 [8 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6881172762SG	Policy/Cover Note No.:	2100412055-04 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJH4648U	Policy No. (Claimant):							
		Excess:							
Repairer:	William Lee Car Air Con () KAKI BUKIT AUTOHUB , #02-17, 417921 Kaki Bukit - Tel: 94557994								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/05/2019]								
				View All	Compose Case Mail				
ASSOCIATED MAIL RECEIVED									
<ul style="list-style-type: none"> AIG_SG (15/05/2019): Request To Upload TP GIA Report AIG_SG (15/05/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD6875C (6881172762SG)
[SJH4648U]

TP
EDWARD LEE YAO WEI
May 7 2019 3:00PM
[Manogaran s/o Suppiah]
William Lee Car Air Con

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/> <input type="button" value="Upload Video"/> <input type="button" value="Upload Audio"/>			View <input type="button" value="View in Browser"/>
			3 per page <input type="button" value="v"/>
Photos/Images			Thumbnail <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Print <input type="checkbox"/>
1	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
2	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
3	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
4	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
5	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
6	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
7	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
8	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
9	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
10	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
11	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
12	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
13	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
14	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
15	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
16	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
17	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
18	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
19	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
20	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
21	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
22	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
23	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
24	08/07/19 17:31	General View	<input checked="" type="checkbox"/>
25	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
26	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
27	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
28	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
29	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
30	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
31	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
32	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
33	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
34	08/07/19 17:33	Photographs of Damaged Parts	<input checked="" type="checkbox"/>
35	08/07/19 17:33	Photo After Spray	<input checked="" type="checkbox"/>

**Photos/Images**

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
			 Load JPG	<input checked="" type="checkbox"/>
36	08/07/19 17:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	08/07/19 17:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	08/07/19 17:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	08/07/19 17:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	08/07/19 17:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	08/07/19 17:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	08/07/19 17:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	08/07/19 17:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

Reset

Save

Print

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19008436/T1CD3S2
Date: 19/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100412055-04
Claimant Vehicle No : SMD6875C **Insured Vehicle No :** SJH4648U
 Date of Loss: 07/05/2019 Nature of Claim: TP Claim No: 6881172762SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD6875C** Engine No: PE31271709
 Make & Model: MAZDA CX-3, 2.0 SKYACTIV-G 6AT (A) Chassis No: JM6DK2W7AK0406250
 Reg. Date: 30/08/2018 (Man. Year: 2018) Odometer: 8466 km
 Colour: Red
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50R18 Rear Tyre Size: 215/50R18
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/05/2019
 Date Inspected: 13/05/2019 Inspected At: NO.2 KAKI BUKIT AVE 2 #01-33
 Estimated Period of Repair: 4.0 days Repairer: William Lee Car Air Con

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

7/19/2019

REPAIR DETAILS**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Dented	0.00 F	*- F	
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
3	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F	
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F	
5	1		*REVERSE SENSOR	Damaged	0.00 F	*- F	
6	1		*REAR END PANEL	Repair	0.00 F	*- F	
7	1		*TAILGATE	Repair	0.00 F	*- F	
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >