

ASS. REC. BY:

REF: CS/MSG/19008374/1/10 d327

Special Instruction:

Survivor: Marcus

**ASSIGNMENT (Office)**

From (Person): Chhin Mynt Pui

of

MSG

Date/Time: 14.5.19 9:58 a.m

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: SGR 92215

Insured: SLG 6235X

at Workshop m/s U E motor

Tel: 82238601

of 3006 Ub Road 1

Policy No: 29034026QMY

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11.5.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.5.19 10:34 a.m

Person Contacted:

MR NG

Vehicle **IN** / OUT

Date/Time	Action/Instruction (X) Estimate
	SGR 92215 - NA/MSG/19008379/1/4 D.O.A - 11/05/2019
	SLG 6235X - NA/MSG/19008379/1/4 D.O.A - 11/05/2019
	Diamond: 15/5/2019
	After repair: 21/5/2019

ASS. REC. BY: Marcus

REF:

MS161  
**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SAR 92215at Workshop m/s UE rh

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 196.

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 5

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

25-2022

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: 277

Date / Time Action / Instruction

HTA 14023 byg. sub.  
no action ntt 4977  
4-5/2.

Veh No: SAR 92215Yr Regn: 2, 07Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: M.P. LenderC.C. 1584Colour: Beige

A/C: Insured / Std / NI / NA

Sp. Reading: 234587

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JMYSTCS3A74007522Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6Rear 6

R/Bal. \_\_\_\_\_

mm

R/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

D.O.A. 11/5/19D.O.I. 14/5/19

Survey held at \_\_\_\_\_

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 5

1)

☐

: Final Report

Resurvey No. of Trip: 2Survey Fee: 120

Date/Time, File Return to?

Transportation: \_\_\_\_\_

2)

Add Fee: ☐

: Site Insp (\$ \_\_\_\_\_)

) \$ + RS. \$ \_\_\_\_\_

☐

: Interview (\$ \_\_\_\_\_)

) Photos \_\_\_\_\_

☐

: Tech. Invs (\$ \_\_\_\_\_)

) Others \_\_\_\_\_

☐

: Weekend (\$ \_\_\_\_\_)

) \_\_\_\_\_

Report Format: PRE

Lump Sum / I.B.I. (\$) \_\_\_\_\_

TOTAL

121

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019 15:07		14 May 2019 09:58 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

Insured:		TEE CHEE SIONG, ID: S7176923B		[Created by insurer]
Main Claimant:		ANG KIM HOCK, ID: S1329229I		
Vehicle Reg. No.:	SGR9221S	Date of Loss:	11/05/2019 00:00 - :59 [31 Months and 5 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	29034026QMY Coverage: 06/10/2018 - 05/10/2019	
Vehicle Reg. No. (Insured):	SLG6235X	Policy No. (Claimant):		
		Excess:		
Repairer:	U E MOTOR (HQ) 3006, Ubi Road 1, #01-334, 408700 Ubi - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/05/2019]			
Driver/Custodian (Insured):	TEE CHEE SIONG ( ), NRIC: S7176923B Email:			
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: MR NG 8223 8601			

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Sent Message

This mail is associated with :

**\*SGR9221S**  
**[SLG6235X]**

TP  
ANG KIM HOCK  
May 11 2019 12:00AM  
[TEE CHEE SIONG]  
U E MOTOR

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **15/05/2019 15:13 PM.**  
**To** nyukpui\_cchia@sg.msig-asia.com  
**Subject** **SGR9221S [SLG6235X]**

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGR 9221S on 14/05/2019  
We are pending estimate from repairer.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9229I
<b>Vehicle Details</b>	
Vehicle No.:	SGR9221S
Vehicle to be Exported:	No
Intended Deregistration Date:	14 May 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	4G18HT6433
Chassis No.:	JMYSTCS3A7U007522
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,026.00
Original Registration Date:	26 Feb 2007
First Registration Date:	26 Feb 2007
Transfer Count:	1
Actual ARF Paid:	\$12,129.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	25 Feb 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,197.00
COE Rebate Amount:	\$14,023.00
<b>Total Rebate Amount:</b>	<b>\$14,023.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 14 May 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Invest with Fast Direct Execution

Multi-awarded, multi-regulated broker

USAIN BOLT  
OFFICIAL SPONSOR

XM  
WWW.XM.COM

Our services involve a significant risk and can result in the loss of your invested capital. T&Cs Apply

Open an Account

lancer

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Car Guru.Com Pte Ltd » Mitsubishi Lancer 1.6M GLX (COE till 01/2022)

Mitsubishi Lancer 1.6M GLX (COE till 01/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price

\$20,800

Depreciation

\$7,760 /yr

Reg Date

17-Jan-2007  
(2yrs 8mths 2days COE left)

Mileage

145,249 km (11.8k /yr)

Manufactured

2006

Road Tax

\$881 /yr

Transmission

Manual

Dereg Value

\$13,570 as of today (change)

OMV

\$10,449

COE

\$25,323

ARF

\$5,588

Engine Cap

1,584 cc

Power

79.0 kW (105 bhp)

Curb Weight

1,162 kg

No. of Owners

3

Type of Vehicle

Mid-Sized Sedan

Features

Super Durable 1.6L Inline 4 Cylinder 16 Valve SOHC Engine, 5 Speed, 105BHP, Good Fuel Efficient, 4XABS Disc Brakes, 2XSRS Airbags, Knockdown Rear Seat View specs of the Mitsubishi Lancer (2006-2008)

Accessories

Genuine Leather Seats, Sports Rims, Rear Spoiler, CD/MP3 Audio, Fog Lamps, Solar Film, Remote Alarm, Reverse Sensors.

Description

Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Before The Car Is Gone.

Category

COE Car

Status

Available


Resources







Car Valuation - Free

Find out the market value of your existing car for free. Get started

Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more





Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Car Guru.Com Pte Ltd

» dealer's pricelist

» 68 vehs sold | 50 vehs available

Address

210 Turf Club Road Lot A7/A8/A9

Search cars nearby this location

Location

Car Mall @ The Grandstand

Office No

67639595

Contact Person(s)

Lawrence 92228747

Jimmy 90079944

Posted on: 09-May-2019 | Last Updated on: 09-May-2019

Compare

[https://www.sgcarmart.com/used\\_cars/info.php?ID=815860&DL=2756](https://www.sgcarmart.com/used_cars/info.php?ID=815860&DL=2756)

14-May-19



**CONNECTING CAR BUYERS & SELLERS.**  
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



lancerPrice RangeDepreciation> 10 yearVehicle TypeSubmitAdvanced Search

Home » Used Cars » Direct Owners » Mitsubishi Lancer 1.6A GLX (COE till 05/2022)

Mitsubishi Lancer 1.6A GLX (COE till 05/2022)

OverviewFinancialInsuranceAccessoriesSimilarResearchPhotosMap

Price\$20,888

Depreciation\$6,960 /yr

MileageN.A.

Road Tax\$881 /yr

Dereg Value\$15,214 as of today (change)

COE\$25,333

Engine Cap1,584 cc

Curb Weight1,162 kg

Type of VehicleMid-Sized Sedan

Reg Date15-May-2007  
(3yrs COE left)

Manufactured2007


TransmissionAuto





OMV\$11,194

ARF\$11,124


Power79.0 kW (105 bhp)

No. of Owners4





100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER



Preferred Viewing Area

ShortlistReport Error

CompareMore Actions

Add note

DIRECT OWNER

**Features**  
Mitsubishi Lancer GLX (CS3) Reg: May 2007, COE Renew: May 2022. View specs of the Mitsubishi Lancer (2006-2008)


**Accessories**  
NRG Steering, K&N Filter, S90 Throttle, Unichip, Remus Exhaust, BC Coilover, SSCUS Seats, 15" Sports Rims, Evo 3 Brake Kit, Sound System.

**Description**  
Nicely Done Up, Health Engine, Brand New Paintwork.


**Category**  
COE Car, Direct Owner Sale

**Status**  
Available

Resources



Vehicle Evaluation  
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free  
Find out the market value of your existing car for free. Get started

Seller Information

Contact Person(s)Jeremy

Contact No.90685052


Enquiry[+] Contact Seller

ESSENTIAL TRANSACTION FORMS


» Indemnity form» Sales agreement

» Receipt» Hand-over form

» Ownership Transfer



GET HELP WITH PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with Car Loans, Insurance, Payments & Ownership Transfer. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement


Read our 8 Step Guide for Direct Buyers & Sellers

Posted on: 28-Apr-2019 | Last Updated on: 28-Apr-2019

Upfront Payment		» more Financial info
Transfer Fee	\$25	
Down Payment	\$6,266 (change)	Maximum 70% Loan
1st Instalment	\$452	Based on 3.75% interest rate

Products and Services

» View All



BRAND NEW FLEET AVAILABLE FOR RENT / LEASE

\$1,200

\$1,200


CALL: 8482 3003

EMAIL: sales@panpacific.com.sg


Service You Deserve. People you Trust.

Compare

Chrome Fuel Tank Cover (Mitsubishi Lancer EX)



Chrome Fuel Tank Cover



2 Din Console Compartment

https://www.sgcarmart.com/used\_cars/info.php?ID=753483&DL=1000

14-May-19

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

lancer

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » AKK Wheels Pte Ltd » Mitsubishi Lancer 1.6A GLX (COE till 06/2022)

Mitsubishi Lancer 1.6A GLX (COE till 06/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$17,800		
Depreciation	\$5,820 /yr	Reg Date	04-Jun-2007 (3yrs 20days COE left)
Mileage	167,000 km (14k /yr)	Manufactured	2007
Road Tax	\$881 /yr	Transmission	Auto
Dereg Value	\$15,479 as of today (change)	OMV	\$11,020
COE	\$25,313	ARF	\$8,629
Engine Cap	1,584 cc	Power	79.0 kW (105 bhp)
Curb Weight	1,162 kg	No. of Owners	3
Type of Vehicle	Mid-Sized Sedan		

**Features**  
ABS Braking System, SRS Airbags, Fuel Efficient And Reliable Single Cam 1,6L SOHC Engine, Powerful 4 Cylinder Inline 16 Valves Engine. View specs of the Mitsubishi Lancer (2006-2008)

**Accessories**  
Leather Seats, Sports Rims, Pioneer Touch Screen Audio System/MP3/USB, Reverse Sensors.

**Description**  
100% Accident Free, In House/Banks Loans Available, Call Us At Our Showroom For An Appointment Today. Buy And Sell With Assurance From AKK Wheels. Where Quality Service Really Matters.

**Category**  
COE Car

**Status**  
Available

Resources

- Car Valuation - Free**  
Find out the market value of your existing car for free. [Get started](#)
- Vehicle Evaluation**  
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



- Shortlist

Report Error
- Compare

More Actions
- Add note

Seller Information		
Company	AKK Wheels Pte Ltd	
	» dealer's pricelist	
	» 32 vehs sold   14 vehs available	
Address	7 Kaki Bukit Road 1 #03-05	
	<a href="#">Search cars nearby this location</a>	
Location	Eunos Technolink	
Office No	67424123	
Contact Person(s)	Aris Sidek	91086131
	Adrian Lim	93889933

Posted on: 18-Apr-2019 | Last Updated on: 14-May-2019

Upfront Payment

» more Financial info

Transfer Fee

\$25



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/05/2019 15:05
Date Of Accident	11/05/2019 12:05
Exact Location Of Accident	JUNCTION OF RIVERVALE DRIVE/SENGKANG EAST WAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGR9221S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ANG KIM HOCK
NRIC No	S1329229I
Email Address	ANG.KIMHOCK@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91172166
Alternative Phone No	OTHERS-91172166
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	LANCER-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5078810031-03
Cover Note Number	
<b>Driver</b>	
Name of Driver	ANG KIM HOCK
NRIC No	S1329229I
Date Of Birth	10/11/1958
Occupation	INDOOR
Date Of Driving Pass	19/12/1979
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91172166
Fax Number	
Contact Number	OTHERS-91172166
EMail Address	ANG.KIMHOCK@YAHOO.COM.SG

Address	BLK 123 RIVERVALE DRIVE #07-147
Postcode	542123
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	AFTER RAIN
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG6235X
Vehicle Make/Model/Colour	TOYOTA HARRIER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEE CHEE SIONG
NRIC/Passport Number	S7176923B
Contact Number	88090637
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 10/01/2018 AT 10:00 AM I WAS IN MY KAYAK  
 DRIVING & WANTED TO TURN RIGHT TO GO TO THE EAST SIDE  
 OF THE ROAD. I WAS IN THE LANE & THE OPPOSITE DIRECTION  
 A CAR SLAMMED INTO ME. I DID NOT SEE IN THE CAR LIGHTS &  
 I HAD NO COLLISION WITH MY CAR. SGT 97212

1. 10/01/2018 AT 10:00 AM

## DECLARATION

I declare the foregoing particulars are true in every respect.

Signature  
 Date & Time

Driver's Signature  
 (If driver is not the solicitor)  
 Date & Time

10/01/2018  
 Reporting Centre Personnel's Signature  
 Name  
 NRIC/PS No

### SKETCH PLAN

1. Please report correctly in the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information given must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may amount to a breach of conditions to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. As the signatory of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(1) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;

(2) investigating the accident and/or my claims;

(3) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(4) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(5) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(vi) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(vii) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(2) My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(iii) Information so collected under (a) above may be shared / disclosed

(i) to all Insurers, and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for compliance with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature  
Name *R. J. Gutter*  
NRIC/E.S. No.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 May 2019 15:07		14 May 2019 09:58 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>TEE CHEE SIONG</b> , ID: S7176923B								
Main Claimant:	<b>ANG KIM HOCK</b> , ID: S1329229I								
Vehicle Reg. No.:	<b>SGR9221S</b>	Date of Loss:	11/05/2019 00:00 - :59 [146 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	29034026QMY Coverage: 06/10/2018 - 05/10/2019						
Vehicle Reg. No. (Insured):	<b>SLG6235X</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>U E MOTOR (HQ)</b> 3006, Ubi Road 1, #01-334, 408700 Ubi - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Imm.Advice due 15/05/2019]								
Driver/Custodian (Insured):	TEE CHEE SIONG ( ), NRIC: S7176923B Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: MR NG 8223 8601								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents




\*SGR9221S  
[SLG6235X]  
TP  
ANG KIM HOCK  
May 11 2019 12:00AM  
[TEE CHEE SIONG]  
U E MOTOR

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	15/05/19 08:20	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
2	15/05/19 08:20	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
3	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
4	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
5	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
6	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
7	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
8	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
9	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
10	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
11	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
12	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
13	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
14	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
15	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
16	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
17	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
18	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
19	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
20	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
21	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
22	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
23	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
24	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
25	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
26	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
27	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
28	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
29	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
30	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
31	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
32	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
33	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
34	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
35	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
36	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	
37	15/05/19 08:21	General View						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
48	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
49	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
50	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
51	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
52	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
53	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
54	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
55	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
56	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
57	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
58	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
59	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
60	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
61	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
62	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
63	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
64	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
65	15/05/19 08:21	General View	 Load JPG	<input checked="" type="checkbox"/>
66	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	15/05/19 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	21/05/19 14:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 15:10	SLG6235X GIA Rpt	 Load PDF	
2	13/05/19 15:11	SGR9221S GIA Rpt	 Load PDF	
3	13/05/19 16:09	TP LIST OF SURVEYORS	 Load PDF	
4	13/05/19 16:09	SURVEY DISAGREE ON SJE - ASSIGN LKK.	 Load PDF	
5	13/05/19 16:48	EMAIL FROM TP ON WORKSHOP DETAIL	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19008474/UCD3E2

Date: 20/06/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29034026QMY

Claimant Vehicle No : SGR9221S

Insured Vehicle No : SLG6235X

Date of Loss: 11/05/2019

Nature of Claim: TP

Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGR9221S

Make &amp; Model: MITSUBISHI LANCER, 1.6 (A)

Engine No: 4G18HT6433

Reg. Date: 26/02/2007 (Man. Year: 2006)

Chassis No: JMYSTCS3A7U007522

Colour: Beige

Odometer: 234587 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 14/05/2019

Date Inspected: 14/05/2019

Inspected At:

U E MOTOR (HQ)  
3006, Ubi Road 1, #01-334  
Singapore 408700

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2019)
<b>Parts:</b> 143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGR9221S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >