

NATIONAL Assessment Centre Services. [ver 1 Jan'03] MNEA 119062469.

Date In: 14/5/19 11:41	Job description	Date & Time Completed	Done by
Ref No: MA/INC19008492/h4.	SAS e-filing		
Veh No: SKN 4769 M	E-mail (within 3hrs, AIC 2hrs)		
D.O.A: 13/5/19 16:30.	I-Motor Claim Form	MT/1044546-01	15/5/19 09:16.
☒ TP / Reporting Only	I-Motor W/O (Within: OD 2hrs, TP 4hrs)		
TP Insurer:	I-Photo Uploaded		
	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wks12		

Preferred Wksp / HRC Assign Wksp / QW: () Tel: () Fax: ()

TP Particulars:	Veh No: Tree	INC () / Non-INC ()
Owner / Driver: ()	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: ()	Date: ()	Time: ()
Insured/Driver Liability: ()	% [Note-Est. Status (WO): N: 0-20%; P: 21-79%; P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:

() Walk-In Customer: Customer's Information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks: (INC 1000000 0700 0010)

1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: ()

Date/Time	Actions

MA1904659

Claimant's Particulars:	Invoice Ref: MA1904659	Am't (\$)	PAID (\$)
Driver/Owner:	1) AR: Accident Reporting (\$30);	30.00	
Contact No:	2) DA: Damage Assessment (\$100); INC (\$80)	80.00	
Damaged Portion:	3) TP: Towing Fee \$40/\$45		
QC Checked by (Engr-In-Charge):	4) PT: Follow-Through Survey \$120		
Auditors Comments:	5) PT: Follow-Through Survey (Resurvey) \$30		
Tel. 1:	For claiming against INC Only (ver 10 Jan 2003)		
Tel. 2/3:	6) TR: Re-Inspection \$75		
	7) NI: Idea DA + SMRT Survey \$160		
	8) NTUC Additional Services:		
	QD:		
	*N5: Courtesy Car / Tpt Allowance \$3		
	*N6: Repair Co-ordination \$10	10.00	
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$3		
	TP (N11): TP (Non INC) against INC \$20		
	9) N12: Idea Mobile \$0		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/05/2019 11:41
Date Of Accident	13/05/2019 16:30
Exact Location Of Accident	TAMPINES ST 42
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKN4768M
Insured/Policyholder	
Name Of Registered Owner	M MOHAN S/O V P N MENON
NRIC No	S2512160J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96578129
Alternative Phone No	OFFICE-96578129
Vehicle Particulars	
Manufacturer	HONDA
Model	ACCORD 2.4L
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5071104281-03
Cover Note Number	-
Driver	
Name of Driver	LATA KURUP MRS. LATA MENON
NRIC No	S1504187J
Date Of Birth	16/02/1961
Occupation	INDOOR
Date Of Driving Pass	03/06/1996
Driving Experience	22 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91765114
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	15 TAMAN BEDOK
Postcode	487064
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 461 TAMPINES STREET 44 #01-56 , POSTCODE: 520461 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7818999 - FAX NO: 67838603
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	TRAFFIC POLICE TAKE THE MEMORY CARD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	TREE
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LATA KURUP MRS. LATA MENON

Approximate Age

Injuries Sustain

SLIGHTY

Injured person in which vehicle?

SKN4768M

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Diagram illustrating a road layout on a grid background. The road starts as a curve on the left, passing a building labeled 'A' and a tree. It then curves to the right, passing a dashed line with arrows indicating a lane change. The road continues straight to the right. Labels include 'xrec' near the tree, 'A = SKN 4768 M' on the right, and 'Tampines St 42.' at the bottom right.

Please Refer to Police Report

I/We declare the foregoing particulars are true in every respect.

S. Mead.
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190513/2138

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

1 of 3

Report No. T/20190513/2138

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/05/2019 17:54		Vide Report No.:		Station Diary No.: 36	
Informant's Particulars					
Name of Informant: LATA KURUP			Address: 15 TAMAN BEDOK SINGAPORE 487064		
ID Type / ID No.: NRIC NO / S1504187J			Contact No.: Home/Office: Mobile: 91765114		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 58	Date of Birth: 16/02/1961	Type of Informant: Driver		
Race: Indian			Language: English		Institution / School Name:
Occupation: Teacher			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 13/05/2019 16:30	Type of Location: Bend
Location: Along Road 1 TAMPINES STREET 42 the bend outside East View Secondary, towards Pasir Ris				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKN4768M	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190513/2138

2 of 3

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

Report No. T/20190513/2138

CONTINUATION OF REPORT

Driver				
Name	LATA KURUP		ID No.	S1504187J
Related Vehicle	NIL		Contact No.	91765114
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On 13-05-2019 at about 1630hrs, I turn left after exiting from Gongshang Primary School into Tampines St 42. I was travelling along Tampines St 42 and negotiating a right bend when suddenly my car went up the kerb and collided onto a tree on the left.

The location is just outside East View Secondary Sch. I do not know what happened, and I was not speeding. Traffic Police also attended to my accident and have already taken my onboard car camera memory card.



**SINGAPORE
POLICE FORCE**



T/20190513/2138

3 of 3

Report No. T/20190513/2138

Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461
Tel No: 1800-7818999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

SI ABU BAKAR BIN ESKAR

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Signature Of Informant:

Date/Time:

13/05/2019 17:54

Classification Of Case:

Authentication Stamp

NP168

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1504187J



Name
**LATA KURUP
MRS. LATA MENON**

Race
INDIAN

Date of Birth
16-02-1961

Country of Birth
SINGAPORE

Sex
F

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licensee Number
S1504187J

Name
**LATA KURUP
MRS LATA MENON**

Birth Date
16 Feb 1961

Issue Date
29 May 2003



2169563




NRIC No. **S1504187J**

Blood Group
A+

Date of issue
23-06-1994

15 TAMAN BEDOK
SINGAPORE 487064

NRIC No: **S1504187J** Date: **16-06-1999** No: **2984710**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE
03 Jun 1996

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

NP 428A

License No: **S1504187J**



Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident								
Vehicle No. (For Motor)	SKN4768M	Certificate Number								
Search										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5071104281-03		M MOHAN S/O V P N MENON	S2512160J	GPC	drivo CLASSIC	SKN4768M	SKN4768M	19/06/2018	18/06/2019

Claim Handling

Accident MT/1044546

Policy No.	5071104281-03	Vehicle No.	SKN4768M	GST Registration No.	
Certificate No.					
Policyholder Name	M MOHAN S/O V P N MENON				
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Policyholder NRIC	S2512
Contact No.(Mobile)	96578129	Contact No.(Office)		Loading	0
Email Address		Special Remark		Contact No.(Home)	
KFK	☐ No ☒ Yes	TCA	☐ No ☒ Yes	eCode	No
NCD Protection	Yes	NCD Entitlement(%)	50	eCode Reason	
				Private Hire	No

Accident Details

Report Date	15/05/2019 09:10	Accident Report Within 24 hrs	Yes	Accident Type	Collide
Date of Accident	13/05/2019	Time of Accident hh:mm	16:30	Country of Accident	Singap
Reporting Centre		Orange Force		ICM No.	
Accident Location	TAMPINES ST 42				

Excess

Own damage Excess	0.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	0.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

Coverage		Sum Insured	99999999.99
Excess Waiver			

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	15 TAMAN BEDOK	Address 2	SINGAPORE 487064	Address 3	
Address 4		Address Type	Singapore address	Post Code	487064
Unit No.		Related Policy Number	5071104281-03		

OT Driver Info

Driver Name	LATA KURUP MRS LATA MENON	Driver Type	Named Driver	Driver DOB	16/02/19
Unnamed driver Name		Driver NRIC	S1504187J	Driving Experience	19
Register Date of Driver License	01/01/2000	Driver Age	58	Contact No.(Home)	
Contact No.(Mobile)	91765114	Contact No.(Office)		Address 3	
Address 1	15 # TAMAN BEDOK	Address 2	SINGAPORE 487064	Post Code	487064
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Claim 001 New

Claim Type *

Contact No.(Mobile)	96578129	Insured Name	M MOHAN S/O V P N MENON
Email Address	Leo1500@gmail.com	Contact No. (Home)	62457629
Claim Description	SKN4768M / TREE ON 13 May 2019		
Preferred Workshop	0	Insured Liability	Fully at Fault
Workshop No.		Preferred Repair Option	income to assign workshop
Finalisation	Yes	GIA report	Received
Date Registered	15/05/2019 09:13	Claim Close Date	
Report Taken By	LIEW SHAN HUI		
Print AK letter			

Attachment

Save Submit

Accident No.

MT/1044546

Claim No.

001

Last Doc. Received

☒ Yes ☐ No

Upload Date

15/05/2019 09:16

Path *

Choose File No file chosen

Choose File No file chosen

Choose File No file chosen

Choose File No file chosen

Choose File No file chosen

Choose File No file chosen

Message Read

Category *

Confidential

Urgency *

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Clear

Please Select

NO

Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:16	NRIC/ Driving License	Normal	NRIC/ Driving License 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:16	SAS	Normal	SAS 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:16	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:16	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:16	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:16	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:16	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:15	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:15	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:15	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:15	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:15	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:14	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:14	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:14	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:14	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:14	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:14	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:13	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:13	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:13	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:13	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:13	Photos	Normal	Photos 2019-5-15
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) o 15 May 2019 09:13	Photos	Normal	Photos 2019-5-15



15 May 2019 09:13

Video List

Uploaded By/Date

Folder Date

File Name



Source

Display in New Window

Scan and uploading

ASSIGNMENT (IDAC)**By CSO- Nature of Accident:**

- 1) Vehicle hit Vehicle: ()
 a) Motorcar ()
 b) M/cycle ()
 c) Bicycle ()
- 2) Vehicle hit ??
 a) Pedestrian ()
 b) Animal ()
- 3) Vehicle hit Road Side Objects:
 a) Govn. Property ()
 (E.g: signboard, barrier, tree etc)
 b) Road Work Object ()
 c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 a) Fallen Object ()
 b) Flood ()
 c) Other, _____
- 6) Parked & Found Damaged:
 a) Vandalism ()
 b) Hit by Moving Object ()
- 7) Theft Case
 a) Stolen ()
 b) Damage found ()
 when recovered.
- 8) Fire
 a) Whilst driving ()
 b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information**Remarks to appear in Works Order & Assessment report**

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No. SKN 4768 M Yr Regn. 19 Jun 2014
 Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / MPV
 / Truck / Trailer or
 Make & Model: Honda Accord 2.4L c.c 2356
 Colour Black Transmission Type: Auto / Manual
 Eng/No: _____ Sp. Reading: No Key
103450
 C/No: MRHCR2630EP000007
 Gen. Cond: Good / Fair / Poor / Burnt or
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or
 Tyre Size: F: 235/45 R18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 4 mm R/Bal. 5 mm
 L/Bal. 4 mm L/Bal. 5 mm
 Parallel Import: Yes / No Towed-In: Yes / No
 Repair Type: LS / I.B.I Towing Required: Yes / No
 No of Repair Days: 18 Vehicle in Idac: Yes / No
 D.O.I. 14/5/2019 Time: 3.40 pm

By Assessor- 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
 e. Animal () f. Govn Object () g. Road Work Object ()
 h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()

3) Vehicle does not seem damaged as a result of:

- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
 e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

MOTOR CAR (Fr)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	BR		
1006	991325	Frt Bumper Bracket	NEC	6	
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	CRA	2	
1009	991318	Frt Bumper Beam	DD		
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding	CRA		
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	991100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	BR		
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CRA		
1022	991328	Frt Grille Emblem	CRA		
1023	991799	Frt Grille Chrome Moulding	NEC		
1024	991222	Frt Apron Panel	CRA		
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover	BT		
1027	992416	Horn	CRA		
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	BR		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem	BUC		
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator	BT		
1037	990273	Bonnet Hinge	BT		
1038	990261	Bonnet Damper	BT		
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable	BT		
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)	BT		
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)	DD		
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe	BT		
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom	CRA		
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct	DD		
1060	990070	Air Cleaner Assy	CRA		
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No **SKN 4768M**

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor	DD		
1075	990139	Alternator Assy	CRA		
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump	AS		
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit	CRA		
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover	BR		
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member	DD		
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	SCR		
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	CRA		
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim	CUT		
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BUC		
1106	991739	Frt RH Fender Inner Panel	BUC		
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	CRA		
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass	CRA		
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding	NEC		
1117	992098	Frt Windscreen Sealant	NEC		
1118	991019	ERP Bracket	NEC		
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish	LT BRN DIS		
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy	BR		
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag	BUS		
1128	994485	Steering Wheel Airbag Sensor	NEC		
1129	990749	Dashboard Airbag	BUS		
1130	990750	Dashboard Airbag Sensor	NEC		
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat	Airbag		
1133	991922	Frt RH Seat Belt Assy	BUS		
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Front Wire Harness	TNA		
		Rear LH Door	SCR		

Condition (CDS)

(01)Item (2)Dented (3)Distorted (4)Cracked (5)Cin (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing
(13)Torn (14)Unconfirmed (15)Not Working

MOTOR CAR (RH)

ACTION (ACS)

(1)Replace (✓) (2)Repair (X) (3)Check (?)
(4)Not Consistent (NC)

Aug 2/05

Vehicle No: SKN 4768 M

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	DDR		
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar	DDR		
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel Lining		TN	
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag		BUS	
1314	994084	Roof Top Air-bag Sensor		NEC	
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items:

Assessor:

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scatched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (UC)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug 2006

313

Undercarriage

Vehicle No: SKN 4768M

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm		?	/
1376	995199	Frt LH Knuckle Arm Bearing		?	/
1377	995178	Frt LH Lower Arm		?	/
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod		?	/
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper		?	/
1386	991292	Frt LH Brake Pipe		?	/
1387	991287	Frt LH Brake Hose		?	/
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion		?	/
1391	994435	Steering Cross Member	DD	/	/
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar		?	/
1395	991219	Frt Anti Roll Bar Linkage		?	/
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump		?	/
1399	990960	Engine Oil		?	/
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump		?	/
1403	992257	Gear Oil		?	/
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel		?	/
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam		?	/
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber	BT	/	/
1429	991944	Frt RH Shock Absorber Mounting			/
1430	990632	Frt RH Coil Spring			/
1431	991844	Frt RH Knuckle Arm	DIS	/	/
1432	991845	Frt RH Knuckle Arm Bearing	NGC	/	/
1433	991851	Frt RH Lower Arm	BT	/	/
1434	992064	Frt RH Upper Arm			/
1435	992040	Frt RH Tie Rod			/
1436	991692	Frt RH Drive Shaft	BR	/	/
1437	990661	Frt RH Control Arm			/
1438	992062	Frt RH Trailing Arm			/
1439	991848	Frt RH Leaf Spring			/
1440	991293	Frt RH Brake Disc Rotor			/
1441	991281	Frt RH Brake Caliper		?	/
1442	991292	Frt RH Brake Pipe		?	/
1443	991287	Frt RH Brake Hose		?	/
1444	991295	Frt RH Brake Sensor Wire			/
1445	993720	Rear RH Shock Absorber			/
1446	993723	Rear RH Shock Absorber Mounting			/
1447	993173	Rear RH Coil Spring			/
1448	993550	Rear RH Knuckle Arm			/
1449	993551	Rear RH Knuckle Arm Bearing			/
1450	993601	Rear RH Lower Arm			/
1451	993885	Rear RH Upper Arm			/
1452	993322	Rear RH Drive Shaft			/
1453	993178	Rear RH Control Arm			/
1454	995117	Rear RH Trailing Arm			/
1455	995110	Rear RH Leaf Spring			/
1456	992942	Rear RH Brake Disc Rotor			/
1457	992938	Rear RH Brake Caliper Assy			/
1458	990434	Rear RH Brake Pipe			/
1459	992947	Rear RH Brake Hose			/
		Rear LH Wheel Rim	GR	/	/
		" " " Tyre			/

No of Items:

Assessor:

Original copy

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2160J
Vehicle Details	
Vehicle No.:	SKN4768M
Vehicle to be Exported:	No
Intended Deregistration Date:	17 May 2019
Vehicle Make:	HONDA
Vehicle Model:	ACCORD 2.4L 5AT
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	K24W31200074
Chassis No.:	MRHCR2630EP000007
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$31,858.00
Original Registration Date:	19 Jun 2014
First Registration Date:	19 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$36,602.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2024
PARF Rebate Amount:	\$27,451.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,103.00
COE Rebate Amount:	\$34,637.00
Total Rebate Amount:	\$62,088.00

The information contained herein is correct as at 14 May 2019

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Very Rare MINI Hampton 50 Clubman.



Hampton Edition, Ultra Low Mileage, Special Indent Unit, Not The Common Clubman. Direct Owner StarAd



Browse by Category ▼

2 vehicles

Honda Accord

Sort by

Advanced

Search Selection

Honda Accord

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mil

Any

Any

2014

Any



Honda Accord 2.4A

\$81,500

\$11,300 /yr

16-Dec-2014

2,356 cc

73

Elegant Silver, Agent Unit, Spacious Sedan, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maint Flexible In House Loan Packages Available.

Prime Motor & Leasing

Posted: 04-May-2019

Tags: 2014 Honda Accord, 2014 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Honda



Honda Accord 2.4A

\$84,800

\$12,030 /yr

05-Dec-2014

2,356 cc

40

Consignment Unit, Viewing Strictly By Appointment Basis. Call Now!

Car Search

Posted: 02-May-2019

Tags: 2014 Honda Accord, 2014 honda accord, Honda Accord, honda accord, Honda, Accord, accord, Honda

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mil

For old advertisements, view **Expired ads**

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [For](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, insurance. Find buy used Honda Accord, Honda Accord Singapore, used Honda Accord Singapore, used Honda Accord, used vehicles Singapore have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car la sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, i

All prices and other information di
that this information is

Compare

n are gathered from sources and based on algorithms that are believed by sgCarMart. irrent, sgCarMart.com does not assume any responsibility for errors or omissions or wa

Claim Handling

Task Transfer Exit

Accident MT/1044546

LOS SAL SUB

Policy No.	5071104281-03	Vehicle No.	SKN4768M	GST Registration No.	
Certificate No.					
Policyholder Name	M MOHAN S/O V P N MENON			Policyholder NRIC	S25121603
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	96578129	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☐ No ☐ Yes	TCA	☐ No ☐ Yes	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No

Accident Details

Report Date	15/05/2019 09:10	Accident Report Within 24 hrs	Yes	Accident Type	Collided into Property
Date of Accident	13/05/2019	Time of Accident hh:mm	16:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	TAMPINES ST 42				

Excess

Own damage Excess	0.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	0.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

Coverage		Sum Insured	99999999.99
Excess Waiver			

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	15 TAMAN BEDOK	Address 2	SINGAPORE 487064	Address 3	
Address 4		Address Type	Singapore address	Post Code	487064
Unit No.		Related Policy Number	5071104281-03		

OI Driver Info

Driver Name	LATA KURUP MRS LATA MENON	Driver Type	Named Driver		
Unnamed driver Name		Driver NRIC	S1504187J	Driver DOB	16/02/1961
Register Date of Driver License	01/01/2000	Driver Age	58	Driving Experience	19
Contact No.(Mobile)	91765114	Contact No.(Office)		Contact No.(Home)	
Address 1	15 # TAMAN BEDOK	Address 2	SINGAPORE 487064	Address 3	
Address 4		Address Type	Singapore address	Post Code	487064
Unit No.					
Does he own a Singapore Registered car?	☐ Yes ☐ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☐ No
-------------------------------------	------	-------------	--

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Zuraimie Bin Mantau

LOS SAL SUB

Claim Type	OD-MD	Insured Name	M MOHAN S/O V P N MENON	Insured NRIC	S25121603
Contact No.(Mobile)	96578129	Contact No. (Home)	62457629	Contact No. (Office)	
Email Address	Leo1500@gmail.com	OI Vehicle Number	SKN4768M	TP Vehicle Number	TREE
Claim Description	SKN4768M / TREE ON 13 May 2019			Name of Preferred Workshop	0
Preferred Workshop	☐ No ☐ Yes	Preferred Repair Option	Income to assign workshop	Insured Liability report	Fully at Resolved
Date Registered	15/05/2019 09:17	Claim Close Date		Date Received	15/05/2019 00:00
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected by Workshop	

Print AK letter

Modification History

Special Claim Creation Approval

Approval Remarks	Reason
------------------	--------

damage assessment

Attachment

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	ACCORD	Engine Capacity	
Date of Registration	19/06/2014	Classis No.	MRHCR2630EP000007		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	

Remark

REMARK: NO OF REPAIR DAYS: 18 DAYS. 1X FRT GRILLE CHROME MOULDING - REPLACE. 1X FRT SUPPORT PANEL TOP GARNISH COVER - REPLACE. 1X AIRCON SUCTION PIPE-REPLACE. 1X AIRCON SUCTION HOSE - UNCONFIRM. 1X AIRCON LIQUID PIPE - REPLACE. 1X AIRCON BELT - UNCONFIRM. 1X AIRDUCT - REPLACE. 1X ABS PUMP CONTROL UNIT - REPLACE. 1X FRT LH WHEEL RIM - REPLACE. 1X FRT RH WHEEL RIM - UNCONFIRM. 1X FRT DRIVER SEAT AIRBAG - REPLACE. 1X FRT RH DOOR OUTER PILLAR - REPAIR. 1X FRT LH TIE ROD - UNCONFIRM. 1X FRT RH TIE ROD - UNCONFIRM. 1X FRT LH & RH BRAKE PIPE - UNCONFIRM. 1X FRT LH & RH BRAKE HOSE - UNCONFIRM. 1X ENGINE OIL - UNCONFIRM. 1X GEAR BOX OIL SUMP - UNCONFIRM. 1X GEAR OIL - UNCONFIRM. 1X REAR LH WHEEL RIM - REPLACE.

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	16000101	BUMPER (FRONT)	1	Replace	X
ABS	2	16002401	BUMPER CLIPS (FRONT)	6	Replace	X
ABSORBER	3	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	X
ACCELERATOR	4	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	X
ACTUATOR	5	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace	X
ADVERTISEMENT STICKER	6	16003201	BUMPER GRILLE (FRONT)	1	Replace	X
AIR BAG	7	16005501	BUMPER SENSOR (FRONT)	1	Unconfirm	X
AIR BLOWER	8	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm	X
AIR BOX	9	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace	X
AIR CHAMBER BOX	10	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Unconfirm	X
AIR CLEANER	11	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Replace	X
AIR COMPRESSOR	12	27100101	GRILLE (FRONT)	1	Replace	X
AIR CON	13	27100801	GRILLE EMBLEM (FRONT)	1	Replace	X
AIR CON (VAN)	14	41300101	SUPPORT PANEL (FRONT)	1	Replace	X
AIR COOLER	15	15600101	BRACE PANEL (FRONT)	1	Unconfirm	X
AIR DISTRIBUTOR	16	27700101	HEAD LAMP (LEFT)	1	Unconfirm	X
AIR FILTER	17	27700102	HEAD LAMP (RIGHT)	1	Replace	X
AIR FLOW	18	149001	BONNET	1	Replace	X
AIR GRILLE	19	14903401	BONNET LOCK (LOWER)	1	Replace	X
AIR HORN	20	149029	BONNET INSULATOR	1	Replace	X
AIR INTAKE	21	14902201	BONNET HINGE (LEFT)	1	Replace	X
AIR RESONATOR BOX	22	14902202	BONNET HINGE (RIGHT)	1	Replace	X
AIR THROTTLE BODY AND SENSOR	23	14901301	BONNET DAMPER (LEFT)	1	Unconfirm	X
ALARM	24	14901302	BONNET DAMPER (RIGHT)	1	Unconfirm	X
ALTERNATOR	25	149043	BONNET RUBBER (LONG)	1	Replace	X
ALUMINIUM PANEL - SIDE	26	112023	AIR CON CONDENSER	1	Unconfirm	X
AMPLIFIER	27	112060	AIR CON FAN	1	Unconfirm	X
ANTENNA	28	112044	AIR CON DISCHARGE PIPE	1	Replace	X
ANTI ROLL	29	112043	AIR CON DISCHARGE HOSE	1	Unconfirm	X
APRON	30	112011	AIR CON COMPRESSOR	1	Unconfirm	X
ARCH	31	344001	RADIATOR	1	Unconfirm	X
ARM REST	32	344005	RADIATOR COWLING	1	Unconfirm	X
ASH TRAY	33	344008	RADIATOR FAN	1	Unconfirm	X
AUTO CLUTCH	34	344011	RADIATOR FAN CLUTCH	1	Unconfirm	X
AUTO COOLER PIPE	35	34402802	RADIATOR HOSE (TOP)	1	Replace	X
AUTO CRUISE MOTOR	36	34402801	RADIATOR HOSE (BOTTOM)	1	Unconfirm	X
AUTO TRANSMISSION	37	344007	RADIATOR EXPANSION TANK	1	Replace	X
AXLE	38	110037	AIR CLEANER RESONATOR	1	Unconfirm	X
BACK REST (M/C)	39	454012	WIPER WASHER TANK	1	Replace	X
BACK SEAT	40	454014	WIPER WASHER TANK MOTOR	1	Replace	X
BALANCER	41	124001	ALTERNATOR	1	Unconfirm	X
BATTERY						
BEADING (M/C)						
BELT COVER (M/C)						
BELT TENSIONER						
BODY						
BODY (M/C)						
BOLT CAP (M/C)						
BOLT HEAD COVER (M/C)						
BONNET						
BOOT						
BOX (M/C)						
BOX BRACKET (M/C)						
BOX CARRIER (M/C)						
BOX DOOR						
BOX STICKER (M/C)						
BRACE PANEL						

BRAKE	42	124002	ALTERNATOR BELT	1	Replace	X
BRAKE - ABS	43	338013	POWER STEERING PUMP	1	Unconfirm	X
BRAKE (M/C)	44	338007	POWER STEERING COOLER PIPE	1	Unconfirm	X
BUMPER	45	338010	POWER STEERING HOSE	1	Unconfirm	X
GABIN	46	243014	ENGINE LOWER COVER	1	Replace	X
CAMBER	47	24301906	ENGINE MOUNTING (RIGHT)	1	Unconfirm	X
CAMSHAFT	48	19600502	CHASSIS MEMBER (FRONT RIGHT)	1	Replace	X
CAR AUDIO SYSTEM	49	25400102	FENDER (FRONT LEFT)	1	Repair	X
CAR JACK	50	25400103	FENDER (FRONT RIGHT)	1	Replace	X
CARBURATOR	51	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	X
CD CHANGER	52	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace	X
CD PLAYER	53	43600101	TYRE (FRONT LEFT)	1	Unconfirm	X
CDI UNIT (M/C)	54	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Replace	X
CENTRE BOTTOM	55	31900102	MUDFLAP (FRONT RIGHT)	1	Unconfirm	X
CENTRE BRACKET	56	43600102	TYRE (FRONT RIGHT)	1	Unconfirm	X
CENTRE CONSOLE	57	45100401	WINDSCREEN GLASS (FRONT)	1	Replace	X
CENTRE COWLING (M/C)	58	451020	WINDSCREEN SEALANT	1	Replace	X
CENTRE CROSS MEMBER	59	245001	ERP BRACKET	1	Replace	X
CENTRE EXHAUST	60	45400101	WIPER ARM (FRONT LEFT)	1	Unconfirm	X
CENTRE FARING (M/C)	61	45400102	WIPER ARM (FRONT RIGHT)	1	Unconfirm	X
CENTRE FOOTREST COVER (M/C)	62	45400301	WIPER BLADE (FRONT LEFT)	1	Replace	X
CENTRE GARNISH	63	45400302	WIPER BLADE (FRONT RIGHT)	1	Replace	X
CENTRE GLASS FRAME	64	454009	WIPER PANEL GARNISH	2	Replace	X
CENTRE GRILLE	65	401001	STEERING AIR BAG	1	Replace	X
CENTRE JAW (M/C)	66	401005	STEERING AIR BAG SENSOR	1	Replace	X
CENTRE LOWER MEMBER	67	226002	DASHBOARD AIR BAG	1	Replace	X
CENTRE OUTER PILLAR	68	226003	DASHBOARD AIR BAG SENSOR	1	Replace	X
CENTRE PILLAR	69	106007	AIR BAG CONTROL UNIT	1	Unconfirm	X
CENTRE SEAT	70	36300102	SEAT BELT (FRONT RIGHT)	1	Unconfirm	X
CENTRE SHAFT	71	36300101	SEAT BELT (FRONT LEFT)	1	Unconfirm	X
CENTRE SILENCER	72	455001	WIRE HARNESS	1	Replace	X
CENTRE STAND (M/C)	73	23300203	DOOR (REAR LEFT)	1	Repair	X
CHAIN (M/C)	74	23300202	DOOR (FRONT RIGHT)	1	Repair	X
CHAMBER (M/C)	75	23303002	DOOR HINGE (BOTTOM) (FRONT RIGHT)	1	Unconfirm	X
CHASSIS	76	23303102	DOOR HINGE (UPPER) (FRONT RIGHT)	1	Unconfirm	X
CHROME COVER (M/C)	77	356006	ROOF LINING	1	Replace	X
CIGARETTE LIGHTER	78	356017	ROOF TOP AIRBAG	1	Replace	X
CLEANER	79	356016	ROOF TOP AIR BAG SENSOR	1	Replace	X
CLUTCH	80	356015	ROOF TOP AIR BAG CONTROL UNIT	1	Unconfirm	X
CLUTCH (M/C)	81	30000101	KNUCKLE ARM (FRONT LEFT)	1	Unconfirm	X
COIL	82	30000102	KNUCKLE ARM (FRONT RIGHT)	1	Replace	X
COMPARTMENT	83	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1	Unconfirm	X
COMPONENT SPEAKERS	84	30000202	KNUCKLE ARM BEARING (FRONT RIGHT)	1	Replace	X
COMPRESSOR	85	30500101	LOWER ARM (FRONT LEFT)	1	Unconfirm	X
CONNECTING LINK	86	30500102	LOWER ARM (FRONT RIGHT)	1	Replace	X
CONNECTING ROD	87	23600102	DRIVE SHAFT (FRONT RIGHT)	1	Replace	X
CONSOLE BOX	88	15700801	BRAKE CALIPER (FRONT LEFT)	1	Unconfirm	X
CONTROL ARM	89	15700802	BRAKE CALIPER (FRONT RIGHT)	1	Unconfirm	X
CONVERTER	90	45101401	WINDSCREEN MOULDING (LEFT)	1	Replace	X
COOLING COIL	91	45101403	WINDSCREEN MOULDING (RIGHT)	1	Replace	X
COOLING FAN	92	401028	STEERING RACK & PINION	1	Unconfirm	X
CORNER PANEL	93	401021	STEERING CROSS MEMBER	1	Replace	X
COVER ENGINE GUARD (M/C)	94	12800101	ANTI ROLL BAR (FRONT)	1	Unconfirm	X
COVER FRAME (M/C)	95	12800401	ANTI ROLL BAR LINK (FRONT)	1	Unconfirm	X
COWLING	96	243030	ENGINE OIL SUMP	1	Unconfirm	X
COWLING (M/C)	97	256005	FLOOR PANEL	1	Unconfirm	X
CRANK CASE	98	13700101	AXLE BEAM (FRONT)	1	Unconfirm	X
CRANK SHAFT	99	43600103	TYRE (REAR LEFT)	1	Unconfirm	X
CRASH BAR (M/C)	100	36600102	SHOCK ABSORBER (FRONT RIGHT)	1	Replace	X
CRASH PAD (M/C)	101	36600602	SHOCK ABSORBER MOUNTING (FRONT RIGHT)	1	Unconfirm	X
CROSS MEMBER	102	22600102	DASHBOARD (TOP)	1	Replace	X



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315

NAC
NATIONAL
ASSESSMENT
CENTRE

Vehicle Movement Form

Vehicle Check-In

Vehicle No: SKN 4768 M Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: MODERN MOTOR

Collection Date: 16/05/19 Time: 1145 with Keys: Yes / No

Tow Truck No: GD 7571 A Tow Man: PHUA THIAN CHEONG NRIC: S6802638D

Signature: _____

91883945

For office use

Attended by: _____

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Zuraimie Bin Mantau <zuraimie.mantau@income.com.sg>
Sent: Thursday, 16 May 2019 10:21 AM
To: Modern Automotive (admin@modernautomotive.com.sg)
Cc: LKK Paya Ubi; Chin
Subject: Vehicle SKM4768M, OD Claim No: MT/1044546-001, DOA: 13/05/2019

Dear Modern Automotive

Excess Waiver applies.

Vehicle is currently at NAC Paya Ubi.

Please arrange to tow away the vehicle and help update Mr Mohan at 96578129 once vehicle is in the workshop.

Strictly no further supplementary is allowed and please arrange for a **survey before repair**.

Please forward the invoice and DV within 7 working days to us once repairs has been done and survey has been conducted.

Update the 'Repair Status' when repairs are done.

XX

Our Ref: MT/CA/OD/051/1044546-001/ZBM

16 May 2019

MODERN AUTOMOTIVE PTE LTD

BLK 3023A #01-61 UBI ROAD 1

SINGAPORE 408717

Dear Sir

CLAIM NUMBER: MT/1044546-001

REPAIR OF VEHICLE NUMBER: SKN4768M

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 16 May 2019

Make: HONDA

Model: ACCORD

Estimated Repair Days: 14

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: Excess Waiver

Excess Applicable: 0.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Zuraimie Bin Mantau at 64307891 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Thank you

Zuraimee Bin Mantau

Senior Executive

Motor Insurance

T +65 6430 7891

www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.