

Estimate

Date 05 / 14 / 2019

001 / 001

Name	QUOTATION FOR SFY5276K	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5DK7C
		Vin-Code	JF1SJ5KC5GG078958

Part Number	Part Code Name	Part Code	Q'ty	Price
57704SG012	BUMPER-FACE,REAR <i>ee</i>	FIG-591 57704A	1	540.00
57711SG0219P	BACK BEAM COMPLETE-REAR <i>?</i>	FIG-591 57711D	1	288.00
E7710SG000	R BUMPER STEP S/S <i>ee</i>	FIG-591 57711D	1	460.00
57707SG080	BRACKET-REAR BUMPER SIDE,RIGHT <i>X</i>	FIG-591 57707H	1	14.40
57707SG090	BRACKET-REAR BUMPER SIDE,LEFT <i>X</i>	FIG-591 57707I	1	14.40
57707SG060	BRACKET-REAR BUMPER CORNER,RIG <i>X</i>	FIG-591 57707AC	1	18.00
57707SG070	BRACKET-REAR BUMPER CORNER,LEF <i>X</i>	FIG-591 57707AD	1	18.00
57731SG010NN	COVER-REAR BUMPER <i>?</i>	FIG-591 57731C	1	12.60
84281SC000	REFLEX REFLECTOR ASSEMBLY-RIGH <i>?</i>	FIG-842 84281	1	20.40
84281SC010	REFLEX REFLECTOR ASSEMBLY-LEFT <i>X</i>	FIG-842 84281A	1	20.40
		Page-Total		1,406.20
		Sub-Total		1,406.20
		Total		1,406.20
		Tax		0.00
		Grand Total		1,406.20

Memo

Grand Total
1,406.20

--

Tel



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SFY5276K	MODEL : FORESTER 2.0I-L AWD CVT
REF NO: INS/IC/CHI/200/2019	YEAR: 28-OCT-2016
ENGINE NO: FB20Y448269	CHASSIS NO: JF1SJ5KC5GG078958
DOA: 13/05/2019	TOA: 0720HRS
TYPE OF CLAIM: 3RD PARTY	INS COMPANY: FWD

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE REAR BUMPER & END PANEL 560	\$2240.00
2.	RESpray REAR BUMPER & END PANEL 420	\$1680.00
3.	TO CONDUCT REAR LIGHTING TEST N/A	\$50.00
4.	TO SUPPLY & INSTALL REVERSE SENSOR – 2 EYES ✓	\$300.00
5.	SUNDRIES 20	\$100.00
6.		
7.		
8.		
9.		
10.		
	Total Labour	\$4370.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Guo Qiang
HP / EMAIL:	82880282 / Guo.Qiang@lkkauto.com
BEFORE PAINT:	before paint photos.
DAYS GIVEN:	3

26/6/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: