

ASS. REC. BY:

REF: CS/C711900 8499/ U9/d3

n2

Special Instruction:

Surveyor: marcus

## ASSIGNMENT (Office)

From (Person): Elaine Chuong of CTI Date/Time: 14.5.19 11.57 a.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 3646L Insured: YP 6045Bat Workshop m/s Hock Wah motor Tel: 64415655of BK 3011 Bedok Industrial park 6 #01-2008Policy No: DMCVSN 3024971901 Claim No: SNM19D 202019102

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 4.5.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 14.5.19 12.54 p.m Person Contacted: Janice H.O.D. Endorsement: \_\_\_\_\_Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBF 3646L - X</u>
	<u>YP 6045B - X</u>

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

Gls / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn:

9 / 16

c.c 2998

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

FEA01BA20227

Good / Fair / Poor / Burnt

In order / Jammed / Leaked / Burnt or

In order / Jammed / Leaked / Burnt or

Nil / S/Rim / STD A/Rim or

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

RECEIVED 06 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

220

4/6/19 confirmed final by 6093.62 with Any. 9. (mermen system \$6093.63)

(Red \$7789.12, 56.50)

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 May 2019		14 May 2019 11:57 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:				
Main Claimant:		A LINK PETROLEUM PTE LTD, Co. Reg. No.: 200004696K		
Vehicle Reg. No.:		GBF3646L	Date of Loss:	04/05/2019 13:00 - :59
Claim Type:		TP / SNM19D202019C02	Policy/Cover Note No.:	DMCVSN3024971901
Vehicle Reg. No. (Insured):		YP6045B	Policy No. (Claimant):	S103567527
		Excess:	S\$600.00	
Repairer:		Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655		
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/05/2019]		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



**Win a 1-month supply\***  
when you try NEW Huggies® Platinum

**TRY FREE SAMPLE**

\*Terms and conditions apply

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 10 Years Coe Renewal Toyota Estima 2.4A



2.98% p.p.a \$0 Admin Fees@Gv  
Finance.2 Years Warranty.\$4800  
Down Monthly From \$988  
GV Credit Pte Ltd StarAd



**Think One Automobile**

**NEW & USED COMMERCIAL VEHICLES**









Browse by Category

Sort by Date Posted 20 results/page

15 vehicles

Mitsubishi Canter

Advanced Search Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Mitsubishi Canter	Any	Any	2016	Any	Any	Any	Available
	<b>Mitsubishi Fuso Canter FEB21</b>	<b>\$51,800</b>	<b>\$7,590 /yr</b>	<b>22-Mar-2016</b>	<b>2,998 cc</b>	<b>-</b>	<b>Truck</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel New Paintwork, Auto Transmission, In House Loan Available, Trade In Welcome.								
Posted: 27-May-2019 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi								
	<b>Mitsubishi Fuso Canter FEB50</b>	<b>\$55,800</b>	<b>\$8,180 /yr</b>	<b>22-Mar-2016</b>	<b>2,998 cc</b>	<b>57,000 km</b>	<b>Truck</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel 1 Owner. 14 Feet Lorry, Class 3 Can Drive, No VPC Needed. Tip Top Condition, Doorstep Viewing Can Be Arrange, 100% Loan Are Welcome!								
Qifei Auto Pte Ltd Posted: 27-May-2019 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi								
	<b>Mitsubishi Fuso Canter FEB21</b>	<b>\$59,800</b>	<b>\$8,140 /yr</b>	<b>28-Sep-2016</b>	<b>2,998 cc</b>	<b>-</b>	<b>Truck</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel As Good As New, With New Canopy, High Trade In, Low Interest, Door Step View, Call Now For Appointment!								
ABWIN (1994) Pte Ltd Posted: 27-May-2019 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi								
	<b>Mitsubishi Fuso Canter FECX1</b>	<b>\$76,800</b>	<b>\$10,350 /yr</b>	<b>27-Oct-2016</b>	<b>2,998 cc</b>	<b>39,850 km</b>	<b>Truck</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel Best Selling 18 Feet Open Truck In The Market. Superb Well Maintained By Seller With Mileage Clocked Less Than 40km. Under Agent Warranty As Well. With Our Team Of Finance And Insurance To Assist You....								
Bell Auto Pte Ltd Posted: 27-May-2019 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi								
	<b>Toyota Dyna With Canopy (For Rent)</b>							
Toyota Dyna 150D (10ft) Full Canopy for rent. Truck Lorry 10ft Find out more!								
	<b>Mitsubishi Fuso Canter FEB71</b>	<b>\$55,800</b>	<b>\$8,100 /yr</b>	<b>14-Apr-2016</b>	<b>2,998 cc</b>	<b>83,779 km</b>	<b>Truck</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel Like New. Previous Owner Kept This Lorry As Spare Vehicle. Interior And Exterior No Difference From New Vehicle. New Tyres. Very Reliable In The Long Run. Good For Carrying Heavy Loads And Workers. On...								
ABWIN (1994) Pte Ltd Posted: 25-May-2019 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi								
	<b>Mitsubishi Fuso Canter 3.0M</b>	<b>\$57,800</b>	<b>\$8,240 /yr</b>	<b>01-Jun-2016</b>	<b>2,998 cc</b>	<b>-</b>	<b>Truck</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel 1 Owner 14 Feet Truck With Canopy. Class 3 Can Drive No Need VPC. Vehicle In A Very Good Condition. Doorstep Viewing Can Be Arrange.								
ABWIN (1994) Pte Ltd Posted: 23-May-2019 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi								
	<b>Mitsubishi Fuso Canter 3.0M</b>	<b>\$56,800</b>	<b>\$8,250 /yr</b>	<b>13-Apr-2016</b>	<b>2,998 cc</b>	<b>88,000 km</b>	<b>Truck</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel Think One Automobile & Trading								
Posted: 22-May-2019 Tags: 2016 Mitsubishi Fuso, 2016 mitsubishi fuso, Mitsubishi Fuso, mitsubishi fuso, Mitsubishi, Fuso, fuso, Used Mitsubishi								

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	4696K
<b>Vehicle Details</b>	
Vehicle No.:	GBF3646L
Vehicle to be Exported:	No
Intended Deregistration Date:	27 May 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEA01BR1SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C15651
Chassis No.:	FEA01BA20227
Maximum Power Output:	-
Open Market Value:	\$28,702.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$1,436.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Sep 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$49,890.00
COE Rebate Amount:	\$36,613.00
<b>Total Rebate Amount:</b>	<b>\$36,613.00</b>

The information contained herein is correct as at 27 May 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/05/2019 09:29
Date Of Accident	04/05/2019 13:05
Exact Location Of Accident	BEDOK RESERVOIR ROAD BLK 743 OPEN CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF3646L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	A LINK PETROLEUM PTE LTD
Co Reg No	200004696K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64425050
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	CANTER FEA01BR1SDEB (CBU)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103567527
Cover Note Number	30/09/2018 - 29/09/2019

### Driver

Name of Driver	TAN SZE WAH (CHEN SIHUA)
NRIC No	S7301492A
Date Of Birth	20/01/1973
Occupation	OUTDOOR
Date Of Driving Pass	26/05/1994
Driving Experience	24 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97889929
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	25 MOONSTONE LANE #13-02
Postcode	328465
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE STATED DATE & TIME, I WAS DRIVING MY VEHICLE A (GBF3646L) ALONG BEDOK RESERVOIR ROAD BLK 743 OPEN CARPARK. MY VEHICLE WAS STATIONARY AS I WAS WAITING FOR VEHICLE B (YP6045B) WHICH WAS REVERSING OUT FROM A ROAD END AND THE DISTANCE BETWEEN OUR VEHICLES WERE ABOUT 10 METERS APART. SENSING THE COLLISION, I SOUNDED MY HORN CONTINUOUSLY BUT VEHICLE B DID NOT STOP AND COLLIDED INTO THE FRONT OF MY STATIONARY VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6045B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	97301537
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:




Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan Pg. 2

### SKETCH PLAN



Job A: 68/3646L

5. 706455

Location: Zeller Reservoir Pond Site 103

John Connor

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to CIA Report

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated time-frame from the day of occurrence.

Reporting Only

Claim OD

✓	Claim TP
---	----------

Claim OD/TP at other workshop	
-------------------------------	--

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4.  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

6093.62

TO : 200004696K  
A LINK PETROLEUM PTE LTD  
NO 44 EASTWOOD DRIVE

SINGAPORE 486140  
TEL : 64425050 FAX : 64439804  
PH : 97889929  
ATTN :

## ESTIMATE BILL

Number : EB00005151  
Date : 07/05/2019  
Case No : AD00010389  
Vehicle No : GBF3646L  
Chassis : FEA01BA20227  
Year of Mfr : 2016  
Policy No :  
Model : MITSUBISHI CANTER

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT WIPER GARNISH	1.0	572.57	10	515.31
2	FRONT PANEL	1.0	2,197.00	10	1,977.30
3	FRONT PANEL LOGO - FUSO	1.0	154.96	10	139.46
4	FRONT GRILLE	1.0	1,053.14	10	947.83
5	FRONT GRILLE CLIP	2.0	6.90	10	12.42
6	FRONT GRILLE EMBLEM	1.0	82.54	10	74.29
7	FRONT GRILLE LOGO - CANTER	1.0	78.41	10	70.57
8	CORNER PANEL LH	1.0	506.76	10	456.08
9	CORNER PANEL RH	1.0	506.76	10	456.08
10	WING MIRROR BRACKET LH	1.0	458.95	10	413.06
11	WING MIRROR ROUND LH	1.0	58.79	10	52.91
12	WING MIRROR TOP COVER LH	2.0	38.61	10	69.50
13	FRONT SIGNAL LAMP LH	1.0	266.36	10	239.72
14	AIR CON BLOWER HOUSING	1.0	607.54	10	546.79
15	AIR CON HOUSING	1.0	2,584.78	10	2,326.30
16	FRONT WIPER TANK	1.0	330.48	10	297.43
17	FRONT WIPER MOTOR	1.0	685.33	10	616.80
18	FRONT BRAKE BOOSTER	1.0	1,966.22	10	1,769.60
19	FRONT WINDSCREEN RUBBER	1.0	423.66	10	381.29
List Price - Parts Sub Total					11,362.74
Parts Total					11,362.74
20	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
21	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
22	ANTI-RUST COATING	1.0	200.00	0	200.00
23	WIRING	1.0	40.00	0	40.00
24	TO REMOVE & REFIT DASHBOARD	1.0	350.00	0	350.00
25	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
26	TO REMOVE & REFIT AIR CON SYSTEM	1.0	150.00	0	150.00
Labour 1 Sub Total					2,520.00
Total					13,882.74

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 200004696K  
A LINK PETROLEUM PTE LTD  
NO 44 EASTWOOD DRIVE

SINGAPORE 486140  
TEL : 64425050 FAX : 64439804  
PH : 97889929  
ATTN :

## ESTIMATE BILL

Number : EB00005151  
Date : 07/05/2019  
Case No : AD00010389  
Vehicle No : GBF3646L  
Chassis : FEA01BA20227  
Year of Mfr 2016  
Policy No  
Model : MITSUBISHI  
CANTER

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
SINGAPORE DOLLARS : FOURTEEN THOUSAND EIGHT HUNDRED FIFTY-FOUR AND CENTS FIFTY-THREE ONLY			Less Excess		0.00
			SUBTOTAL		13,882.74
			GST 7.00%		971.79
			TOTAL		14,854.53

Date of accident : 04/05/2019 01:05 PM. Place : BEDOK RESERVOIR ROAD BLK743 OPEN CARPARK

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19008499/UQD3N2

Date: 06/06/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3024971901
Claimant Vehicle No :	GBF3646L	Insured Vehicle No :	YP6045B
Date of Loss:	04/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202019C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	GBF3646L	Engine No:	4P10C15651
Make & Model:	MITSUBISHI CANTER, 3.0 D FEA01B (M)	Chassis No:	FEA01BA20227
Reg. Date:	30/09/2016 (Man. Year: 2016)	Odometer:	27797 km
Colour:	Silver		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/70R15	Rear Tyre Size:	185/75R15 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,362.74	4,543.63	6,819.11	60.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,550.00	970.00	38.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,882.74</b>	<b>6,093.63</b>	<b>7,789.11</b>	<b>56.11</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,093.62</b>		
<b>(S\$)</b>	<b>13,882.74</b>	<b>6,093.62</b>	<b>7,789.12</b>	<b>56.11</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>971.79</b>	<b>426.55</b>	<b>545.24</b>	<b>56.11</b>
<b>Nett Amount (S\$)</b>	<b>14,854.53</b>	<b>6,520.17</b>	<b>8,334.36</b>	<b>56.11</b>

## INSPECTION

Date of Assignment: 14/05/2019

Date Inspected: 27/05/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd  
(Bedok)  
Blk 3011, Bedok Industrial Park E., #01-  
2008/2010/2012  
Singapore 489977

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Jun 2019)	
<b>Parts:</b>	N/A	mitsubishi canter 3.0 D FEA01B (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF3646L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WIPER GARNISH	Cracked	572.57 FL	*572.57 FL
2	1		*FRONT PANEL	Badly Dented	2,197.00 FL	*1,455.00 FL
3	1		*FRONT PANEL LOGO-FUSO	Necessary	154.96 FL	*154.96 FL
4	1		*FRONT GRILLE	Not Necessary	1,053.14 FL	*- FL
5	2		*FRONT GRILLE CLIP	Not Necessary	13.80 FL	*- FL
6	1		*FRONT GRILLE EMBLEM	Not Necessary	82.54 FL	*- FL
7	1		*FRONT GRILLE LOGO-CANTER	Not Necessary	78.41 FL	*- FL
8	1		*CORNER PANEL LH	Cracked	506.76 FL	*506.76 FL
9	1		*CORNER PANEL RH	Repair	506.76 FL	*- FL
10	1		*WING MIRROR BRACKET LH	Bent	458.95 FL	*458.95 FL
11	1		*WING MIRROR ROUND LH	Missing/Broken	58.79 FL	*58.79 FL
12	2		*WING MIRROR TOP COVER LH	Not Necessary	77.22 FL	*- FL
13	1		*FRONT SIGNAL LAMP LH	Cracked	266.36 FL	*266.36 FL
14	1		*AIR CON HOUSING }	Cracked	2,584.78 FL	*2,584.78 FL
15	1		*AIR CON BLOWER HOUSING }		607.54 FL	*- FL
16	1		*FRONT WIPER TANK	Not Necessary	330.48 FL	*- FL
17	1		*FRONT WIPER MOTOR	Not Necessary	685.33 FL	*- FL
18	1		*FRONT BRAKE BOOSTER	Not Necessary	1,966.22 FL	*- FL
19	1		*FRONT WINDSCREEN RUBBER	Not Necessary	423.66 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,625.27</b>	<b>6,058.17</b>
<b>- List Item Discount on L Items 10.00/25.00% (\$\$)</b>	<b>1,262.53</b>	<b>1,514.54</b>
<b>Total Parts (\$\$)</b>	<b>11,362.74</b>	<b>4,543.63</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	600.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	600.00
3	ANTI-RUST COATING	New	200.00	30.00
4	WIRING	New	40.00	20.00
5	TO REMOVE & REFIT DASHBOARD	New	350.00	200.00
6	TO REMOVE & REFIT WINDSCREEN	New	180.00	0.00
7	TO REMOVE & REFIT AIR CON SYSTEM	New	150.00	100.00
Gross Labour Cost (\$\$)			<b>2,520.00</b>	<b>1,550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >