

2/15/2019

ASS. REC. BY:

REF: CS/SMD/9008505/Eqd382

Special Instruction:

Surveyor: Hwai Jie

**ASSIGNMENT (Office)**

From (Person): Hwang Shiang Yi

of SMD

Date/Time: 14.5.19 9.11 AM

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: SHB 5424Y

Insured: SLJ 4911A

at Workshop m/s SMRT Automobile

Tel: 6866 2628

of 60 Woodlands Industrial Park E4

Policy No: D18MTPV01017683

Claim No: CMTD1902298

Sum Insured:

Excess:

Make of Veh:

D.O.A 12.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"rup"

H.O.D. Endorsement:

Date/Time: 14.5.19 9.52 a.m

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 5424Y - X

SLJ 4911A - X

15/5/19 @ 5.39pm revised to Hwang Shiang Yi via Messenger.

19/7/19 @ 1.13M confirmed with Poh Guan final fig \$8067.22, 5 days.

(Red \$15363.72, 66%)

REF: Hwee Jie


REF: SMO

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s: \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB5424Y Yr Regn: 30 Nov 2017  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798  
 Colour: maroon A/C: Insured / Std / NI / NA  
 Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTDKB3FU203575570

Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Wustlake

| Front                 |  | Rear                  |  |
|-----------------------|--|-----------------------|--|
| R/Bal. <u>6</u> mm    |  | R/Bal. <u>6</u> mm    |  |
| L/Bal. <u>6</u> mm    |  | L/Bal. <u>6</u> mm    |  |
| D.O.A. <u>12/5/19</u> |  | D.O.A. <u>14/5/19</u> |  |

Survey held at Swrt  
 Des. of Damages: Fr / Rear / O/S / NI / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                                    |
|-------------|---------------------------------------------------------|
| 19/7/19     | Final amount \$8067.22, 5 days<br>(Red \$15363.77, 66%) |
|             |                                                         |
|             |                                                         |
|             |                                                         |
|             |                                                         |
|             |                                                         |
|             |                                                         |
|             |                                                         |
|             |                                                         |
|             |                                                         |

05/19/2052

SLJ 4911A

RECEIVED 19 JUL 2019

Date/Time. File Pass to? ☐ : Prel. Report  
☐ : Final Report

1) 19/12 19/12  
 Date/Time. File Return to?

Days Of Repair: 5  
 Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech Invs (\$)  
☐ : Weekend (\$)

Survey Fee:  
 Transportation:  
 ) S + PS. SI  
 ) Photos  
 ) Other

Report Format: TP  
 Lump Sum / I.B.I. (\$ 8067.22)

|     |
|-----|
| 490 |
| 11  |
| 461 |

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 12 May 2019 |               | 14 May 2019<br>09:11<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

| Main                             | Reference                                                                                                      | Claim Details                                                                                                  | Documents                          | Show All |         |             |              |            |       |
|----------------------------------|----------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>   |                                                                                                                | <b>[Created by insurer]</b>                                                                                    |                                    |          |         |             |              |            |       |
| Insured:                         | LOW WAI MUN (LIU WEIWEN), ID: S8029818H                                                                        |                                                                                                                |                                    |          |         |             |              |            |       |
| Main Claimant:                   | SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K                                                                   |                                                                                                                |                                    |          |         |             |              |            |       |
| Vehicle Reg. No.:                | SHB5424Y                                                                                                       | Date of Loss:                                                                                                  | 12/05/2019 15:00 - :59             |          |         |             |              |            |       |
| Claim Type:                      | TP / CMTD1902298                                                                                               | Policy/Cover Note No.:                                                                                         | D18MTPV01017683<br>(Comprehensive) |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):      | SLJ4911A                                                                                                       | Policy No. (Claimant):                                                                                         |                                    |          |         |             |              |            |       |
|                                  |                                                                                                                | Excess:                                                                                                        |                                    |          |         |             |              |            |       |
| Repairer:                        | SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628 |                                                                                                                |                                    |          |         |             |              |            |       |
| Handling Insurer:                | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]         |                                                                                                                |                                    |          |         |             |              |            |       |
| Adjuster:                        | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 24/05/2019]</b>                       |                                                                                                                |                                    |          |         |             |              |            |       |
| Driver/Custodian (Insured):      | KWOK FENG YI ( ), NRIC: S8114567L, Tel: +6596910758 Email:                                                     |                                                                                                                |                                    |          |         |             |              |            |       |
| Adj Asg. Remarks:                | WS: SHANTI 68662671/2                                                                                          |                                                                                                                |                                    |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b>  |                                                                                                                | <a href="#">View All</a> <a href="#">Compose Case Mail</a>                                                     |                                    |          |         |             |              |            |       |
| There are no mail for this case. |                                                                                                                |                                                                                                                |                                    |          |         |             |              |            |       |
|                                  |                                                                                                                |                                                                                                                |                                    |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b>      |                                                                                                                | <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |                                    |          |         |             |              |            |       |
| Due Date                         | Priority                                                                                                       | Type                                                                                                           | Task Group                         | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                      |                                                                                                                |                                                                                                                |                                    |          |         |             |              |            |       |

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 19 July 2019 1:13 PM  
**To:** Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis); SUR; CS A Team  
**Cc:** Leong Chee kwong  
**Subject:** RE: SHB5424Y

Dear Poh Suan,

WITHOUT PREJUDICE

Confirm final fig \$8,067.22 before GST and 5 repair days.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>  
Sent: Tuesday, 16 July 2019 5:21 PM  
To: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>  
Cc: Leong Chee kwong <cheekwongwega@gmail.com>  
Subject: SHB5424Y

Hi All,

Attached herewith the repair estimate of SHB 5424Y having Case No: TAX/05/19/2052.

There is no change to the approved amount of \$8,067.22 @ 5 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)  
Sent: Tuesday, 16 July 2019 5:11 PM  
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)  
Subject: Scan Data from FX-D421D6

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hwang Shiang Yi

Date: 15 May 2019

**Preliminary Advice**

|                    |                                                                                                       |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLJ4911A                                                                                            |                         |              |
| TP Vehicle No      | : SHB5424Y                                                                                            | Accident Date           | : 12/05/2019 |
| Make               | : TOYOTA PRIUS TAXI                                                                                   | Assignment Date         | : 14/05/2019 |
| Date of Inspection | : 14/05/2019                                                                                          | Est. Duration of Repair | : 5.00       |
| Inspection At      | : SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS)<br>60 WOODLANDS INDUSTRIAL PARK E4<br>SINGAPORE 757705 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 17,068.14 |
| Revised Amount              | :S\$ | 6,105.49  |
| Check Items (Estimated)     | :S\$ | 1,749.21  |
| Total                       | :S\$ | 7,854.70  |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                              |
|----------------------------|------------------------------|
| Date Of Report             | 13/05/2019 11:42             |
| Date Of Accident           | 12/05/2019 15:00             |
| Exact Location Of Accident | EAST COAST PARK SERVICE ROAD |
| Country/State of Loss      | SINGAPORE                    |

### DETAILS OF OWN VEHICLE

|                             |                    |
|-----------------------------|--------------------|
| Vehicle Registration Number | SHB5424Y           |
| <b>Insured/Policyholder</b> |                    |
| Name Of Registered Owner    | SMRT TAXIS PTE LTD |
| Co Reg No                   | 198905369K         |
| Email Address               | NOEMAIL            |
| Mobile Phone No             |                    |
| Alternative Phone No        | OFFICE-800000000   |

### Vehicle Particulars

|                                                                              |                    |
|------------------------------------------------------------------------------|--------------------|
| Manufacturer                                                                 | TOYOTA             |
| Model                                                                        | PRIUS TAXI-1.8 (A) |
| Exact Purpose for which vehicle was being used at time of accident           | HIRE AND REWARD    |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                 |
| If No, Please state action to be taken                                       | THIRD PARTY        |
| Vehicle Category                                                             | TAXI               |

### Insurance Company

|                           |                                |
|---------------------------|--------------------------------|
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage          | THIRD PARTY FIRE AND/OR THEFT  |
| Fleet Policy              | YES                            |
| Policy Number             | D - 19093197 MFSH              |
| Cover Note Number         |                                |

### Driver

|                      |                           |
|----------------------|---------------------------|
| Name of Driver       | FARALI KHAN BIN BABU KHAN |
| NRIC No              | S0057851G                 |
| Date Of Birth        | 26/07/1953                |
| Occupation           | OUTDOOR                   |
| Date Of Driving Pass | 23/08/1990                |
| Driving Experience   | 28 YEARS AND 8 MONTHS     |
| Gender               | MALE                      |
| Mobile Number        | (LOCAL) +65-800000000     |
| Fax Number           |                           |
| Contact Number       |                           |
| Email Address        | NOEMAIL                   |

|                                                     |                |
|-----------------------------------------------------|----------------|
| Address                                             | 750            |
| Postcode                                            |                |
| Was driver an employee of the Insured's Company     | NO             |
| If No, Relationship of the Driver with the Insured  | OTHER - RELIEF |
| Vehicle Registration Number of Driver's Own Vehicle | -              |
|                                                     | -              |
| Insurance Company of Driver's Own Vehicle           | -              |
|                                                     | -              |
|                                                     | -              |

#### General Information of the Accident

|                    |                            |
|--------------------|----------------------------|
| Type Of Accident   | COLLISION - MAJOR/MINOR RD |
| Weather Conditions | CLEAR                      |
| Road Surface       | DRY                        |

#### Other Information

|                                                                                             |                                     |
|---------------------------------------------------------------------------------------------|-------------------------------------|
| Was any foreign vehicle involved in this accident?                                          | NO                                  |
| Number of vehicles (including own vehicle) involved in the accident                         | 2                                   |
| Was any body injured in the Accident?                                                       | NO                                  |
| Was any injured conveyed to hospital by ambulance?                                          | NO                                  |
| Was any other material or property damaged?                                                 | YES                                 |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                                  |
| Number of Passengers (Including Driver)                                                     | 5                                   |
| Passenger 1                                                                                 | NAME: : UNKNOWN<br>GENDER: : MALE   |
| Passenger 2                                                                                 | NAME: : UNKNOWN<br>GENDER: : FEMALE |
| Passenger 3                                                                                 | NAME: : UNKNOWN<br>GENDER: : MALE   |
| Passenger 4                                                                                 | NAME: : UNKNOWN<br>GENDER: : FEMALE |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG EAST COAST PARK SERVICE ROAD WHEN THE VEHICLE SLJ4911A DID NOT STOP AT THE STOP LINE, DASHED OUT OF THE MINOR ROAD AND HEAD ON COLLIDED ONTO THE FRONT LEFT PORTION OF MY TAXI.

#### Attachment(s)

|                                               |              |
|-----------------------------------------------|--------------|
| Are accident photos available for attachment? | YES          |
| Was there any video captured by Car Camera?   | YES          |
| Remarks/ Reasons:                             | FLIE TOO BIG |
| Was there any audio recorded?                 | NO           |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SLJ4911A |
| Vehicle Make/Model/Colour   |          |

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

KWOK FENGYI

NRIC/Passport Number

S8114567I

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

*[Signature]* 13-05-2019  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]* 13/5/19  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a full page of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper. At the very bottom left corner, there is a small portion of a label that reads "DECLARATION".

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 12-5-2019  
9:05 AM

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 5369K   |

### Vehicle Details

|                               |                      |
|-------------------------------|----------------------|
| Vehicle No.:                  | SHB5424Y             |
| Vehicle to be Exported:       | No                   |
| Intended Deregistration Date: | 15 May 2019          |
| Vehicle Make:                 | TOYOTA               |
| Vehicle Model:                | PRIUS HYBRID 1.8 CVT |
| Primary Colour:               | Maroon               |
| Manufacturing Year:           | 2017                 |
| Engine No.:                   | 2ZRS109448           |
| Chassis No.:                  | JTDKB3FU203575570    |
| Maximum Power Output:         | 90.0 kW (120 bhp)    |
| Open Market Value:            | \$29,007.00          |
| Original Registration Date:   | 30 Nov 2017          |
| First Registration Date:      | 30 Nov 2017          |
| Transfer Count:               | 0                    |
| Actual ARF Paid:              | \$5,000.00           |

### Intended PARF Rebate Details

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 29 Nov 2025 |
| PARF Rebate Amount:           | \$3,750.00  |

### Intended COE Rebate Details

|                             |                                      |
|-----------------------------|--------------------------------------|
| COE Expiry Date:            | 29 Nov 2025                          |
| COE Category:               | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):          | 8                                    |
| PQP Paid:                   | \$33,596.00                          |
| COE Rebate Amount:          | \$27,460.00                          |
| <b>Total Rebate Amount:</b> | <b>\$31,210.00</b>                   |

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 May 2019.

OK



## Case Details

Case Reference Number : TAX/05/19/2052  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB5424Y

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-6860-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Sompo Insurance Singapore Pte. Ltd  
 Accident Date and Time : 12/05/2019 07:00 AM  
 Vehicle Age(In Months) : 18

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| BOM Type        | Costing Type | Portion | Material Number | Part Name                    | Qty | SMRT Recommendation     |                |        |                 | Repair/ Replace | Surveyor Quantity | Surveyor Approval        |                | Remarks |
|-----------------|--------------|---------|-----------------|------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
|                 |              |         |                 |                              |     | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) |                 |                   | Surveyor Final Price(\$) | Repair/Replace |         |
| One Time Key In | Main         |         |                 | COVER, FR BUMPER             | 1   | 495.50                  | 495.50         | 25.00  | 371.63          | Replace         | 1                 | 371.63                   | Replace *      | BUC     |
| One Time Key In | Main         |         |                 | COVER, FR BUMPER LH          | 1   | 28.10                   | 28.10          | 25.00  | 21.08           | Replace         | 1                 | 21.08                    | Replace *      | SCR     |
| One Time Key In | Main         |         |                 | CLIPS PIECE, FRT & RR BUMPER | 10  | 1.50                    | 15.00          | 25.00  | 11.25           | Replace         | 10                | 11.25                    | Replace *      | REC     |
| One Time Key In | Main         |         |                 | GRILLE SUB-ASSY              | 1   | 335.60                  | 335.60         | 25.00  | 251.70          | Replace         | 1                 | 251.70                   | Replace *      | DEF     |
| One Time Key In | Main         |         |                 | GRILLE, RADIATOR             | 1   | 165.00                  | 165.00         | 25.00  | 123.75          | Replace         | 1                 | 123.75                   | Replace *      | DEF     |
| One Time Key In | Main         |         |                 | SUPPORT, FR BUMPER LH        | 1   | 82.30                   | 82.30          | 25.00  | 61.72           | Replace         | 1                 | 61.72                    | Replace *      | CRA     |
| One Time Key In | Main         |         |                 | LAMP ASSY, FOG, LH           | 1   | 910.20                  | 910.20         | 10.00  | 819.18          | Replace         | 1                 | 819.18                   | Replace *      | SCR     |
| One Time Key In | Main         |         |                 | SEAL, HOOD TO FR END         | 1   | 24.40                   | 24.40          | 25.00  | 18.30           | Replace         | 0                 | 0                        | Not Give *     | UN      |
| One Time Key In | Main         |         |                 | ABSORBER, FR BUMPER          | 1   | 70.30                   | 70.30          | 25.00  | 52.72           | Replace         | 0                 | 0                        | Check *        | UN      |
| One Time Key In | Main         |         |                 | REINFORCEMENT FRONT UPPER    | 1   | 691.10                  | 691.10         | 25.00  | 518.33          | Replace         | 0                 | 0                        | Check *        | UN      |

Total Spare Part Cost 13,466.14

Surveyor Total 4,775.50

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 13,466.14

Final Sur Total 4,775.50

| BOM Type              | Costing Type | Portion | Material Number | SMRT Recommendation                  |     |                         |                |           |                 |                          | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|--------------------------------------|-----|-------------------------|----------------|-----------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
|                       |              |         |                 | Part Name                            | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%)    | Final Price(\$) | Repair/Replace           | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | ABSORBER, FR BUMPER LOWER            | 1   | 117.00                  | 117.00         | 25.00     | 87.75           | Replace                  | 0                 | 0                        | Check          | * XAN   |
| One Time Key In       | Main         |         |                 | REINFORCEMENT FRONT LOWER            | 1   | 238.50                  | 238.50         | 25.00     | 178.88          | Replace                  | 0                 | 0                        | Check          | * XAN   |
| One Time Key In       | Main         |         |                 | EXTENSION SUBASSY, LH                | 1   | 116.30                  | 116.30         | 25.00     | 87.22           | Replace                  | 0                 | 0                        | Check          | * XAN   |
| One Time Key In       | Main         |         |                 | EXTENSION SUBASSY, RH                | 1   | 116.30                  | 116.30         | 25.00     | 87.22           | Replace                  | 0                 | 0                        | Not Give       | * m     |
| One Time Key In       | Main         |         |                 | COVER ASSY, ENGINE                   | 1   | 180.10                  | 180.10         | 25.00     | 135.07          | Replace                  | 0                 | 0                        | Check          | * XAN   |
| One Time Key In       | Main         |         |                 | HOOD SUB-ASSY                        | 1   | 938.40                  | 938.40         | 25.00     | 703.80          | Replace                  | 1                 | 0                        | Repair         | *       |
| One Time Key In       | Main         |         |                 | HINGE ASSY, HOOD, LH                 | 1   | 57.00                   | 57.00          | 25.00     | 42.75           | Replace                  | 0                 | 0                        | Not Give       | * m     |
| One Time Key In       | Main         |         |                 | HINGE ASSY, HOOD, RH                 | 1   | 57.00                   | 57.00          | 25.00     | 42.75           | Replace                  | 0                 | 0                        | Not Give       | * m     |
| One Time Key In       | Main         |         |                 | MOULDING LH                          | 1   | 83.30                   | 83.30          | 25.00     | 62.47           | Replace                  | 0                 | 0                        | Check          | * XAN   |
| One Time Key In       | Main         |         |                 | PILLAR, FRONT BODY, LH               | 1   | 339.40                  | 339.40         | 25.00     | 254.55          | Replace                  | 1                 | 0                        | Repair         | *       |
| One Time Key In       | Main         |         |                 | COVER SUB-ASSY, FRONT PILLAR, UPR LH | 1   | 96.90                   | 96.90          | 25.00     | 72.68           | Replace                  | 1                 | 72.68                    | Replace        | * MIS   |
| One Time Key In       | Main         |         |                 | COVER, RADIATOR                      | 1   | 227.80                  | 227.80         | 25.00     | 170.85          | Replace                  | 0                 | 0                        | Not Give       | * m     |
| One Time Key In       | Main         |         |                 | SUPPORT S/A UPPER                    | 1   | 364.90                  | 364.90         | 25.00     | 273.67          | Replace                  | 0                 | 0                        | Not Give       | * m     |
| One Time Key In       | Main         |         |                 | SUPPORT SUB-ASSY LOWER               | 1   | 397.40                  | 397.40         | 25.00     | 298.05          | Replace                  | 0                 | 0                        | Not Give       | * m     |
| One Time Key In       | Main         |         |                 | SUPPORT S/A LH                       | 1   | 237.00                  | 237.00         | 25.00     | 177.75          | Replace                  | 0                 | 0                        | Not Give       | * m     |
| One Time Key In       | Main         |         |                 | SUPPORT, RADIATOR UPPER LH           | 1   | 76.70                   | 76.70          | 25.00     | 57.53           | Replace                  | 0                 | 0                        | Not Give       | * m     |
| Total Spare Part Cost |              |         |                 |                                      |     |                         |                | 13,466.14 |                 | Surveyor Total 4,775.50  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                                      |     |                         |                | 0.00      |                 | Lump Sum Dis (%) 0       |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                                      |     |                         |                | 13,466.14 |                 | Final Sur Total 4,775.50 |                   |                          |                |         |

| BOM Type        | Costing Type | Portion | Material Number | SMRT Recommendation                  |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |   | Remarks |
|-----------------|--------------|---------|-----------------|--------------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---|---------|
|                 |              |         |                 | Part Name                            | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |   |         |
| One Time Key In | Main         |         |                 | UNIT, HEADLAMP , LH                  | 1   | 2,558.90                | 2,558.90       | 10.00  | 2,303.01        | Replace         | 1                 | 2,303.01                 | Replace        | * | CRA     |
| One Time Key In | Main         |         |                 | COOLANT                              | 1   | 12.30                   | 12.30          | 0.00   | 12.30           | Replace         | 0                 | 0                        | Not Give       | * | nn      |
| One Time Key In | Main         |         |                 | COMPUTER SUB-ASSY, HEADLAMP, LH NO.1 | 1   | 486.40                  | 486.40         | 10.00  | 437.76          | Replace         | 0                 | 0                        | Check          | * | km      |
| One Time Key In | Main         |         |                 | BATTERY                              | 1   | 1,584.90                | 1,584.90       | 10.00  | 1,426.41        | Replace         | 0                 | 0                        | Not Give       | * | nn      |
| One Time Key In | Main         |         |                 | CLAMP SUB-ASSY, BATTERY              | 1   | 41.40                   | 41.40          | 25.00  | 31.05           | Replace         | 0                 | 0                        | Not Give       | * | nn      |
| One Time Key In | Main         |         |                 | CLAMP, BATTERY, NO.2                 | 1   | 43.30                   | 43.30          | 25.00  | 32.47           | Replace         | 0                 | 0                        | Not Give       | * | nn      |
| One Time Key In | Main         |         |                 | FENDER SUB-ASSY, FR , LH             | 1   | 933.10                  | 933.10         | 25.00  | 699.83          | Replace         | 1                 | 699.83                   | Replace        | * | BUC     |
| One Time Key In | Main         |         |                 | EMBLEM, SIDE PANEL ( HYBRID)         | 1   | 52.90                   | 52.90          | 25.00  | 39.67           | Replace         | 1                 | 39.67                    | Replace        | * | hec     |
| One Time Key In | Main         |         |                 | LINER, FR FENDER, LH                 | 1   | 194.30                  | 194.30         | 25.00  | 145.73          | Replace         | 0                 | 0                        | Check          | * | nn      |
| One Time Key In | Main         |         |                 | PAD, FR WHEEL LH                     | 1   | 57.70                   | 57.70          | 25.00  | 43.28           | Replace         | 0                 | 0                        | Check          | * | nn      |
| One Time Key In | Main         |         |                 | APRON SUB-ASSY, FRONT FENDER , LH    | 1   | 944.20                  | 944.20         | 25.00  | 708.15          | Replace         | 0                 | 0                        | Not Give       | * | nn      |
| One Time Key In | Main         |         |                 | TYRE                                 | 1   | 126.74                  | 126.74         | 0.00   | 126.74          | Replace         | 0                 | 0                        | Not Give       | * | nn      |
| One Time Key In | Main         |         |                 | WHEEL, DISC FRONT                    | 1   | 1,555.10                | 1,555.10       | 25.00  | 1,166.32        | Replace         | 0                 | 0                        | Not Give       | * | nn      |
| One Time Key In | Main         |         |                 | PROTECTOR, FR FENDER LH              | 1   | 90.40                   | 90.40          | 25.00  | 67.80           | Replace         | 0                 | 0                        | Not Give       | * | nn      |
| One Time Key In | Main         |         |                 | PANEL SUB-ASSY, FRONT DOOR LH        | 1   | 1,249.80                | 1,249.80       | 25.00  | 937.20          | Replace         | 0                 | 0                        | Not Give       | * | nn      |
| One Time Key In | Main         |         |                 | STICKER DECAL SMRT (DOOR)            | 1   | 60.00                   | 60.00          | 0.00   | 60.00           | Replace         | 0                 | 0                        | Not Give       | * | nn      |

Total Spare Part Cost 13,466.14

Surveyor Total 4,775.50

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 13,466.14

Final Sur Total 4,775.50

| SMRT Recommendation |              |         |                 |                                  |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|----------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                        | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | HINGE ASSY, FRONT DOOR, UPPER LH | 1   | 82.10                   | 82.10          | 25.00  | 61.57           | Replace         | 0                 | 0                        | Not Give       | hu      |
| One Time Key In     | Main         |         |                 | HINGE ASSY, FRONT DOOR, LOWER LH | 1   | 92.10                   | 92.10          | 25.00  | 69.07           | Replace         | 0                 | 0                        | Not Give       | hu      |
| One Time Key In     | Main         |         |                 | CHECK ASSY, FRONT DOOR           | 1   | 153.50                  | 153.50         | 25.00  | 115.13          | Replace         | 0                 | 0                        | Not Give       | hu      |

Total Spare Part Cost 13,466.14

Surveyor Total 4,775.50

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 13,466.14

Final Sur Total 4,775.50

Labour's Cost Detail

| S.No.  | Costing Type | Job Scope                  | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|----------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR FRONT LH PORTION | 1,014.00                | 600 ✓                   |         |
| Total: |              |                            | 1,014.00                | 600.00                  |         |

Spray Cost Detail

| S.No.  | Costing Type | Job Scope                         | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-----------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPSRAY FRONT BUMPER           | 378.00                  | 200 ✓                   |         |
| 2      | Main         | TO REPSRAY FRONT HOOD             | 378.00                  | 200 ✓                   |         |
| 3      | Main         | TO RESPRAY FRONT SUPPORT PANEL    | 180.00                  | 0                       |         |
| 4      | Main         | TO RESPRAY RADIATOR SUPPORT LOWER | 180.00                  | 0                       |         |
| 5      | Main         | TO RESPRAY FRONT FENDER LH        | 378.00                  | 200 ✓                   |         |
| 6      | Main         | TO RESPRAY APRON PANEL LH         | 180.00                  | 0                       |         |
| 7      | Main         | TO RESPRAY FRONT PILLAR LH        | 180.00                  | 80 ✓                    |         |
| 8      | Main         | TO RESPRAY RIM                    | 180.00                  | 0                       |         |
| 9      | Main         | TO RESPRAY FRONT DOOR LH          | 378.00                  | 0                       |         |
| Total: |              |                                   | 2,412.00                | 680.00                  |         |

Other Cost Detail

| S.No. | Costing Type | Job Scope | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|-------|--------------|-----------|-------------------------|-------------------------|---------|
|-------|--------------|-----------|-------------------------|-------------------------|---------|

| S.No.         | Costing Type | Job Scope                                                                       | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks   |
|---------------|--------------|---------------------------------------------------------------------------------|-------------------------|-------------------------|-----------|
| 1             | Main         | TOWING CHARGE                                                                   | 56.00                   | 0                       | 40 ✓      |
| 2             | Main         | TO CHECK WIRING AND SYSTEM FUNCTION                                             | 80.00                   | 20                      | ✓         |
| 3             | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA                                         | 100.00                  | 30                      | ✓         |
| 4             | Main         | TO DO WHEEL ALIGNMENT / TYRE BALANCING                                          | 120.00                  | 0                       |           |
| 5             | Main         | TO TOP UP A/C GAS                                                               | 120.00                  | 0                       |           |
| 6             | Main         | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)                                 | 120.00                  | 0                       |           |
| 7             | Main         | TO REMOVE AND REFIT WIRE HARDESS                                                | 200.00                  | 0                       |           |
| 8             | Main         | TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER | 120.00                  | 0                       |           |
| 9             | Main         | TO REPLACE SUNDRY PARTS                                                         | 100.00                  | 0                       |           |
| 10            | Main         | TO WASH AND VACUUM                                                              | 60.00                   | 0                       |           |
| <b>Total:</b> |              |                                                                                 | <b>1,076.00</b>         | <b>50.00</b>            | <b>90</b> |

## Summary

|                          | Estimator Assessment(\$) | Surveyor Assessment(\$)         |
|--------------------------|--------------------------|---------------------------------|
| Total Spare Part Detail  | 13,466.14                | 4,775.50                        |
| Total Labour Cost        | 1,014.00                 | 600.00                          |
| Total Spray Painting     | 2,412.00                 | 680.00                          |
| Other                    | 1,076.00                 | 50.00                           |
| Overall Total            | 17,968.14                | 6,105.50                        |
| Lump Sum Repair Option   |                          |                                 |
| Lump Sum Total           | 0.00                     | 6,105.50                        |
| Surveyor Approved Amount |                          | 6,105.50                        |
| No of Repair Days*       | 7                        | 5                               |
| Remarks                  |                          | p/p repair, photo before paint. |
| Surveyor Name            |                          | Hwee Jie                        |



Signature

Estimator Assessment(\$)

Surveyor Assessment(\$)



  
15/5/19

Save Clear

Survey Date

14/05/2019

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

**Section A - Accident Details**

|                                    |                           |
|------------------------------------|---------------------------|
| Registration Number                | SHB5424Y                  |
| Case Reference Number              | TAX/05/19/2052            |
| Registration Date                  | 30/11/2017                |
| Company Type                       | SMRT Taxis Pte Ltd        |
| Make                               | TOYOTA                    |
| Model                              | PRIUS4                    |
| Name of Driver                     | FARALI KHAN BIN BABU KHAN |
| Type of Accident                   | Head On                   |
| Accident Date and Time             | 12/5/2019 3:00 PM         |
| Accident Reported Date and Time    | 13/5/2019 9:15 AM         |
| Is Surveyor Required?              | Yes                       |
| Survey by                          |                           |
| Vehicle is Towed Back?             | Yes                       |
| Towed Back Date and Time           | 12/5/2019 3:29 PM         |
| Replacement Vehicle issued?        | No                        |
| Job Card Number                    | 24101472                  |
| Special Instruction to ARC, if any | TOWED \$40                |
| Prepared Date and Time             | 13/5/2019 4:25 PM         |
| Chassis Number                     |                           |
| Mileage                            |                           |
| Work Shop                          |                           |
| Repair Completion Date and Time    |                           |



1/2/2019

**Section B - Summary of Repair Estimates**
**Summary of Repair Estimates**

|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Total Labour Cost            | \$1,014.00                                                                          | \$500.00                                                                            |
| Total Spray Cost             | \$2,412.00                                                                          | \$580.00                                                                            |
| Total Spare Part Cost        | \$15,387.84                                                                         | \$6,897.22                                                                          |
| Total Other Cost             | \$1,075.00                                                                          | \$90.00                                                                             |
| <b>TOTAL COST</b>            | <b>\$19,889.84</b>                                                                  | <b>\$8,067.22 (P/P)</b>                                                             |
| Lump Sum Total               | \$0.00                                                                              | \$0.00                                                                              |
| Number of Repair Days        | 7.0                                                                                 | 5.0                                                                                 |
| Prepared / Adjusted By       | B. Thiyal Nayagi                                                                    | Hwee Jie (LKK) / Somp                                                               |
| ARC / Surveyor Sign Off Date | 14/05/2019 8:59 AM                                                                  | 14/05/2019 11:56 AM                                                                 |
| Signature                    |  |  |
| Remarks                      |                                                                                     | p/p repair, photo before paint.                                                     |

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1907-0260 | Invoice Number |  |
| Quotation Date   | 16.07.2019   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates:

## Part 1 - Labour Works

| Job Scope                  | Quotation from AR | Adjusted by Surveyor, if applicable |
|----------------------------|-------------------|-------------------------------------|
| TO REPAIR FRONT LH PORTION | \$1,014.00        | \$600.00 /                          |
| Total Labour               | \$1,014.00        | \$600.00                            |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY FRONT BUMPER              | \$378.00           | \$200.00 /                          |
| TO REPSRAY FRONT HOOD                | \$378.00           | \$200.00 /                          |
| TO RESPRAY FRONT SUPPORT PANEL       | \$180.00           | \$0.00                              |
| TO RESPRAY RADIATOR SUPPORT LOWER    | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT FENDER LH           | \$378.00           | \$200.00 /                          |
| TO RESPRAY APRON PANEL LH            | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT PILLAR LH           | \$180.00           | \$80.00 /                           |
| TO RESPRAY RIM                       | \$180.00           | \$0.00                              |
| TO RESPRAY FRONT DOOR LH             | \$378.00           | \$0.00                              |
| Total Spray Painting & Panel Beating | \$2,412.00         | \$680.00                            |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                                                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------------------------------------------------------------|--------------------|-------------------------------------|
| TOWING CHARGE                                                                   | \$56.00            | \$40.00 /                           |
| TO CHECK WIRING AND SYSTEM FUNCTION                                             | \$80.00            | \$20.00 /                           |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                                         | \$100.00           | \$30.00 /                           |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING                                          | \$120.00           | \$0.00                              |
| TO TOP UP A/C GAS                                                               | \$120.00           | \$0.00                              |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)                                 | \$120.00           | \$0.00                              |
| TO REMOVE AND REFIT WIRE HARDESS                                                | \$200.00           | \$0.00                              |
| TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER | \$120.00           | \$0.00                              |
| TO REPLACE SUNDRY PARTS                                                         | \$100.00           | \$0.00                              |
| TO WASH AND VACUUM                                                              | \$60.00            | \$0.00                              |
| Total Other Costs                                                               | \$1,075.00         | \$90.00                             |

## Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name                    | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 52119479 62  | COVER, FR BUMPER             | 1.00     | \$485.50        | 25.00        | \$371.63         | Replace            | Replace           |
|             |         | 52128479 06  | COVER, FR BUMPER LH          | 1.00     | \$28.10         | 25.00        | \$21.08          | Replace            | Replace           |
|             |         | 52161160 10  | CLIPS PIECE, FRT & RR BUMPER | 10.00    | \$1.50          | 25.00        | \$11.25          | Replace            | Replace           |

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
 50 Woodlands Industrial Park EA, Singapore 731709  
 FAX Number: 63660360  
 Estimate Telephone Number: 68602522  
 Accident Reporting Number: 68603672

Date Generated: 16/01/2016

User ID: PooBuan

|                 |                                         |      |            |        |            |         |           |   |
|-----------------|-----------------------------------------|------|------------|--------|------------|---------|-----------|---|
| 53101470<br>80  | GRILLE SUB-ASSY                         | 1.00 | \$335.60   | 25.00  | \$251.70   | Replace | Replace   | ✓ |
| 53112472<br>40  | GRILLE, RADIATOR                        | 1.00 | \$165.00   | 25.00  | \$123.75   | Replace | Replace   | ✓ |
| 52116470<br>50  | SUPPORT, FR BUMPER LH                   | 1.00 | \$62.30    | 25.00  | \$61.73    | Replace | Replace   | ✓ |
| 81220470<br>20  | LAMP ASSY, FOG, LH                      | 1.00 | \$910.20   | 10.00  | \$819.18   | Replace | Replace   | ✓ |
| 53395470<br>40  | SEAL, HOOD TO FR END                    | 0.00 | \$24.40    | 0.00   | \$0.00     | Replace | Not Given | X |
| 52611471<br>40  | ABSORBER, FR BUMPER                     | 0.00 | \$70.30    | 0.00   | \$0.00     | Replace | Check     | X |
| 52021471<br>10  | REINFORCEMENT FRONT<br>UPPER            | 0.00 | \$691.10   | 0.00   | \$0.00     | Replace | Check     | X |
| 52618470<br>90  | ABSORBER, FR BUMPER<br>LOWER            | 0.00 | \$117.00   | 0.00   | \$0.00     | Replace | Check     | X |
| 52132470<br>10  | REINFORCEMENT FRONT<br>LOWER            | 0.00 | \$238.50   | 0.00   | \$0.00     | Replace | Check     | X |
| 52103470<br>10  | EXTENSION SUBASSY, LH                   | 0.00 | \$116.30   | 0.00   | \$0.00     | Replace | Check     | X |
| 52102470<br>20  | EXTENSION SUBASSY, RH                   | 0.00 | \$116.30   | 0.00   | \$0.00     | Replace | Not Given | X |
| 51420470<br>30  | COVER ASSY, ENGINE                      | 0.00 | \$180.10   | 0.00   | \$0.00     | Replace | Check     | X |
| 53301471<br>10  | HOOD SUB-ASSY                           | 1.00 | \$938.40   | 100.00 | \$0.00     | Replace | Repair    | ✓ |
| 53420471<br>30  | HINGE ASSY, HOOD, LH                    | 0.00 | \$57.00    | 0.00   | \$0.00     | Replace | Not Given | X |
| 53410471<br>30  | HINGE ASSY, HOOD, RH                    | 0.00 | \$57.00    | 0.00   | \$0.00     | Replace | Not Given | X |
| 75536470<br>20  | MOULDING LH                             | 0.00 | \$83.30    | 0.00   | \$0.00     | Replace | Check     | X |
| 61014470<br>10  | PILLAR, FRONT BODY, LH                  | 1.00 | \$339.40   | 100.00 | \$0.00     | Replace | Repair    | ✓ |
| 60118470<br>20  | COVER SUB-ASSY, FRONT<br>PILLAR, UPR LH | 1.00 | \$98.90    | 25.00  | \$72.68    | Replace | Replace   | ✓ |
| 53289470<br>72  | COVER, RADIATOR                         | 0.00 | \$227.80   | 0.00   | \$0.00     | Replace | Not Given | X |
| 53205479<br>00  | SUPPORT S/A UPPER                       | 0.00 | \$364.90   | 0.00   | \$0.00     | Replace | Not Given | X |
| 53028470<br>10  | SUPPORT SUB-ASSY<br>LOWER               | 0.00 | \$397.40   | 0.00   | \$0.00     | Replace | Not Given | X |
| 53203479<br>01  | SUPPORT S/A LH                          | 0.00 | \$237.00   | 0.00   | \$0.00     | Replace | Not Given | X |
| 53214470<br>50  | SUPPORT, RADIATOR<br>UPPER LH           | 0.00 | \$76.70    | 0.00   | \$0.00     | Replace | Not Given | X |
| 81155476<br>91  | UNIT, HEADLAMP, LH                      | 1.00 | \$2,558.90 | 10.00  | \$2,303.01 | Replace | Replace   | ✓ |
|                 | COOLANT                                 | 0.00 | \$12.30    | 0.00   | \$0.00     | Replace | Not Given | X |
| 81056476<br>90  | COMPUTER SUB-ASSY,<br>HEADLAMP, LH NO.1 | 0.00 | \$486.40   | 0.00   | \$0.00     | Replace | Check     | X |
| 28800371<br>30  | BATTERY                                 | 0.00 | \$1,584.90 | 0.00   | \$0.00     | Replace | Not Given | X |
| 74404470<br>30  | CLAMP SUB-ASSY,<br>BATTERY              | 0.00 | \$41.40    | 0.00   | \$0.00     | Replace | Not Given | X |
| 74482470<br>10  | CLAMP, BATTERY, NO.2                    | 0.00 | \$43.30    | 0.00   | \$0.00     | Replace | Not Given | X |
| 53802471<br>00  | FENDER SUB-ASSY, FR<br>LH               | 1.00 | \$933.10   | 25.00  | \$699.83   | Replace | Replace   | ✓ |
| 75374471<br>40  | EMBLEM, SIDE PANEL (HYBRID)             | 1.00 | \$52.90    | 25.00  | \$39.68    | Replace | Replace   | ✓ |
| 53876471<br>10  | LINER, FR FENDER, LH                    | 0.00 | \$194.30   | 0.00   | \$0.00     | Replace | Check     | X |
| 53852470<br>41  | PAD, FR WHEEL LH                        | 0.00 | \$57.70    | 0.00   | \$0.00     | Replace | Check     | X |
| 53702471<br>01  | APRON SUB-ASSY, FRONT<br>FENDER, LH     | 0.00 | \$944.20   | 0.00   | \$0.00     | Replace | Not Given | X |
|                 | TYRE                                    | 0.00 | \$126.74   | 0.00   | \$0.00     | Replace | Not Given | X |
| 42611-<br>47450 | WHEEL, DISC FRONT                       | 0.00 | \$1,555.10 | 0.00   | \$0.00     | Replace | Not Given | X |
| 53828470<br>70  | PROTECTOR, FR FENDER<br>LH              | 0.00 | \$90.40    | 0.00   | \$0.00     | Replace | Not Given | X |
| 67002471<br>62  | PANEL SUB-ASSY, FRONT<br>DOOR LH        | 0.00 | \$1,249.60 | 0.00   | \$0.00     | Replace | Not Given | X |
|                 | STICKER DECAL SMRT<br>(DOOR)            | 0.00 | \$60.00    | 0.00   | \$0.00     | Replace | Not Given | X |
| 68720121<br>51  | HINGE ASSY, FRONT<br>DOOR, UPPER LH     | 0.00 | \$82.10    | 0.00   | \$0.00     | Replace | Not Given | X |
| 68740121<br>20  | HINGE ASSY, FRONT<br>DOOR, LOWER LH     | 0.00 | \$92.10    | 0.00   | \$0.00     | Replace | Not Given | X |

|       |                |                           |      |             |      |            |         |             |
|-------|----------------|---------------------------|------|-------------|------|------------|---------|-------------|
|       | 68810470<br>40 | CHECK ASSY, FRONT<br>DOOR | 0.00 | \$153.50    | 0.00 | \$0.00     | Replace | Not Given X |
| Total |                |                           |      | \$16,766.94 |      | \$4,775.52 |         |             |

## Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number   | Part Name                               | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|----------------|-----------------------------------------|----------|---------------|--------------|------------------|-----------|----------------|
|             |         | 28500371<br>30 | BATTERY                                 | 1.00     | \$1,584.90    | 10.00        | \$1,426.41       | Replace   | Replace ✓      |
|             |         | 81056478<br>90 | COMPUTER SUB-ASSY,<br>HEADLAMP, LH NO.1 | 1.00     | \$486.40      | 10.00        | \$437.76         | Replace   | Replace ✓      |
|             |         | 53214470<br>50 | SUPPORT, RADIATOR<br>UPPER LH           | 1.00     | \$76.70       | 25.00        | \$57.53          | Replace   | Replace ✓      |
| Total       |         |                |                                         |          | 2,148.00      |              | 1,921.70         |           |                |

SPP  
JEP  
JEP  
JEP

6697.22  
+ 600.00  
+ 770.00

8067.22

23430.44

# REQUEST FOR SUPPLYMENT PARTS

|                      |                          |                                   |         |
|----------------------|--------------------------|-----------------------------------|---------|
| Contractor:          | WEGA ENGINEERING PTE LTD |                                   |         |
| Accident Case Number | 7A4/05/19/2052           | Date of Collection                | 15/5/19 |
| Vehicle No           | SHB 5424 Y               | Date of Request                   | 16/5/19 |
| Vehicle Model        | TOYOTA PRIUS 4           | Number of Days to Extend (If any) |         |

| S/N | Part Number   | Part Description                    | Quantity | Unit Price |
|-----|---------------|-------------------------------------|----------|------------|
|     | 0635,36,37    | Support Radiator Upper L&R          |          | #76.70 ✓   |
|     | 0628,29,30    | Computer Sub Assy Head Lamp LH No 1 |          | #486.40 ✓  |
|     | 0631,32,33,34 | Battery                             |          | #1584.90 ✓ |
|     |               |                                     |          |            |
|     |               |                                     |          |            |
|     |               |                                     |          |            |
|     |               |                                     |          |            |
|     |               |                                     |          |            |
|     |               |                                     |          |            |
|     |               |                                     |          |            |

BT  
CRA  
DEF

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position) \_\_\_\_\_

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

|                 |                                                |                                          |
|-----------------|------------------------------------------------|------------------------------------------|
| Acknowledge By  | ARC Executive / Supervisor / SA                |                                          |
| Approval By     | Surveyor / In-house Staff                      |                                          |
| Parts Ordering  | SMRT Store / Contractor Supply / Form 22 / WOC | Form22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO                                       | Date of submission                       |

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |                                                      |                                                      |                                                |            |                                                                 |
|--------------------------|-------------|---------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified    | Est Submitted | Adj Assigned                                         | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
| Main                     | 12 May 2019 |               | 14 May 2019<br>09:11<br><a href="#">Edit Adj Rpt</a> | <b>\$48,067.22</b><br><a href="#">Edit Estimates</a> | <b>\$48,067.22</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                          | Reference                                                                                                       | Claim Details          | Documents                                                                    | Show All |         |             |              |            |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>                                                                                        |                                                                                                                 |                        |                                                                              |          |         |             |              |            |       |
| Insured:                                                                                                                                                                      | LOW WAI MUN (LIU WEIWEN), ID: S8029818H                                                                         |                        |                                                                              |          |         |             |              |            |       |
| Main Claimant:                                                                                                                                                                | SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K                                                                    |                        |                                                                              |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                                                             | SHB5424Y                                                                                                        | Date of Loss:          | 12/05/2019 15:00 - :59<br>[17 Months and 12 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                                                                                   | TP / CMTD1902298                                                                                                | Policy/Cover Note No.: | D18MTPV01017683 (Comprehensive)                                              |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                                                   | SLJ4911A                                                                                                        | Policy No. (Claimant): |                                                                              |          |         |             |              |            |       |
|                                                                                                                                                                               |                                                                                                                 | Excess:                |                                                                              |          |         |             |              |            |       |
| Repairer:                                                                                                                                                                     | SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628  |                        |                                                                              |          |         |             |              |            |       |
| Handling Insurer:                                                                                                                                                             | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]          |                        |                                                                              |          |         |             |              |            |       |
| Adjuster:                                                                                                                                                                     | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 24/05/2019] |                        |                                                                              |          |         |             |              |            |       |
| Driver/Custodian (Insured):                                                                                                                                                   | KWOK FENG YI (), NRIC: S8114567I, Tel: +6596910758 Email:                                                       |                        |                                                                              |          |         |             |              |            |       |
| Adj Asg. Remarks:                                                                                                                                                             | WS: SHANT1 68662671/2                                                                                           |                        |                                                                              |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                 |                                                                                                                 |                        |                                                                              |          |         |             |              |            |       |
| There are no mail for this case.                                                                                                                                              |                                                                                                                 |                        |                                                                              |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |                                                                                                                 |                        |                                                                              |          |         |             |              |            |       |
| Due Date                                                                                                                                                                      | Priority                                                                                                        | Type                   | Task Group                                                                   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                   |                                                                                                                 |                        |                                                                              |          |         |             |              |            |       |

## Claim Documents

\*SHB5424Y (CMTD1902298)  
 [SLJ4911A]  
 TP  
 SMRT TAXIS PTE LTD  
 May 12 2019 3:00PM  
 [LOW WAI MUN (LIU WEIWEN)]  
 SMRT Automotive Services Pte Ltd

| <a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a> |                 |                                                                                               | <b>View</b> <a href="#">View in Browser</a> |                                     |
|-------------------------------------------------------------------------------------------------------|-----------------|-----------------------------------------------------------------------------------------------|---------------------------------------------|-------------------------------------|
| <b>Assessment Reports</b>                                                                             |                 |                                                                                               | 1 per page                                  | <input checked="" type="checkbox"/> |
| No                                                                                                    | Finalized On    | Sompo Insurance Singapore Pte. Ltd. (HQ)                                                      | Thumbnail                                   | Print                               |
| 1                                                                                                     | 14/05/19 09:11  | <b>Accident Statement</b><br>From: OD - Reg. No: SLJ4911A, Claimant: LOW WAI MUN (LIU WEIWEN) | Load HTM                                    |                                     |
| No                                                                                                    | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                                                             | Thumbnail                                   | Print                               |
| 1                                                                                                     | 15/05/19 17:39  | <b>Adjuster Immediate Advice</b>                                                              | Load HTM                                    |                                     |
| <b>Photos/Images</b>                                                                                  |                 |                                                                                               | 3 per page                                  | <input checked="" type="checkbox"/> |
| No                                                                                                    | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                                             | Thumbnail                                   | Print                               |
| 1                                                                                                     | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 2                                                                                                     | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 3                                                                                                     | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 4                                                                                                     | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 5                                                                                                     | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 6                                                                                                     | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 7                                                                                                     | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 8                                                                                                     | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 9                                                                                                     | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 10                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 11                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 12                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 13                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 14                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 15                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 16                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 17                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 18                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 19                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 20                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 21                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 22                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 23                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 24                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 25                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 26                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 27                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 28                                                                                                    | 24/05/19 09:26  | <b>General View</b>                                                                           | Load JPG                                    | <input checked="" type="checkbox"/> |
| 29                                                                                                    | 24/05/19 09:26  | <b>Dismantled Parts</b>                                                                       | Load JPG                                    | <input checked="" type="checkbox"/> |
| 30                                                                                                    | 24/05/19 09:26  | <b>Dismantled Parts</b>                                                                       | Load JPG                                    | <input checked="" type="checkbox"/> |
| 31                                                                                                    | 24/05/19 09:26  | <b>Dismantled Parts</b>                                                                       | Load JPG                                    | <input checked="" type="checkbox"/> |
| 32                                                                                                    | 24/05/19 09:26  | <b>Dismantled Parts</b>                                                                       | Load JPG                                    | <input checked="" type="checkbox"/> |



| Assessment Reports |                 |                                          | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|------------------------------------------|------------|-------------------------------------|
| No                 | Finalized On    | Sompo Insurance Singapore Pte. Ltd. (HQ) | Thumbnail  | Print                               |
|                    |                 |                                          |            | <input checked="" type="checkbox"/> |
| 33                 | 24/05/19 09:26  | Dismantled Parts                         | Load JPG   | <input checked="" type="checkbox"/> |
| 34                 | 24/05/19 09:26  | Dismantled Parts                         | Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 24/05/19 09:26  | Dismantled Parts                         | Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 24/05/19 09:26  | Dismantled Parts                         | Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 24/05/19 09:26  | Dismantled Parts                         | Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 19/07/19 09:44  | Reinspection Photo                       | Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 19/07/19 09:44  | Reinspection Photo                       | Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 19/07/19 09:44  | Reinspection Photo                       | Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 19/07/19 09:44  | Reinspection Photo                       | Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 19/07/19 09:44  | Reinspection Photo                       | Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 19/07/19 09:44  | Reinspection Photo                       | Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 19/07/19 09:44  | Reinspection Photo                       | Load JPG   | <input checked="" type="checkbox"/> |
| Documentation      |                 |                                          | 1 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | Sompo Insurance Singapore Pte. Ltd. (HQ) | Thumbnail  | Print                               |
| 1                  | 14/05/19 09:01  | TP - SAS                                 | Load PDF   |                                     |
| 2                  | 14/05/19 09:10  | TP - ACK+ASSIGN LKK                      | Load PDF   |                                     |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)        | Thumbnail  | Print                               |
| 1                  | 22/07/19 12:18  | Supplementary                            | Load PDF   |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                |  | Reset | Save | Print |
|----------------------------------------------------------------------------------------------------------------------------------------------------|--|-------|------|-------|
| There are no document checklists configured.                                                                                                       |  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |  |       |      |       |

# LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19008505/JQD3E2

Date: 22/07/2019

### REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01017683

Claimant Vehicle No: SHB5424Y

Insured Vehicle No: SLJ4911A

Date of Loss: 12/05/2019

Nature of Claim: TP

Claim No: CMTD1902298

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB5424Y

Make &amp; Model: TOYOTA PRIUS TAXI, 1.8 (A)

Reg. Date: 30/11/2017 (Man. Year: 2017)

Colour: Maroon

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 2ZRS109448

Chassis No: JTDKB3FU203575570

Odometer: 0 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Tyre Size:

195/65 R15

Rear Left Side:

West Lake 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|--------------------------|------------------|-----------------|------------------|--------------|
| Parts                    | 18,928.44        | 6,697.22        | 12,231.22        | 64.62        |
| Miscellaneous Items      | 0.00             | 0.00            | 0.00             |              |
| Labour                   | 4,502.00         | 1,370.00        | 3,132.00         | 69.57        |
| Paintwork Labour         | 0.00             | 0.00            | 0.00             |              |
| Towing                   | 0.00             | 0.00            | 0.00             |              |
| <b>Nett Amount (S\$)</b> | <b>23,430.44</b> | <b>8,067.22</b> | <b>15,363.22</b> | <b>65.57</b> |

### INSPECTION

Date of Assignment: 14/05/2019

Date Inspected: 14/05/2019 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

|                                                              |                                                                                                                                                                              |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 22 Jul 2019)                                                                                                                                |
| <b>Parts:</b> 144                                            | TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)                                                                                                                  |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> (Unsubmitted, no print-code for SHB5424Y) |                                                                                                                                                                              |
| <b>Validity:</b>                                             | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>                                         | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

## Recommended Parts

| No. | Qty | Part No. | Particulars                                         | Condition     | Repairer's | Amount      |
|-----|-----|----------|-----------------------------------------------------|---------------|------------|-------------|
| 1   | 1   |          | *COVER, FR BUMPER (DISC 25%)                        | Buckled       | 495.50 F   | *371.63 F   |
| 2   | 1   |          | *COVER, FR BUMPER LH (DISC 25%)                     | Scratched     | 28.10 F    | *21.08 F    |
| 3   | 1   |          | *CLIPS PIECE, FRT & RR BUMPER (DISC 25%)<br>(10PCS) | Necessary     | 15.00 F    | *11.25 F    |
| 4   | 1   |          | *GRILLE SUB-ASSY (DISC 25%)                         | Deformed      | 335.60 F   | *251.70 F   |
| 5   | 1   |          | *GRILLE, RADIATOR (DISC 25%)                        | Deformed      | 165.00 F   | *123.75 F   |
| 6   | 1   |          | *SUPPORT, FR BUMPER LH (DISC 25%)                   | Cracked       | 82.30 F    | *61.73 F    |
| 7   | 1   |          | *COVER SUB-ASSY, FRONT PILLAR, UPR LH (DISC 25%)    | Missing       | 96.90 F    | *72.68 F    |
| 8   | 1   |          | *FENDER SUB-ASSY, FR, LH (DISC 25%)                 | Buckled       | 933.10 F   | *699.83 F   |
| 9   | 1   |          | *EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)             | Necessary     | 52.90 F    | *39.68 F    |
| 10  | 1   |          | *LAMP ASSY, FOG, LH (DISC 10%)                      | Scratched     | 910.20 F   | *819.18 F   |
| 11  | 1   |          | *UNIT, HEADLAMP, LH (DISC 10%)                      | Cracked       | 2,558.90 F | *2,303.01 F |
| 12  | 1   |          | *BATTERY (DISC 10%)                                 | Deformed      | 1,584.90 F | *1,426.41 F |
| 13  | 1   |          | *COMPUTER SUB-ASSY, HEADLAMP, LH NO.1 (DISC 10%)    | Cracked       | 486.40 F   | *437.76 F   |
| 14  | 1   |          | *SUPPORT, RADIATOR UPPER LH (DISC 25%)              | Bent          | 76.70 F    | *57.53 F    |
| 15  | 1   |          | *SEAL, HOOD TO FR END                               | Not Necessary | 24.40 F    | *- F        |
| 16  | 1   |          | *ABSORBER, FR BUMPER                                | Not Necessary | 70.30 F    | *- F        |
| 17  | 1   |          | *REINFORCEMENT FRONT UPPER                          | Not Necessary | 691.10 F   | *- F        |
| 18  | 1   |          | *ABSORBER, FR BUMPER LOWER                          | Not Necessary | 117.00 F   | *- F        |
| 19  | 1   |          | *REINFORCEMENT FRONT LOWER                          | Not Necessary | 238.50 F   | *- F        |
| 20  | 1   |          | *EXTENSION SUBASSY, LH                              | Not Necessary | 116.30 F   | *- F        |
| 21  | 1   |          | *EXTENSION SUBASSY, RH                              | Not Necessary | 116.30 F   | *- F        |
| 22  | 1   |          | *COVER ASSY, ENGINE                                 | Not Necessary | 180.10 F   | *- F        |
| 23  | 1   |          | *HINGE ASSY, HOOD, LH                               | Not Necessary | 57.00 F    | *- F        |
| 24  | 1   |          | *HINGE ASSY, HOOD, RH                               | Not Necessary | 57.00 F    | *- F        |
| 25  | 1   |          | *MOULDING LH                                        | Not Necessary | 83.30 F    | *- F        |
| 26  | 1   |          | *COVER, RADIATOR                                    | Not Necessary | 227.80 F   | *- F        |
| 27  | 1   |          | *SUPPORT S/A UPPER                                  | Not Necessary | 364.90 F   | *- F        |
| 28  | 1   |          | *SUPPORT SUB-ASSY LOWER                             | Not Necessary | 397.40 F   | *- F        |
| 29  | 1   |          | *SUPPORT S/A LH                                     | Not Necessary | 237.00 F   | *- F        |
| 30  | 1   |          | *SUPPORT, RADIATOR UPPER LH                         | Not Necessary | 76.70 F    | *- F        |
| 31  | 1   |          | *COOLANT                                            | Not Necessary | 12.30 F    | *- F        |
| 32  | 1   |          | *COMPUTER SUB-ASSY, HEADLAMP, LH NO.1               | Not Necessary | 486.40 F   | *- F        |
| 33  | 1   |          | *BATTERY                                            | Not Necessary | 1,584.90 F | *- F        |
| 34  | 1   |          | *CLAMP SUB-ASSY, BATTERY                            | Not Necessary | 41.40 F    | *- F        |
| 35  | 1   |          | *CLAMP, BATTERY, NO.2                               | Not Necessary | 43.30 F    | *- F        |
| 36  | 1   |          | *LINER, FR FENDER, LH                               | Not Necessary | 194.30 F   | *- F        |
| 37  | 1   |          | *PAD, FR WHEEL LH                                   | Not Necessary | 57.70 F    | *- F        |
| 38  | 1   |          | *APRON SUB-ASSY, FRONT FENDER, LH                   | Not Necessary | 944.20 F   | *- F        |
| 39  | 1   |          | *TYRE                                               | Not Necessary | 126.74 F   | *- F        |

Report was unsubmitted during this print-out.

| No.               | Qty | Part No. | Particulars                       | Condition     | Repairer's | Amount   |
|-------------------|-----|----------|-----------------------------------|---------------|------------|----------|
| 40                | 1   |          | *WHEEL, DISC FRONT                | Not Necessary | 1,555.10 F | *- F     |
| 41                | 1   |          | *PROTECTOR, FR FENDER LH          | Not Necessary | 90.40 F    | *- F     |
| 42                | 1   |          | *PANEL SUB-ASSY, FRONT DOOR LH    | Not Necessary | 1,249.60 F | *- F     |
| 43                | 1   |          | *STICKER DECAL SMRT (DOOR)        | Not Necessary | 60.00 F    | *- F     |
| 44                | 1   |          | *HINGE ASSY, FRONT DOOR, UPPER LH | Not Necessary | 82.10 F    | *- F     |
| 45                | 1   |          | *HINGE ASSY, FRONT DOOR, LOWER LH | Not Necessary | 92.10 F    | *- F     |
| 46                | 1   |          | *CHECK ASSY, FRONT DOOR           | Not Necessary | 153.50 F   | *- F     |
| 47                | 1   |          | *HOOD SUB-ASSY                    | Repair        | 938.40 F   | *- F     |
| 48                | 1   |          | *PILLAR, FRONT BODY, LH           | Repair        | 339.40 F   | *- F     |
| Total Parts (S\$) |     |          |                                   |               | 18,928.44  | 6,697.22 |

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                     | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                 |          |                 |                 |
| 1                              | PANEL BEATING & BODY WORK                                                       | New      | 1,014.00        | 600.00          |
| 2                              | SPRAY PAINT                                                                     | New      | 2,412.00        | 680.00          |
| 3                              | TOWING CHARGE                                                                   | New      | 56.00           | 40.00           |
| 4                              | TO CHECK WIRING AND SYSTEM FUNCTION                                             | New      | 80.00           | 20.00           |
| 5                              | TO APPLY RUST-PROOFING ON AFFECTED AREA                                         | New      | 100.00          | 30.00           |
| 6                              | TO DO WHEEL ALIGNMENT / TYRE BALANCING                                          | New      | 120.00          | 0.00            |
| 7                              | TO TOP UP A/C GAS                                                               | New      | 120.00          | 0.00            |
| 8                              | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)                                 | New      | 120.00          | 0.00            |
| 9                              | TO REMOVE AND REFIT WIRE HARDESS                                                | New      | 200.00          | 0.00            |
| 10                             | TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER | New      | 120.00          | 0.00            |
| 11                             | TO REPLACE SUNDRY PARTS                                                         | New      | 100.00          | 0.00            |
| 12                             | TO WASH AND VACUUM                                                              | New      | 60.00           | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                                                                 |          | <b>4,502.00</b> | <b>1,370.00</b> |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;