

22/01/2020

ASS. REC. BY:

Surveyor:

REF:

REF: CS/INC19008522/T1td3 | n2

Special Instructions:

ASSIGNMENT (Office)

From (Person):

Annie Koh

9

INC

Date/Time: 14/5/19 @ 9:51am

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / KVA / INV / MV / CS

To Inspect Vehicle No:

GBH 2121E

Insured:

YN 6003H

at Workshop m/s

Fulco Autocare

Tel

96391626

of

176 Sin Ming Drive #03-02

Policy No:

Claim No:

MT/1094250-00

Sum Insured:

Excent

Make of Vehi:

D.O.A.

9/5/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.B. Endowment:

Date/Time:

1007mm 14/5/14

Person Contacted:

funny

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	GBA 2121 E-X		
	YN G063A-X		

ASSIGNMENT

From: Date: 14/5/19
 Estimated Cost:
 OD / TP WS / TP RES / OD RES / EVA / INV / MY
 To inspect Vehicle No: GBH 2121E
 at Workshop m/s: Fulco Autocare
 of: 176 Sin Ming Drive #03-02
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Expenses:
 (Client's Record)
 Make of Veh: Jenny @ 9639 1626

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBH 2121E Yr Regit: 2d81 Mark
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: G. from Berlygo cc 1560
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 21488 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: VF 77 FSHYH H 377403
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: 195/65R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kleber
 Front: R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.A. 14/5/19 3.18
 Rear: R/Bal. 6 mm
 L/Bal. 6 mm
 D.O.A. 14/5/19 3.18
 Survey held at
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Frt 4/5
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

W/s will mail GIA estimate
 1/5/5250, 5 days (Red: 7075.17, 57%)

RECEIVED 21 OCT 2019

Date/Time, File Pass to?

☐

: Prel. Report

1) 21/10 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RSL, 14

) Photos

) Others

TOTAL

250

Report Format: TP

Lump Sum / L.B.I: (\$ 5750

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 14 May 2019 11:16 AM
To: 'assignments@lkkauto.com'
Subject: RE: TP CASES FARMED OUT TO LKK ON 14/05/2019

Dear LKK,

Resend with the following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg

income
make a difference



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Annie Koh
Sent: Tuesday, 14 May 2019 9:51 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Cynthia Ang <Cynthia.Ang@income.com.sg>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 14/05/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Helena Tan	MT/1044374-001	SGF9666E	EM-1 AUTO PTE LTD.	BLK 8 #01-68 SIN MING INDUSTRIAL EST SECTOR C SINGAPORE 575643	KAREN / 9666+6556		YP4984D	11/05/2019	
2	Fiona Shen	MT/1043823-001	SLF6832C	ESTEEM PERFORMANCE PTE LTD	385 SIN MING DRIVE VICOM INSPECTION CENTRE SINGAPORE 575718	Carmen Lim/6484 1221 / 8799 0066	11:00-12:00	SJF1195P	02/02/2019	
3	Jeff Lin	MT/1044250-001	GBH2121E	FULCO AUTOCARE PTE LTD	176 SIN MING DRIVE #03-02 SIN MING AUTOCARE	Jenny / 96391626		YN6003H	09/05/2019	
4	David Phua	MT/1041919-002	GBB1695D	MEGA AUTO PTE LTD	160 SIN MING DRIVE #02-01 SIN MING AUTOCITY	MR MENG / 97582943		YP9237U	26/04/2019	
5	Azhari	MT/1043758-002	SBJ2848G	SUPREME AUTOCARE AUTO SERVICE PTE LTD	176 SIN MING DRIVE #02-01 SIN MING SINGAPORE 575721	Admin / 64528211		GBJ1100L	09/05/2019	Call workshop b4 survey
6	Jared Liu	MT/1043407-002	SLG9127E	TEAMWORK GARAGE PTE LTD	53 UBI AVENUE 1 #01-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	DARREN / 68442475		SMJ245D	06/05/2019	
7	Jared Liu	MT/1043815-002	SMA8238U	TEAMWORK GARAGE PTE LTD	53 UBI AVENUE 1 #01-24	SHU SHAN / 68442475		SJL1464G	09/05/2019	

8	Jared Liu	MT/1037847-002	SJW2484J	TEAMWORK GARAGE PTE LTD	PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	darren / 68442475	ER8010P	27/03/2019	
---	-----------	----------------	----------	-------------------------	---	-------------------	---------	------------	--

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Denise Tay (LKKAuto)

From: Fulco Autocare Pte Ltd <fulco0302@gmail.com>
Sent: Friday, 18 October 2019 11:00 AM
To: Denise Tay (LKKAuto)
Subject: Re: GBH2121E - Estimate

Dear Denise,

Noted with thanks!

Best Regards,

Fulco Autocare Pte Ltd

On Mon, Oct 7, 2019 at 2:28 PM Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Dear Sir,

Checked with taufikh, revised to 5 days.

Please contact Taufikh if any queries.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Fulco Autocare Pte Ltd <fulco0302@gmail.com>
Sent: Wednesday, 2 October 2019 1:28 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: Re: GBH2121E - Estimate

Denise Tay (LKKAuto)

From: Fulco Autocare Pte Ltd <fulco0302@gmail.com>
Sent: Wednesday, 2 October 2019 1:28 PM
To: Denise Tay (LKKAuto)
Subject: Re: GBH2121E - Estimate

Hi Denise,

Sorry for our late reply.

We confirm the repair costs at lump sum \$5,250 (before GST). The repair days able to revise to 7 days?

Best Regards,

Fulco Autocare Pte Ltd

On Fri, Sep 20, 2019 at 9:05 AM Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Dear Sir,

Enclosed offer at lump sum \$5250, 4days.

Please check and confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Fulco Autocare Pte Ltd <fulco0302@gmail.com>
Sent: Friday, 13 September 2019 6:06 PM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/05/2019 11:23
Date Of Accident	09/05/2019 19:00
Exact Location Of Accident	CARPARK GEUAM1 LOADING BAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH2121E
Insured/Policyholder	
Name Of Registered Owner	FULCO LEASING PTE LTD
Co Reg No	201021308G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98387928
Alternative Phone No	OFFICE-67436266

Vehicle Particulars

Manufacturer	CITROEN
Model	BERLINGO L2-1.6 D BLUEHDI S&S ETG6 (M)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994292/100864878-00000
Cover Note Number	

Driver

Name of Driver	MOHAMED TAUFIQ BIN MOHAMED NOH
NRIC No	S7710633B
Date Of Birth	06/04/1977
Occupation	OUTDOOR
Date Of Driving Pass	14/09/2001
Driving Experience	17 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98460877
Fax Number	
Contact Number	HOME-62840961
Email Address	MOHAMEDTAUFIK77@GMAIL.COM

Address	BLK 17 JOO SENG ROAD #08-141 SINGAPORE
Postcode	360017
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LEASE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

UPON ARRIVAL TO PARKING LOT, SAW NEXT VEHICLE DRIVER STANDING IN FRONT OF VAN AND WAITING. AS PER DRIVER, HE MOVING OFF FROM LOT TURNING LEFT KNOCKED MY VAN. THEN REVERSED BACK INTO LOT TO WAIT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN6003H
Vehicle Make/Model/Colour	MITSUBISHI FUSO CANTER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SIVALINGAM JEGATHEESAN
NRIC/Passport Number	G3034385P
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan



CYCLE & CARRIAGE - POLICE

MOTOR ACCIDENT REPORT FORM

BASIC INFORMATION	
Date of Report:	10/05/2019
Date of Accident:	09/05/2019
Exact Location of Accident:	carpark GEUAMI loading bay
Time: 1900	
DETAILS OF OWN VEHICLE	
Vehicle Registration Number:	GBH2121E
Name of Registered Owner:	Fico Leasing Pte Ltd
NRIC/Passport No./FIN:	-
Company Reg. No (for Company Veh):	201021308G
VEHICLE PARTICULARS	
Manufacturer:	CITCV
Model:	Berlingo
Exact Purpose for which vehicle was being used at time of Accident:	☒ Normal Usage ☐ Others
Are You Claiming Under Your Own Insurance?	☐ YES ☐ NO Reporting Only ☒ NO 3rd Party
Vehicle Category:	☐ Private car ☒ Commercial Vehicle
INSURANCE DETAILS	
Name of Insurance:	AIG
Type of Coverage:	☒ Comprehensive ☐ Third Party
Policy Number:	999994292/100864878-00000
Driver when the Accident Happen	
Name of Driver:	Muhamad Taufiq Bin Muhamad Noh
Date of Birth:	06/04/1977
Occupation:	Senior Engineer
Date of Driving Pass:	14/09/2001
Gender:	☒ Male ☐ Female
Mobile No.:	98460877
Home No.:	62840961
Address:	Blk 17 Joo Seng Road #108-141 Singapore
Postal Code:	360017
Email Address:	muhamad.taufiq77@gmail.com
Was the Driver an Employee of the Insured's Company:	☐ Yes ☒ No State the relationship of the driver to Insured: Lease
Vehicle Registration Number of driver's Own Vehicle:	-
Insurance Company:	-
OTHER INFORMATION OF THE ACCIDENT	
Type of Accident:	3rd Party collided to parked vehicle
Weather Condition:	☒ Clear ☐ Raining ☐ Others, please specify
Road Surface:	☒ Dry ☐ Wet ☐ Others, please specify
Was Anybody Injured:	☒ No ☐ Yes
Was Any other material or Property Damaged:	☒ Yes ☐ No
Any Accident Photo in the Scene of Accident:	☒ Yes ☐ No
Was the Accident reported to police:	☐ Yes ☒ No
Which Police Station:	-
Was notice of Intended Prosecution given:	-
DETAILS OF OTHER VEHICLE (Please fill Annex A if more vehicles involve)	
Vehicle Registration Number:	YN 6003H
Name of Registered Owner:	-
NRIC/Passport No./FIN:	-
Company Reg. No (for Company Veh):	-
Name of Driver:	SIVATINGAM Jegathesan
NRIC/Passport/Fin No.:	G1034385P
Mobile No.:	-
Home No.:	-
Address:	-
Postal Code:	-
Email Address:	-
Insurance Company:	-
Details of Passenger if any	
Passenger Name:	-
Contact Number:	-
Gender:	-
Details of Injured Person	
Name:	-
Age:	-
Address:	-
Injured Sustained:	-
Injured Person in which vehicle:	-
Were Seatbelts worn:	☐ Yes ☐ No
Were Injured Convey to Hospital by Ambulance:	☐ Yes ☐ No

CB 042012

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Wahs

h.b.

Driver's Signature
(If driver is not the policyholder)
Date & Time:


[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan #3

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Upon arrival to parking alot, saw next vehicle driver standing in front of van and waiting. As per driver, he moving off from lot turning left knocked my van. Then reversed back into lots to wait.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Names:

AIRC/FIN No.:



Wand

AL

[illegible]

Repair Estimate

Fulco Automotive
Thiam Heng Huat

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: CITROEN BERLINGO

Engine/Chassis No.: VF77FBHYMHJ777423

Date of accident:

Damaged area: O/S Front

Date: 15/05/2019

Claim Type: TP

VRN: GBH2121E



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet	1	\$ 945.30	\$ 945.30
2	Bonnet rubber seal	1	\$ 55.00	\$ 55.00
3	Bonnet lock	1	\$ 238.00	\$ 238.00
4	Bonnet hinge	2	\$ 112.00	\$ 224.00
5	Front grille top panel	1	\$ 560.00	\$ 560.00
6	Front grille chrome garnish	1	\$ 368.00	\$ 368.00
7	Front bumper	1	\$ 886.00	\$ 886.00
8	Front bumper bracket	2	\$ 146.00	\$ 292.00
9	Front bumper side retainer	2	\$ 109.00	\$ 218.00
10	Front bumper reinforcement	1	\$ 465.00	\$ 465.00
11	Front bumper inner sponge	1	\$ 248.00	\$ 248.00
12	Front bumper foglamp o/s	1	\$ 361.00	\$ 361.00
13	Front bumper foglamp garnish o/s	1	\$ 278.00	\$ 278.00
14	Front bumper tow cover	1	\$ 38.00	\$ 38.00
15	Front support panel	1	\$ 466.00	\$ 466.00
16	Aircon condenser	1	\$ 1,287.00	\$ 1,287.00
17	Headlamp o/s	1	\$ 1,594.00	\$ 1,594.00
18	Front fender o/s	1	\$ 731.00	\$ 731.00
19	Front fender inner shield o/s	1	\$ 221.00	\$ 221.00
20	Front bumper lower grille	1	\$ 388.00	\$ 388.00
21	Day running lamp o/s	1	\$ 298.00	\$ 298.00
Subtotal				\$ 10,161.30
List discount				10.00%
Total				\$ 9,145.17

X }
 X }
 X }
 de-
 de-
 de-
 RH-de, LH-
 RH-de, LH-
 Xrh-
 Xun
 Cus-
 mis-
 Xun
 Xun
 Cus-
 bt-
 fu-
 de-
 Cus-
 5940-
 5346-

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bonnet insulator clips	8	\$ 5.50	\$ 44.00
2	Bonnet rubber seal clips	4	\$ 3.50	\$ 14.00
3	Front bumper clips	10	\$ 5.50	\$ 55.00
4	Front fender inner shield o/s clips	8	\$ 5.50	\$ 44.00
5	Radiator coolant	1	\$ 60.00	\$ 60.00
6	Front bumper sensor o/s	1	\$ 263.00	\$ 263.00
7	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 530.00

Xun
Lun
30m
Xun
Xun
150m
Xun
180

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and replace a/c condenser to facilitate repair work. To recharge system and check a/c functionality.	0.75	\$ 150.00
4	To remove and refit radiator to facilitate repair. To perform pressure test and check cooling system functionality.	0.75	\$ 150.00
5	Supply spray paint material and necessary items to respray front bumper, bonnet, support panel, o/s fender and other affected area / panel.	5	\$ 1,000.00
6	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,650.00

500
30
Xun
Xun
50
30
1060

Estimate Grand Total	\$ 12,325.17
----------------------	--------------

Tanjik 97495746
up
14/5/19
4 days
bump sum
Money after repair
Tanjik @ Kuantan
5346
180
1060
6586
20% - 5268.80
4/5/ 5250 #
4 days

LKK Auto Consultants hereby notify the Repairer of the following:

- To recovery before/after spray painting
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature
Date

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC19008522/T1td3n2

Date: 22-10-2019



ATTN: JEFF LIN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 6003H	Veh. Inspected	GBH 2121E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1044250-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	14/05/2019

2. Vehicle Particulars & Condition

Make & Model	CITROEN BERLINGO	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VF77FBHYMHJ777423	Colour	WHITE
Odometer	21488 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	KLEBER	6 mm
L/H Front Tyre	195/65 R15	KLEBER	6 mm
R/H Rear Tyre	195/65 R15	KLEBER	6 mm
L/H Rear Tyre	195/65 R15	KLEBER	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/05/2019	Inspect Date / Time	14/05/2019 (03:18 PM)
Survey held at	FULCO AUTOCARE PTE LTD 176 SIN MING DRIVE# 03-02 SIN MING AUTOCARE, SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No, 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 2121E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	NOT NECESSARY	945.30	-
1	BONNET RUBBER SEAL	NOT NECESSARY	55.00	-
1	BONNET LOCK	NOT NECESSARY	238.00	-
2	BONNET HINGE @\$112.00	NOT NECESSARY	224.00	-
1	FRONT GRILLE TOP PANEL	DEFORMED	560.00	560.00
1	FRONT GRILLE CHROME GARNISH	DISTORTED	368.00	368.00
1	FRONT BUMPER	DEFORMED	886.00	886.00
2	FRONT BUMPER BRACKET @\$146.00	O/S DEFORMED / N/S NOT NECESSARY	292.00	146.00
2	FRONT BUMPER SIDE RETAINER @\$109.00	O/S DEFORMED / N/S NOT NECESSARY	218.00	109.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	465.00	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	248.00	-
1	FRONT BUMPER FOGLAMP O/S	CRACKED	361.00	361.00
1	FRONT BUMPER FOGLAMP GARNISH O/S	CUT	278.00	278.00
1	FRONT BUMPER TOW COVER	NOT NECESSARY	38.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	466.00	-
1	AIRCON CONDENSER	NOT NECESSARY	1,287.00	-
1	HEADLAMP O/S	CRACKED	1,594.00	1,594.00
1	FRONT FENDER O/S	BENT	731.00	731.00
1	FRONT FENDER INNER SHIELD O/S	TORN	221.00	221.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	388.00	388.00
1	DAY RUNNING LAMP O/S	CRACKED	298.00	298.00
	LESS 10% DISCOUNT		-1,016.13	-594.00
			9,145.17	5,346.00
SPECIAL NETT ITEMS				
8	BONNET INSULATOR CLIPS @\$5.50 (SN)	NOT NECESSARY	44.00	-
4	BONNET RUBBER SEAL CLIPS @\$3.50 (SN)	NOT NECESSARY	14.00	-
10	FRONT BUMPER CLIPS @\$5.50 (SN)	NECESSARY	55.00	30.00
8	FRONT FENDER INNER SHIELD O/S CLIPS @\$5.50 (SN)	NOT NECESSARY	44.00	-

Report Ref No. CS/INC19008522/T1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR COOLANT (SN)	NOT NECESSARY	60.00	-
1	FRONT BUMPER SENSOR O/S (SN)	NOT WORKING	263.00	150.00
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			530.00	180.00
	LABOUR			
	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.		1,200.00	500.00
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS.		50.00	30.00
	TO REMOVE AND REPLACE A/C CONDENSER TO FACILITATE REPAIR WORK.TO RECHARGE SYSTEM AND CHECK A/S FUNCTIONALITY.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT RADIATOR TO FACILITATE REPAIR.TO PERFORM PRESSURE TEST AND CHECK COOLING SYSTEM FUNCTIONALITY.	NOT NECESSARY	150.00	-
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY FRONT BUMPER,BONNET,SUPPORT PANEL,O/S FENDER AND OTHER AFFECTED AREA/PANEL.		1,000.00	500.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.		100.00	30.00
			2,650.00	1,060.00
	GRAND TOTAL		12,325.17	6,586.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			5,250.00

Report Ref No. CS/INC19008522/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.