

ASS. REC. BY:

REF: CS/C1219008526 / R19d3n2

Special Instruction:

Surveyor: RusuASSIGNMENT (Office)From (Person): Ong chin kiat

of

CT1Date/Time: 15.5.19 11.34am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLJ 7502 C

Insured:

GBC 43007at Workshop m/s Auto wheels

Tel:

97684247of MD 1 Bukit Batok Crescent # 02-40Policy No: DMCVSU 1917 3019000

Claim No:

SNM19020216002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

13.5.2019CA / REV / REP. / REV 24 HRS"up"

H.O.D. Endorsement:

Date/Time: 15.5.19 11.50am

Person Contacted:

LouisVehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 7502 C - XGBC 43007 - X

10/6/19 @ 2:15pm confirmed with Louis is \$6750, 10 days by email.
(Net \$9037.40, 57%)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 7502C

at Workshop m/s Auto wheel

of Bukit Batok CRG #02-40

Insured:

CTI

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLJ 7502C

Yr Regn: 2016 / ME

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA WISH 1.8 CVT C.C. : 1798

Colour:

Gold

A/C: Insured / Std / NI / NA

Sp. Reading

60187

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDGH 20W 70J 006155

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

DOUBLE STAR

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/05/19

D.O.I.

15/05/19

Survey held at

Auto wheel

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 10 JUN 2019

Date/Time, File Pass to?

1) 10/6/19

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Lump Sum

6750

220

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 15 May 2019 | | 15 May 2019 11:34 Assign | | | | New Assignment Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|--|------------------------|--|
| Insured: | ABS LEASING SERVICES PTE LTD, Co. Reg. No.: 201819528D | | |
| Main Claimant: | SUNRICH CAR LEASING, Co. Reg. No.: 53370662M | | |
| Vehicle Reg. No.: | SLJ7502C | Date of Loss: | 13/05/2019 17:00 - :59 [28 Months and 20 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / SNM19D202160C02 | Policy/Cover Note No.: | DMCVSN19173019000 (Comprehensive) Coverage: 18/04/2019 - 17/04/2020 |
| Vehicle Reg. No. (Insured): | GBC4300T | Policy No. (Claimant): | 5094848919-01(CLASSIC) |
| | | Excess: | S\$0.00 |
| Repairer: | Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247 | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat] | | |
| Claimant's Insurer: | NTUC Income Insurance Co-operative Ltd (HQ) - Tel: | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/05/2019] | | |
| Driver/Custodian (Insured): | MUHAMMAD SALMAN BIN ABDUL GHANI (23 / Male) , NRIC: S9617119F Email: | | |

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 10 June 2019 2:25 PM
To: Louis Ong; Rasul (LKKAUTO); SUR
Subject: RE: Finalize for vehicle SLJ7502C lumpsum \$6,750/- with 10 repair days

Dear Louis,

WITOUT PREJUDICE

Confirm Lump Sum \$6,750.00 and 10 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Friday, 31 May 2019 4:59 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Finalize for vehicle SLJ7502C lumpsum \$6,750/- with 10 repair days

Hi Rasul,

The above attachment is the finalize and after paint photo.

Can help to finalize for vehicle SLJ7502C lumpsum \$6,750/- with 10 repair days.

No Supplementary items.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-------------------------------|
| Date Of Report | 14/05/2019 12:36 |
| Date Of Accident | 13/05/2019 17:50 |
| Exact Location Of Accident | KALLANG PAYA LEBAR EXPRESSWAY |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLJ7502C |
| Insured/Policyholder | |
| Name Of Registered Owner | SUNRICH CAR LEASING |
| Co Reg No | 53370662M |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-97577604 |
| Alternative Phone No | OFFICE-97577604 |

Vehicle Particulars

| | |
|--------------|--------|
| Manufacturer | TOYOTA |
| Model | WISH |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5094848919-01(CLASSIC) |
| Cover Note Number | |

Driver

| | |
|----------------------|-------------------------|
| Name of Driver | MUSTAFA BIN VAPUMARICAN |
| NRIC No | S1657654I |
| Date Of Birth | 04/03/1964 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 29/12/1995 |
| Driving Experience | 23 YEARS AND 4 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-97577604 |
| Fax Number | |
| Contact Number | |
| E-Mail Address | NOEMAIL |

Address BLK 172A EDGEDALE PLAINS #13-400

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - RENTAL

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] BT BATOK NPC

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. POLICE REPORT NO. T/20190514/2053

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC4300T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

DRIVER

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLJ7502C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature?
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle NO GBC H300T hit me
from behind while I was driving
along KFE TUNNEL towards TPE

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190514/2053

1 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20190514/2053

REPORT OF A TRAFFIC ACCIDENT

| | | | | | |
|---|------------|------------------------------|--|--------------------------|----------------------------|
| Date/Time Report Made: 14/05/2019 12:23 | | Vide Report No.: | | Station Diary No.: 71 | |
| Informant's Particulars | | | | | |
| Name of Informant: MUSTAFA BIN VAPUMARICAN | | | Address: APT BLK 172A EDGEDALE PLAINS #13-400 SINGAPORE 821172 | | |
| ID Type / ID No.: NRIC NO / S1657654I | | | Contact No.: Home/Office: Mobile: 97577604 | | |
| Nationality: SINGAPORE CITIZEN | | | Email: | | |
| Sex: Male | Age: 55 | Date of Birth: 04/03/1964 | Type of Informant: Driver | | |
| Race: Indian | | | Language: | | Institution / School Name: |
| Occupation: GRAB DRIVER | | | Driving Licence Information: Class: 2B,2A,3 | | Date of Expiry: |

General Information of the Accident

| | | | | |
|--|------------------|------------------------------------|---|--|
| Type of Accident: | Injury Others | Drink Drive: No | Date/Time of Accident: 13/05/2019 17:50 | Type of Location: Expressway |
| Location: Along Road 1 KALLANG PAYA LEBAR EXPRESSWAY KPE towards TPE under tunnel | | | | |
| Weather: Clear | | Road Surface: Dry | | Road Speed Limit: |
| Traffic Flow: One Way | | Traffic Control: Not Controlled | | Traffic Volume: Moderate |
| Type of Collision: Between Moving Vehicles - Head To Rear | | | | Anyone conveyed by ambulance: No |

Details of Vehicle Involved

| Vehicle No | Type | Make | Model | Color | Condition | No of Passenger |
|------------|------|--------|-------|-------|----------------------|-----------------|
| GBC4300T | Van | | | | Slightly Damaged | 0 |
| SLJ7502C | Car | TOYOTA | wish | Grey | Seriously Damaged | 0 |

Details of Person Involved

| | |
|---------------------------------|--------------------------------|
| Any Pedestrian Involved: No | Use of Pedestrian Crossing: NA |
| No. of Pedestrians Injured: NIL | |



**SINGAPORE
POLICE FORCE**



T/20190514/2053

2 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20190514/2053

CONTINUATION OF REPORT

| | | | |
|-----------------------------------|-------------------------------------|--|---------------------------------------|
| Driver: | | | |
| Name | MUHAMMAD SULMAN BIN ABDUL GHANE | ID No. | S9517119F |
| Related Vehicle | GBC4300T (Van) | Contact No. | 90667304 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |
| Driver: | | | |
| Name | MUSTAFA BIN VAPUMARICAN | ID No. | S1657654I |
| Related Vehicle | SLJ7502C (Car) | Contact No. | 97577604 |
| Hospital/Clinic | SENGKANG GENERAL HOSPITAL PTE. LTD. | Class of Driving Licence & Expiry Date | Class: 2B,2A,3 Date of Expiry: NIL |
| Date Treatment | 13/05/2019 | Date Discharge | 13/05/2019 |
| No. of Days granted Medical Leave | 03 | Degree of Injury | Slight |

Brief Details.

On 13/05/2019 at about 1750hrs, I was driving my car bearing the registration number SLJ7502C along KPE towards TPE. I was travelling on very left lane and intend to make an exit at Tampines exit at 150m ahead. As nearing to the exit, all of a sudden, a van bearing the registration number GBC4300T collided against the rear of my car. Both of us stopped and alighted at the road shoulder assessing each other damages. While we were assessing the damages, shortly after, one LTA officer arrived at scene and advised us to shift our vehicle to a safer location since no one sustains any injuries. We agreed, hence drove off and parked along Greenwich Drive which was nearby to the accident location. We exchanged particulars and thereafter left, no assault or dispute took place. Subsequently, I started to feel aching around my back shoulder. I went to consult doctor at Sengkang General Hospital and was given 3 days' medical leave due to the strain sustain.



**SINGAPORE
POLICE FORCE**



T/20190514/2053

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

3 of 3

Report No. T/20190514/2053

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
J /
Sgt 3 MUHAMMAD FAZLIE BIN JOHAR *afie*

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Sr. Staff Sgt ONG YONG HOCK
Contact No: 65476436 *afie*

Authentication Stamp
NP168
Singapore Police Force

Signature Of Informant:
[Signature]

Date/Time:
14/05/2019 12:23

Classification Of Case:

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 13/05/2019
VEHICLE NO: SLJ7502C
MODEL: TOYOTA WISH
YEAR: 2016
ACCIDENT DATE: 13/05/2019
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATE

| DESCRIPTION | QTY | LIST PRICE |
|--|-----|-------------------------------|
| PARTS | | |
| REAR WINDSCREEN <i>pro</i> ✓ | 1 | \$ 1,342.10 |
| TAILGATE <i>bt</i> ✓ | 1 | \$ 1,556.10 |
| TAILGATE DAMPER <i>x su</i> | 2 | \$ 488.90 |
| TAILGATE OUTER CHROME MOULDING <i>cr</i> ✓ | 1 | \$ 497.60 |
| TAILGATE LOCK <i>am</i> ✓ | 1 | \$ 355.70 |
| TAILGATE LAMP <i>cr</i> ✓ | 2 | \$ 898.40 |
| TAILGATE UPPER TRIM <i>x su</i> | 2 | \$ 786.40 |
| TAILGATE INNER TRIM BOARD <i>? x su</i> | 1 | \$ 568.20 x |
| TAILLAMP INNER TRIM BOARD HANDLE <i>? x su</i> | 1 | \$ 155.60 x |
| COVER | | |
| REAR NUMBER PLATE LAMP <i>? x su</i> | 2 | \$ 288.40 x |
| REAR EMBLEM <i>rec</i> ✓ | 1 | \$ 67.50 |
| TAILGATE WIPER ARM <i>cut</i> ✓ | 1 | \$ 101.20 |
| TAILGATE WIPER MOTOR <i>x su</i> | 1 | \$ 342.50 |
| TAILLAMP - LH- <i>cr</i> / RH- <i>? x su</i> | 2 | \$ 572.30 1,024.60 |
| TAILLAMP SEAL LH- <i>rec</i> / RH- <i>? x su</i> | 2 | \$ 52.10 104.20 |
| TAILLAMP PANEL <i>x su</i> | 2 | \$ 484.60 |
| REAR BUMPER <i>DE</i> ✓ | 1 | \$ 968.40 |
| REAR BUMPER CLIPS <i>rec</i> ✓ | 10 | \$ 30.00 |
| REAR BUMPER RETAINER <i>rec</i> <i>LH-? / RH-<i>x su</i></i> | 2 | \$ 122.60 x |
| REAR BUMPER BRACKET <i>rec</i> ✓ | 2 | \$ 199.60 |

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 13/05/2019
VEHICLE NO: SJ7502C
MODEL: TOYOTA WISH
YEAR: 2016
ACCIDENT DATE: 13/05/2019
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATE

| | | | | |
|--------------------------|--------|---|----|----------|
| REAR BUMPER REFLECTOR | X | 2 | \$ | 388.60 |
| REAR BUMPER TOWING COVER | X } su | 2 | \$ | 88.60 |
| END PANEL | bt | 1 | \$ | 678.30 |
| SPARE TYRE PANEL | Repair | 1 | \$ | 768.30 |
| END PANEL TOP GARNISH | ? de | 1 | \$ | 244.50 ✓ |
| REAR WEATHER STRIP | su | 1 | \$ | 245.30 |
| SPARE TYRE BOARD | ? su | 1 | \$ | 435.10 X |
| REAR SMART SENSOR | X su | 1 | \$ | 399.30 |
| REAR FENDER INNER TRIM | ? su | 2 | \$ | 992.60 X |
| REAR FENDER | | 2 | | REPAIR |

TOTAL: \$ 14,623.20
DISCOUNT 25%: \$ 3,655.80
\$ 10,967.40

S/NET

| | | | | | |
|-------------------------|-----|---|----|----|------------------|
| TAILGATE WIPER BLADE | cut | 1 | \$ | 15 | 30.00 |
| REAR NUMBER PLATE | su | 1 | \$ | 35 | 50.00 |
| REAR END PANEL SEALANT | su | 1 | \$ | 60 | 80.00 |
| REAR WINDSCREEN SEALANT | su | 1 | \$ | 60 | 80.00 |
| | | | \$ | | <u>240.00</u> |

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 13/05/2019

VEHICLE NO: SLJ7502C

MODEL: TOYOTA WISH

YEAR: 2016

ACCIDENT DATE: 13/05/2019

CLAIM ADVISOR: LOUIS (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATE

LABOUR

LABOUR FOR FACILITATE REPAIR
TO RESPRAY TAILGATE
TO RESRAY REAR BUMPER
TO RESPRAY END PANEL
TO RESPRAY SPARE TYRE PANEL
TO RESPRAY RH REAR FENDER
TO RESPRAY LH REAR FENDER
TO CHECK AND RECONNECT ALL NECESSARY WIRING
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT REVERSE SENSOR
TO REMOVE AND REFIT TAILGATE COMPONENT FOR FACILITATE REPAIR
TO REMOVE AND REFIT REAR WINDSCREEN
TO VACCUM AND CLEAN FRAGMENT GLASS
SUNDARIES *NEC*
RUST PROOFING

PRICE

\$ 1,800.00 *1000*
\$ 300.00 *200*
\$ 300.00 *200*
\$ 300.00 *200*
\$ 300.00 *200*
\$ 300.00 *200*
\$ 300.00 *200*
\$ 300.00 *200*
\$ 50.00 *30*
\$ 200.00 *80*
\$ 100.00 *60*
\$ 200.00 *80*
\$ 150.00 *120*
\$ 100.00 *20*
\$ 80.00 *20*
\$ 100.00 *60*

TOTAL: \$ 4,580.00

TOTAL: \$ 15,787.40

7% GST: \$ 1,105.12

\$ 16,892.52

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1, BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 13/05/2019
VEHICLE NO: SU7502C
MODEL: TOYOTA WISH
YEAR: 2016
ACCIDENT DATE: 13/05/2019
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATE

| DESCRIPTION | QTY | LIST PRICE |
|---|-----|---------------------------------|
| PARTS | | |
| REAR WINDSCREEN <i>pro</i> ✓ | 1 | \$ - 1,342.10 |
| TAILGATE <i>bt</i> ✓ | 1 | \$ - 1,556.10 |
| TAILGATE DAMPER <i>x</i> | 2 | \$ x 488.90 |
| TAILGATE OUTER CHROME MOULDING <i>ca</i> ✓ | 1 | \$ - 497.60 |
| TAILGATE LOCK <i>jam</i> ✓ | 1 | \$ - 355.70 |
| TAILGATE LAMP <i>ca</i> ✓ | 2 | \$ - 898.40 |
| TAILGATE UPPER TRIM <i>x</i> | 2 | \$ x 786.40 |
| TAILGATE INNER TRIM BOARD <i>?</i> | 1 | \$ x 568.20 |
| TAILLAMP INNER TRIM BOARD HANDLE <i>?</i> | 1 | \$ x 155.60 |
| COVER | | |
| REAR NUMBER PLATE LAMP <i>?</i> | 2 | \$ x 288.40 |
| REAR EMBLEM <i>nee</i> ✓ | 1 | \$ - 67.50 |
| TAILGATE WIPER ARM <i>cut</i> ✓ | 1 | \$ - 101.20 |
| TAILGATE WIPER MOTOR <i>x</i> | 1 | \$ x 342.50 |
| TAILLAMP - LH- <i>ca</i> / RH- <i>?</i> | 2 | \$ - 1,024.60 512.30 |
| TAILLAMP SEAL LH- <i>nee</i> / RH- <i>?</i> | 2 | \$ - 104.20 52.10 |
| TAILLAMP PANEL <i>x</i> | 2 | \$ x 484.60 |
| REAR BUMPER <i>DE</i> ✓ | 1 | \$ - 968.40 |
| REAR BUMPER CLIPS <i>nee</i> ✓ | 10 | \$ - 30.00 |
| REAR BUMPER RETAINER <i>nee</i> <i>x</i> LH- <i>?</i> / RH- <i>x</i> <i>x</i> 1pc | 2 | \$ x 122.60 |
| REAR BUMPER BRACKET <i>nee</i> ✓ | 2 | \$ - 199.60 |

6,581

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 13/05/2019
VEHICLE NO: SJ7502C
MODEL: TOYOTA WISH
YEAR: 2016
ACCIDENT DATE: 13/05/2019
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louis@autowheels@yahoo.com

ESTIMATE

REAR BUMPER REFLECTOR X
REAR BUMPER TOWING COVER X
END PANEL *bl* ✓
SPARE TYRE PANEL *Repair*
END PANEL TOP GARNISH ? *crack*
REAR WEATHER STRIP *new* ✓
SPARE TYRE BOARD ?
REAR SMART SENSOR X
REAR FENDER INNER TRIM ?
REAR FENDER

| | | | | |
|---|----|---|--------|----------|
| 2 | \$ | X | 388.60 | |
| 2 | \$ | X | 88.60 | |
| 1 | \$ | ✓ | 678.30 | |
| 1 | \$ | X | 768.30 | |
| 1 | \$ | ✓ | 244.50 | * |
| 1 | \$ | ✓ | 245.30 | |
| 1 | \$ | X | 435.10 | |
| 1 | \$ | X | 399.30 | 1,168.10 |
| 2 | \$ | X | 992.60 | |
| 2 | | | REPAIR | |

| | | | |
|---------------|----|-----------|----------|
| TOTAL: | \$ | 14,623.20 | 7,749.10 |
| DISCOUNT 25%: | \$ | 3,655.80 | 25% |
| | \$ | 10,967.40 | 5,811.83 |

S/NET

TAILGATE WIPER BLADE *cut* ✓
REAR NUMBER PLATE *scr* ✓
REAR END PANEL SEALANT *new* ✓
REAR WINDSCREEN SEALANT *new* ✓

| | PRICE |
|---|------------------------|
| 1 | \$ 15 30.00 |
| 1 | \$ 35 50.00 |
| 1 | \$ 60 80.00 |
| 1 | \$ 60 80.00 |
| | \$ 240.00 |

170

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 13/05/2019

VEHICLE NO: SLJ7502C

MODEL: TOYOTA WISH

YEAR: 2016

ACCIDENT DATE: 13/05/2019

CLAIM ADVISOR: LOUIS (91928963)

EMAIL: louisongautowheels@yahoo.com

ESTIMATE

LABOUR

LABOUR FOR FACILITATE REPAIR
TO RESPRAY TAILGATE
TO RESRAY REAR BUMPER
TO RESPRAY END PANEL
TO RESPRAY SPARE TYRE PANEL
TO RESPRAY RH REAR FENDER
TO RESPRAY LH REAR FENDER
TO CHECK AND RECONNECT ALL NECESSARY WIRING
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT REVERSE SENSOR
TO REMOVE AND REFIT TAILGATE COMPONENT FOR FACILITATE REPAIR
TO REMOVE AND REFIT REAR WINDSCREEN
TO VACCUM AND CLEAN FRAGMENT GLASS
SUNDARIES
RUST PROOFING

PRICE

| | | |
|-----------|----------|-------|
| \$ | 1,800.00 | 1000 |
| \$ | 300.00 | 200 |
| \$ | 300.00 | 200 |
| \$ | 300.00 | 200 |
| \$ | 300.00 | 200 |
| \$ | 300.00 | 200 |
| \$ | 300.00 | X |
| \$ | 300.00 | 200 |
| \$ | 50.00 | 30 |
| \$ | 200.00 | 80 |
| \$ | 100.00 | 60 |
| \$ | 200.00 | 80 |
| \$ | 150.00 | 120 |
| \$ | 100.00 | 20 |
| \$ | 80.00 | 20 |
| \$ | 100.00 | 60 |
| TOTAL: \$ | 4,580.00 | 2,470 |

| | | |
|------------|-----------|-------------|
| TOTAL: \$ | 15,787.40 | 8,451.83 |
| 7% GST: \$ | 1,105.12 | |
| \$ | 16,892.52 | 15: 6,750/2 |

Signature: _____
Acknowledged by Repairer: _____

is subject to final approval from Insurance Company

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LKK Auto Consultants

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: _____

Signature: _____

Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19008586/R1QD3N2

Date: 14/06/2019

REFERENCE

| | | | |
|-----------------------|---|----------------------|-------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSN19173019000 |
| Claimant Vehicle No : | SLJ7502C | Insured Vehicle No : | GBC4300T |
| Date of Loss: | 13/05/2019 | Nature of Claim: | TP |
| | | Claim No: | SNM19D202160C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SLJ7502C | Engine No: | 2ZR1863160 |
| Make & Model: | TOYOTA WISH, 1.8 CVT (A) | Chassis No: | JTDGG20W70J006155 |
| Reg. Date: | 23/12/2016 (Man. Year: 2016) | Odometer: | 60187 km |
| Colour: | Gold | | |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 195/65R15 | Rear Tyre Size: | 195/65R15 |
| Front Left Side: | Double Star 6 mm | Rear Left Side: | Double Star 6 mm |
| Front Right Side: | Double Star 6 mm | Rear Right Side: | Double Star 6 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|-----------------|--------------|
| Parts | 11,287.40 | 6,001.82 | 5,285.58 | 46.83 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,500.00 | 2,450.00 | 2,050.00 | 45.56 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 15,787.40 | 8,451.82 | 7,335.58 | 46.46 |
| Approved Total (Overridden) (S\$) | | 6,750.00 | | |
| (S\$) | 15,787.40 | 6,750.00 | 9,037.40 | 57.24 |
| + GST 7.00/7.00% (S\$) | 1,105.12 | 472.50 | 632.62 | 57.24 |
| Nett Amount (S\$) | 16,892.52 | 7,222.50 | 9,670.02 | 57.24 |

INSPECTION

| | | |
|---------------------|--------------------------|---|
| Date of Assignment: | 15/05/2019 | |
| Date Inspected: | 15/05/2019 Inspected At: | Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA Singapore 658064 |

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|--|--|---|
| Reference | | |
| Part Source: MRM-SG | | Version: 1.0 (Last Synchronised: 14 Jun 2019) |
| Parts: | M1-MPV | TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLJ7502C) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-------------------------------|-------------|--------------|
| 1 | 1 | | *REAR WINDSCREEN | Broken | 1,342.10 FL | *1,342.10 FL |
| 2 | 1 | | *TAILGATE | Bent | 1,556.10 FL | *1,556.10 FL |
| 3 | 2 | | *TAILGATE DAMPER | Serviceable | 488.90 FL | *- FL |
| 4 | 1 | | *TAILGATE OUTER CHROME MOULDING | Cracked | 497.60 FL | *497.60 FL |
| 5 | 1 | | *TAILGATE LOCK | Jammed | 355.70 FL | *355.70 FL |
| 6 | 2 | | *TAILGATE LAMP | Cracked | 898.40 FL | *898.40 FL |
| 7 | 2 | | *TAILGATE UPPER TRIM | Serviceable | 786.40 FL | *- FL |
| 8 | 1 | | *TAILGATE INNER TRIM BOARD | Serviceable | 568.20 FL | *- FL |
| 9 | 1 | | *TAILGATE INNER TRIM BOARD HANDLE COVER | Serviceable | 155.60 FL | *- FL |
| 10 | 2 | | *REAR NUMBER PLATE LAMP | Serviceable | 288.40 FL | *- FL |
| 11 | 1 | | *REAR EMBLEM | Necessary | 67.50 FL | *67.50 FL |
| 12 | 1 | | *TAILGATE WIPER ARM | Cut | 101.20 FL | *101.20 FL |
| 13 | 1 | | *TAILGATE WIPER MOTOR | Serviceable | 342.50 FL | *- FL |
| 14 | 1 | | *TAILLAMP | N/s Cracked/O/s Serviceable | 1,024.60 FL | *512.30 FL |
| 15 | 1 | | *TAILLAMP SEAL | N/s Necessary/O/s Serviceable | 104.20 FL | *52.10 FL |
| 16 | 2 | | *TAILLAMP PANEL | Serviceable | 484.60 FL | *- FL |
| 17 | 1 | | *REAR BUMPER | Deformed | 968.40 FL | *968.40 FL |
| 18 | 10 | | *REAR BUMPER CLIPS | Necessary | 30.00 FL | *30.00 FL |
| 19 | 2 | | *REAR BUMPER RETAINER | Serviceable | 122.60 FL | *- FL |
| 20 | 2 | | *REAR BUMPER BRACKET | Necessary | 199.60 FL | *199.60 FL |
| 21 | 2 | | *REAR BUMPER REFLECTOR | Serviceable | 388.60 FL | *- FL |
| 22 | 2 | | *REAR BUMPER TOWING COVER | Serviceable | 88.60 FL | *- FL |
| 23 | 1 | | *END PANEL | Bent | 678.30 FL | *678.30 FL |
| 24 | 1 | | *SPARE TYRE PANEL | Repair | 768.30 FL | *- FL |
| 25 | 1 | | *END PANEL TOP GARNISH | Deformed | 244.50 FL | *244.50 FL |
| 26 | 1 | | *REAR WEATHER STRIP | Necessary | 245.30 FL | *245.30 FL |
| 27 | 1 | | *SPARE TYRE BOARD | Serviceable | 435.10 FL | *- FL |
| 28 | 1 | | *REAR SMART SENSOR | Serviceable | 399.30 FL | *- FL |
| 29 | 2 | | *REAR FENDER INNER TRIM | Serviceable | 992.60 FL | *- FL |
| 30 | 2 | | *REAR FENDER (NPA) | Repair | 0.00 FL | *- FL |
| 31 | 1 | | *TAILGATE WIPER BLADE | Cut | 30.00 FS | *15.00 FS |
| 32 | 1 | | *REAR NUMBER PLATE | Scratched | 50.00 FS | *35.00 FS |
| 33 | 1 | | *REAR END PANEL SEALANT | Necessary | 80.00 FS | *60.00 FS |
| 34 | 1 | | *REAR WINDSCREEN SEALANT | Necessary | 80.00 FS | *60.00 FS |
| 35 | 1 | | *SUNDARIES | Necessary | 80.00 FS | *20.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 14,943.20 7,939.10
 - List Item Discount on L Items 25.00/25.00% (S\$) 3,655.80 1,937.28

Total Parts (S\$) 11,287.40 6,001.82

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|-------------|-------------|-----------|------------|--------|
| Report was unsubmitted during this print-out. | | | | | | |