

22/03/2001

ASS. REC. BY:

REF:

CS3/FAD19008591/Ecd321

Special Instruction:

Surveyor: Sevl

ASSIGNMENT (Office)

From (Person): Josey Loh

of

FAD

Date/Time: 14/5/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDW308U

Insured: SLS 8886 R

at Workshop m/s Hiap Lek

Tel: 96601347 Han Wei

of 160 Sin Ming Drive #05-17

Policy No: PNFV2017-00007521-01

Claim No: 1201900013088

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/5/2019

CA / REV / REP. / REV 24 HRS

Date/Time: 15/5

Person Contacted: Han Wei

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	SDW308U-X	
	SLS 8886R - CCH/ASM18019874/Riha3 DOA: 30/10/2018	
15/5	Han Wei said vehicle not in, will arrange.	
	Dismantle: 27/5/2019	
	After repair: 28/5/2019	

Steve

REF:

ASSIGNMENT

From: Date: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: at Workshop n/s: of Insured: Policy No: Claims No: Sum Insured: Excess: (Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  
Bal. or Market Value: IDAC Accident Report: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: days Res.: Yes or No  
Lump Sum: % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT

Veh No: SDW 3084 To Regn: 8/3/16  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or  
Make: Honda Vezel C.C. 1496  
Colour: White A/C Insured / Std / Nil / N/  
Sp. Reading: 79364 T/Radio: Insured / Std / Nil / N.  
Eng/No: C/N: R4 311 08567  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Locked / Burnt or  
Brake: In order / Jammed / Locked / Burnt or  
Mod: Nil / S/Rim. / STD A/Rim or  
Tyre Size: F: 215/55ZR17 R: 1  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI / TOYO / YOKO or  
Front R/Bal. 3 mm Rear R/Bal. 3 mm  
L/Bal. 3 mm L/Bal. 3 mm  
D.O.A. 14/5/19 D.O.I. 23/5/19  
Survey held at Hip lek  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision

N/S	O/S

Date / Time Action / Instruction  
Mv - 6SK Repa. 10 days 4K-5K 5

28/5/2019

RECEIVED 07 JUN 2019

Date/Time, File Pass to? ☐ : Prel. Report  
4) ☐ : Final Report

Days Of Repair: 5  
Resurvey No. of Trip: 2

Date/Time, File Return to?

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech Insp (\$)  
☐ : Weekend (\$)

Survey Fee:  
Transportation  
3 - R/S  
Photos  
Index

Report Format: PR

Lump Sum / I.B.L. (\$)

80
50
50
180

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2019 <a href="#">Edit Reg</a>		24 May 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by adjuster]</b>	
Insured:	Huang Qianyun Rafaela, ID: S8615873F			
Main Claimant:	OOI YI JUN, ID: S8268889G			
Vehicle Reg. No.:	SDW308U	Date of Loss:	14/05/2019 10:00 - :59	
Claim Type:	TP / 1201900013088	Policy/Cover Note No.:	PNPV2017-00007521-01 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLS8886R	Policy No. (Claimant):		
		Excess:		
Repairer:	Hiap Lek Automobile Trading ( ) Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:			
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... <b>[Final Rpt due 04/06/2019]</b>			
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.				
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a>	<a href="#">Search Tasks</a>
			<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

## Nivitha (LKK Auto)

---

**From:** josey.loh@fwd.com  
**Sent:** Tuesday, 14 May 2019 5:46 PM  
**To:** assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com  
**Subject:** FW: OUR REF : AW-INS-H2-SDW 308 U -19.jgv & YR REF: SLS 8886 R (PNPV2017-00007521-01)

Hi LKK team,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

Regards,  
Josey

---

**From:** Josey Loh Kah Wai - SGUser  
**Sent:** Tuesday, 14 May, 2019 5:44 PM  
**To:** 'Jennifer Guay'  
**Cc:** Motor Claims SG - SG Common; hiaplek@hotmail.com  
**Subject:** RE: OUR REF : AW-INS-H2-SDW 308 U -19.jgv & YR REF: SLS 8886 R (PNPV2017-00007521-01)

### WITHOUT PREJUDICE

Dear Sir/ Madam,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK Auto Consultants Pte Ltd, to conduct the pre-repair survey (PRS) on your client's vehicle, SDW308U. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.


***\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.***

Kind Regards  
Josey Loh  
Executive, Claims

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872  
E [josey.loh@fwd.com](mailto:josey.loh@fwd.com)  
W [fwd.com.sg](http://fwd.com.sg)

Veh Out



**From:** Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]  
**Sent:** Tuesday, 14 May, 2019 5:34 PM  
**To:** Josey Loh Kah Wai - SGUser  
**Cc:** Motor Claims SG - SG Common; [hiaplek@hotmail.com](mailto:hiaplek@hotmail.com)  
**Subject:** RE: OUR REF : AW-INS-H2-SDW 308 U -19.jgv & YR REF: SLS 8886 R (PNPV2017-00007521-01)  
**Importance:** High

**PRE - REPAIR SURVEY**  
**CLAIMANT:** OOI YI JUN  
**ACCIDENT INVOLVING SDW 308 U & SLS886R ON 14 MAY 2019 ALONG BEDOK NORTH AVE 3**

Dear Sirs

Refer to your email of 14 May 2019 informing that you wish to conduct a pre-repair survey and to your list of surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following surveyors for your consideration:-

1. B J Loi (Par Automotive Consultancy)	2. Marc (United Appraisal And Management PL)
3. Oh Han Cheong (Oh Appraisal & Management P L)	4. S Kuaman (SK Auto Consultants)
5. Lee K W (Lee Automobile Appraisers )	6. Ng Cheng Meng (CM Automotive Consultancy)
7. Zali Saidi (ISP Management Pte Ltd)	

Please be informed that the pre-repair survey of our clients vehicle can be survey as follows :

**Venue**      **HIAP LEK AUTOMOBILE TRADING**  
 160 Sin Ming Drive #05-17  
 Sin Ming Autocity  
 Singapore 575722

**Contact**        :      Mr Han Wei (Tel: 9660 1347)

Please let us hear from you by 15 May 2019 . Thank you.

Regards

**Jennifer Guay**

(Secretary for Ms Audrey Wong)

**VISION LAW LLC**

133 New Bridge Road #18-01

Chinatown Point

Singapore 059413

Tel : 6534 2811 (Ext 116)

Fax : 6535 6802

---

**From:** [josey.loh@fwd.com](mailto:josey.loh@fwd.com) [mailto:[josey.loh@fwd.com](mailto:josey.loh@fwd.com)]

**Sent:** Tuesday, 14 May, 2019 5:23 PM

**To:** [jenniferguay@visionlawllc.com](mailto:jenniferguay@visionlawllc.com)

**Cc:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com); [hiaplek@hotmail.com](mailto:hiaplek@hotmail.com)

**Subject:** RE: OUR REF : AW-INS-H2-SDW 308 U -19.jgv & YR REF: SLS 8886 R (PNPV2017-00007521-01)

**WITHOUT PREJUDICE**

Dear Jennifer,

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

***\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.***

Kind Regards

Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E [josey.loh@fwd.com](mailto:josey.loh@fwd.com)

W [fwd.com.sg](http://fwd.com.sg)



**From:** Jennifer Guay [mailto:jenniferguay@visionlawllc.com]  
**Sent:** Tuesday, 14 May, 2019 4:57 PM  
**To:** Motor Claims SG - SG Common; Clara Li Zirong - SGUser  
**Cc:** hiaplek@hotmail.com  
**Subject:** OUR REF : AW-INS-H2-SDW 308 U -19.jgv & YR REF: SLS 8886 R  
**Importance:** High

**PRE - REPAIR SURVEY**  
**CLAIMANT:** OOI YI JUN

**ACCIDENT INVOLVING SDW 308 U & SLS886R ON 14 MAY 2019 ALONG BEDOK NORTH AVE 3**

Dear Sirs

We are instructed by **OOI YI JUN** to notify you of a road accident on **14 MAY 2019** at about 10.50hr **ALONG BEDOK NORTH AVE 3** involving our client's **SDW 308 U & SLS 886 R** driven by your driver at the material time.

As a result of the accident, our client's vehicle has been damage. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

**Jennifer Guay**  
 (Secretary)  
**VISION LAW LLC**  
 133 New Bridge Road #18-01  
 Chinatown Point  
 Singapore 059413  
 Tel : 6534 2811 (Ext 116)  
 Fax : 6535 6802

For Surveyor

Please initial here after completion of pre-repair survey.  
 Thank you.

Appointed Surveyor: \_\_\_\_\_  
 Name & Signature

Contact : \_\_\_\_\_

Date & Time \_\_\_\_\_

Surveyor during repair : \_\_\_\_\_

Date & Time : \_\_\_\_\_

Surveyor after repair : \_\_\_\_\_

Date & Time : \_\_\_\_\_

**VISION LAW LLC**  
 Advocates & Solicitors  
 (Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments. Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

---

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.



Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8889G
<b>Vehicle Details</b>	
Vehicle No.:	SDW308U
Vehicle to be Exported:	No
Intended Deregistration Date:	23 May 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5Z HYBRID AUTO
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	LEB5058576
Chassis No.:	RU31108567
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,560.00
Original Registration Date:	08 Mar 2016
First Registration Date:	08 Mar 2016
Transfer Count:	1
Actual ARF Paid:	\$11,384.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Mar 2026
PARF Rebate Amount:	\$8,538.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	07 Mar 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$33,978.00
<b>Total Rebate Amount:</b>	<b>\$42,516.00</b>

The information contained herein is correct as at 23 May 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/05/2019 16:30
Date Of Accident	14/05/2019 10:50
Exact Location Of Accident	BEDOK NORTH AVE 3 (BLK 401)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDW308U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	OOI YI JUN
NRIC No	S8268889G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90255048
Alternative Phone No	OFFICE-90255048

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107985469
Cover Note Number	

### Driver

Name of Driver	LIU TERENCE
NRIC No	S8371061F
Date Of Birth	07/10/1983
Occupation	INDOOR
Date Of Driving Pass	06/07/2004
Driving Experience	14 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98225133
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 550 #06-170 HOUGANG STREET 51
Postcode	530550
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS8886R
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

14 MAY 2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/Passport:

WING KIN JAMES


admin.vac@vicom.com.sg



SKETCH PLAN

(A) 5PW 3084

(B) SLS 8886R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/05/19, @ about 10.50am, I am travelling along Bedok North Ave 3. I stopped my vehicle as it was red light, when the traffic just turn green, a vehicle (B) SLS 8886R suddenly change lane abruptly and its left side portion hit into my vehicle front right portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

14 MAY 2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name: NG WING KIN JAMES  
NRIC/FIN No.: admin.vac@vicom.com.sg

### ...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 May 2019 <a href="#">Edit Reg</a>		14 May 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>





























Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by adjuster]</a></span>									
Insured: <b>Huang Qianyun Rafaela</b> , ID: S8615873F									
Main Claimant: <b>OOI YI JUN</b> , ID: S8268889G									
Vehicle Reg. No.: <b>SDW308U</b>		Date of Loss: 14/05/2019 10:00 - :59 <b>[38 Months and 6 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / 1201900013088</b>		Policy/Cover Note No.: <b>PNPV2017-00007521-01 (Comprehensive)</b>							
Vehicle Reg. No. (Insured): <b>SLS8886R</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Hiap Lek Automobile Trading ()</b> Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:									
Handling Insurer: <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Josey Loh</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 04/06/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SDW308U (1201900013088)  
[SLS8886R]  
TP  
OOI YI JUN  
May 14 2019 10:00AM  
[Huang Qianyun Rafaela]  
Hiap Lek Automobile Trading

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
2	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
3	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
4	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
5	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
6	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
7	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
8	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
9	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
10	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
11	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
12	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
13	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
14	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
15	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
16	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
17	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
18	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
19	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
20	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
21	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
22	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
23	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
24	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
25	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
26	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
27	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
28	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
29	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
30	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
31	06/06/19 17:41	General View		Load JPG	<input checked="" type="checkbox"/>					
32	06/06/19 17:42	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
33	06/06/19 17:42	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
34	06/06/19 17:42	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
35	06/06/19 17:42	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
36	06/06/19 17:42	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
37	06/06/19 17:42	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/06/19 17:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/06/19 17:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	06/06/19 17:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	06/06/19 17:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	06/06/19 17:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	06/06/19 17:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	06/06/19 17:42	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/19 16:48	E-filed GIA report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19008591/ECD3E2

Date: 10/06/2019

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00007521-01

Claimant Vehicle No : SDW308U Insured Vehicle No : SLS8886R

Date of Loss: 14/05/2019 Nature of Claim: TP Claim No: 1201900013088

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDW308U**  
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: LEB5058576  
 Reg. Date: 08/03/2016 (Man. Year: 2015) Chassis No: RU31108567  
 Colour: White Odometer: 79364 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55Z R17 Rear Tyre Size: 215/55Z R17  
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm  
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 14/05/2019

Date Inspected: 23/05/2019 Inspected At:

160 SIN MING DRIVE # 05-17

Repairer : Hiap Lek Automobile Trading

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDW308U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >