

22/03/2002

ASS. REC. BY:

REF: CS3/MSG19008593/ Gcd3er

Special Instruction:

Survivor: GQ

ASSIGNMENT (Office)

From (Person): Jaryn Tay mi luy of MSG Date/Time: 8.5.19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 8565P Insured: SDD 2191A

at Workshop m/s King's Auto Air-Conditioning Tel: 96956517

of Block 176 sin ming Drive #02-10

Policy No: 27567961 SMP Claim No: 593230

Sum Insured: Excess:

Make of Veh: D.O.A. 8.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 15.5.19 10:59 AM Person Contacted: Alex

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SMC 8565P - X
	SDD 2191A - X
	Dismantle: 16/5/2019
	After repair: 23/5/2019

PRS

REF: MS19

## ASSIGNMENT

From: Date: 15.5.2019

Estimated Cost: .

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SMC 8565P

at Workshop m/s King's Auto Air Conditioning  
of Black 176 sin ming Drive #02-10

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT.

Date: Person Contacted:

Veh No: SMC8565P Yr Regn: Jan / 10

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda odyssey 2.4 2354

Colour: Grey

Sp. Reading: -

Eng/No:

C/No: JHM RB3850 9C290577

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ Rim / STD A/Rim or

Tyre Size: F: 225/50 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

16/5/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

120

11

131

Report Format: PRS.

Lump Sum / I.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		15 May 2019 10:03 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	TAY LAY PING, ID: S6915495F, Tel: +6596228259, Email: LAYPINGLPT@GMAIL.COM		
Main Claimant:	LOH KOK WENG, ID: S7349329C		
Vehicle Reg. No.:	SMC8565P	Date of Loss:	08/05/2019 20:00 - :59 [111 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 593230	Policy/Cover Note No.:	27567961SMP (Comprehensive) Coverage: 23/08/2018 - 22/08/2019
Vehicle Reg. No. (Insured):	SDD2191A	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	King's Auto Air-Conditioning Service (HQ) Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/05/2019]		
Driver/Custodian (Insured):	TAY LAY PING (49 / Female) , NRIC: S6915495F, Tel: +6596228259 Email: LAYPINGLPT@GMAIL.COM		
Adj Asg. Remarks:	on WP. (MANUAL ASSIGNED) SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: 6457 8629		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9329C
<b>Vehicle Details</b>	
Vehicle No.:	SMC8565P
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4L AT SR
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	K24Z21300583
Chassis No.:	JHMRB38509C200577
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$33,690.00
Original Registration Date:	29 Jan 2010
First Registration Date:	29 Jan 2010
Transfer Count:	3
Actual ARF Paid:	\$33,690.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2020
PARF Rebate Amount:	\$16,845.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Jan 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$22,400.00
COE Rebate Amount:	\$1,439.00
<b>Total Rebate Amount:</b>	<b>\$18,284.00</b>

The information contained herein is correct as at 06 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/05/2019 14:26
Date Of Accident	08/05/2019 20:15
Exact Location Of Accident	JUNCTION OF CAVENAGH ROAD AND BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMC8565P
Insured/Policyholder	
Name Of Registered Owner	LOH KOK WENG
NRIC No	S7349329C
Email Address	KOKWENG@UNI-CABLING.COM
Mobile Phone No	(LOCAL) +65-81002133
Alternative Phone No	OTHERS-66341588
Vehicle Particulars	
Manufacturer	HONDA
Model	ODYSSEY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102457559
Cover Note Number	
Driver	
Name of Driver	LOH KOK WENG
NRIC No	S7349329C
Date Of Birth	10/08/1973
Occupation	OUTDOOR
Date Of Driving Pass	21/11/1997
Driving Experience	21 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81002133
Fax Number	
Contact Number	OTHERS-66341588
EMail Address	KOKWENG@UNI-CABLING.COM

Address	100 CLEMENCEAU AVENUE NORTH #12-103 CAVENAGH HOUSE
Postcode	229491
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDD2191A
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MS TAY
NRIC/Passport Number	
Contact Number	96228259
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

09 MAY 2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

**NG WING KIN JAMES**  
admin.vac@vicom.com.sg



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stop my car at the give way line waiting for oncoming vehicle to clear. Out of sudden, I feel an impact from the rear as the car behind did not stop. therefore hit onto my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature

Date & Time:

09 MAY 2019

  
Driver's Signature  
(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: **NG WING KIN JAMES**

admin.vac@vicom.com.sg



### ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		15 May 2019 10:03 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  


























Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>TAY LAY PING</b> , ID: S6915495F, Tel: +6596228259, Email: LAYPINGLPT@GMAIL.COM									
Main Claimant: <b>LOH KOK WENG</b> , ID: S7349329C									
Vehicle Reg. No.: <b>SMC8565P</b>		Date of Loss: 08/05/2019 20:00 - :59 [111 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 593230</b>		Policy/Cover Note No.: 27567961SMP (Comprehensive) Coverage: 23/08/2018 - 22/08/2019							
Vehicle Reg. No. (Insured): <b>SDD2191A</b>		Policy No. (Claimant):							
		Excess: S\$1,000.00							
Repairer: <b>King's Auto Air-Conditioning Service (HQ)</b> Block 176 Sin Ming Drive, #02-10, 575721 Sin Ming - Tel: 6457 8629									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Jowyn Tay Mei Ling</b> - 6643 1307]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 16/05/2019]									
Driver/Custodian (Insured): TAY LAY PING (49 / Female) , NRIC: S6915495F, Tel: +6596228259 Email: LAYPINGLPT@GMAIL.COM									
Adj Asg. Remarks: on WP. (MANUAL ASSIGNED) SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: 6457 8629									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SMC8565P (593230)**  
**[SDD2191A]**  
**TP**  
**LOH KOK WENG**  
**May 8 2019 8:00PM**  
**[TAY LAY PING]**  
**King's Auto Air-Conditioning Service**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/05/19 09:23	<b>Accident Statement</b> <small>From:OD - Reg. No: SDD2191A, Claimant: TAY LAY PING</small>	 <a href="#">Load HTM</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
2	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
3	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
4	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
5	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
6	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
7	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
8	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
9	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
10	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
11	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
12	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
13	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
14	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
15	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
16	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
17	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
18	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
19	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
20	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
21	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
22	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
23	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
24	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
25	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
26	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
27	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
28	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
29	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
30	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
31	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
32	06/06/19 13:50	General View	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
33	06/06/19 13:51	Photographs of Damaged Parts	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	06/06/19 13:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	06/06/19 13:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/05/19 09:23	TP SAS REPORT From:OD - Reg. No: SDD2191A, Claimant: TAY LAY PING	 Load PDF	
2	15/05/19 09:23	PRI-SMC8565P	 Load PDF	
3	15/05/19 09:33	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	15/05/19 10:01	email - manual assign	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19008593/GCD3E2

Date: 10/06/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27567961SMP

Claimant Vehicle No : SMC8565P

Insured Vehicle No : SDD2191A

Date of Loss: 08/05/2019

Nature of Claim: TP

Claim No: 593230

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMC8565P

Make &amp; Model: HONDA ODYSSEY, 2.3 (A)

Reg. Date: 29/01/2010 (Man. Year: 2009)

Colour: Grey

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: K24Z21300583

Chassis No: JHMRB38509C200577

Odometer: 0 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 15/05/2019

Date Inspected: 15/05/2019 Inspected At:

King's Auto Air-Conditioning Service (HQ)  
Block 176 Sin Ming Drive, #02-10  
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 10 Jun 2019)

**Parts:** M1-MPV      HONDA ODYSSEY 2.3 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMC8565P)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >