

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/1

Company
AXA Insurance Pte Ltd
8 SHENTON WAY
#27-01 AXA TOWER
Singapore 068811

Customer Details:
Ms.
STEBBINGS
LYN-HWA AMY
33 JALAN UNGGAS
Singapore 298930

Document no.
Document date 15-05-2019
Customer no. 5211000859
Customer GST-ID 196900406D
Dealer 39999
Job order number 2019000607/ 1
Job order date 14-05-2019
Service Advisor EDMUND, HUI HUANG GOH

License plate	Model code	First registration	VIN	Model	Mileage
SDE2992A	5G13GZ	17-09-2014	WVWZZZAUZFW032553	Golf 1.4 CLBMT 90 TSI D7F	38,616

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	360.00	#1	360.00	385.20
	Check Short Circuit / Harness Repair	1	pcs.	200.00	#1	200.00	214.00
	WHEEL ALIGNMENT	1	pcs.	360.00	#1	360.00	385.20
5G6807417APGRU	COVER	1	pcs.	1,080.14	28.00% #1	777.70	832.14
5G0807305D	(FRT BUMPER COVER) CUT	1	pcs.	572.31	28.00% #1	412.06	440.90
5G6807863C	Bumper	1	pcs.	59.89	28.00% #1	43.12	46.14
5G6807393A	(BUMPER REINFORCEMENT) X	1	pcs.	34.51	28.00% #1	24.85	26.59
5G6807393	Attachment Strip	1	pcs.	34.51	28.00% #1	24.85	26.59
5G0601025 8Z8	Guide Piece	1	pcs.	34.51	28.00% #1	24.85	26.59
311601361	(REAR BUMPER GUIDE LH) ?	1	pcs.	1,015.34	28.00% #1	731.04	782.21
	(REAR BUMPER BRACKET LH)	1	pcs.	3.22	28.00% #1	2.32	2.48
	Alloy Wheel Diamond Silve	1	pcs.	580.00	#1 1160/	2,320.00	2,482.40
	Rubber Valve - MEC	1	pcs.	500.00	#1 1000/	2,000.00	2,140.00
	LABOUR	42	pcs.	50.00	#1	50.00	53.50
	Spray Painting	1	pcs.	680.00	#1	680.00	727.60
	R&R RIM & BALANCE	1	pcs.				
	TYRE	1	pcs.				

Quotation valid till 21-05-2019

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	920.00	7,065.94	783.98	7%	559.02	783.98	7,985.94	8,544.96
Total	920.00	7,065.94	783.98		559.02	783.98	7,985.94	8,544.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions)

Service Advisor

Steve (LKK) w/L Parulie 22/5/19, 4.30pm
8322 8813
P/P
Ry bef spy
4 Days