

Surveyor: MAZ

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping of CT1 Date/Time: 15.5.19 14.33pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No: SLD 7335A Insured: GBC 8947B

at Workshop m/s JC motor Consultancy Tel: 91170086

of 71 woodlands Ave 10 #02-09

Policy No: DMCVS N30062119000 Claim No: SNM19D202155102

Sum Insured: Excess:

Make of Veh: D.O.A. 11.5.2019
(Client's Record) "WP" 22.5.2019 After 12.00pm

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 15.5.19 5.26pm Person Contacted: -Xiao Xiang Vehicle: IN (OUT)

Date/Time	Action/Instruction (X) Estimate
	SLD 7335A - CCH/Asm/8019410/khb3 DOA-24/10/2018
	GBC 8947B - CCB/CTI/6023157/929392 DOA-02/12/2016
	Dismantle: 23/5/2019
	After repair: 28/5/2019

Summary

NAZ

REF: CTI

ASSIGNMENT

From:

Date:

22.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLD 7335A

at Workshop m/s

JC Motor Consultancy

of

71 Woodlands Ave 10 #02-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 2.00 p.m

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

"up"

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLD 7335A

Yr Regn: 28 JUN 2016

Type: ☒ Car / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA SHUTTLE

1.5GA

c.c

1496

Colour

WHITE

AC:

Insured

Std / NI / NA

Sp. Reading

62088

T/Radio:

Insured

Std / NI / NA

Eng/No:

C/No:

BK8-1005321

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering:

☒ Inorder / Jammed / Leaked / Burnt or

Brake:

☒ Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / ☒ S/Rim /

STD A/Rim or

Tyre Size:

F:

205 / 45 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/5/19

D.O.I.

22/5/19

Survey held at

JC MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range + Day Repair Range 83K-84K

RECEIVED 07 JUN 2019

28/5/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format :

PRS

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2019		15 May 2019 14:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	WWB ENGINEERING, Co. Reg. No.: 53030541X								
Main Claimant:	KIANG WEE KHIM PEGGY, ID: S1344890F								
Vehicle Reg. No.:	SLD7335A	Date of Loss:	11/05/2019 15:00 - :59 [34 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202155C02	Policy/Cover Note No.:	DMCVSN30062119000 (Comprehensive) Coverage: 11/02/2019 - 10/02/2020						
Vehicle Reg. No. (Insured):	GBC8947B	Policy No. (Claimant):	5102699584 (CLASSIC)						
		Excess:	S\$0.00						
Repairer:	Jc Motor Consultancy (HQ) 71 WOOLANDS AVE 10 #02-09 WOODLANDS INDUSTRIAL XCHANGE, 737743 Woodlands - Tel: 91170086								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/05/2019]								
Driver/Custodian (Insured):	WONG KAR TAK (46 / Male), NRIC: S73724522 Email:								
Adj Asg. Remarks:	please contact Xiao Xing at 9117 0086 for PRS. workshop at 71 Woodlands Ave 10 #02-09 Woodlands Industrial Exchange Singapore 737743								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MVA119061335 / VAC - Bukit Batok
 ENTRY DATE & TIME: 11/05/2019 15:37
 SUBMITTED BY: SUSAN SEAH SOH ENG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/05/2019 15:37
Date Of Accident	11/05/2019 15:15
Exact Location Of Accident	CARPARK AT CHOA CHU KANG AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD7335A
Insured/Policyholder	
Name Of Registered Owner	KIANG WEE KHIM PEGGY
NRIC No	S1344890F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91451858
Alternative Phone No	Office-91451858
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102699584 (CLASSIC)
Cover Note Number	
Driver	
Name of Driver	KIANG WEE KHIM PEGGY
NRIC No	S1344890F
Date Of Birth	15/04/1959
Occupation	OUTDOOR
Date Of Driving Pass	02/02/1994
Driving Experience	25 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91451858

Fax Number

Contact Number

OFFICE-91451858

EMail Address

NOEMAIL

Address

425 CHOA CHU KANG AVENUE 4
#12-156

Postcode

S680425

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG THE CARPARK DRIVEWAY AT CHOA CHU KANG AVE 5 TO PICK UP A PASSENGER , IT'S A 2 WAY LANE, I WAS FOLLOWING BEHIND A VAN SLOWLY, THE SAID VAN THAT MOVED TO THE RIGHT LANE (WRONG DIRECTION OF THE LANE). UPON SEEING THE SAID VAN MOVED TO THE RIGHT , I THEN STARTED TO DRIVE STRAIGHT. ALL OF A SUDDEN, THE SAID VEHICLE TURNED TO REVERSED HIS VEHICLE TO PARKED ON THE RIGHT SIDE WITHOUT SHOWING ANY WARNING OR SIGNAL SIGN. AS A RESULT, THE FRONT LEFT PORTION OF THE SAID VAN HIT ONTO THE RIGHT SIDE PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

SENT TO INSURANCE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBC8947B

Vehicle Make/Model/Colour

VAN

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

WONG KAR TAK

6/6/2019

E-FILE

NRIC/Passport Number

S7372452Z

Contact Number

91443497

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vschb@singnet.com.sg

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

11 MAY 2019

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A hand-drawn graph on lined paper. The vertical axis (y-axis) is labeled "Distance" and the horizontal axis (x-axis) is labeled "Time". A straight line is drawn starting from the origin (0,0) and extending diagonally upwards to the right, representing a constant positive slope.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

511 Chulia Street 23
Singapore 059545
Tel: 6560 3312 Fax: 6569 0722
Email: vachb@singnet.com.sg

11 MAY 2019

Policyholder's Signature _____
Date & Time: _____

五、

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4890F
Vehicle Details	
Vehicle No.:	SLD7335A
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G A
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B3536235
Chassis No.:	GK81005321
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$17,803.00
Original Registration Date:	28 Jun 2016
First Registration Date:	28 Jun 2016
Transfer Count:	1
Actual ARF Paid:	\$7,803.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2026
PARF Rebate Amount:	\$5,852.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$38,962.00
Total Rebate Amount:	\$44,814.00

The information contained herein is correct as at 06 Jun 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 May 2019		15 May 2019 14:33 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WWB ENGINEERING, Co. Reg. No.: 53030541X		
Main Claimant:	KIANG WEE KHIM PEGGY, ID: S1344890F		
Vehicle Reg. No.:	SLD7335A	Date of Loss:	11/05/2019 15:00 - :59 [34 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202155C02	Policy/Cover Note No.:	DMCVSN30062119000 (Comprehensive) Coverage: 11/02/2019 - 10/02/2020
Vehicle Reg. No. (Insured):	GBC8947B	Policy No. (Claimant):	S102699584 (CLASSIC)
		Excess:	S\$0.00
Repairer:	Jc Motor Consultancy (HQ) 71 WOOLANDS AVE 10 #02-09 WOODLANDS INDUSTRIAL XCHANGE, 737743 Woodlands - Tel: 91170086		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 27/05/2019]		
Driver/Custodian (Insured):	WONG KAR TAK (46 / Male) , NRIC: S7372452Z Email:		
Adj Asg. Remarks:	please contact Xiao Xing at 9117 0086 for PRS, workshop at 71 Woodlands Ave 10 #02-09 Woodlands Industrial Exchange Singapore 737743		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLD7335A (SNM19D202155C02)
[GBC8947B]**


































TP








KIANG WEE KHIM PEGGY

May 11 2019 3:00PM










[WWB ENGINEERING]

Jc Motor Consultancy

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	11/05/19 16:06	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/06/19 15:54	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
19	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
20	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	06/06/19 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
33	06/06/19 15:55	Photo After Spray	 Load JPG	✓
34	06/06/19 15:55	Photo After Spray	 Load JPG	✓
35	06/06/19 15:55	Photo After Spray	 Load JPG	✓
36	06/06/19 15:55	Photo After Spray	 Load JPG	✓
37	06/06/19 15:55	Photo After Spray	 Load JPG	✓
38	06/06/19 15:55	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/05/19 14:31	INSD GBC8947B GIA REPORT	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser ▼
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	11/05/19 16:06	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	11/05/19 16:04	Accident Photo	 Load JPG	✓
2	11/05/19 16:04	Accident Photo	 Load JPG	✓
3	11/05/19 16:04	Accident Photo	 Load JPG	✓
4	11/05/19 16:04	Accident Photo	 Load JPG	✓
5	11/05/19 16:04	Accident Photo	 Load JPG	✓
6	11/05/19 16:04	Accident Photo	 Load JPG	✓
7	11/05/19 16:04	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	11/05/19 16:06	Sketch Plan	 Load TIF	
2	11/05/19 16:06	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119008625/NCD3S2

Date: 13/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30062119000		
Claimant Vehicle No :	SLD7335A	Insured Vehicle No :	GBC8947B		
Date of Loss:	11/05/2019	Nature of Claim:	TP	Claim No:	SNM19D202155C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD7335A		Engine No:	L15B3536235
Make & Model:	HONDA SHUTTLE, 1.5 (A)		Chassis No:	GK81005321
Reg. Date:	28/06/2016 (Man. Year: 2016)		Odometer:	62088 km
Colour:	White			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/45R17	Rear Tyre Size:	205/45R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/05/2019		
Date Inspected:	22/05/2019	Inspected At:	71 WOODLANDS AVENUE 10 #02-09 Repairer: JC Motor Consultancy
Estimated Period of Repair:	4.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Jun 2019)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD7335A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >