

ASS. REC. BY:

REF: CS/SMD19008678/RLSD3

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person):

Melvin Ye

of

SMD

Date/Time:

16.5.2019 12:23 p.m

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFY 3223B

Insured:

SLB 1801 X

at Workshop m/s:

WARRYS AUTOMOTIVE

Tel:

9770 4368

of

45 Long Kee Road

Policy No:

DIBMTPV01014679

Claim No:

CMTD1A02365

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14.9.2019

21.5.2019 11:30am of work

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time:

16.5.19

1:30pm

Person Contacted:

Patricia

Vehicle-IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SFY 3223B - CS/A191402220/R201302

ROA - 23/1/2014

SLB 1801 X - X

22/5/19

Send preli revised via merimen

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U005765914

Mileage

0

Work Shop :

Summary of Repair Estimates

Quotation from ARC		Adjusted by Surveyor, if applicable	
Total Labour Charges	338.00	200.00	
Total Spray Painting Charges	378.00	200.00	
Total Material Charges	120.00	120.00	
Other Charges	260.00	-70.00	
<b>TOTAL</b>	<b>1,096.00</b>	<b>450.00</b>	
Lum Sum Total	0.00	0.00	
No. of Repair Days	3.00	2.00	
Prepared / Adjusted By			
Arc / Surveyor Sing Off Date	08/05/2018 06:08:50 PM	09/05/2018 04:39:43 PM	

*(Handwritten signature)*

*(Handwritten signature)*

Prepared / Adjusted Date :

Remarks :

Prepared Date : 08/05/2018 06:08:50 PM

Signature: *Ram*

REF: SMO

0042J

ASSIGNMENT

From: \_\_\_\_\_ Date: 21.9.2019

Estimated Cost: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFY 3223B

at Workshop n/s: WEARNES Automotive

of 445 Long Ke Road

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 11.30a.m Umur waby

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 91k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS "up"

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: SFY 3223B Yr Regn: 2014 JUN

Type:  M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: LAND ROVER FREELANDER 2-2 c.c 1999

Colour: GOLD A/C: Insured / Std / NI / NA

Sp. Reading: 060470 T/Ratio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: SALFA2A96EH394300

Gen. Cond: Good  Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil  STD A/Rim or

Tyre Size: F: 235/60R18  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZ / MIC  OHTSU / PIR / SUMI / TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 14/05/19 D.O.I: 21/05/19

Survey held at: WEARNES

Des. of Damages: Fnt /  Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/06/19	Confirmed P/P \$ 13,122.38 @ 6 days with Resul. (\$ 3,785-12 Red - 22%)

RECEIVED 18 JUN 2019

*[Signature]*  
18/6/2019

Date/Time, File Pass to? 18/06/19

1) Typist

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum (L.B.) (\$ 13,122.38 p/p)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Inv: (\$)  
 Weekend (\$)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photos: \_\_\_\_\_

Others: \_\_\_\_\_

TOTAL: 461

pg 2/3

Photo Submitted	YBS / NO	Date of Submission
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Approval By	Surveyor / In-house Staff	
Acknowledged By	ARC Executive / Supervisor / SA	

For SMRT Staff

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.  
 Signature of person making this declaration  
 [to be signed in front of an authorized witness]

I, (Name) \_\_\_\_\_ do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid (Position) \_\_\_\_\_ vehicle.

Please submit photographs for damaged parts

S/N	Part Number	Part Description	Quantity	Unit Price
		WINDSCREEN SEALANT	2 pcs	/ pcc
	Labour	to spray roof panel LH		\$ 200 per
	Labour	to repair roof spec panel LH		\$ 200 100
		Repair tender tank / tank LH	1 pc	/ pc
		TANK MOUNT LOWER LASH RH 1pc		/ pcc
		TANK MOUNT LOWER BRASS LH 1pc		/ pcc

Contractor:	Accident Case Number	Vehicle No	Vehicle Model
Taxi 12/12/15	81B 1235 C	TOYOTA PRUS	
Date of Collection	Date of Request	Number of Days to Extend (if any)	
1 / 1	04/01/2018	3 24h	

REQUEST FOR SUPPLEMENT PARTS

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199507198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

<b>To:</b> Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	--

<b>Attn:</b> Melvin Ye	<b>Date:</b> 22 May 2019
------------------------	--------------------------

### Preliminary Advice

<b>Insured Vehicle No</b> : SLB1801X	
<b>TP Vehicle No</b> : SFY3223B	<b>Accident Date</b> : 14/05/2019
<b>Make</b> : LAND ROVER DISCOVERY	<b>Assignment Date</b> : 16/05/2019
<b>Date of Inspection</b> : 21/5/2019	<b>Est. Duration of Repair</b> : 6
<b>Inspection At</b> : WEARNES AUTOMOTIVE PTE LTD	

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	16,907.50
Revised Amount	:SS	14,223.80
Check Items (Estimated)	:SS	1,583.70
<b>Total</b>	<b>:SS</b>	<b>15,807.50</b>

Lump Sum Repair	:SS	
-----------------	-----	--

#### Total Loss Consideration

New for Old Value	:SS	
Pre-Accident Value	:SS	
COE / PARF Rebate	:SS	
Salvage Value	:SS	
Margin for Repair	:SS	

#### Remarks

The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments : The above survey was conducted on a 'Without Prejudice' basis.



## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 May 2019		16 May 2019 12:23 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	LIM HOCK MENG ARTHUR, ID: S1728607B								
Main Claimant:	HAN CHAN JUAN, ID: S0010042J								
Vehicle Reg. No.:	SFY3223B	Date of Loss:	14/05/2019 11:00 - :59						
Claim Type:	TP / CMTD1902365	Policy/Cover Note No.:	D18MTPV01014679 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLB1801X	Policy No. (Claimant):							
		Excess:							
Repairer:	Wearnes automotive Pte Ltd (HQ) 45 LENG KEE ROAD, 159103 Leng Kee - Tel: 64737755								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/05/2019]								
Driver/Custodian (Insured):	ZHANG LINGYUN (), NRIC: S7682771J, Tel: +6590175186 Email:								
Adj Asg. Remarks:	WS: PATRICIA 9770 4368 D: 6378 9336 - PLS ARR SUV ON 17.05.19 at 10am-11am								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All   Search Tasks   Create New Task   Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Tuesday, 18 June 2019 3:30 PM  
**To:** 'Patricia Kueh Anak Slin'; Rasul (LKKAuto)  
**Cc:** 'Paul Ong Qing Yong'  
**Subject:** RE: SFY3223B Finalise

Dear Patricia,

Confirmed final fig of \$ 13,122.38 (part by part) @ 6 days of repairs before GST.

Final invoice and all supporting documents sent over to Sompo Insurance Singapore Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Patricia Kueh Anak Slin [mailto:[patricia.kueh@wearnes.com](mailto:patricia.kueh@wearnes.com)]  
**Sent:** Friday, 14 June 2019 5:46 PM  
**To:** Rasul@lkkauto.com  
**Cc:** Paul Ong Qing Yong <[paul.ong@wearnes.com](mailto:paul.ong@wearnes.com)>  
**Subject:** SFY3223B Finalise

Hi,

Please refer above attachments for final bill.

Thank you.

Best Regards,

**Patricia Kueh**  
Service Consultant  
Bodyshop & Paint



**Wearnes Automotive Pte Ltd**  
249 Alexandra Road Singapore 159935  
M (65) 9770 4368 D (65) 6378 9336  
[www.wearnesauto.com](http://www.wearnesauto.com) [patricia.kueh@wearnes.com](mailto:patricia.kueh@wearnes.com)

*This email, including any attachment, is confidential and may also be privileged.  
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.  
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

VEHICLE OWNER INFORMATION	
Owner ID Type:	Singapore NRIC
Owner ID:	0042J
VEHICLE DETAILS	
Vehicle No.:	SFY3223B
Vehicle to be Exported:	No
Intended Deregistration Date:	23 May 2019
Vehicle Make:	LAND ROVER
Vehicle Model:	FREELANDER 2 2.0 I4
Primary Colour:	Beige
Manufacturing Year:	2014
Engine No.:	300913082621204PT
Chassis No.:	SALFA2AG6EH394300
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$44,675.00
Original Registration Date:	26 Jun 2014
First Registration Date:	26 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$54,545.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2024
PARF Rebate Amount:	\$40,908.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$67,290.00
COE Rebate Amount:	\$34,243.00
<b>Total Rebate Amount:</b>	<b>\$75,151.00</b>

The information contained herein is correct as at 23 May 2019

OK

91,000  
 75,151  
 -----  
 15,849  
 -----



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/05/2019 15:22
Date Of Accident	14/05/2019 11:00
Exact Location Of Accident	SAINT ANDREW'S ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFY3223B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HAN CHAN JUAN
NRIC No	S0010042J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98166006
Alternative Phone No	OFFICE-98166006

### Vehicle Particulars

Manufacturer	LAND ROVER
Model	DISCOVERY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM110137131404 (COMP)
Cover Note Number	

### Driver

Name of Driver	HAN LIGUANG
NRIC No	S8534152I
Date Of Birth	12/11/1985
Occupation	INDOOR
Date Of Driving Pass	02/09/2010
Driving Experience	8 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98283083
Fax Number	
Contact Number	OTHERS-98283083
Email Address	HANLG@LABYRINTH.COM.SG



Address	58 TREVOSE CRESCENT #03-13
Postcode	298089
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN

Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS EXITING PARLIAMENT PLACE MERGING ONTO SAINT ANDREW'S ROAD WHEN I BRAKED AT THE EXIT TO ALLOW ON COMING VEHICLE FROM ST ANDREW'S ROAD TO PASS BY BEFORE MERGING ONTO ST ANDREW'S ROAD. THE MOMENT I BRAKED, SLB 1801X HIT MY CAR FROM BEHIND, CAUSING THE ACCDIENT. AS PER WRITTEN REPORT. (ATTENDED BY CHRISTINA)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB1801X
Vehicle Make/Model/Colour	VOLVO
Details Of Properties	N/A
Vehicle Category	PRIVATE CAR
Name of Driver	ZHANG LINGYUN
NRIC/Passport Number	S7682771J
Contact Number	90175186
Address	N/A
Postcode	N/A
Insurance Company Name	
Nature Of Damage	FRONT PORTION
No. Of Passenger (Including Driver)	1



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*[Handwritten Signature]*  
14 MAY 2019  
14/5/19 1530 hrs





SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

~~Being~~ I was exiting Parliament place merging onto Saint Andrew's Road when I braked to allow an on coming vehicle from St Andrew's Road <sup>at the exit</sup> to pass by before merging onto St Andrew's Road. The moment I braked, SLB1801X hit my car from behind, causing the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

14 MAY 2019



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 14/5/2019,  
15:30hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





SERVICE ESTIMATE

77849 - C00001 SL: SERVICE SALES - PC

Mr Han Han Chan Juan  
58 Trevoze Crescent  
#03-13 The Trevoze

Singapore 298089

GST Reg.No: M28920628X  
Inv.No. : B&P 0 Page 1  
Inv.date. : 15/05/2019  
WIP No. : 15069  
Veh.In/Out:  
\*Tel.No. : Mobile: 98166006  
Reg.No. : SFY32238  
Reg.date : 26/06/2014  
Mileage : 0  
Chassis No: SALFA2AG6EH394300

Closed by : Patricia Kueh Anak S  
Svc Consultant :  
Remarks : Mr Han Chan Juan

Op.No Description Mech Qty Price Disc% Pkg Amount G

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, TAILGATE, PARKING SENSOR REAR RH, ETC		0	3000.00	0		<del>3,000.00</del>	\$ 2800
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, TAILGATE, ETC		0	2500.00	0		<del>2,500.00</del>	\$ 2000
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	486.00	0		486.00	\$ /
802	TO TRANSFER TAILGATE PARTS		0	500.00	0		500.00	\$ /
802	TO REPLACE REAR WINDSCREEN		0	1200.00	0		1,200.00	\$ / 600
0080	TO REPLACE REAR WINDSCREEN FIL		0	280.00	0		280.00	\$ /
	BUMPER COVER REAR FL	DE	1.0 EA	1852.80			1,852.80	\$ 167.52
	POC HOLDER REAR RH D	DE	1.0 EA	65.10			65.10	\$ 58.59
	POC HOLDER REAR IHNE	DE	2.0 EA	65.10			130.20	\$ 117.18
	POC HOLDER REAR LH D	DE	1.0 EA	65.10			65.10	\$ 58.59
	BUMPER BRACKET REAR	DE	1.0 EA	122.10			122.10	\$ X
	BUMPER BRACKET REAR	DE	1.0 EA	122.10			122.10	\$ X
	BUMPER BEAM REAR FL2	DE	1.0 EA	911.80			911.80	\$ X
	BUMPER TRIM REAR FL2	DE	1.0 EA	181.60			181.60	\$ 168.44



**SERVICE ESTIMATE**

77849 - C00001 SL: SERVICE SALES - PC

Mr Han Han Chan Juan  
58 Trevoze Crescent  
#03-13 The Trevoze

Singapore 298089

GST Reg.No: M28920628X  
Inv.No. : B8P 0 Page 2  
Inv.date. : 15/05/2019  
WIP No. : 15069  
Veh.In/Out:  
\*Tel.No. : Mobile: 98166006  
Reg.No. : SFY32238  
Reg.date. : 26/06/2014  
Mileage : 0  
Chassis No: SALFA2AG6EH394300

Closed by .... : Patricia Kueh Anak S  
Svc Consultant :  
Remarks ..... : Mr Han Chan Juan

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	B
-------	-------------	----------	-------	-------	-----	--------	---

*Monte*  
*23/5/19*  
*Passive*  
*Hp 90000068*  
*6 days*  
*21/05/19 @ 1145*  
*Ready before paint*

	BUMPER BRACKET REAR	1.0 EA	167.30			167.30	S X
	PARKING AID Straight	1.0 EA	225.60			225.60	S 203.04
	LOGO 'FREELANDER 2'	1.0 EA	208.40			208.40	S 187.56
	LOGO REAR FL2 BH0000	1.0 EA	39.10			39.10	S 35.19
	BADGE S14 HSE	1.0 EA	143.90			143.90	S 129.51
	BOOT REAR FL2 BH0000	1.0 EA	3076.80			3,076.80	S 2769.12
	WINDSCREEN REAR FL2	1.0 EA	1296.40			1,296.40	S 1166.76
	LLR002238/WINDSCREEN	4.0 EA	5.90			23.60	S 21.24
	*D* PRIMER GLASS & P	1.0 EA	37.40			37.40	S 33.66
	ADHESIVE AND SEALER	2.0 EA	136.10			272.20	S 244.98

Gross Total. 16,907.50

Labour Total 7,966.00  
Parts Total 8,941.50  
Package Total 0.00

Net..... 16,907.50  
GST @ 7.0% 1,183.53  
Total..... 18,091.05  
Paid..... 0.00  
Please Pay... 18,091.05

GST: S=StdRated; O=OutOfScope; Z=ZeroRated







### SERVICE ESTIMATE

0 - T00003	SL: SOMPO INSURANCE SINGAPORE PTE LTD
SOMPO INSURANCE SINGAPORE PTE LTD	GST Reg.No:M28920628X
50 RAFFLES PLACE #05-01/06	Inv.No. . : B&P 0 Page 1
SINGAPORE LAND TOWER	Inv.date. : 14/06/2019
SINGAPORE 048623	WIP No. . : 15069
	Veh.In/Out: 24/05/2019 14/06/2019
	*Tel.No. . : 63295160
	Reg.No. . : 3FY3223B
Closed by .... : Patricia Kueh Anak S	Reg.date .: 26/06/2014
Svc Consultant : ACC	Mileage ..: 60,500
Remarks ..... : Mr Han Chan Juan	Chassis No: SALFA2AG6EH394300

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, TAILGATE,PARKING SENSOR REAR RH, ETC	0	2400.00	0		2,400.00	S
800	TO PUTTY SPRAYPAINT ON REAR BUMPER,TAILGATE,ETC	0	2000.00	0		2,000.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
802	TO TRANSFER TAILGATE PARTS	0	500.00	0		500.00	S
802	TO REPLACE REAR WINDSCREEN	0	600.00	0		600.00	S
0080	TO REPLACE REAR WINDSCREEN FIL	0	280.00	0		280.00	S
	BUMPER COVER REAR FL	1.0 EA	1852.80	10		1,667.52	S
	BUMPER TRIM REAR FL2	1.0 EA	181.60	10		163.44	S
	PARKING AID Straight	1.0 EA	225.60	10		203.04	S
	LOGO 'FREELANDER 2'	1.0 EA	208.40	10		187.56	S
	LOGO REAR FL2 BH0000	1.0 EA	39.10	10		35.19	S
	BADGE S14 HSE	1.0 EA	143.90	10		127.51	S
	BOOT REAR FL2 BH0000	1.0 EA	3076.80	10		2,769.12	S
	WINDSCREEN REAR FL2	1.0 EA	1296.40	10		1,166.76	S



## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19008678/R1SD3N2

Date: 19/06/2019

#### REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01014679
Claimant Vehicle No :	SFY3223B	Insured Vehicle No :	SLB1801X
Date of Loss:	14/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902365

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFY3223B	Engine No:	300913082621204PT
Make & Model:	LAND ROVER DISCOVERY, 3 4.4 (A)	Chassis No:	SALFA2AG6EH394300
Reg. Date:	26/06/2014 (Man. Year: 2014)	Odometer:	60420 km
Colour:	Gold		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	235/60R18	Rear Tyre Size:	235/60R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,941.50	6,856.38	2,085.12	23.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,966.00	6,266.00	1,700.00	21.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,907.50</b>	<b>13,122.38</b>	<b>3,785.12</b>	<b>22.39</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,183.53</b>	<b>918.57</b>	<b>264.96</b>	<b>22.39</b>
<b>Nett Amount (S\$)</b>	<b>18,091.03</b>	<b>14,040.95</b>	<b>4,050.08</b>	<b>22.39</b>

#### INSPECTION

Date of Assignment:	16/05/2019	Inspected At:	Wearnes automotive Pte Ltd (HQ)
Date Inspected:	21/05/2019		45 LENG KEE ROAD
			Singapore 159103
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

Reference	
Part Source:	MRM-SG Version: 1.0 (Last Synchronised: 19 Jun 2019)
Parts:	192 LAND ROVER DISCOVERY 3 4.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFY3223B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR FL	Deformed	1,852.80 FS	*1,667.52 FS
2	1		*PDC HOLDER REAR RH 0	Necessary	65.10 FS	*58.59 FS
3	2		*PDC HOLDER REAR INNE	Necessary	130.20 FS	*117.18 FS
4	1		*PDC HOLDER REAR LH 0	Necessary	65.10 FS	*58.59 FS
5	1		*BUMPER BRACKET REAR	Serviceable	122.10 FS	*- FS
6	1		*BUMPER BRACKET REAR	Serviceable	122.10 FS	*- FS
7	1		*BUMPER BEAM REAR FL2	Serviceable	911.80 FS	*- FS
8	1		*BUMPER TRIM REAR FL2	Deformed	181.60 FS	*163.44 FS
9	1		*BUMPER BRACKET REAR	Serviceable	167.30 FS	*- FS
10	1		*PARKING AID STRAIGHT	Necessary	225.60 FS	*203.04 FS
11	1		*LOGO FREELANDER 2	Necessary	208.40 FS	*187.56 FS
12	1		*LOGO REAR FL2 BH0000	Necessary	39.10 FS	*35.19 FS
13	1		*BADGE SI4 HSE	Necessary	143.90 FS	*129.51 FS
14	1		*BOOT REAR FL2 BH0000	Bent	3,076.80 FS	*2,769.12 FS
15	1		*WINDSCREEN REAR FL2	Necessary	1,296.40 FS	*1,166.76 FS
16	4		*LLR002238/WINDSCREEN	Necessary	23.60 FS	*21.24 FS
17	1		**D* PRIMER GLASS & P	Necessary	37.40 FS	*33.66 FS
18	2		*ADHESIVE AND SEALER	Necessary	272.20 FS	*244.98 FS
<b>Total Parts (\$\$)</b>					<b>8,941.50</b>	<b>6,856.38</b>

F=Franchise part. S=SpocNett.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER, TAILGATE, PARKING SENSOR REAR RH, ETC	New	3,000.00	2,400.00
2	TO PUTTY SPRAYPAINT ON REAR BUMPER, TAILGATE ETC	New	2,500.00	2,000.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	486.00	486.00
4	TO TRANSFER TAILGATE PARTS	New	500.00	500.00
5	TO REPLACE REAR WINDSCREEN	New	1,200.00	600.00
6	TO REPLACE REAR WINDSCREEN FIL	New	280.00	280.00
<b>Gross Labour Cost (S\$)</b>			<b>7,966.00</b>	<b>6,266.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

