

ASS. REC. BY:

REF: (S3/C1219008683/Ecd30)

Special Instruction:

26/6/19

Survivor: Steve

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

C12

Date/Time: 16.5.19 10.36am

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 9702K

Insured:

GBJ 34642

at Workshop m/s

MS Car Auto Pte Ltd

Tel:

9725 4442

of 8 Kaki Bukit Ave 4 #01-07

Policy No:

Claim No: SNM19D202106

Sum Insured:

Excess:

Make of Veh:

D.O.A. 4.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"rup"

H.O.D. Endorsement:

Date/Time: 16.5.19 1.47pm

Person Contacted:

Desmond

Vehicle ~~IN~~ / OUT

Date/Time:

Action/Instruction (X) Estimate Inspector at #06-21

SLW 9702J -X

GBJ 34642 -X

No movement

Dismantle: 17/5/2019

After repair: 23/5/2019

PRIS

Steve

REF: 01

ASSIGNMENT

From: Date: 16.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 9702 J

at Workshop m/s ms car Auto

of 8 Kaki Bukit Ave 4 # 06-21

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "wp"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLW 9702 K Yr Reg: 25/6/15

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel 1.5X C.C. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 39249 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: R41191 7905

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 4/5/19 D.O.I. 16/5/19

Survey held at MS car

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair range - 4K - 5K
Days - 5
MV - 60K

[Signature]

17/5/2019

RECEIVED 01 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

150

Transportation,

) \$ + RS, SI

) Photos

) Others

TOTAL

150

Report Format : PRS

Lump Sum / I.B.I. (\$))

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		27 Jun 2019 11:55 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	KHONG HUI MIN (KANG HUIMIN), ID: S7814970A			
Vehicle Reg. No.:	SLW9702K	Date of Loss:	04/05/2019 00:00 - :59	
Claim Type:	TP	Policy/Cover Note No.:		
Vehicle Reg. No. (Insured):	GBJ3464Z	Policy No. (Claimant):	5099942332	
		Excess:	S\$0.00	
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 08/07/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 16 May 2019 10:36 AM
To: Chia Jia Rong
Cc: Admin-D (LKKAuto)
Subject: RE: SNM19D202106 / GBJ3464Z YOUR REF: MKR/307/8947/2019/ASJR

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chia Jia Rong [mailto:jiarong@roypartners.com.sg]
Sent: Thursday, 16 May, 2019 9:54 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: SNM19D202106 / GBJ3464Z YOUR REF: MKR/307/8947/2019/ASJR

Dear Sirs,

We refer to the above matter and your email on even date.

Our client rejects your list of proposed motor surveyors.

Our client does not have a list of 10 motor surveyors. Our client propose their motor surveyor namely Mr. Patrick Ng from CarLink Consultancy and Mr. Dave from Sincere Appraisal as the Single Joint Expert

Pursuant to the new NIMA protocol, kindly let us know within **2 working days** of receipt of our letter whether you agree or have any objection to any of the motor surveyors proposed by our client, failing which you are deemed to have agreed to the appointment of any of the motor surveyors listed by our client.

With regards,

Chia Jia Rong

M/s Roy & Partners

101 Cecil Street

#11-09 Tong Eng Building

Singapore 069533

Tel : 6536 8466 Fax : 6536 1963

Email : jiarong@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Thursday, 16 May, 2019 9:45 AM

To: jiarong@roypartners.com.sg

Subject: SNM19D202106 / GBJ3464Z YOUR REF: MKR/307/8947/2019/AS.JR

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 16 May 2019 11:06 AM
To: Admin-D (LKKAuto); 'Chia Jia Rong'
Cc: assignments
Subject: RE: SNM19D202106 / GBJ3464Z YOUR REF: MKR/307/8947/2019/AS.JR

M/S MS car auto pte ltd no 8 kaki bukit ave 4, #01-07 premier @ kaki bukit, s415875

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 16 May, 2019 11:04 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; 'Chia Jia Rong' <jiarong@roypartners.com.sg>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: SNM19D202106 / GBJ3464Z YOUR REF: MKR/307/8947/2019/AS.JR

Dear Sir/Mdm,

Thank you for the assignment.

Kindly assist to provide us the workshop details.

Best Regards,

G.Nivitha| Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]
Sent: Thursday, 16 May 2019 10:36 AM
To: Chia Jia Rong <jiarong@roypartners.com.sg>
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: RE: SNM19D202106 / GBJ3464Z YOUR REF: MKR/307/8947/2019/AS.JR

WITHOUT PREJUDICE

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4970A
Vehicle Details	
Vehicle No.:	SLW9702K
Vehicle to be Exported:	No
Intended Deregistration Date:	16 May 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X AUTO
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B3517023
Chassis No.:	RU11017005
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,589.00
Original Registration Date:	25 Jun 2015
First Registration Date:	25 Jun 2015
Transfer Count:	1
Actual ARF Paid:	\$8,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2025
PARF Rebate Amount:	\$6,441.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$37,243.00
Total Rebate Amount:	\$43,684.00

The information contained herein is correct as at 16 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/05/2019 11:35
Date Of Accident	04/05/2019 00:15
Exact Location Of Accident	YISHUN AVE 6 OSCP BLK 288
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW9702K
Insured/Policyholder	
Name Of Registered Owner	KHONG HUI MIN (KANG HUIMIN)
NRIC No	S7814970A
Email Address	KHONGHUIMIN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98519848
Alternative Phone No	OTHERS-98519848

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099942332
Cover Note Number	20/04/2018 - 24/06/2019

Driver

Name of Driver	KHONG HUI MIN (KANG HUIMIN)
NRIC No	S7814970A
Date Of Birth	29/05/1978
Occupation	INDOOR
Date Of Driving Pass	04/09/2006
Driving Experience	12 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98519848
Fax Number	
Contact Number	OTHERS-98519848
EEmail Address	KHONGHUIMIN@GMAIL.COM

Address	BLK 716 YISHUN ST 71 #09-250
Postcode	760716
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT (T/20190504/2025)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ3464Z
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SCK3138Z
Vehicle Make/Model/Colour	BMW
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	3855M
Vehicle Make/Model/Colour	KIA
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN



REFER TO POLICE REPORT (T/20190504/2025)

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 4/5/2019 11:49
 Policyholder's Signature
 Date & Time:

4/5/2019 11:49
 Driver's Signature (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: Chen JunLiang
 NRIC/ Fin No: S990765

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Report No: M1

D.O.A:

Vehicle No:

Make / Model:

Report Date: 4/5/2019 Start Time: 11:54 AM

Reporting Type: 7P End Time: / /

SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.


Policyholder's Signature
Date & Time: 4/5/2019 11:49


Driver's Signature (If driver is not the policyholder)
Date & Time: 4/5/2019 11:49


Reporting Centre Personnel's Signature
Name: Chen JunLiang
NRIC/ Fin No: S990765



**SINGAPORE
POLICE FORCE**



T/20190504/2025

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No. T/20190504/2025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/05/2019 08:49			Vide Report No.: L/20190504/0001		Station Diary No.: 23
Informant's Particulars					
Name of Informant: KHONG HUI MIN			Address: APT BLK 716 YISHUN STREET 71 #09-250 SINGAPORE 760716		
ID Type / ID No.: NRIC NO / S7814970A			Contact No.: Home/Office: Mobile: 98519848		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 40	Date of Birth: 29/05/1978	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: Personnel/Human resource officer			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/05/2019 00:15	Type of Location:
Location: Along Road 1 YISHUN AVENUE 6 At Blk 288 Yishun Ave 6 open carpark lot no. 159				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBJ3464Z	Lorry	TOYOTA		Grey		0
SLW9702K	Car	HONDA		Black	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190504/2025

2 of 3

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20190504/2025

CONTINUATION OF REPORT

Vehicle Owner			
Name	KHONG HUI MIN	ID No.	S7814970A
Related Vehicle	NIL	Contact No.	98519848
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 03/05/2019 at about 2245hrs, I parked my vehicle(SLW9702K) at Blk 288 Yishun Ave 6 carpark lot no.159.

On 04/05/2019 at about 0015hrs, I discovered my vehicle damaged at the front after being hit by a lorry(GBJ3464Z). However, I did not see how the said lorry collided into my vehicle.

Case was tagged under TP DD IO Affendy.



**SINGAPORE
POLICE FORCE**



T/20190504/2025

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20190504/2025

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Sgt 2 MUHAMMAD KHIDHIR BIN MOHAMED RAZUWAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 04/05/2019 08:49
Officer In Charge Of Case: TP / GIT / SI MOHAMMAD ABDILLAH BIN PALIL Contact No.: 65476246	Classification Of Case:
Authentication Stamp NP168	

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jul 2019 15:13		27 Jun 2019 11:55 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	KHONG HUI MIN (KANG HUIMIN) , ID: S7814970A								
Vehicle Reg. No.:	SLW9702K	Date of Loss:	04/05/2019 00:00 - :59 [46 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	GBJ3464Z	Policy No. (Claimant):	5099942332						
		Excess:	S\$0.00						
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 08/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents















*SLW9702K
[GBJ3464Z]
TP
KHONG HUI MIN (KANG HUIMIN)
May 4 2019 12:00AM
[-]
Ms Car Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print					
1	04/05/19 12:13	Accident Statement		Load HTM						
							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print					
1	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
10	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
11	04/05/19 11:44	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
2	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
3	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
4	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
5	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
6	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
7	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
8	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
9	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
10	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
11	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
12	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
13	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
14	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
15	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
16	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
17	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					
18	01/07/19 11:12	General View		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
19	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
29	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
30	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
31	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
32	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
33	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
34	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
35	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
36	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
37	01/07/19 11:12	General View	 Load JPG	<input checked="" type="checkbox"/>
38	01/07/19 11:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	01/07/19 11:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	01/07/19 11:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	01/07/19 11:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	01/07/19 11:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	01/07/19 11:14	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	01/07/19 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
69	01/07/19 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	01/07/19 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	01/07/19 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	01/07/19 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	01/07/19 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	01/07/19 11:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/06/19 11:55	pri contact	 Load PDF	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	04/05/19 12:03	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	
2	04/05/19 12:11	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	04/05/19 12:13	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	04/05/19 11:44	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	04/05/19 12:03	POLICE REPORT	 Load TIF	
2	04/05/19 12:11	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19008683/ECD3E2

Date: 01/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No : SLW9702K

Insured Vehicle No : GBJ3464Z

Date of Loss: 04/05/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW9702K**

Make & Model: HONDA VEZEL, 1.5 X (A)

Reg. Date: 25/06/2015 (Man. Year: 2015)

Colour: Black

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: L15B3517023

Chassis No: RU11017005

Odometer: 39249 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Hankook 7 mm

Rear Left Side:

Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side:

Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/06/2019

Date Inspected: 16/05/2019 Inspected At:

Ms Car Auto Pte Ltd (HQ)

8 KAKI BUKIT AVE 4 #01-07 PREMIER @

KAKI BUKIT

Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Jul 2019)

Parts: M1-SUV HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW9702K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >