

REF: CS3/MSG/9008736/RIC d3d Special Instruction:

Surveyor: Rasu ASSIGNMENT (Office)

From (Person): Pauline Tham of MSIG Date/Time: 16.5.19 16.32p.m

Estimated Cost: _____ Bill to: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JMC 2525 Insured: SGY 6146 J

at Workshop m/s DSC motor Tel: 9272 0009

of 25 kaki Bukit Road 4 #05-49

Policy No: 60271452 Claim No: 592682

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 4.5. 2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 11.5.19 5:11 PM Person Contacted: Derrick Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	Jmc 2525 -x
	SGY 61463 -x

PRS


REF: MSIG

ASSIGNMENT

From: . Date: 17.5.2019
 Estimated Cost:
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: JMC 2525
 at Workshop m/s DSC motor
 of 25 Kaki Bukit Road 4 # 05-49
 Insured:
 Policy No.
 Claims No.
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS my

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: JMC 2525 Yr Regn:
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: YAMAHA 135LC C.C 135
 Colour: Red A/C Insured / Std / NI / NA
 Sp. Reading: 37853 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No:
 Gen. Cond: Good Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 70/90-17
 R: 80/90-17
 BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. mm L/Bal. mm
 D.O.A. 04/05/19 D.O.I. 17/05/19
 Survey held at DSC motor
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 N/S Frt & O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- (2K - 3K) / 4 days

RECEIVED 19 JUN 2019

13/6/2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: -

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format : PRS

Lump Sum / I.B.I: (\$)

120

11

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 May 2019		16 May 2019 16:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	ZHANG CHUNYAN, ID: S7479097F, Tel: +6588667472		
Main Claimant:	MARZUKI BIN BAKAR, ID: F7831639W		
Vehicle Reg. No.:	JMC2525	Date of Loss:	04/05/2019 11:00 - :59
Claim Type:	TP / 592682	Policy/Cover Note No.:	60271452 (Comprehensive) Coverage: 01/10/2018 - 30/09/2019
Vehicle Reg. No. (Insured):	SGY6146J	Policy No. (Claimant):	
		Excess:	
Repairer:	Dsc Motor Lip (HQ) 25 KAKI BUKIT ROAD 4, #05-49, 417800 Kaki Bukit - Tel: 92720009		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/05/2019]		
Driver/Custodian (Insured):	ZOU YU (), NRIC: S7280499F, Tel: +6594793567 Email:		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: DISPUTE. CONTACT: DERRICK CHEO 9272 0009		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS								View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?		
No results.											

15 MAY 2019

MAHADI ABU BAKAR & PARTNERS

ADVOCATES & SOLICITORS

(UEN No. 53179837B)

#14-01, TONG ENG BUILDING, 101 CECIL STREET SINGAPORE 069533

TEL: 62252355 FAX: 62279913 email: mab_law06@yahoo.com.sg

SL/Has-

YOUR REF: SGY 6146 J

15 May 2019

OUR REF: MAB/10779/19/zila

ZOU YU

9 Serangoon Garden Place

Singapore 554439

Dear Sirs

CLAIMANT: MR MARZUKI BIN ABU BAKAR**ACCIDENT INVOLVING SGY 6146 J & JMC 2525 ALONG THE T-JUNCTION OF YIO CHU KANG ROAD & SERANGOON GARDEN WAY ON THE 04/05/2019 AT 11.00 AM**

We are instructed by *Mr Marzuki Bin Abu Bakar* to notify you of a road traffic accident on 04/05/2019 at 11.00 am along the T-Junction of Yio chu Kang Road & Serangoon Garden Way involving our client's vehicle registration number *JMC 2525* and vehicle registration number *SGY 6146 J* driven by you at the material time. A copy of the Singapore Accident Statement and/or Traffic Police Report filed are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

cc. 1) Client

- 2) Claims Department
MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01
SGX Centre 2
Singapore 068807
YOUR REF: SGY 6146 J

FAX & MAIL
6225 7402**URGENT**

enc


**SINGAPORE
POLICE FORCE**


T/20190510/2077

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190510/2077

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/05/2019 13:20		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MARZUKI BIN BAKAR			Address: C/O APT BLK 1001 EUNOS AVENUE 8 #04-24 EUNOS INDUSTRIAL ESTATE SINGAPORE 409496		
ID Type / ID No.: FIN NO / F7831639W			Contact No.: Home/Office: 0197672552 Mobile: 90522573		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 44	Date of Birth: 07/06/1974	Type of Informant: Rider		
Race:			Language:	Institution / School Name:	
Occupation: OTHERS			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 04/05/2019 11:00	Type of Location: T-Junction
Location: Along Road 1 YIO CHU KANG ROAD SERANGOON GARDEN WAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JMC2525	Motorcycle					0
SGY6146J	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190510/2077

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190510/2077

CONTINUATION OF REPORT

Rider			
Name	MARZUKI BIN BAKAR	ID No.	F7831639W
Related Vehicle	NIL	Contact No.	0197672552
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	04/05/2019	Date Discharge	10/05/2019
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE & LOCATION,

I WAS RIDING MY BIKE ALONG THE T-JUNCTION. TRAFFIC LIGHT WAS GREEN IN MY FAVOUR. I WAS GOING STRAIGHT TOWARDS YIO CHU KANG RD. THE OTHER DRIVER WAS COMING ALONG AT THE OPPOSITE LANE. SUDDENLY THE DRIVER TURNED TO THE RIGHT WITHOUT GIVING ME WAY AND HE NEVER STOP AT THE WHITE LINE.

I HORNED AT THE DRIVER TO ALERT, AND I APPLIED TO MY EMERGENCY BRAKE.

BUT I COULDN'T STOP IN TIME AND COLLIDED ON THE CAR.

I SUSTAINED INJURY AND WAS BROUGHT OVER TO THE HOSPITAL.

THATS ALL



**SINGAPORE
POLICE FORCE**



T/20190510/2077

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190510/2077

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

TP /

YOGENDRAN S/O RAJASAKARAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sgt 3 MUHAMMAD RIZWAN BIN KAMALUDIN

Contact No.: 65476185

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

10/05/2019 13:20

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 May 2019		16 May 2019 16:32 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ZHANG CHUNYAN , ID: S7479097F, Tel: +6588667472								
Main Claimant:	MARZUKI BIN BAKAR , ID: F7831639W								
Vehicle Reg. No.:	JMC2525	Date of Loss:	04/05/2019 11:00 - :59						
Claim Type:	TP / 592682	Policy/Cover Note No.:	60271452 (Comprehensive) Coverage: 01/10/2018 - 30/09/2019						
Vehicle Reg. No. (Insured):	SGY6146J	Policy No. (Claimant):							
		Excess:							
Repairer:	Dsc Motor Llp (HQ) 25 KAKI BUKIT ROAD 4, #05-49, 417800 Kaki Bukit - Tel: 92720009								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 17/05/2019]								
Driver/Custodian (Insured):	ZOU YU (), NRIC: S7280499F, Tel: +6594793567 Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: DISPUTE. CONTACT: DERRICK CHEO 9272 0009								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JMC2525 (592682)
[SGY6146J]



































TP























MARZUKI BIN BAKAR

May 4 2019 11:00AM

[ZHANG CHUNYAN]

Dsc Motor Llp

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/05/19 10:51	Accident Statement From: SC - Reg. No: SGY6146J, Claimant: ZHANG CHUNYAN	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
2	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
3	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
4	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
5	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
6	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
7	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
8	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
9	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
10	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
11	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
12	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
13	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
14	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
15	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
16	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
17	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
21	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/05/19 11:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
49	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
50	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
51	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
52	28/05/19 11:36	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/05/19 10:51	PRI & TP DETAILS From: SC - Reg. No: SGY6146J, Claimant: ZHANG CHUNYAN	 Load PDF	
2	16/05/19 14:43	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	
3	16/05/19 14:57	EMAIL FROM TP ON WORKSHOP DETAILS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19008736/R1CD3E2

Date: 08/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 60271452

Claimant Vehicle No : JMC2525

Insured Vehicle No : SGY6146J

Date of Loss: 04/05/2019

Nature of Claim: TP

Claim No: 592682

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JMC2525

Make & Model: YAMAHA 135LC, 135cc ES

Reg. Date: (Man. Year:)

Colour: Red

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: HIDDEN

Chassis No: HIDDEN

Odometer: 37853 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size: 80/90-17

Front Left Side: Dunlop 3 mm

Rear Left Side: Dunlop 3 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/05/2019

Date Inspected: 17/05/2019 Inspected At:

Dsc Motor Llp (HQ)
25 KAKI BUKIT ROAD 4, #05-49
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 -\$3,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Jun 2019)	
Parts:	N/A	YAMAHA 135LC 135cc ES (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JMC2525)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >