

22/03/2019

ASS. REC. BY:

REF: CS/MSG19008774/Klgd3⁵² Special Instruction:Surrey: Kalvin

ASSIGNMENT (Office)

From (Person): Winnie chuaof MSIGDate/Time: 16/5/19 4.18pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHC 6642YInsured: IMDEX281at Workshop m/s Premier AutomotiveTel: 6544 6689of 23 chengj south Ave 2 # 01-02Policy No: 2917347807AClaim No: 593862

Sum Insured: _____

Excess: _____

Make of Veh:

D.O.A. 15/05/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10.18am @ 17/5/19Person Contacted: VincentVehicle IN OUT

Date/Time	Action/Instruction	Initials
	SHC 6642Y - CS/MSG19018438/Klgbn2	Don: 23/9/2017
	IMDEX281 - X	
71/5/19 @ 244M	revised to msg by email.	

Bureau: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Surv: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN/OUT

Veh No: SHC 6642Y Yr Regt: 27 Feb, 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima cc 1685

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 392293 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAHM44MF5578376

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / 6 STD A/Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxys

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 15/5/19 D.O.I. 17/5/19

Survey held at Premier

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

n/s Bulb

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>21/6/19</u>	<u>Chk u/s \$1850 / 4 Rys. (Red B 57369, 24%)</u> <u>MS26</u>

RECEIVED 24 JUN 2019

21/6/2019

Date/Time, File Pass to?

☐ : Prell. Report

11/7/6 Final

☐ : Final Report

Date/Time, File Return to?

3

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: 150

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

Report Format: MER-P

Lump Sum / L.R.I: (\$ 1850)

11

Nivitha (LKK Auto)

From: Motor Survey <motorsurvey@sg.msig-asia.com>
Sent: Thursday, 16 May 2019 4:18 PM
To: Vincent Chua
Cc: Venessa Chan; Nabilah Rasol; Goh Wee Dek; Liew Hai Leong; Crystal Lee; Ong Zi Hui; assignments
Subject: RE: Pre-inspection/Accident involving SHC6642Y and IMDEX281 on 15.05.19

Dear Vincent,

Thank you on your selection of LKK Auto Consultants Pte Ltd

We will proceed to appoint LKK Auto Consultants Pte Ltd via manual assignment first at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol

Thank you.

Dear LKK,

Please assign surveyor for TP Claim. Tks.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Vincent Chua [mailto:vincent.chua@premiertaxi.com]

Sent: Thursday, 16 May 2019 2:24 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Cc: Venessa Chan <venessa_chan@sg.msig-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>; Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>

Subject: RE: Pre-inspection/Accident involving SHC6642Y and IMDEX281 on 15.05.19

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

We would like to appoint Mr Calvin Ang of "LKK Auto Consultants" as the SJE for this PRS.

Please kindly arrange for survey soonest.

Vehicle available for survey at any time



Thank you for your time.

Regards

Vincent Chua
Operations Assistant
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 

From: Motor Survey [<mailto:motorsurvey@sg.msig-asia.com>]
Sent: Thursday, 16 May, 2019 2:17 PM
To: Vincent Chua <vincent.chua@premiertaxi.com>
Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>; Venessa Chan <venessa_chan@sg.msig-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>
Subject: Pre-inspection/Accident involving SHC6642Y and IMDEX281 on 15.05.19

Dear Vincent,

We refer to your email on 16.05.19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors**

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

- 1 Calvin Ang
- 2 Kenneth Kong
- 3 Marcus Chua
- 4 Henry Ng
- 5 Lau Kwok Kwong

6 Frankie Pang
7 Ng You Han
8 Gary Soon
9 Chow Bo Xiong
10 Axel Lee

NB:

- (a) *Fast-Lane Settlement is not applicable for cases that liability is in dispute*
(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Thank you .

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Vincent Chua [<mailto:vincent.chua@premiertaxi.com>]

Sent: Thursday, 16 May 2019 1:02 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>

Subject: Pre-inspection/Accident involving SHC6642Y and IMDEX281 on 15.05.19

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

We refer to the vehicles mentioned above.

Vehicle to be Surveyed: SHC6642Y

Insured Vehicle: IMDEX281

Date of Accident: 15/05/2019

Name of Workshop: Premier Automotive Services Pte Ltd

Address of Survey Location: 23 Changi South Avenue 2, #01-02, S (486443)

Name of Contact Person: Mr Chua

Contact Number: 65446689

Email Address of Contact Person: vincent.chua@premiertaxi.com

Vehicle available for survey at any time

Kindly arrange for survey soonest.

Kindly send us your panel surveyor list and arrange for survey.



Thank you.

Regards

Vincent Chua
Operations Assistant
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 21 May 2019 2:44 PM
To: motorsurvey@sg.msig-asia.com; assignments
Cc: 'Venessa Chan'; 'Nabilah Rasol'; 'Crystal Lee'; 'Ong Zi Hui'; SUR
Subject: RE: Pre-inspection/Accident involving SHC6642Y and IMDEX281 on 15.05.19
Attachments: CSMSG19008774K1qd3.pdf

Dear Sir/Madam,

Enclosed herewith preliminary advice of SHC 6642Y.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 17 May 2019 10:21 AM
To: 'Motor Survey' <motorsurvey@sg.msig-asia.com>; assignments <assignments@lkkauto.com>
Cc: 'Venessa Chan' <venessa_chan@sg.msig-asia.com>; 'Nabilah Rasol' <nabilah_rasol@sg.msig-asia.com>; 'Crystal Lee' <crystal_lee@sg.msig-asia.com>; 'Ong Zi Hui' <zihui_ong@sg.msig-asia.com>; SUR <sur@lkkauto.com>
Subject: RE: Pre-inspection/Accident involving SHC6642Y and IMDEX281 on 15.05.19

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Survey [mailto:motorsurvey@sg.msig-asia.com]
Sent: Thursday, 16 May 2019 4:18 PM
To: Vincent Chua <vincent.chua@premiertaxi.com>
Cc: Venessa Chan <venessa_chan@sg.msig-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>; Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>; Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>; assignments <assignments@lkkauto.com>
Subject: RE: Pre-inspection/Accident involving SHC6642Y and IMDEX281 on 15.05.19



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 21st May 2019

Our Ref: CS/MSG19008774/K1qd3

The Motor Claims Department
MSIG Insurance

Attn: Winnie

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHC 6642Y


We thank you for the instruction on 16/05/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/05/2019 at the premises of M/s PREMIER AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,423.69</u>
Revised Estimate Amount	: S\$ <u>2,348.29</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s body.



Comments/ Present Status:

Damages consistent.

We have not authorized repair.

Yours faithfully

Kalvin Ang
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/05/2019 10:39
Date Of Accident	15/05/2019 21:35
Exact Location Of Accident	BAYFRONT AVE & SLIP/EXIT FROM MBS TOWER 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC6642Y
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107202885
Cover Note Number	

Driver

Name of Driver	ANG GHIM SENG (HONG JINCHENG)
NRIC No	S7103631F
Date Of Birth	02/02/1971
Occupation	OUTDOOR
Date Of Driving Pass	02/10/1997
Driving Experience	21 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96363987
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 809A #07-628 CHOA CHU KANG AVE 1
Postcode	681809
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : PAX IN THE FRONT SEAT - FOREIGNER/CHINA GENDER: : MALE
Passenger 2	NAME: : PAX IN THE REAR SEAT - FOREIGNER/CHINA GENDER: : MALE
Passenger 3	NAME: : PAX IN THE REAR SEAT - FOREIGNER/CHINA GENDER: : FEMALE
Passenger 4	NAME: : PAX IN THE REAR SEAT - FOREIGNER/CHINA GENDER: : FEMALE
Passenger 5	NAME: : PAX IN THE REAR SEAT - FOREIGNER/CHINA/INFANT GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - 5 PAX (4 ADULTS + 1 INFANT) VEH. B - NO PAX *REFER TO ATTACH POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	IMDEX281
Vehicle Make/Model/Colour	BMW
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	FEMALE CHINESE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	DAMAGED ON THE FRONT RIGHT PORTION
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	ANG GHIM SENG (HONG JINCHENG)
Approximate Age	
Injuries Sustain	WENT TO POLYCLINIC FOR MEDICAL TREATMENT & HAD 3 DAYS MC
Injured person in which vehicle?	SHC6642Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/RIAC Sketch Plan Form_V3

16 MAY 2019
S7103631F
SAC6642Y

SKETCH PLAN

EXIT FROM
MBS
TOWER
3

GIVE WAY
LINES

BAYFRONT
AVE

A

A

B

A: SHIC 66424

B: INDEX 281

- * Refer to attach police report
- * Video footage captured

I/We declare the foregoing particulars are true in every respect.

[Signature]

Signature

✓ CJS

S7103631F

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20190516/7003

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190516/7003

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/05/2019 09:50		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: ANG GHIM SENG (HONG JINCHENG)			Address: 809A CHOA CHU KANG AVENUE 1 #07-628 KEAT HONG AXIS SINGAPORE 681809		
ID Type / ID No.: NRIC NO / S7103631F			Contact No.: Home/Office:		Mobile: 96363987
Nationality: SINGAPORE CITIZEN			Email: agshjc@gmail.com		
Sex: Male	Age: 48	Date of Birth: 02/02/1971	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation:			Driving Licence Information: Class: 3,4		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Special Vehicle	Drink Drive: No	Date/Time of Accident: 15/05/2019 21:35	Type of Location: Y-Junction
Location: BAYFRONT AVENUE				
Lamp Post Number: 36F				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 60 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
IMDEX281	Car	BMW		Black	Seriously Damaged	0
SHC6642Y	Car	KIA	optimal K5	Silver	Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190516/7003

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190516/7003

CONTINUATION OF REPORT

Driver			
Name	ANG GHIM SENG (HONG JINCHENG)	ID No.	S7103631F
Related Vehicle	SHC6642Y (Car)	Contact No.	96363987
Hospital/Clinic	NATIONAL CLINIC	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	16/05/2019	Date Discharge	16/05/2019
No. of Days granted Medical Leave	03	Degree of Injury	Serious

Brief Details.

I am a Premier taxi driver . On 15th May 2019 i pick up passenger at 2135hrs at MBS casino taxi stand and driving towards Rivervale Walk . So as i proceed to the location and making a U-turn at Bayfront Ave infront of MBS tower 3 lamp post 36F , suddenly a black BMW turning out of MBS tower 3 without stopping and crash onto my left side of my taxi from front left side bonet to the rear of my taxi . causing damage to the left side of my taxi, i felt pain on my neck,chest and back . The BMW damage its front right headlight , bumper and bonet . i went to see doctor and was given 3 days medical leave . My taxi carplate is SHC6642Y
Black BMW carplate is IMDEX281

Sketch Plan Pg. 5



**SINGAPORE
POLICE FORCE**



T/20190516/7003

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190516/7003

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPB /
MOHAMAD ZULFAZDLI BIN ABDULLAH
Contact No.: 65476204

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
16/05/2019 09:50

Classification Of Case:

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	27 Feb 2015 / 09:02:33	Receipt No.:	AACCK001-AX239-150227-000003
Asset Type:	Vehicle	Transaction Amount:	\$66,712.00
Asset ID:	SHC6642Y	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150227090233389823		

Vehicle No.:	SHC6642Y
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	27 Feb 2015
Original Registration Date:	27 Feb 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5578376
Engine No.:	D4FDEH313318
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$20,834.00
Minimum PARF Benefit:	\$8,200.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	27 Feb 2015 09:02:33
COE No.:	2015022701001612W
COE Expiry Date:	26 Feb 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$52,904.00
Lifespan Expiry Date:	26 Feb 2023

CASH SALE/WORK ORDER

No: AE 4256



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 15.5.16

寶號

Messrs:

車號

Vehicle No:

由

From:

到

To:

其他

Remark:

時間

Time:

Premier

SHC 66424

車型

Model No:

OPTIMA

Marina Bay Sands Tower 3

Omega

(1 day)

21:52:22-22:23:02

AMOUNT: \$

注意: 本公司外所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

C446

收貨人

Received by:

SH

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: 005322

Version: 1810

Date calculated: 17/05/2019 10:48 AM

Full Report

Registration: SHC6642Y

Printed: 17/05/2019 10:48 AM

Summary Information

Claim

Location: Singapore (SG)

Work Provider:

MSIG Insurance
(Singapore) Pte Ltd

Printed by: WEEDEK GOH

Currency:

SGD

Claim Reference:

Date of Incident:

15/05/19

Estimated Repair Time:

Hire Car Start:

Actual Repair Days:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer: KIA

Model: OPTIMA (TF)

Sub Model: 2 LUXE

Model Sheet Number: 28 36 38

Registration: SHC6642Y

VIN number:

Odometer:

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: 005322

Version: 1810

Date calculated: 17/05/2019 10:48 AM

Full Report

Registration: SHC6642Y

Printed: 17/05/2019 10:48 AM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
76000R00	RENEW L/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		16.0	80.00
77000R00	RENEW L/R DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		18.0	90.00
2207	L/SILL PANELLING REPAIR		20.0*	100.00
2583	REAR BUMPER REPAIR		20.0*	100.00
3485	L/R OUTER SIDE PANEL REPAIR		20.0*	100.00
Labour Cost			Hrs	WU
Panel / Mechanical Labour			9.40	94.0
Total of Labour				470.00

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: 005322

Version: 1810

Date calculated: 17/05/2019 10:48 AM

Full Report

Registration: SHC6642Y

Printed: 17/05/2019 10:48 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	LEFT FRONT DOOR NEW PART PAINTING		15.0	
	L/R DOOR NEW PART PAINTING		14.0	
	L/F DOOR OUT HANDLE NEW PART PAINT K1R		3.0	
	L/SILL PANELLING REPAIR PAINT PLASTIC		11.0	
	REAR BUMPER REPAIR PAINT PLASTIC		15.0	
	L/R OUTER SIDE PANEL REPAIR PAINTING <50%		15.0	

Paint Material Per Part

Code	Description	Price SGD
1481	LEFT FRONT DOOR NEW PART PAINTING	35.06
1781	L/R DOOR NEW PART PAINTING	31.03
1565	L/F DOOR OUT HANDLE NEW PART PAINT K1R	0.70
2207	L/SILL PANELLING REPAIR PAINT PLASTIC	17.40
2583	REAR BUMPER REPAIR PAINT PLASTIC	42.90
3485	L/R OUTER SIDE PANEL REPAIR PAINTING <50%	20.25

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			73.0	
	Preparation Main Work Metal		1.70	17.0	85.00
	Preparation Comp. Work Plastic		0.60	6.0	30.00
Total		10 WU/h	9.60	96.0	480.00

Material Cost - Paint

	Price SGD
New Part Painting	66.09
New Part Painting - Plastic K1R	0.70
Repair Painting	20.25
Repair Painting Plastic	60.30
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	178.14

Spare Parts

prices as at 2015-06-01

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: 005322

Version: 1810

Date calculated: 17/05/2019 10:48 AM

Full Report

Registration: SHC6642Y

Printed: 17/05/2019 10:48 AM

Code	Description	Part Number	Supplier	Price SGD
1481	LEFT FRONT DOOR	760032T000	✓ <i>hpl</i>	761.00
1563	L/F DOOR HANDLE BRKT	826552T000	✓ <i>cm</i>	39.00
1565	L/F DOOR OUT HANDLE	826512T000	✓ <i>cm</i>	40.00
1687	L/F DOOR RR MOULDING	863632T010	✗ <i>sm</i>	0.00
1691	L/F UPP DOOR MLDG	828502T000	✗ <i>sm</i>	0.00
1781	L/R DOOR	770032T000	✓ <i>hpl</i>	791.00
1983	L/R DR FRM FRT TRIM	831352T000	✗ <i>sm</i>	0.00
1985	L/R DOOR FRM UP TRIM	831342T000	✗ <i>sh</i>	0.00
1987	L/R DOOR FRT MLDG	863812T000	✗ <i>sm</i>	0.00
1991	L/R UPP DOOR MLDG	838502T000	✗ <i>sm</i>	0.00
9559	L/R WHEEL COVER	529602T100	✗ <i>reg. 2</i>	116.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 1,747.00
u: Used parts				Subtotal Discount(+35.00%) -611.45
Total				1,135.55

Extras

Code	Description	Price SGD
1000	LH door stickers ✓ <i>nc</i>	100.00*
1001	Rear LH wing sticker ✓ <i>nc</i>	60.00*
Total Extras		160.00

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: 005322

Version: 1810

Date calculated: 17/05/2019 10:48 AM

Full Report

Registration: SHC6642Y

Printed: 17/05/2019 10:48 AM

Final Calculation

	SGD	SGD
Parts	1,747.00	
Total Discount(+35.00%)	-611.45	
Total Parts		1,135.55
Labour Time Base 10 WU/h		
Total 94.0 WU X 50.00 SGD/h	470.00	
Total of Labour		470.00
Total Of Extras		160.00
Paint Work Time Base 10 WU/h		
Labour Cost 96.0 WU X 50.00 SGD/h	480.00	
Material Cost	178.14	
Total Paint Including Material		658.14
Repair Cost Excludes GST		2,423.69
GST (+7.0%)		169.66
Repair Cost Included GST		2,593.35

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS



Ka/lin 16/19
21/5/19
17/5/19 1606
4 days
4/5
After Repair photo

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: 005322
Version: 1810
Date calculated: 21/05/2019 2:25 PM

Full Report
Registration: SHC6642Y
Printed: 21/05/2019 2:25 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	15/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	KIA
Model:	OPTIMA (TF)
Sub Model:	2 LUXE
Model Sheet Number:	28 36 38
Registration:	SHC6642Y
VIN number:	
Odometer:	

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 005322
 Version: 1810
 Date calculated: 21/05/2019 2:25 PM

Full Report
 Registration: SHC6642Y
 Printed: 21/05/2019 2:25 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
76000R00	RENEW L/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		16.0	80.00
77000R00	RENEW L/R DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		18.0	90.00
2207	L/SILL PANELLING REPAIR		20.0*	100.00
2583	REAR BUMPER REPAIR		20.0*	100.00
3485	L/R OUTER SIDE PANEL REPAIR		20.0*	100.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		9.40	94.0	470.00
Total of Labour				470.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 005322
 Version: 1810
 Date calculated: 21/05/2019 2:25 PM

Full Report
 Registration: SHC6642Y
 Printed: 21/05/2019 2:25 PM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	LEFT FRONT DOOR NEW PART PAINTING		15.0	
	L/R DOOR NEW PART PAINTING		14.0	
	L/F DOOR OUT HANDLE NEW PART PAINT K1R		3.0	
	L/SILL PANELLING REPAIR PAINT PLASTIC		11.0	
	REAR BUMPER REPAIR PAINT PLASTIC		15.0	
	L/R OUTER SIDE PANEL REPAIR PAINTING <50%		15.0	

Paint Material Per Part

Code	Description	Price SGD
1481	LEFT FRONT DOOR NEW PART PAINTING	35.06
1781	L/R DOOR NEW PART PAINTING	31.03
1565	L/F DOOR OUT HANDLE NEW PART PAINT K1R	0.70
2207	L/SILL PANELLING REPAIR PAINT PLASTIC	17.40
2583	REAR BUMPER REPAIR PAINT PLASTIC	42.90
3485	L/R OUTER SIDE PANEL REPAIR PAINTING <50%	20.25

Labour Cost - Paint

	50.00 SGD/h	Hrs	WU	Price SGD
Factor			73.0	
Time Paint				
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
Total	10 WU/h	9.60	96.0	480.00

Material Cost - Paint

	Price SGD
New Part Painting	66.09
New Part Painting - Plastic K1R	0.70
Repair Painting	20.25
Repair Painting Plastic	60.30
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	178.14

Spare Parts

prices as at 2015-06-01

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:

Assessment number: 005322

Version: 1810

Date calculated: 21/05/2019 2:25 PM

Full Report

Registration: SHC6642Y

Printed: 21/05/2019 2:25 PM

Code	Description	Part Number	Supplier	Price SGD
1481	LEFT FRONT DOOR	760032T000		761.00
1563	L/F DOOR HANDLE BRKT	826552T000		39.00
1565	L/F DOOR OUT HANDLE	826512T000		40.00
1687	L/F DOOR RR MOULDING	863632T010		0.00
1691	L/F UPP DOOR MLDG	828502T000		0.00
1781	L/R DOOR	770032T000		791.00
1983	L/R DR FRM FRT TRIM	831352T000		0.00
1985	L/R DOOR FRM UP TRIM	831342T000		0.00
1987	L/R DOOR FRT MLDG	863812T000		0.00
1991	L/R UPP DOOR MLDG	838502T000		0.00
9559	L/R WHEEL COVER	529602T100		0.00
f: OEM Parts				0.00
n: Non-OEM Parts				1,631.00
u: Used parts				-570.85
Savings				
Subtotal				1,631.00
Subtotal Discount(+35.00%)				-570.85
Total				1,060.15

Extras

Code	Description	Price SGD
1000	LH door stickers	100.00*
1001	Rear LH wing sticker	60.00*
9559	[E]: L/R WHEEL COVER :	0.00*
Total Extras		160.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: 005322
Version: 1810
Date calculated: 21/05/2019 2:25 PM

Full Report
Registration: SHC6642Y
Printed: 21/05/2019 2:25 PM

Final Calculation

	SGD	SGD
Parts	1,631.00	
Total Discount(+35.00%)	-570.85	
Total Parts		1,060.15
Labour Time Base 10 WU/h		
Total 94.0 WU X 50.00 SGD/h	470.00	
Total of Labour		470.00
Total Of Extras		160.00
Paint Work Time Base 10 WU/h		
Labour Cost 96.0 WU X 50.00 SGD/h	480.00	
Material Cost	178.14	
Total Paint Including Material		658.14
Repair Cost Excludes GST		2,348.29
GST (+7.0%)		164.38
Repair Cost Included GST		2,512.67

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2

486443

Claim Reference:

Assessment number: SHC6642Y

Version: 1810

Date calculated: 21/06/2019 9:36 AM

Full Report

Registration: SHC6642Y

Printed: 21/06/2019 9:37 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	15/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	KIA
Model:	OPTIMA (TF)
Sub Model:	2 LUXE
Model Sheet Number:	28 36 38
Registration:	SHC6642Y
VIN number:	
Odometer:	

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SHC6642Y

Version: 1810

Date calculated: 21/06/2019 9:36 AM

Full Report

Registration: SHC6642Y

Printed: 21/06/2019 9:37 AM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
76000R00	RENEW L/F DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		16.0	80.00
77000R00	RENEW L/R DOOR INCLUDES: R + R DOOR AND ALL NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		18.0	90.00
2207	L/SILL PANELLING REPAIR		20.0*	100.00
2583	REAR BUMPER REPAIR		20.0*	100.00
3485	L/R OUTER SIDE PANEL REPAIR		20.0*	100.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		9.40	94.0	470.00
Total of Labour				470.00

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
 Assessment number: SHC6642Y
 Version: 1810
 Date calculated: 21/06/2019 9:36 AM

Full Report
 Registration: SHC6642Y
 Printed: 21/06/2019 9:37 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	LEFT FRONT DOOR NEW PART PAINTING		15.0	
	L/R DOOR NEW PART PAINTING		14.0	
	L/F DOOR OUT HANDLE NEW PART PAINT K1R		3.0	
	L/SILL PANELLING REPAIR PAINT PLASTIC		11.0	
	REAR BUMPER REPAIR PAINT PLASTIC		15.0	
	L/R OUTER SIDE PANEL REPAIR PAINTING <50%		15.0	

Paint Material Per Part

Code	Description	Price SGD
1481	LEFT FRONT DOOR NEW PART PAINTING	35.06
1781	L/R DOOR NEW PART PAINTING	31.03
1565	L/F DOOR OUT HANDLE NEW PART PAINT K1R	0.70
2207	L/SILL PANELLING REPAIR PAINT PLASTIC	17.40
2583	REAR BUMPER REPAIR PAINT PLASTIC	42.90
3485	L/R OUTER SIDE PANEL REPAIR PAINTING <50%	20.25

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			73.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
Total	10 WU/h	9.60	96.0	480.00

Material Cost - Paint

	Price SGD
New Part Painting	66.09
New Part Painting - Plastic K1R	0.70
Repair Painting	20.25
Repair Painting Plastic	60.30
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	178.14

Spare Parts

prices as at 2015-06-01

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SHC6642Y

Version: 1810

Date calculated: 21/06/2019 9:36 AM

Full Report

Registration: SHC6642Y

Printed: 21/06/2019 9:37 AM

Code	Description	Part Number	Supplier	Price SGD
1481	LEFT FRONT DOOR	760032T000		761.00
1563	L/F DOOR HANDLE BRKT	826552T000		39.00
1565	L/F DOOR OUT HANDLE	826512T000		40.00
1687	L/F DOOR RR MOULDING	863632T010		0.00
1691	L/F UPP DOOR MLDG	828502T000		0.00
1781	L/R DOOR	770032T000		791.00
1983	L/R DR FRM FRT TRIM	831352T000		0.00
1985	L/R DOOR FRM UP TRIM	831342T000		0.00
1987	L/R DOOR FRT MLDG	863812T000		0.00
1991	L/R UPP DOOR MLDG	838502T000		0.00
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				1,631.00
Subtotal Discount(+35.00%)				-570.85
Total				1,060.15

Extras

Code	Description	Price SGD
1000	LH door stickers	100.00*
1001	Rear LH wing sticker	60.00*
Total Extras		160.00

**Premier Automotive Services Pte
Ltd**

**#01-02, 23 Changi Sth Ave 2
486443**

Claim Reference:

Assessment number: SHC6642Y

Version: 1810

Date calculated: 21/06/2019 9:36 AM

Full Report

Registration: SHC6642Y

Printed: 21/06/2019 9:37 AM

Final Calculation

	SGD	SGD
Parts		
Total Discount(+35.00%)	1,631.00	
Total Parts	-570.85	1,060.15
Labour Time Base 10 WU/h		
Total 94.0 WU X 50.00 SGD/h	470.00	
Total of Labour		470.00
Total Of Extras		160.00
Paint Work Time Base 10 WU/h		
Labour Cost 96.0 WU X 50.00 SGD/h	480.00	
Material Cost	178.14	
Total Paint Including Material		658.14
Repair Cost Excludes GST		2,348.29
GST (+7.0%)		164.38
Repair Cost Included GST		2,512.67

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019		22 May 2019 11:19 Edit Adj Rpt	S\$1,850.00 Edit Estimates	S\$1,850.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PERFORMANCE MOTORS LTD, Co. Reg. No.: 197401559W		
Main Claimant:	PREMIER TAXIS PTE LTD		
Vehicle Reg. No.:	SHC6642Y	Date of Loss:	15/05/2019 21:00 - :59 [50 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 593862	Policy/Cover Note No.:	29123478MTR (Comprehensive) Coverage: 02/05/2019 - 18/05/2019
Vehicle Reg. No. (Insured):	IMDEX281	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02, 486443 Changi - Tel: 62148880		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Imm.Advice due 23/05/2019]		
Driver/Custodian (Insured):	LIM BENG HWA (), NRIC: S1229156F, Tel: +6594520338 Email:		
Adj Asg. Remarks:	Manual assigned to LKK on 17/05/19.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

































ALL ASSOCIATED TASKS







[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC6642Y (593862)**
[IMDEX281]
TP
PREMIER TAXIS PTE LTD
May 15 2019 9:00PM
[PERFORMANCE MOTORS LTD]
Premier Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/05/19 10:47	Accident Statement From:OD - Reg. No: IMDEX281, Claimant: PERFORMANCE MOTORS LTD	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/05/19 16:53	General View	 Load JPG	<input checked="" type="checkbox"/>
30	21/06/19 09:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	21/06/19 09:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	21/06/19 09:54	Reinspection Photo	 Load JPG	✓
33	21/06/19 09:54	Reinspection Photo	 Load JPG	✓
34	21/06/19 09:54	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/05/19 10:47	TP GIA REPORT - SHC6642Y From:OD - Reg. No: IMDEX281, Claimant: PERFORMANCE MOTORS LTD	 Load PDF	
2	22/05/19 10:47	Facing Sheet + Policy From:OD - Reg. No: IMDEX281, Claimant: PERFORMANCE MOTORS LTD	 Load PDF	
3	22/05/19 11:20	email to outsource	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19008774/K1QD3S2

Date: 24/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29123478MTR

Claimant Vehicle No : SHC6642Y

Insured Vehicle No : IMDEX281

Date of Loss: 15/05/2019

Nature of Claim: TP

Claim No: 593862

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC6642Y

Make & Model: KIA OPTIMA, 1.7 D (A)

Engine No: D4FDEH313318

Reg. Date: 27/02/2015 (Man. Year: 2014)

Chassis No: KNAGM414MF5578376

Colour: Silver

Odometer: 392293 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65R16

Rear Tyre Size:

205/65R16

Front Left Side: Maxxis 7 mm

Rear Left Side:

Maxxis 7 mm

Front Right Side: Maxxis 7 mm

Rear Right Side:

Maxxis 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,295.55	1,220.15	75.40	5.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,128.14	1,128.14	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,423.69	2,348.29	75.40	3.11
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	2,423.69	1,850.00	573.69	23.67
+ GST 7.00/7.00% (S\$)	169.66	129.50	40.16	23.67
Nett Amount (S\$)	2,593.35	1,979.50	613.85	23.67

INSPECTION

Date of Assignment: 22/05/2019

Date Inspected: 17/05/2019 Inspected At:

Premier Automotive Services Pte Ltd (HQ)

23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair: 4.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=825109&extid=304473&CFID=54873490&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2019)
Parts:	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC6642Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT FRONT DOOR (WCP)	Buckled	761.00 F	*761.00 F
2	1		*L/F DOOR HANDLE BRKT (WCP)	Cracked	39.00 F	*39.00 F
3	1		*L/F DOOR OUT HANDLE (WCP)	Cracked	40.00 F	*40.00 F
4	1		*L/F DOOR RR MOULDING (NPA)	Serviceable	0.00 F	*- F
5	1		*L/F UPP DOOR MLDG (NPA)	Serviceable	0.00 F	*- F
6	1		*L/R DOOR (WCP)	Bent	791.00 F	*791.00 F
7	1		*L/R DR FRM FRT TRIM (NPA)	Serviceable	0.00 F	*- F
8	1		*L/R DOOR FRM UP TRIM (NPA)	Serviceable	0.00 F	*- F
9	1		*L/R DOOR FRT MLDG (NPA)	Serviceable	0.00 F	*- F
10	1		*L/R UPP DOOR MLDG (NPA)	Serviceable	0.00 F	*- F
11	1		*L/R WHEEL COVER (WCP)	Repair	116.00 F	*- F
12	1		*LH DOOR STICKERS	Necessary	100.00 FS	*100.00 FS
13	1		*REAR LH WING STICKER	Necessary	60.00 FS	*60.00 FS
					Sub Total (\$\$)	1,907.00
					- Add. Disc. on L,N Items 35.00/35.00% (\$\$)	611.45
					Total Parts (\$\$)	1,295.55
						1,220.15

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL LABOUR.	New	470.00	470.00
2	PAINT WORK: LABOUR COST.	New	480.00	480.00
3	PAINT WORK: MATERIAL COST.	New	178.14	178.14
Gross Labour Cost (S\$)			1,128.14	1,128.14

Report was unsubmitted during this print-out.

< END OF ESTIMATES >