

ASS. REC. BY:

REF: CS3/CT1/9008778/TICd302

Special Instruction:

Survivor: Taufik

ASSIGNMENT (Office)

From (Person): Ong Chin Kiat

of CT1

Date/Time: 17.5.19 11.42 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 5791C

Insured: 4P76201

at Workshop m/s Das Auto & Aircon

Tel: 6266296

of B1K.9 Pioneer Road MOAH #01-58

Policy No: DMCVSN 30668218000

Claim No: SNM19D202150C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 12.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wfp"

H.O.D. Endorsement:

Date/Time: 17.5.19 11.59 a.m

Person Contacted: Candy

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GBC 5791C - X
	4P 76201 - X
	Dismantle: 23/5/2019
	After repair: 28/5/2019

Tanfield

REF

CT1

ASSIGNMENT

Team _____ Date _____
 Estimated Cost _____
 OP / ☒ W5 / ☐ P / ☐ R5 / ☐ O / ☐ R5 / ☐ VA / ☐ HV / ☐ MV
 To inspect Vehicle No. _____
 at Workshop no. _____
 of _____
 Insured _____
 Policy No. _____
 Claim No. _____
 Sum Insured _____ Excess _____
 (Client's Record) _____
 Make of Veh. _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value _____
 IDAC Accident Report _____ Consistent? : Yes or No _____
 GIA / IR Score _____ Consistent? : Yes or No _____
 Est. Repair: 4 days Res. Yes or No _____
 Lump Sum: % 3 Val: Yes or No _____

CA / REV / REP. / 24 HRS will
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. GBC5791C Date 2013 Jan.
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Pick-up
 Make: Toyota Hilux D-cab C.V. 2982
 Colour: Grey A/C. Insured / STD / HI / HA
 Exp Reading 271270 I/Radio: Insured / STD / HI / HA
 Eng No. _____
 C/No. MROE 2129004/56576
 Gen. Cond. Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brakes: In order / Jammed / Leaked / Burnt or
 Mod: Oil / S/Rim / STD A/Rim
 Tyre Size: F: 205/70R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 17/5/19 @ 3pm
 Survey held at Das Auto
 Des. of Damages: Frt / Rear / O/S / H/S / U/C / Rooltop or
N/S Frt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction PRS

Range + days

Estimated repair range \$3,000 - \$4,000

4/7/2019

Date/Time, File Pass to? ☐ : Prel. Report

11 ☐ : Final Report

Date/Time, File Return to?

5

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Weekend (\$)

Report Format: PRS

Lump Sum / U.B.I. (\$) _____

Survey Fee:

Transportation:

) S + RS: \$1

) Photos

) Others

TOTAL

190

190

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 0141M

Vehicle Details

Vehicle No.: GBC5791C

Vehicle to be Exported: No

Intended Deregistration Date: 24 Jun 2019

Vehicle Make: TOYOTA

Vehicle Model: HILUX D CAB MANUAL

Primary Colour: Grey

Manufacturing Year: 2012

Engine No.: 1KD5937427

Chassis No.: MR0EZ12G004156576

Maximum Power Output: -

Open Market Value: \$24,718.00

Original Registration Date: 15 Jan 2013

First Registration Date: 15 Jan 2013

Transfer Count: 0

Actual ARF Paid: \$24,718.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 14 Jan 2023

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$62,201.00

COE Rebate Amount: \$22,121.00

Total Rebate Amount: \$22,121.00

The information contained herein is correct as at 24 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/05/2019 11:04
Date Of Accident	12/05/2019 09:25
Exact Location Of Accident	PIE SLIP RD TO THOMSON ROAD IN FRONT ETON HOUSE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC5791C
Insured/Policyholder	
Name Of Registered Owner	SINGAPORE TAKADA INDUSTRIES P/L
Co Reg No	197100141M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68613666

Vehicle Particulars

Manufacturer	TOYOTA
Model	HILUX-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	19-ME000085-R05
Cover Note Number	

Driver

Name of Driver	WONG WAI THONG
NRIC No	S0133395Z
Date Of Birth	16/12/1950
Occupation	OUTDOOR
Date Of Driving Pass	19/11/1979
Driving Experience	39 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91161515
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	21 HAZEL PARK TERRACE #03-01
Postcode	678946
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE SIEW GUAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP7620J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SERAVALI MURUGESAN
NRIC/Passport Number	F8107551N
Contact Number	83173651
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

SINGAPORE TAKATA IND. PTE. LTD.
 FOR SITE OFFICE USE ONLY
 61 GUL ROAD, S(629352)
 TEL: 6961 3663

Y

Policyholder's Signature
 Date & Time:


Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/05/19 @ around 09:45 hrs, I was travelling along PIE to Ent to Thomson RD. While I was making my turn to Thomson RD at the traffic light junction in front Eton House there is roadwork along the road, suddenly vehicle B cut into my lane & collided onto my front left side portion but the driver did not stop when I sounded my horn to him then I chased him & found him at the petrol station. Pls refer to the attachment on the conversation between vehicle B driver & me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

- ☐ Claim own policy
- ☐ Claim third party
- ☒ Claim OD (TP at other works hop DAS Auto)
- ☐ For record purpose

Policy No. W000 Veh. No. REC579IC
Insurer W000

Policyholder's Signature

Driver's Signature

Reporting Centre Personnel's Signature

Date: 12/05/19

(If driver is not the policyholder)

Name:

41 GUL ROAD, S(629382)

Date & Time:

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 May 2019		17 May 2019 11:42 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TOPZONE E&C P/L, Co. Reg. No.: 199700562Z		
Main Claimant:	SINGAPORE TAKADA INDUSTRIES P/L, Co. Reg. No.: 197100141M		
Vehicle Reg. No.:	GBC5791C	Date of Loss:	12/05/2019 09:00 - :59 [75 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202150C02	Policy/Cover Note No.:	DMCVSN30668218000 (Comprehensive)
Vehicle Reg. No. (Insured):	YP7620J	Policy No. (Claimant):	19-ME000085-R05
		Excess:	S\$0.00
Repairer:	Das Auto & Aircon Services (HQ) BLK 9 Pioneer Road North, #01-58, 628461 Pioneer - Tel: 6266-1296		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 29/05/2019]		
Driver/Custodian (Insured):	SERAVALI MURUGESAN (41 / Male) , NRIC: F8107551N Email:		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

































There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





























Claim Documents

*GBC5791C (SNM19D202150C02)
[YP7620J]
TP
SINGAPORE TAKADA INDUSTRIES P/L
May 12 2019 9:00AM
[TOPZONE E&C P/L]
Das Auto & Aircon Services

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		▼
Photos/Images								3 per page		▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
2	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
3	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
4	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
5	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
6	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
7	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
8	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
9	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
10	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
11	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
12	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
13	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
14	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
15	01/07/19 09:40	General View							Load JPG	<input checked="" type="checkbox"/>	
16	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
17	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
18	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
19	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
20	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
21	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
22	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
23	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
24	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
25	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
26	01/07/19 09:43	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
27	01/07/19 09:43	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>	
28	01/07/19 09:43	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>	
29	01/07/19 09:43	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>	
30	01/07/19 09:43	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>	
31	01/07/19 09:43	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>	
32	01/07/19 09:43	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	13/05/19 18:00	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
18	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
20	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
23	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
24	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
25	13/05/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	13/05/19 18:00	Sketch Plan	 Load TIF	<input type="checkbox"/>
2	13/05/19 18:00	CI,IC,DL	 Load TIF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19008778/T1CD3E2

Date: 11/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30668218000

Claimant Vehicle
No : GBC5791C

Insured Vehicle
No : YP7620J

Date of Loss: 12/05/2019

Nature of Claim: TP

Claim
No: SNM19D202150C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC5791C**

Make & Model: TOYOTA HILUX, 3.0 D (M)

Engine No: 1KD5937427

Reg. Date: 15/01/2013 (Man. Year: 2012)

Chassis No: MR0EZ12G004156576

Colour: Grey

Odometer: 271270 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/70 R15

Rear Tyre Size: 205/70 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/05/2019

Date Inspected: 17/05/2019 Inspected At:

Das Auto & Aircon Services (HQ)
BLK 9 Pioneer Road North, #01-58
Singapore 628461

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Jul 2019)	
Parts:	N/A	TOYOTA HILUX 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC5791C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >