

22/03/2001

ASS. REC. BY:

REF: S3

FWD 19008788 / Gcd36

Special Instruction:

Singer: Guadalupe

ASSIGNMENT (Office)

From (Person): Josey loh

of

FWDDate/Time: 10:09 am @ 16/5/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP8998M

Insured:

SKW 5386T

at Workshop m/s

LKT Group

Tel:

98300271

of

B1k 3006 Ubi Rd 1 #01-384

Policy No:

PNPV2018-00013112/JL

Claim No:

1201900013098

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:41 am @ 16/5/19

Person Contacted:

MabelVehicle IN / OUT

Date/Time

Action/Instruction

Estimate

4YP8998M - NA/NC19008636/24DOA: 14/5/2019SKW 5386T - NA/NC19008636/24DOA: 14/5/2019Dismantle: 29/5/2019After repair: 31/5/2019

PRS
GL.

REF: PWD

C6618 IV

ASSIGNMENT

From: Date: 17/5/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YP8998M

at Workshop n/s

of B/k 3006 ubi Rd 1 # 01-384

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 11am

Mabel @ 98300271

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: YP 8998 M Yt Regn: 27 Apr 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M.t Canter 3.0 2998

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 93147 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: 205/70R16

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 5 mm

L/Bal: 5 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

W/N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal: 5/5 mm

L/Bal: 5/5 mm

D.O.I: 17-05-19

w/s 12:30pm

Date / Time

Action / Instruction

\$4000 - \$5000

21/5/2019

RECEIVED 07 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Report Format: PRE.

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

: S + R.S. SI

: Photos

: Others

TOTAL

20

50

90

180

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2019 Edit Reg		17 May 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ZHANG JUN HONG , ID: S2646652J									
Main Claimant: New Eminent Construction Pte Ltd									
Vehicle Reg. No.: YP8998M		Date of Loss: 14/05/2019 19:00 - :59							
Claim Type: TP / 1201900013098		Policy/Cover Note No.: PNPV2018-00013112 (Comprehensive)							
Vehicle Reg. No. (Insured): SKW5380T		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: Lkt Group Pte Ltd (HQ) Blk 3006 Ubi Road 1, #01 - 384 Kampong Ubi Industrial Estate, 408700 Ubi - Tel: 68461836									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: josey.loh@fwd.com
Sent: Thursday, 16 May 2019 10:04 AM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Notice of PRI of vehicle YP 8998 M Your Ref: PNPV2018-00013112/JL
Attachments: PRI-YP8998M-LKT.PDF

Hi LKK team,

Please refer to the attached and liaise with TP repairer for PRS.

Please create the case in Merimen.

Thank you.

Regards,
Josey

From: Josey Loh Kah Wai - SGUser
Sent: Thursday, 16 May, 2019 10:02 AM
To: 'Mdm Ling'
Cc: lhling@tcmg.com.sg; Motor Claims SG - SG Common
Subject: RE: Notice of PRI of vehicle YP 8998 M Your Ref: PNPV2018-00013112/JL

WITHOUT PREJUDICE

Dear Mdm Ling,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK Auto Consultants Pte Ltd, to conduct the pre-repair survey (PRS) on your client's vehicle, YP8998M. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16

MANHATTAN HOUSE

SINGAPORE 169876

TEL : (65) 6532 2455

FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg

Our Ref: TCMG/YP8998M/0519/LKT

Your Ref: SKW 5380 T

15 May 2019

M/S FWD SINGAPORE PTE LTD

6 Temasek Boulevard

#18-01

Suntec Tower 4

Singapore 038986

BY E-MAIL ONLY
(motorclaims.sg@fwd.com)

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **M/s New Eminent Construction Pte Ltd**, the owner and/or driver of motor vehicle no. **YP 8998 M**, which was involved in an accident along Tampines Avenue 10 on 14 May 2019 at 19:00 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SKW 5380 T** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s LKT Group Pte Ltd, (Blk 3006 Ubi Road 1 #01-384, Singapore 408700 – Mabel Teng @ 98300271

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.


Yours faithfully,



LING LEONG HUI (MR)

cc.: M/s LKT GROUP PTE LTD
(Yref: YP8998M)

BY EMAIL ONLY



From: Mdm Ling [<mailto:mdmling@tcmg.com.sg>]
Sent: Thursday, 16 May, 2019 8:42 AM
To: Motor Claims SG - SG Common
Cc: lhling@tcmg.com.sg; Josey Loh Kah Wai - SGUser
Subject: RE: Notice of PRI of vehicle YP 8998 M Your Ref: PNPV2018-00013112/JL

Dear Sir,

We refer to the above matter and to your email dated 15 May 19.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

Yours faithfully,

Mdm Ling
TOMMY CHOO MARK GO LLC

From: motorclaims.sg@fwd.com [<mailto:motorclaims.sg@fwd.com>]
Sent: Wednesday, May 15, 2019 6:11 PM
To: mdmling@tcmg.com.sg
Cc: lhling@tcmg.com.sg; josey.loh@fwd.com
Subject: RE: Notice of PRI of vehicle YP 8998 M Our Ref: PNPV2018-00013112/JL

WITHOUT PREJUDICE

Dear Sir/ Madam,

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards,
Clara Li




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



From: Mdm Ling [<mailto:mdmling@tcmg.com.sg>]

Sent: Wednesday, 15 May, 2019 5:55 PM

To: Motor Claims SG - SG Common

Cc: Ling Leong Hui

Subject: Notice of PRI of vehicle YP 8998 M Our Ref: PNPV2018-00013112/CL

Dear Sir,

We refer to the above matter.

Attach herewith the notice of PRI of vehicle YP 8998 M for your attention.

Best Regards,

Mdm Ling
Tommy Choo Mark Go LLC

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any

attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	6618N
Vehicle No.:	YP8998M
Vehicle to be Exported:	No
Intended Deregistration Date:	21 May 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER 3.0 DIESEL MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	4P10B92527
Chassis No.:	FEB50542899
Maximum Power Output:	-
Open Market Value:	\$37,480.00
Original Registration Date:	27 Apr 2016
First Registration Date:	27 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$1,874.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	26 Apr 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$36,806.00
COE Rebate Amount:	\$25,788.00
Total Rebate Amount:	\$25,788.00

The information contained herein is correct as at 20 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/05/2019 11:04
Date Of Accident	14/05/2019 19:00
Exact Location Of Accident	TAMPINES AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP8998M
Insured/Policyholder	
Name Of Registered Owner	NEW EMINENT CONSTRUCTION PTE LTD
Co Reg No	201216618N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93225775
Alternative Phone No	OFFICE-93225775

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER 3.0 DIESEL MANUAL
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106443346
Cover Note Number	

Driver

Name of Driver	DEVISIGAMANI ASHOK KUMAR
Passport No/FIN	G2100601M
Date Of Birth	20/12/1992
Occupation	OUTDOOR
Date Of Driving Pass	23/05/2017
Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86731594
Fax Number	
Contact Number	OFFICE-86731594
EMail Address	NOEMAIL

Address 10 JALAN BESAR
#07-02 SIM LIM TOWER
Postcode 208787
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 24
Passenger 1 NAME: : -
GENDER: : MALE
Passenger 2 NAME: : -
GENDER: : MALE
Passenger 3 NAME: : -
GENDER: : MALE
Passenger 4 NAME: : -
GENDER: : MALE
Passenger 5 NAME: : -
GENDER: : MALE
Passenger 6 NAME: : -
GENDER: : MALE
Passenger 7 NAME: : -
GENDER: : MALE
Passenger 8 NAME: : -
GENDER: : MALE
Passenger 9 NAME: : -
GENDER: : MALE
Passenger 10 NAME: : -
GENDER: : MALE

Passenger 11	NAME: : - GENDER: : MALE
Passenger 12	NAME: : - GENDER: : MALE
Passenger 13	NAME: : - GENDER: : MALE
Passenger 14	NAME: : - GENDER: : MALE
Passenger 15	NAME: : - GENDER: : MALE
Passenger 16	NAME: : - GENDER: : MALE
Passenger 17	NAME: : - GENDER: : MALE
Passenger 18	NAME: : - GENDER: : MALE
Passenger 19	NAME: : - GENDER: : MALE
Passenger 20	NAME: : - GENDER: : MALE
Passenger 21	NAME: : - GENDER: : MALE
Passenger 22	NAME: : - GENDER: : MALE
Passenger 23	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WHAMPOA NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 29 JALAN BAHAGIA , POSTCODE: 320029 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2507999 - FAX NO: 63554314
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20190515/2113.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW5380T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ZHANG JUNHONG
NRIC/Passport Number	S2646652J
Contact Number	81831229
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	DEVISIGAMANI ASHOK KUMAR
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	YP8998M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time




Driver's Signature
(If driver is not the policyholder)
Date & Time



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Ref to police report 7 May 05/11/13.

[A large diagonal line is drawn across the remaining lines of the form, indicating no further details were recorded.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 May 2019 Edit Reg		16 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	ZHANG JUN HONG , ID: S2646652J								
Main Claimant:	New Eminent Construction Pte Ltd								
Vehicle Reg. No.:	YP8998M	Date of Loss:	14/05/2019 19:00 - :59 [36 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900013098	Policy/Cover Note No.:	PNPV2018-00013112 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKW5380T	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Lkt Group Pte Ltd (HQ) Blk 3006 Ubi Road 1, #01 - 384 Kampong Ubi Industrial Estate, 408700 Ubi - Tel: 68461836								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP8998M (1201900013098)**
[SKW5380T]
TP
New Eminent Construction Pte Ltd
May 14 2019 7:00PM
[ZHANG JUN HONG]
Lkt Group Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/06/19 15:37	General View		Load JPG	<input checked="" type="checkbox"/>
2	06/06/19 15:37	General View		Load JPG	<input checked="" type="checkbox"/>
3	06/06/19 15:37	General View		Load JPG	<input checked="" type="checkbox"/>
4	06/06/19 15:37	General View		Load JPG	<input checked="" type="checkbox"/>
5	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
6	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
7	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
8	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
9	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
10	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
11	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
12	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
13	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
14	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
15	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
16	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
17	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
18	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
19	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
20	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
21	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
22	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
23	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
24	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
25	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
26	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
27	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
28	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
29	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
30	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
31	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
32	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
33	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
34	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
35	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
36	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>
37	06/06/19 15:38	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/06/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 15:38	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/06/19 15:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	06/06/19 15:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	06/06/19 15:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	06/06/19 15:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	06/06/19 15:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	06/06/19 15:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	06/06/19 15:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	06/06/19 15:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	06/06/19 15:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	06/06/19 15:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/19 16:53	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19008788/GCD3E2

Date: 10/06/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00013112

Claimant Vehicle No: YP8998M Insured Vehicle No: SKW5380T

Date of Loss: 14/05/2019 Nature of Claim: TP Claim No: 1201900013098

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP8998M	Engine No:	4P10B92527
Make & Model:	MITSUBISHI CANTER, 3.0 D (M)	Chassis No:	FEB50542899
Reg. Date:	27/04/2016 (Man. Year: 2015)	Odometer:	93147 km
Colour:	Silver		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/70 R16	Rear Tyre Size:	205/70 R16 (D)
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5/5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/05/2019

Date Inspected: 17/05/2019 Inspected At:

Lkt Group Pte Ltd (HQ)
Blk 3006 Ubi Road 1, #01 - 384 Kampong
Ubi Industrial Estate
Singapore 408700

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Jun 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP8998M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >