

72802100

ASS. REC. BY:

REF:

CS/FCI/9008802/Et d3/12

Special Instruction:

Manager: Steve

ASSIGNMENT (Office)

CWS

From (Person): Sikhera

of

FEI

Date/Time: 2:48pm @ 17/5/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLZ 7691E

Insured:

SHA 9464K

at Workshop m/s

Huei Hong

Tel:

66619688

of

25D Sungai Kerat Street 1

Policy No:

Claim No:

D19003272MFSH

Sum Insured:

Excess:

D.O.A. 15/08/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24HRS 'DS'

H.O.D. Endorsement:

Date/Time:

3:33pm @ 17/5/19

Person Contacted:

Jeeen

Vehicle IN OUT

Date/Time

Action/Instruction

Fahmald ✓

SLZ 7691E - X

SHA 9464K - col FCI 18012143/Ard 3rd

D.O.A. 28/6/2018

2/7 @ 4:40pm Rensad via preli advise.

3/12/19 - offer lump sum \$1600, 4days confirm with Ashley.
Cred: 1116.03; 41%

(08/11/13)

ASS. REC. BY:

Star

REF

FCI

ASSIGNMENT

From:

Date:

01/7/19

Veh No:

SLZ 7691E

Yr Regn:

17/5/18

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SLZ 7691E

Make:

Toyota C-HR

c.c

1797

at Workshop m/s

HUA HONG

Colour

Black

A/C: Insured / Std / NI / NA

of

25D Sq. 1st flr St 1

Sp. Reading

99596

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

2YX 10211 6050

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

15/5/19

D.O.I.

1/7/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Hua Hong

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Mr - 95K

RECEIVED 03 DEC 2019

Date/Time, File Pass to?



Preli. Report

1) 3/12 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: -

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

110

50

27

187

Report Format:

TP

Lump Sum / I.B.I. (\$

\$1600



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003272MFSH

Date: 2/7/2019

Our Ref: CS/FCI19008802/Etd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLZ 7691E

Please be informed that we had conducted the inspection of the abovementioned vehicle
1/7/2019 at the premises of M/s Hua Hong have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,473.40</u>
Revised Estimate Amount	: S\$ <u>2,098.72</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages at the
o/s body portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Steve
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	16-05-2019	Our Ref No. D19003272MFSH
Accident Date	15-05-2019	Claim Type. Third Party
Insured Vehicle	SHA9464K	Third Party Vehicle. SLZ7691E
Survey Location	25D SUNGEI KADUT STREET 1	
Contact Person.	YVONNE TOH	
Contact No.	66619688/ 0	Fax No. 66619699
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA HONG PRIVATE LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 2 July 2019 4:40 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003272MFSH/1
Attachments: PRELI ADVISED SLZ 7691E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLZ 7691E**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 17 May 2019 3:39 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003272MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 17 May 2019 2:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003272MFSH/1

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0309M
Vehicle Details	
Vehicle No.:	SLZ7691E
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	2ZR8419769
Chassis No.:	ZYX102116050
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,984.00
Original Registration Date:	17 May 2018
First Registration Date:	17 May 2018
Transfer Count:	0
Actual ARF Paid:	\$9,778.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2028
PARF Rebate Amount:	\$7,333.00
Intended COE Rebate Details	
COE Expiry Date:	16 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$34,607.00
Total Rebate Amount:	\$41,940.00

The information contained herein is correct as at 01 Jul 2019

OK



HUA HONG PRIVATE LIMITED

25D SUNGAI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: Info@huahong.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate Repair List

23 May 2019

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON RD, #16-01
CITY HOUSE
SINGAPORE 068877

Attn: Motor Claims Department

ACCIDENT INVOLVING SLZ7691E & SHA9464K ON 15/05/2019 ALONG PARKWAY PARADE AT ABOUT 1840 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SLZ7691E
Vehicle Make : TOYOTA
Vehicle Model : C-HR HYBRID 1.8S CVT
Vehicle Chassis No. : ZYX102116050
Policy No. : 5087272209-03
Date of Accident : 15/05/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Door (RH) / DD		\$ 1,084.90 /
2	1	Rear Fender Arch Garnish (RH) / PRK CUT		\$ 278.50 /
3	1	Rear Door Garnish (RH) X NM		\$ 321.70 X
4	1	Rear Door Tape (RH) / NR		\$ 110.00 /
				\$ 1,795.10
			Less 20%	\$ 359.02
				\$ 1,436.08
				\$ 600.00 450
		To dismantle & change rear RH door, rear RH fender arch garnish, knocking & pull straight rear RH fender and all area affected by accident.		\$ 20.00 /
		To perform wire checking.		\$ 60.00 50
		To dismantle & transfer rear RH door mechanism & fitting to new door.		\$ 600.00 499
		To spray rear RH fender, rear RH door and touch up rear bumper.		\$ 2,716.08
			7% GST	\$ 190.13
			Total	\$ 2,906.21 920

Stew (LKK)
8322 8813

WHL Repair
4 days

P/P L/S

Ry bef-

AL SM

P-1105.95

L-920

2025.95

L/S - 1620.94

= 1600



Authorised by Claims Dept



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19008802/Etd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-12-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9464K	Veh. Inspected	SLZ 7691E
Policy No.		Coverage (\$)	0.00
Claim No.	D19003272MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	17/05/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA C-HR	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	ZYX102116050	Colour	BLACK
Odometer	99596	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R17	MICHELIN	6 mm
L/H Front Tyre	215/60 R17	MICHELIN	6 mm
R/H Rear Tyre	215/60 R17	MICHELIN	6 mm
L/H Rear Tyre	215/60 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/05/2019	Inspection Date	01/07/2019
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 7691E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR DOOR (RH)	DENTED	1,084.90	1,084.90
1	REAR FENDER ARCH GARNISH (RH)	CUT	278.50	278.50
1	REAR DOOR GARNISH (RH)	NOT NECESSARY	321.70	-
1	REAR DOOR TAPE (RH)	NECESSARY	110.00	110.00
	LESS 20% DISCOUNT		-359.02	-
	LESS 25% DISCOUNT		-	-368.35
			1,436.08	1,105.05
LABOUR				
	TO DISMANTLE & CHANGE REAR RH DOOR, REAR RH FENDER ARCH GARNISH, KNOCKING & PULL STRAIGHT REAR RH FENDER AND ALL AREA AFFECTED BY ACCIDENT.		600.00	450.00
	TO PERFORM WIRE CHECKING.		20.00	20.00
	TO DISMANTLE & TRANSFER REAR RH DOOR MECHANISM & FITTING TO NEW DOOR.		60.00	50.00
	TO SPRAY REAR RH FENDER, REAR RH DOOR AND TOUCH UP REAR BUMPER.		600.00	400.00
			1,280.00	920.00
GRAND TOTAL			2,716.08	2,025.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,600.00

Report Ref No. CS/FCI19008802/Etd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.