

ASS. REC. BY:

REF: CS/LPC19008819/ Jtd 302

Special Instruction:

Surveyor: Hwee Jie

ASSIGNMENT (Office)

From (Person): Gerald Poh

of LPC

Date/Time: 17.5.19 4:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 9677R

Insured:

YL 9292E

at Workshop m/s

E motoring

Tel:

83633050

of

2 Vishnu Industrial Street 1

Policy No:

Claim No:

19/19/19/VCO017801

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

17.5.19 5:01pm

Person Contacted:

Sam hui

Vehicle

IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

FBN 9677R - MA / LPC 19008664 / 24

D.O.A - 11/05/2019

YL 9292E - NA / LPC 19008664 / 24

D.O.A - 11/05/2019

30/5@ 2:15pm - revised via email to Gerald poh

REF: Hwee Jie

REF:

LONPAC

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No. FBN9677R Yr Regn: 11 Jun 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Sniper C.C. 180

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MH3UG0740J0142477

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80/90-17

R: 120/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. - mm L/Bal. - mm

D.O.A. 11/5/19 D.O.I. 17/5/19

Survey held at E-motoring

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Workshop will email estimate

Confirmed L/S \$1300+ 3days of repair. (Red: 1144, 46%)

RECEIVED 14 JUN 2019

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

1) 14/6 Typist.

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1 S + PS. 1 SI

1 Photos

1 Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / L.B.T. (\$ 1300+)

350

350

## Nivitha (LKK Auto)

---


**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Friday, 17 May 2019 4:25 PM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** FW: PRE REPAIR SURVEY OF YL9292E YR REF: 19/19/19/VC00/21801 OUR REF: CL/190529/T/EM [External Confidential]  
**Attachments:** 17052019162141.pdf

### Lonpac External - Confidential

Dear Nivitha,

Please proceed as arranged.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



*Lonpac External - Confidential data is for use by authorised external parties only.*

---

**From:** Catherine Lim LLC [mailto:info@catherinelimllc.com]  
**Sent:** Friday, 17 May, 2019 4:06 PM  
**To:** GERALD POH WEE BIN  
**Subject:** PRE REPAIR SURVEY OF YL9292E YR REF: 19/19/19/VC00/21801 OUR REF: CL/190529/T/EM

Dear Sir

We refer to the above matter (as per your letter attached).

Our client accept LKK – Marcus Chua as the surveyor.

Tks/rgds  
wendy  
Catherine Lim LLC  
20 Havelock Road #03-01  
Central Square  
Singapore 059765  
Tel: 6438 5500  
Fax: 6438 0111  
email: info@catherinelimllc.com



## CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS  
翠 NOTARY PUBLIC - 公証官  
玲 COMMISSIONER FOR OATHS - 宣誓官  
林  
師 CATHERINE C. LIM  
館 DIRECTOR  
LL.B (HONS) SINGAPORE - 法律系 - 律師  
M.B.A. (BUSINESS LAW) - 商業系 - 碩士

20 Havelock Road #03-01  
Central Square Singapore 059765  
UEN No. 201310922K  
GST Registration No. 201310922K  
Tel: (65) 6438 5500  
Fax: (65) 6438 0111  
www.catherinelimllc.com  
Email: info@catherinelimllc.com  
CATHERINE LIM LLC is a law corporation with  
limited liability

Our Ref: CL/190529/T/EM  
Your Ref: YL 9292E  
17 May 2019

M/s Lonpac Insurance Berhad  
100 Beach Road  
#19-00 Shaw Tower  
Singapore 189702  
Attn: Motor Claims Dept

62962706  
via fax: 62507388 & By Hand

Uni-Tat Ice & Marketing Pte Ltd  
51 Ubi Avenue 1  
#01-26 Paya Ubi Industrial Park  
Singapore 408933

CERTIFICATE OF POSTING  
(Please be informed that all supporting documents  
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO  
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING FBN 9677R / YL 9292E ON 11.05.2019 ALONG NORTH BUONA VISTA RD  
SLIP RD TWDS HOLLAND RD**

We are instructed by Dahlan Bin Tapri to notify you of a road traffic accident on 11.05.2019 involving our client's vehicle No FBN 9677R and vehicle No. YL 9292E driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: c/o : E Motoring  
2 Yishun Industrial Street 1  
Northpoint Bizhub #01-23

Contact : Sam Gui @ 8363 3050

Yours faithfully

Enprocc client



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 19/19/19/VC00/21801

Date: 30/5/2019

Our Ref: CS/LPC19008819/Jtd3

The Motor Claims Department  
LONPAC INSURANCE BHD

**PRELIMINARY ADVICE OF VEHICLE NO. FBN 9677R .**


Dear Sir/Madam,

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 17/05/2019 at the premises of M/s E Motoring and have the following to report: -

Workshop Estimate Amount	: S\$ <u>2,444.00</u>
Revised Estimate Amount	: S\$ <u>1,189.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Hwee Jie

Automotive Assessor

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 30 May 2019 2:15 PM  
**To:** GERALD POH WEE BIN  
**Cc:** 'MT\_Claim\_SG'; SUR  
**Subject:** RE: PRE REPAIR SURVEY OF YL9292E YR REF: 19/19/19/VC00/21801 OUR REF: CL/190529/T/EM [External Confidential]  
**Attachments:** PRELI ADVISED FBN 9677R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **FBN 9677R**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]  
**Sent:** Friday, 17 May 2019 4:25 PM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** FW: PRE REPAIR SURVEY OF YL9292E YR REF: 19/19/19/VC00/21801 OUR REF: CL/190529/T/EM [External Confidential]

## Lonpac External - Confidential

Dear Nivitha,

Please proceed as arranged.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



*Lonpac External - Confidential data is for use by authorised external parties only.*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/05/2019 14:03
Date Of Accident	11/05/2019 11:15
Exact Location Of Accident	NORTH BUONA VISTA RD SLIP RD TWDS HOLLAND RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN9677R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DAHLAN BIN TAPRI
NRIC No	S7410229H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86114523
Alternative Phone No	OTHERS-86114523

### Vehicle Particulars

Manufacturer	YAMAHA
Model	SNIPER T150
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5107128811
Cover Note Number	18/01/19 - 17/01/20

### Driver

Name of Driver	MUHAMMAD AFIQ BIN ROSLAN
NRIC No	S9818661A
Date Of Birth	04/06/1998
Occupation	INDOOR
Date Of Driving Pass	01/03/2018
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87152215
Fax Number	
Contact Number	
Email Address	AAAFIIQQQLIFE@GMAIL.COM

Address	BLK 546 WOODLANDS DR.16 #12-213
Postcode	730546
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL9292E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SUN CHANGFANG
NRIC/Passport Number	G6567326L
Contact Number	67448484
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD AFIQ BIN ROSLAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBN9677R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Sketch Plan

### SKETCH PLAN

VEHICLE NO.: FBN 9677R  
INSURER : NTUC  
DATE & TIME: 11/5/19 @ 11:15am

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: (45)  
NRIC/FIN No

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

North Buena Vista Rd

Refer to Police Report No: T/20190511/2091

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

**Date & Time:**

Driver's Signature \_\_\_\_\_

{If driver is not the policyholder}

Date &amp; Time:

Reporting Centre Personnel's Signature

Name \_\_\_\_\_

NRIC/FIN No.

( ) Claim Own Policy ( ) Claim Third Party ( ) Reporting Only  
(x) Claim GB/TP at other workshop (my own workshop)



**SINGAPORE  
POLICE FORCE**



T/20190511/2091

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

1 of 3

Report No: T/20190511/2091

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 11/05/2019 15:12		Vide Report No.:		Station Diary No.: 94	
<b>Informant's Particulars</b>					
Name of Informant: MUHAMMAD AFIQ BIN ROSLAN			Address: APT BLK 546 WOODLANDS DRIVE 16 #12-213 SINGAPORE 730546		
ID Type / ID No.: NRIC NO / S9818661A			Contact No.: Home/Office: Mobile: 87152215		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 20	Date of Birth: 04/06/1998	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: SCDF NS			Driving Licence Information: Class: Date of Expiry:		

<b>General information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 11/05/2019 11:15	Type of Location: T-Junction
Location: Along Road 1 Traveling Toward Road 2 NORTH BUONA VISTA ROAD HOLLAND ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBN9677R	Motorcycle				Seriously Damaged	0
YL9292E	Lorry				Slightly Damaged	0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190511/2091

Police Station Of Origin:  
Woodlands East N.P.C  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No 1800-7679999

2 of 3

Report No T/20190511/2091

## CONTINUATION OF REPORT

<b>Rider</b>			
Name	MUHAMMAD AFIQ BIN ROSLAN	ID No.	S9818661A
Related Vehicle	FBN9677R (Motorcycle)	Contact No.	87152215
Hospital/Clinic	MY FAMILY CLINIC(WOODLANDS)	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	11/05/2019	Date Discharge	11/05/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight
<b>Driver</b>			
Name	SUN CHANGFANG	ID No.	G6567326L
Related Vehicle	NIL	Contact No.	67448484
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the above mentioned time and date, I was at the filter lane turning left towards Holland road. There was a lorry behind me also wanting to turn left at the filter lane. I was inching forward while checking my blind spot before moving when suddenly the lorry hit me from behind. My rear wheel got stuck between the front bumper of the lorry. No ambulance and police were at scene. My bike was damaged and unable to move and have to be towed. I suffered injury on my left foot and headache and was given a 4 days MC.

PR



**SINGAPORE  
POLICE FORCE**



T/20190511/2091

Police Station Of Origin:  
Woodlands East N.P.C  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

3 of 3

Report No: T/20190511/2091

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report L / MARC HANSEL CORPUZ CEPE	Signature Of Informant
Signature Of Interpreter Not applicable	Date/Time 11/05/2019 15.12
Officer In Charge Of Case TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No: 65476172	Classification Of Case
Authentication Stamp NP166	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0229H
Vehicle Details	
Vehicle No.:	FBN9677R
Vehicle to be Exported:	No
Intended Deregistration Date:	21 May 2019
Vehicle Make:	YAMAHA
Vehicle Model:	SNIPER T150
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	G3E6E0459762
Chassis No.:	MH3UG0740J0142477
Maximum Power Output:	-
Open Market Value:	\$2,082.00
Original Registration Date:	11 Jan 2019
First Registration Date:	11 Jan 2019
Transfer Count:	1
Actual ARF Paid:	\$313.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,610.00
COE Rebate Amount:	\$3,478.00
Total Rebate Amount:	\$3,478.00

The information contained herein is correct as at 21 May 2019

OK

# QUOTATION FOR REPAIR : FBN9677R

Qty	Description		Repairer's	
			Estimate	
1	SIDE EXHAUST GUARD	CRA-	<del>120.00</del>	60
1	MUDGUARD	MIS-	<del>120.00</del>	90
1	REAR RIGHT SIDE FAIRING	CRA-	<del>180.00</del>	120
1	REAR FAIRING (ABOVE TAILLIGHT)	CRA-	<del>120.00</del>	60
1	EXHAUST PIPE	SCR-	480.00	
1	REAR LEFT SIDE FAIRING	SCR-	<del>180.00</del>	120
1	TAIL LAMP	SCR-	<del>180.00</del>	120
2	REAR SIGNAL LIGHT	CRA-	<del>120.00</del>	60
1	REAR MUDGUARD HOLDER	CRA-	150.00	
1	REAR NUMBER PLATE LIGHT	MIS-	80.00	
1	REAR EXHAUST GUARD	MIS-	80.00	
1	REAR PILLION BAR	SCR-	<del>150.00</del>	80
			1,960.00	
Less 10%			196.00	
			1,764.00	
<u>Nett items</u>				
1	REAR NUMBER PLATE	MIS-	<del>40.00</del>	15
Total parts			1,804.00	
Towing fees			50.00	30
Rear Disc Alignment			<del>120.00</del>	40
Rear Rim Alignment			<del>120.00</del>	40
Workmanship			<del>350.00</del>	200
Total parts and labour charges			2,444.00	
			5 Days	

*[Signature]*  
24/5/19

Hwee Jie - LKK

21/5/19

L/S 3days.

Total - \$1300/-

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS/LPC19008819/Jtd3e2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 21-06-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YL 9292E	Veh. Inspected	FBN 9677R
Policy No.		Coverage (\$)	0.00
Claim No.	19/19/19/VC00/21801	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	17/05/2019
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA SNIPER	c.c	150
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3UG0740J0142477	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	80/90-17	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70-17	PIRELLI	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/05/2019	Inspection Date	17/05/2019
Survey held at	E MOTORING PTE LTD 2, YISHUN INDUSTRIAL STREET 1 #01-23 NORTH POINT BIZHUB SINGAPORE 768159		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 9677R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SIDE EXHAUST GUARD	CRACKED	120.00	60.00
1	MUDGUARD	MISSING	120.00	90.00
1	REAR RIGHT SIDE FAIRING	CRACKED	180.00	120.00
1	REAR FAIRING (ABOVE TAILLIGHT)	CRACKED	120.00	60.00
1	EXHAUST PIPE	SCRATCHED	480.00	480.00
1	REAR LEFT SIDE FAIRING	SCRATCHED	180.00	120.00
1	TAIL LAMP	SCRATCHED	180.00	120.00
2	REAR SIGNAL LIGHT	CRACKED (1 PC ONLY)	120.00	60.00
1	REAR MUDGUARD HOLDER	CRACKED	150.00	150.00
1	REAR NUMBER PLATE LIGHT	MISSING	80.00	80.00
1	REAR EXHAUST GUARD	MISSING	80.00	80.00
1	REAR PILLION BAR	SCRATCHED	150.00	80.00
	LESS 10% DISCOUNT		-196.00	-150.00
			1,764.00	1,350.00
<b>SPECIAL NETT ITEMS</b>				
1	REAR NUMBER PLATE (SN)	MISSING	40.00	15.00
			40.00	15.00
<b>LABOUR</b>				
	TOWING FEES.		50.00	30.00
	REAR DISC ALIGNMENT.		120.00	40.00
	REAR RIM ALIGNMENT.		120.00	40.00
	WORKMANSHIP .		350.00	200.00
			640.00	310.00
<b>GRAND TOTAL</b>			<b>2,444.00</b>	<b>1,675.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,300.00</b>

Report Ref No. CS/LPC19008819/Jtd3e2

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.