

REF:

REF:

65/Am 1900 8821 BUD 3

SS. REQ. BY:

ASSIGNMENT

Veh No: VAY 2308 Yr Regn: 27/7/2012Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 523i M524i cc 2996
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 19702 T/Radio: Insured / Std / NI / NA

Eng/No:

Chk: WBAFS120206776343Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / STD / STD A/Rim orType Size: F: 245/40/19 ZENIAR: 275/35/19 MIC

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
RBal	7 mm	RBal	7 mm
UBal	7 mm	UBal	7 mm
D.O.A.	15/5/2010	D.O.I.	

Survey held at Deam WorksDes. of Damages: Frt / Rear / O/S / NIS / UIC / Roottop or

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Date / Time

Action / Instruction

Not AuthorisedRange 900/2 - 1000/2Refx to insurance to for insured in Rm.Refx to

Date/Time, File Pass U?

☐ : Preli. Report☐ : Final Report

1) Date/Time, File Return U?

2) _____

Report Form:

Lump Sum / E.R. (%)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS: \$

P/Rate

O/Rate

TOTAL

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Wheel and (\$)