



























PAR Automotive Consultancy

Regn No: 529E6974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0719-18-TCA

19 October 2018

ACCIDENT VEHICLE SURVEY REPORT

Hooi Ah Chye
Blk 172 Bedok South Road #03-427
Singapore 460172

VEHICLE INFORMATION:

Vehicle Reg No.:	SGF255S	Odometer:	212902km
Make & Model:	Volkswagen Golf GTI	Colour:	Black
Chassis number:	WVWZZZ1KZ6U018240	Date of accident:	30/04/2018
Year of Regn.:	29/03/2006	Date inspected:	03/05/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	09/05/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.











