

REF: CS3/ASM18068117/Nsd3-^{er}

Special Instruction:

4/8: \$13,200.00

ASSIGNMENT (Office)

From (Person): Xin Yi of Sen Hong Date/Time: 18/3/2019
Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: PAR Automotive Consultancy

Workshop: Twincar Automotive

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SGF255S Insured: GBD 4892X

at Workshop m/s Twincor Automotive Tel: 68420051

of 2 kaki Bukit Ave 2 #01-17/18

Policy No: _____ Claim No: 19-26561 PD-0

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30/04/2010
(Client's Record)

(Client's Record)


D.O.A. 30/04/2019

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 9 days)

Date/Time: 12/06/19 Submit Final Fig \$7,000/- 45 6 days (Red \$ 6,200/47 47%; Original 9 days)

Date/Time	Action/Instruction
	SGF2555 - CS3/ASM18068117/N24be2
	GBD4892 X - CS3/ASM18008117/N24be2
	DOA: 30/4/2018
	DOA: 30/04/2018
	RECEIVED 17 JUN 2018
	 10/6/2018

Para(1) : Parts found not replaced	(To highlight R or UB , LR , Etc)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : 1000000

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add

Transport

Photos

Others

Total

1) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____