



Your Ref: 19.26561 PD-O

Date: 13th Jun 2019

Our Ref : CS3/ASM18008117/Nsd3e2-1

M/s AXA Insurance Pte Ltd

C/O: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGF 255S

INSURED VEHICLE: GBD 4892X

ACCIDENT DATE: 30/04/2018

We thank you for your instruction on 18/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGF 255S from M/s Par Automotive Consultancy.
- b) Singapore Accident Statement of Vehicles SGF 255S and GBD 4892X.
- c) Final Repair Bill of SGF 255S from M/s Twincar Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of SGF 255S.

Pre-Repair Inspection Date : 04/05/2018 at M/s Twincar Automotive Pte Ltd, 2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGF 255S
Make & Model	: Volkswagen Golf GTI
Year of Registration	: 2006
Chassis Number	: WVWZZZ1KZ6U018240
Engine Capacity	: 1984 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.