

22/03/2012

ASS. REC. BY:

REF: CS/SPF19008827/T1vd30h

Special Instruction:

Inspector: TAUSIFU

ASSIGNMENT (Office)

From (Person): Frankie they of SPF Date/Time: 17/5/19 @ 3pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFA 69B Insured: GBC 759E

at Workshop m/s Truseur/kars Tel: 63310683

of 27A Tenjony Penjuru @ 5th floor

Policy No: _____ Claim No: AEMD/105/009/2019/062

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A 7.5.2019

CA / REV / REP. / REV 24 HRS _____ H.O.D. Endorsement: 22/5/2019 @ 3pm

Date/Time: 4:30pm @ 17/5/2019 Person Contacted: Eva Vehicle IN OUT

Date/Time	Action/Instruction
	Estimate (✓) SFA 69B-x
16/7/19	@ 2:49 pm Eva said vehicle has not send in for repair
26/7/19	Submit preli revised

Do Not Finalise

ASSIGNMENT

From: _____ Date: 22.5.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFA 69B

at Workshop m/s Tran Neurokar s

of 27A Tanjong Pagar @ 5 floor

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 200 p.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS awp'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFA 69B Yr Regn: 2018, Bay

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Cayenne E3 c.c. 2995

Colour: B/wh. A/C: Insured / Std / NI / NA

Sp. Reading: 11719 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP/227942KD A0818

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285/40 R21

R: 315/35R21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 22/5/19 @ 230

Survey held at Tran Neurokar

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 JUL 2019

RECEIVED 15 AUG 2019

Date/Time, File Pass to?

: Preli. Report

: Final Report

1) _____

Date/Time, File Return to?

2) 26/7 - typist

Days Of Repair: 8

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

<u>220</u>
<u>220</u>

Report Format: TP

Lump Sum / I.B.I: (\$ _____)

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Friday, 17 May 2019 3:00 PM
To: Veron Chen (LKKAuto); assignments
Cc: Abdul Rahman MOHAMAD SALIM (SPF); Hafizul Farhan RAHMAT (SPF)
Subject: RE : Pre-Repair Inspection for vehicle SFA69B

Your reference: SFA69B

Our reference: AEMD?105/009/2019/062

Veron,

Please conduct a Pre-Repair Inspection for vehicle SFA 69B at the address and date/time listed below:

22/2/2019 @2pm 27A Tanjong Penjuru 5th floor.

PLEASE CONTACT M/S EVA KOK AT 63310683.

Thanks.

22/2/2019 @2pm
Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/05/2019 15:07
Date Of Accident	07/05/2019 18:05
Exact Location Of Accident	ALONG PIE RIGHT AFTER TOA PAYOH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFA69B
Insured/Policyholder	
Name Of Registered Owner	SONG HWEE TIONG
NRIC No	S1661149B
Email Address	CHRIS@PKWALAW.COM
Mobile Phone No	(LOCAL) +65-96388663
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	PORSCHE
Model	CAYENNE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA392830/1
Cover Note Number	

Driver

Name of Driver	SONG HWEE TIONG
NRIC No	S1661149B
Date Of Birth	28/06/1964
Occupation	INDOOR
Date Of Driving Pass	03/07/1985
Driving Experience	33 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96388663
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	CHRIS@PKWALAW.COM

Address	2A RAMSGATE ROAD SINGAPORE 437472
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SONG ALEXIA XIAO MEI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MOUNTBATTEN NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 60 DAKOTA CRESCENT #01-213/ 215 , POSTCODE: 390060 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-3449999 - FAX NO: 64474185
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT AND SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC759E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NICHOLAS TAN
NRIC/Passport Number	
Contact Number	85065522
Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


Janice Syn



Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

Report No. T/20190507/2197

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Nicholas Tan	ID No.	NIL
Related Vehicle	GBC759E (Van)	Contact No.	85065522
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SONG HWEE TIONG	ID No.	S1661149B
Related Vehicle	SFA69B (Car)	Contact No.	96388663
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 07/05/2019 at about 1805hrs, I was driving my vehicle bearing registration number SFA69B along PIE heading towards Changi with my daughter on the first lane. Right after Toa Payoh exit, there is one vehicle in front had applied jammed brake. I subsequently applied emergency brake and managed to stop my vehicle on time. Out of sudden, there is one vehicle hit onto my vehicle from the back. I went out and made a check, there is one police van bearing registration number GBC759E behind my vehicle.

Traffic police came and given me a case card with vide incident number E/20190507/118. I was advised to lodge a police report as soon as possible. I would like to state that there are no serious injuries on me and the driver of said police van.



**SINGAPORE
POLICE FORCE**



T/20190507/2197

Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

3 of 3

Report No. T/20190507/2197

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Staff Sgt JUHARDI BIN SAADON	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 07/05/2019 21:23
Officer In Charge Of Case: TP / DDGVT / Sgt 3 MUHAMMAD FIRDAUS BIN SULEIMAN Contact No.: 65476223	Classification Of Case:

Authentication Stamp
NP168


T9945



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

SINGAPORE POLICE FORCE		NAME : Mr Song Hwee Tiong	WIP : 45730
ATTN. : MOTOR CLAIMS		ADDRESS : 2A Ramsgate Road Singapore 437472	EXCESS :
FAX :		TEL :	DATE : 13.05.2019
VEH NO :	SFA69B	DATE IN :	CONTACT PERSON : EVA 63310683
CHASSIS NO :	WP1ZZZ9YZKDA03818	MILEAGE :	TYPE OF CLAIM : TP
MODEL :	Cayenne E3	DATE REG.: 27.08.2018	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description		QTY	REVISED	PRICES
1	REAR BUMPER		1	de ✓	\$ 1,935.50
2	REAR BUMPER SOUND MAT LOWER LH		1	X n ✓	\$ 50.80
3	REAR BUMPER SOUND MAT LOWER RH		1	X n ✓	\$ 50.80
4	REAR BUMPER SOUND MAT UPPER LH		1	? ✓	\$ 85.00
5	REAR BUMPER SOUND MAT UPPER RH		1	? ✓	\$ 85.00
6	REAR BUMPER SPOILER		1	de ✓	\$ 1,205.10
7	REAR BUMPER SPOILER LOWER TRIM		1	cut ✓	\$ 840.00
8	TAIL PIPE TRIM COVER LH		1	cut ✓	\$ 137.00
9	TAIL PIPE TRIM COVER RH		1	X n ✓	\$ 127.00
10	REAR BUMPER BLIND RIVET		6	new ✓	\$ 9.00
11	SENSOR GASKET		2	new ✓	\$ 5.20
12	SENSOR PARKASSIST		2	? ✓	\$ 477.00
13	TOW COVER		1	X n ✓	\$ 72.90
14	REINFORCEMENT		1	? ✓	\$ 1,070.10
15	REAR BUMPER ATTACHEMENT STRIPE CENTER		1	? ✓	\$ 159.90
16	REAR BUMPER EXPANDER NUT		8	new ✓	\$ 12.80
17	TAILGATE		1	bt ✓	\$ 3,256.40
18	TAILGATE DAMPER		2	X n ✓	\$ 1,485.00
19	BLIND RIVET NUT		8	new ✓	\$ 34.40
20	TAILGATE DRAIN BUSH		2	X n ✓	\$ 21.80
21	BLIND RIVET		8	new ✓	\$ 44.00
22	STOPPER		1	X n ✓	\$ 7.10
23	P000-043-305-51-/CAVITY PRESERVATION (AK		1	X n ✓	\$ 75.30
24	DRAIN BUSH SPARE-WHEEL WEL		2	repeated	\$ 21.80
25	STOPPER		1	repeated	\$ 7.10
26	TAILGATE ADHESIVE. TAPE		4	new ✓	\$ 48.00
27	REAR TOP SPOILER SEAL TAPE		1	new ✓	\$ 119.30
28	REAR WINDSCREEN GASKET		1	new ✓	\$ 115.90
29	LOGO "CAYENNE"		1	new ✓	\$ 117.80
30	TAIL PIPE LH - photo		1	? ✓	\$ 693.40
TOTAL PARTS					\$ 12,370.40
LESS 10%					\$ 1,237.04
TOTAL PARTS COST					\$ 11,133.36

Labour Description			
1	TO REPLACE REAR BUMPER, TAILGATE & TO REPAIR REAR END PANEL AREAS AFFECTED BY THE ACCIDENT.	1560	3120 \$ 7,020.00
2	TO RESPRAY REAR BUMPER, TAILGATE & REAR END PANEL.		2400 \$ 3,800.00
3	TO TRANSFER THE TAILGATE MECHANISM.		NETT ✓ \$ 780.00
4	TO REPLACE TAIL PIPE LH & CHECK FOR LEAKAGE.		NETT ✓ \$ 780.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.		NETT ✓ \$ 560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.		NETT ✓ \$ 195.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		NETT ✓ \$ 200.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT ✓ \$ 600.00
9	SUNDRIES.		NETT 30 \$ 50.00

TOTAL LABOUR	\$ -	\$ 13,985.00
TOTAL PARTS	\$ -	\$ 11,133.36
TOTAL	\$ -	\$ 25,118.36
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

M. Mansour
22/5/19

Taylor 97495749
- WP'

22/5/19 @ 2:30pm

Resurvey before paint.

540@lkkauto.com.

7-8 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF19008827/T1vd3e2

ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333

Date : 16-08-2019



ATTN : FRANKIE THAY

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 759E	Veh. Inspected	SFA 69B
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/062	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	17/05/2019

2. Vehicle Particulars & Condition

Make & Model	PORSCHE CAYENNE E3	c.c	2995
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WP1ZZZ9YZKDA03818	Colour	BLACK
Odometer	11719	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	285/40 R21	PIRELLI	6 mm
L/H Front Tyre	285/40 R21	PIRELLI	6 mm
R/H Rear Tyre	315/35 R21	PIRELLI	6 mm
L/H Rear Tyre	315/35 R21	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/05/2019	Inspection Date	22/05/2019
Survey held at	27A TANJONG PENJURU		
Repairer	TRANS EUROKARS PTE LTD		

5a. Remarks

A) THE VEHICLE HAS NOT SEND IN FOR REPAIRS.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFA 69B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,935.50	1,935.50
1	REAR BUMPER SOUND MAT LOWER LH	NOT NECESSARY	50.80	-
1	REAR BUMPER SOUND MAT LOWER RH	NOT NECESSARY	50.80	-
1	REAR BUMPER SOUND MAT UPPER LH	* CHECK	85.00	-
1	REAR BUMPER SOUND MAT UPPER RH	* CHECK	85.00	-
1	REAR BUMPER SPOILER	DEFORMED	1,205.10	1,205.10
1	REAR BUMPER SPOILER LOWER TRIM	CUT	840.00	840.00
1	TAIL PIPE TRIM COVER LH	CUT	137.00	137.00
1	TAIL PIPE TRIM COVER RH	NOT NECESSARY	127.00	-
6	REAR BUMPER BLIND RIVET	NECESSARY	9.00	9.00
2	SENSOR GASKET	NECESSARY	5.20	5.20
2	SENSOR PARKASSIST	* CHECK	477.00	-
1	TOW COVER	NOT NECESSARY	72.90	-
1	REINFORCEMENT	* CHECK	1,070.10	-
1	REAR BUMPER ATTACHMENT STRIPE CENTER	* CHECK	159.90	-
8	REAR BUMPER EXPANDER NUT	NECESSARY	12.80	12.80
1	TAILGATE	BENT	3,256.40	3,256.40
2	TAILGATE DAMPER	NOT NECESSARY	1,485.00	-
8	BLIND RIVET NUT	NECESSARY	34.40	34.40
2	TAILGATE DRAIN BUSH	NOT NECESSARY	21.80	-
8	BLIND RIVET	NECESSARY	44.00	44.00
1	STOPPER	NOT NECESSARY	7.10	-
1	P000-043-305-51-/CAVITY PRESERVATION (AK	NOT NECESSARY	75.30	-
2	DRAIN BUSH SPARE-WHEEL WEL	REPEATED	21.80	-
1	STOPPER	REPEATED	7.10	-
4	TAILGATE ADHESIVE. TAPE	NECESSARY	48.00	48.00
1	REAR TOP SPOILER SEAL TAPE	NECESSARY	119.30	119.30
1	REAR WINDSCREEN GASKET	NECESSARY	115.90	115.90
1	LOGO "CAYENNE"	NECESSARY	117.80	117.80
1	TAIL PIPE LH	* CHECK	693.40	-
	LESS 10% DISCOUNT		-1,237.04	-788.04
			11,133.36	7,092.36



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
			50.00	30.00
	LABOUR			
	TO REPLACE REAR BUMPER, TAILGATE & TO REPAIR REAR END PANEL AREAS AFFECTED BY THE ACCIDENT.		7,020.00	3,120.00
	TO RESPRAY REAR BUMPER, TAILGATE & REAR END PANEL.		3,800.00	2,400.00
	TO TRANSFER THE TAILGATE MECHANISM.		780.00	780.00
	TO REPLACE TAIL PIPE LH & CHECK FOR LEAKAGE.		780.00	780.00
	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.		560.00	560.00
	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.		195.00	195.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		200.00	200.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		600.00	600.00
			13,935.00	8,635.00
	GRAND TOTAL		25,118.36	15,757.36
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,313.36 NETT)			15,757.36

Report Ref No. CS/SPF19008827/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.