

ASS. REC. BY:

REF: CS3/MSG 18000490/ Bldg<sup>er</sup>

Range  
Instructing

Surveyor:

ASSIGNMENT (Office)

From (Person):

Pauline Thum of Mui

Date/Time 16/05/2019

Estimated Cost:

Bill to:

OD / FD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 4650D

Insured:

SLF 7666 J

at Workshop m/s

Hiap Lek Automobile

Tel:

9660 1347

of 31K14 #01-19 & for B

Policy No:

80437079QMY

Claim No:

543555

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 30/12/2017

CA / REV / REP. / REV 24 HRS

up?

H.O.D. Endorsement:

Date/Time:

9:15am @ 04/01/18

Person Contacted:

Han Wei

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJS 4650D - X

SLF 7666 J - X

Dismantle Part: 15/12/2018

Lump Sum \$9000 - (Red 63.00, 73%)

Submit

3/6/2019

Do Not Finalise

RECEIVED 06 JUN 2019



PRS  
W. T. Sam

MSLH

INSURANCE

Estimate Cost  
 GO/TP/WS/TP RES/OD RES/EVA/INV/INV  
 To inspect vehicle  
 at location  
 of  
 insured  
 Policy No.  
 Certificate  
 Sum Insured  
 Deductible  
 Name of Insured

SJS 4650 D  
 Hiup Lek

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Sal. or Market Value  
 DAD Accident Report Consistent? Yes or No  
 DIA - PR Seen Consistent? Yes or No  
 Est. Repair Date Res. Yes or No  
 LTR Date Res. Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted Vehicle IN/OUT

Date Time Appt. Instruction

Range \$2500 - \$3000  
 5 Days Repairing

License: SJS 4650 D Date: 19/8/2009  
 Type: M/Cycle Bus Van Lorry Taxi Prime Mover  
 Truck/Trailer  
 Make: Hyundai CC: 1591  
 Color: Silver Insured/Std/N/NA  
 So. Reading: 153362  
 Engine  
 Chassis: KMMD C 81 DMAU 054900  
 Gen. Con: Good Fair Poor Burnt  
 Steering: In order/Jammed/Leaked/Burnt  
 Brake: In order/Jammed/Leaked/Burnt  
 Mod: NE SW SE STD A.R.M.  
 Tyre Size: F 195/65 R15  
 R 195/65 R15  
 BS/DUN/EXNOVA/GY/PS/LZA/NG/OHTSU/PIR/SUMI  
 TOYO/YOKO  
 Front: 4 - 4 -  
 R.E.A. 4 - 4 -  
 L.Bel. 4 - 4 -  
 D.O.A. 30/12/17 12/1/18  
 Survey Note: A3 Above  
 Des. of Damages: Frt/Rear/OS/NS/UC/Reotop  
 Right Rear  
 The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 2018

Copy to: Assessor

0604148

Copy to: Insured

☐ Prel. Report  
☐ Final Report

Days Of Repair

Resurvey No. of Trip

Add Fee:

☐ State Ins. Fee  
☐ Motor Ins. Fee  
☐ Tolls  
☐ Traffic Light Fee

Report Form

Lump Sum (L.B.)

ARS

4/4/2018

120
60
10
130



# ROY & PARTNERS

8 JAN 2018

(Business Registration No. 53131170L)

Advocates & Solicitors

Commissioner For Oaths

Notary Public

MONOJ KUMAR ROY LLB (Hons.) S'pore

GERALD MARTIN WEE LLB (Hons.) Liverpool

101 Cecil Street #11-09 Tong Eng Building, Singapore 069533


Tel : 6536 8466

Fax : 6536 1963 (Not For Service Of Documents)

Enquiries: [rovppartners@rovppartners.com.sg](mailto:rovppartners@rovppartners.com.sg)

Our Ref: MKR/104/7722/2018/as.mt

Your Ref: To be advised (Your insured vehicle: SLF 7666J)



8th January 2018

M/S MSIG INSURANCE (SINGAPORE) PTE LTD

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

(Attn: Motor Claims Department)

BY FAX: 6225 6371 ONLY

Dear Sirs,

**CLAIMANT: NG SWEE SIONG, WILSON**

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NO. SJS 4650D AND SLF 7666J ALONG MALAYSIA CHECKPOINT TOWARDS SINGAPORE ON 30.12.2017 AT ABOUT 1745 HOURS**


We refer to the above matter.

We act for Ng Swee Siong Wilson, the owner of motor car No. SJS 4650D.

We are instructed by our client to notify you of a road traffic accident on **30th December 2017** at about **5.45pm** along **Malaysia Checkpoint towards Singapore** involving our client's motor car registration number **SJS 4650D** and motor car registration number **SLF 7666J** driven by your insured at the material time. A copy of the Singapore Accident Statement is enclosed.

As a result of the accident, our client's motor car **SJS 4650D** has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SJS 4650D** at our client's repairer workshop, M/s Hiap Lek Automobile Trading at 160 Sin Ming Drive, #05-17, Sin Ming Autocity, Singapore 575722. Your said surveyor may contact Mr. Han wei at 6453 1743. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

  
**MONOJ KUMAR ROY**

Enc.

cc. M/s Hiap Lek Automobile Trading  
(Your Ref: SJS 4650D)

(By Fax: 6457 6181 Only)



8 JAN 21

Vehicle No.	535 46501			Model / Make	Hyundai	130
Date of Accident	30/12/17					
Time of Accident	17.45			HRS		
Location of Accident	Malaysia check point toward Singapore					
Exact purpose use during accident	Private Use					
Name of Owner	Ng Suet Siong, Wilson					
Telephone No.	H/P: 9669 2728			Home:	Office:	
NRIC	57107923F					
Address	61 Upper Serangoon View #11-17 S(534015)					
Claim type	OD			(THIRD PARTY) REPORTING ONLY		
Insurance Company	SOMPO					
Type of Coverage	Comprehensive Third Party Third Party / Fire / Theft					
Policy No.	117MTPVO1001315					
Name of Driver	As Above If No,					
NRIC						
Date of birth	Any Passengers: 3					
Occupation	Outdoor / (Indoor)					
Driving License Pass Date	07 Jun 1996					
Gender	Male / Female					
Contact No.	H/P:			Home:	Office:	
Address						
Driver have any own vehicle	(No) If yes, Reg No.					
Relationship	Employee, (If no, state Owner)					
Weather condition	(Clear) Raining Other					
Road Surface	(Dry) Wet Other					
Any Injuries	(No) If Yes, Who?					
Name And Contact No.						
Name And Contact No.						
Police Report	(No) If Yes, Where?					
Vehicle B No.	SLF 7666J			Any Passengers: 2		
Name of Driver				Contact No.:		
Vehicle C No.				Any Passengers:		
Vehicle D No.				Any Passengers:		
Vehicle E No.				Any Passengers:		
Vehicle F No.				Any Passengers:		
Vehicle G No.				Any Passengers:		
Witness Name				Witness Contact:		
Accident Portion	Right Portion					
Camera Recorder	(Yes/No)					
Email Address	N85258@gmail.com					
PARTICULAR WORKSHOP	N-51 Automotive Pte Ltd					
CONTACT NO.	6842 0051 / 6744 0510					
CONTACT PERSON	AMOS					
FAX NO	6741 0510					
WORKSHOP Email Address	Sales@n51.com.sg					



WHOMBY  
95-4016

Malaysia Check Point Toward Singapore



A-SJS 4650-1

B-SLF 7666 J

#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above date and time, I was driving along Malaysia toward Singapore

on the 2 lanes of a 4 lanes road. Somewhere before the check point,

Vehicle ahead of me slowed down and stopped due to heavy traffic flow.

As such, I applied brake to slowed down and stopped. Vehicle B (SLF 7666 J)

that was travelling on the right lane (On My Right). Suddenly filtered

to the left, without any signal thus encroaching into my path. As a

result, The left portion of vehicle B (SLF 7666 J) collided onto the right

portion of my vehicle.

A-SJS 4650-1

B-SLF 7666 J

#### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No:



# PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 64531173, Fax : 64536131.  
Consultants: Vehicle appraisal & inspection, accident investigation, expert witness

Report No: 0036-18-HLm

19 March 2018

Ng Swee Siong Wilson  
160 Sin Ming Drive #05-17 Sin Ming Autocity  
Singapore 575722

INVOICE No. 0036-18-HLm


Vehicle No. SJS4650D

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$618.00
Total amount payable		<u>\$618.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy





Report No: 0036-18-HLm

19 March 2018

## ACCIDENT VEHICLE SURVEY REPORT

Ng Swee Siong Wilson  
160 Sin Ming Drive #05-17 Sin Ming Autocity  
Singapore 575722

### VEHICLE INFORMATION:

Vehicle Reg No.:	SJS4650D	Odometer:	153381km
Make & Model:	Hyundai FD I30 CW 1.6 A	Colour:	Silver
Chassis number:	KMHDC81DMAU054966	Date of accident:	30/12/2017
Year of Regn.:	19/08/2009	Date inspected:	12/01/2018
Repairer at:	Hiap Lek Automobile Trading	Date inspected (After Repair)	18/01/2018
	160 Sin Ming Drive #05-17 Sin Ming Autocity		
	Singapore 575722		

### STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

### TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Michelin	5mm/Michelin	195/60R15
Rear:	5mm/Michelin	5mm/Michelin	195/60R15

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the RH portion.

Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



## Parts and Labour Assessment

Report No: 0036-18-HLM

Vehicle No: SJS4650D

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Rear bumper	1	deformed	448.00	448.00
Rear bumper side retainer	2	necessary	56.00	56.00
Rear bumper clip	10	necessary	35.00	35.00
Rear shock absorber RH	1	bent	220.00	220.00
Rear lower arm RH	1	bent	261.80	261.80
Rear knuckle arm RH	1	bent	383.00	383.00
Rear knuckle assist arm RH	1	bent	162.00	162.00
Rear trailing arm RH	1	bent	166.80	166.80
Rear control arm RH	1	bent	192.80	192.80
Rear stabiliser link RH	1	bent	75.80	75.80
Rear wheel hub/bearing RH	1	dislodged	349.00	349.00
Rear door RH	1	buckled	1,412.20	1,412.20 PDV
Rear door frame sticker RH	1	necessary	27.00	27.00
Rear door frame sticker RH	2	necessary	54.00	54.00
Rear door glass outer moulding RH	1	necessary	58.50	58.50 NEC
Rear door glass inner moulding RH	1	necessary	44.20	44.20 NEC
Rear door outer handle RH	1	fractured	61.10	61.10
Rear door outer handle end cap RH	1	fractured	26.00	26.00
Rear door hinge RH	2	bent	114.40	114.40
Rear door check RH	1	bent	71.50	71.50
Rear door weatherstrip RH	1	deformed	133.00	133.00
Rear door inner trim board RH	1	deformed	632.00	632.00
Rear door window regulator RH	1	bent	236.00	236.00
Rear door window regulator motor RH	1	shorted	229.00	229.00
Rear door window glass channel RH	1	bent	38.00	38.00
Rear door inner lock RH	1	bent	246.00	246.00
Front door RH	1	buckled	1,367.35	1,367.35 R
Front door frame sticker RH	1	necessary	27.00	27.00
Front door frame sticker RH	2	necessary	54.00	54.00
Front door glass outer moulding RH	1	necessary	57.20	57.20
Front door outer handle RH	1	fractured	61.10	61.10
Front door outer key cylinder lock RH	1	bent	78.00	78.00
Front door outer key cylinder lock cover RH	1	fractured	26.00	26.00
Subtotal before discount			7,403.75	7,403.75
Percentage discount 0% and 20%			0.00	1,480.75




		<b>Sub-total 1</b>	7,403.75	5,923.00	
Rear door speaker RH	1	distortion	150.00	<del>150.00</del>	NN
Rear sport rim RH	1	abraded	450.00	<del>450.00</del>	R2
		<i>Subtotal before discount</i>	600.00	600.00	
	<i>Percentage discount</i>	0% and 0%	0.00	0.00	
		<b>Sub-total 2</b>	600.00	600.00	
		<b>Parts-total</b>	8,003.75	6,523.00	
<b>LABOUR</b>					
1. To straighten and panel beating rear RH fender, RH door centre pillar and RH frame members. To remove and refit above parts.			840.00	<del>660.00</del>	
				300.00	
2. To putty, re-spray painting and polish affected areas.			1,500.00	<del>1,000.00</del>	
				600.00	
3. To check and rectify wiring system.			80.00	<del>50.00</del>	
				30.00	
4. To rust proof affected areas.			120.00	60.00	
5. To remove, refit RH front sport rim/tyre and balancing.			50.00	<del>40.00</del>	NN
6. To remove and refit rear suspension system.			400.00	<del>350.00</del>	X
7. To conduct electronic wheel alignment test.			180.00	<del>150.00</del>	
				60.00	
8. To remove, transfer and refit RH rear and front door components.			300.00	<del>200.00</del>	
				100.00	
				50.00	
		<b>Labour total</b>	3,470.00	2,510.00	
		<b>Parts &amp; Labour total</b>	11,473.75	9,033.00	

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is : **\$7,200.00**  
and the recommended number of working days for the repairs is : **7**

  
B J Loi (J Eng. MIMI, AIRTE)  
Automotive Appraiser

*4 days*



## Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SJ54650D
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	HYUNDAI
Vehicle Model :	FD I30 CW 1.6 A
Chassis No. :	KMHDC81DMAU054966
Propellant :	Petrol
Engine No. :	G4FC9U701591
Engine Capacity :	1591 cc
Maximum Power Output :	89.7 kW ( 120 bhp )
Maximum Laden Weight :	1780 kg
Unladen Weight :	1360 kg
Year Of Manufacture :	2009
Original Registration Date :	19 Aug 2009
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$15,291.00
COE Expiry Date :	18 Aug 2019
Road Tax Expiry Date :	18 Feb 2018
PARF Eligibility Expiry Date :	18 Aug 2019
Inspection Due Date :	18 Aug 2018



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/01/2018 17:52
Date Of Accident	30/12/2017 17:45
Exact Location Of Accident	MALAYSIA CHECKPOINT TWDS SINGAPORE
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS4650D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NG SWEE SIONG WILSON
NRIC No	S7107923F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96692728
Alternative Phone No	OFFICE-96692728

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I30
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01001315
Cover Note Number	

### Driver

Name of Driver	NG SWEE SIONG WILSON
NRIC No	S7107923F
Date Of Birth	06/03/1971
Occupation	INDOOR
Date Of Driving Pass	07/06/1996
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96692728
Fax Number	
Contact Number	OFFICE-96692728
EMail Address	NOEMAIL



Address	61 UPPER SERANGOON VIEW #11-17
Postcode	534015
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : LEONG WYNN-NA ROWEENA GENDER: : FEMALE
Passenger 2	NAME: : NG YEE TENG RAENEICE GENDER: : FEMALE
Passenger 3	NAME: : NG JINN KHAI WILSHERE GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE ABOVE DATE AND TIME, I WAS DRIVING ALONG MALAYSIA TOWARDS SINGAPORE ON THE 2 LANES OF 4 LANES ROAD, SOMEWHERE BEFORE THE CHECKPOINT, VEHICLES AHEAD OF ME SLOWED DOWN AND STOPPED DUE TO HEAVY TRAFFIC FLOW. AS SUCH, I APPLIED BRAKE TO SLOW DOWN AND STOPPED. VEHICLE B (SLF7666J) THAT WAS TRAVELLING ON THE RIGHT LANE (ON MY RIGHT) SUDDENLY FILTERED TO THE LEFT WITHOUT ANY SIGNAL THUS ENCROACHING INTO MY PATH. AS A RESULT, THE LEFT PORTION OF VEHICLE B (SLF7666J) COLLIDED ONTO THE RIGHT PORTION OF MY VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF7666J
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR



Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

NB(



## SKETCH PLAN

Malaysia Check Point Toward Singapore.



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above date and time, I was driving along Malaysia toward Singapore on the 2 lanes of a 4 lanes road. Somewhere before the check point, vehicle ahead of me slowed down and stopped due to heavy traffic flow.

As such, I applied brake to slowed down and stopped. Vehicle B (SLF 7666J) that was travelling on the right lane (On my Right), Suddenly filtered to the left, without any signal thus encroaching into my path. As a result, The left portion of vehicle B (SLF 7666J) collided onto the right portion of my vehicle.

A-535 46501)

B-SLF 7666J

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Driving License

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO S7107923F



Name

NG SWEE SIONG WILSON  
(HUANG WEIXIANG)

黄伟翔

Race

CHINESE

Date of birth

05 03 1971 M

Country of birth

SINGAPORE

--- NUTR ---

REPUBLIC OF SINGAPORE DRIVING LICENCE



NAME NG SWEE SIONG WILSON

ALIAS

NG SWEE SIONG WILSON  
(HUANG WEIXIANG)

DATE OF BIRTH 05 Mar 1971

ISSUE DATE 21 Aug 2006



3490774

NAME NG SWEE SIONG WILSON



RACE

CHINESE

DATE OF BIRTH

05 03 1971

81 UPPER SERANGOON WEG #11-17  
SINGAPORE 538015

NRIC No: S7107923F

ISSUE DATE 08/20/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

ISSUE DATE

Class 3B	Motorcycles <= 200 cc	18 Aug 1960
Class 3A	Motorcycles between 201 cc and 400 cc	18 Mar 1964
Class 2	Motorcycles > 400 cc	21 May 2012
Class 3	Motor Cars -> 3000cc with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg	07 Jul 1968

NR 426A





 SGMFO

### Certificate of Insurance

Cert No./Policy No.	U17MTPV01201511
1. Registration No.	RJ024650
2. Insured Name	NO SWEE SHON WY HOON
3. Commencement Date	19 FEBRUARY 2017 00:00
4. Expiry Date	18 FEBRUARY 2018 23:59
5. Coverage	Marked values of 1 rate of loss - Comprehensive - Excess/Driver/Ord. Pass - Excl. COF
6. Excess	\$000 - Section I (Waived up to S\$1,000 Standard Excess and excess at Excess/Driver/Workplace for first two claims per policy year)
7. Voluntary Cancellation	Penalty: \$500 - Section II

## at the ground

\*) Any other reasonable liability, on the insured's order or at his personal risk.

in the event of the death of the insured,

j) Any member of the insured's family, or a paid driver who has been driving the car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured and

any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the insurer.

**Provided** that the person driving a motor car, in compliance with the licensing or other laws or regulations to give the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by means of a conviction or suspension or has been so licensed and shall have driving the Motor Vehicle.

And provided, further, that the Motor Vehicle Importation Act, 1982 (the Act) and its regulations, and the Trade Tariff Act has not been cancelled or the time of the passage, loss, or damage.

The only for social, domestic and personal purposes not for the financial business

That  $P_0$  is a group, and a vector

Use for hire, or towing, racing, packtrailing, speed testing, reliability trial, or carriage of goods other than samples in connection with any trade or business or for any purpose. A combination with the Motor Truck

It is a condition precedent to liability that the Fire Insurance Co., together with the Motor Vehicle

Full of the Company's Accident Reporting Service and report the hazardous within 24 hours of the accident or the next working day.

It is not necessary to have the acceptance message in the terminal window displayed out at Excoffier's Web site, where the client can find it available.

In an emergency and for those listed in the Company's Accident Report on Clinics, please contact our Emergency Hotline: 0800 5225 3033.

Visit [www.sagepub.com/eng](http://www.sagepub.com/eng) for full of English Worksheets and Accounts Required to Cents 2

## As provided in policy settings

THE INFORMATION CONTAINED HEREIN IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE. IT IS THE POLICY OF THE NATIONAL ARCHIVES TO MAKE ALL INFORMATION CONTAINED HEREIN AVAILABLE TO THE PUBLIC. FOR MORE INFORMATION, CONTACT THE NATIONAL ARCHIVES AT 866.834.6746 OR [WWW.ARCHIVES.GOV](http://www.archives.gov).

Sompo Insurance Singapore Pte. Ltd.

Stallan

Received 10 June 2017; accepted 25 June 2017

\*The above results are significant at the 5% level of significance. The above results are significant at the 5% level of significance. The above results are significant at the 5% level of significance.

## WELPS FLAA™ NOTICE

- [illegible]

**Interpretive Code & Name:** SP0709 A PAB-2 HARMONIC ANALYSIS L E CIGUE 794 28612 25000000



Accident Photo





Accident Photo





Accident Photo





Accident Photo





Accident Photo





Accident Photo





Accident Photo





Accident Photo





Accident Photo





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/01/2018 12:39
Date Of Accident	30/12/2017 16:00
Exact Location Of Accident	MALAYSIA CUSTOM TOWARDS SINGAPORE (TUAS)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF7666J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIU YI
NRIC No	S7980358H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91817860
Alternative Phone No	Others-91817860
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	OUTLANDER 2.4 CVT AWD S/R FACELIFT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80437079 QMY (COMP)
Cover Note Number	

### Driver

Name of Driver	LIU YI
NRIC No	S7980358H
Date Of Birth	28/01/1979
Occupation	INDOOR
Date Of Driving Pass	13/06/2009
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91817860



Fax Number	
Contact Number	OTHERS-91817860
EMail Address	NOEMAIL
Address	19 TAMPINES CENTRAL 7 #09-19
Postcode	528773
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	Name: : GUAN HUAHUA Gender: : Female
Passenger 2	Name: : LIU HAOHAN Gender: : Male
Passenger 3	Name: : LIU SHUHAN Gender: : Female
Passenger 4	Name: : LIU WENXI Gender: : Female

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS4650D
Vehicle Make/Model/Colour	HYUNDAI FD I30 CW 1.6 A



Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**IDAC KAKI BUKIT (VAC)**  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [feedback@siar.net.sg](mailto:feedback@siar.net.sg)  
Name:  
NRIC/ID No:



### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was following the traffic in my own lane and another car trying to cut into my lane and some scratches happened.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Polyskander's Signature  
Date & Time

Driver's Signature  
If driver is not the policyholder  
Date & Time

**IDAC KAKI BUKIT (VAC)**  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC ID No. \_\_\_\_\_



Accident Photo





Accident Photo





Accident Photo





Accident Photo





Accident Photo





Accident Photo





Accident Photo





Accident Photo





## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018		08 Jan 2018 16:25 <a href="#">Edit Adj Rpt</a>	<b>S\$1,900.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>LIU YI</b> , ID: S7980358H, Tel: +6591817860									
Main Claimant: <b>NG SWEE SIONG WILSON</b> , ID: S7107923F									
Vehicle Reg. No.: <b>SJS4650D</b>		Date of Loss:	30/12/2017 16:00 - :59 [100 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type: <b>TP / 543555</b>		Policy/Cover Note No.:	80437079QMY (Comprehensive) Coverage: 17/08/2017 - 16/08/2018						
Vehicle Reg. No. (Insured): <b>SLF7666J</b>		Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer: <b>Hiap Lek Automobile Trading ()</b> Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Pauline Tham</b> - 6594 2545]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... <b>[Final Rpt due 21/05/2019]</b>									
Driver/Custodian (Insured): <b>LIU YI (38 / Male)</b> , NRIC: S7980358H, Tel: +6591817860 Email:									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• MSIG_5G (16/05/2019): Report Send Back Alerts - SJS4650D (TP)									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





























## Claim Documents

\*SJS4650D (543555)  
[SLF7666J]  
TP  
NG SWEE SIONG WILSON  
Dec 30 2017 4:00PM  
[LIU YI]  
Hiap Lek Automobile Trading

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On		MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	08/01/18 16:20		Accident Statement From: SC - Reg. No: SLF7666J, Claimant: LIU YI						1	Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
2	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
3	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
4	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
5	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
6	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
7	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
8	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
9	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
10	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
11	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
12	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
13	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
14	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
15	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
16	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
17	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
18	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
19	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
20	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
21	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
22	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
23	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
24	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
25	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
26	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
27	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
28	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
29	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
30	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
31	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
32	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	
33	05/04/18 18:46		General View						1	Load JPG	<input checked="" type="checkbox"/>	



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	05/04/18 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/01/18 16:19	TPD SJS4650D GIA REPORT	 Load PDF	
2	08/01/18 16:19	Pre-Repair Survey	 Load PDF	
3	14/04/18 14:42	TP Surveyor report	 Load PDF	
4	14/04/18 14:43	TP Survey photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/19 14:06	PRS Invoice	 Load PDF	
2	06/06/19 14:06	Colour Photo	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18000490/BTD3E2

Date: 06/06/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80437079QMY

Claimant Vehicle  
No: SJS4650D

Insured Vehicle No: SLF7666J

Date of Loss: 30/12/2017

Nature of Claim: TP

Claim No: 543555

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJS4650D

Make &amp; Model: HYUNDAI I30, 1.6 FD CW (A)

Engine No: G4FC9U701591

Reg. Date: 19/08/2009 (Man. Year: 2009)

Chassis No: KMHDC81DMAU054966

Colour: Silver

Odometer: 153382 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,003.75	1,276.72	6,727.03	84.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,110.00	2,360.00	68.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,473.75</b>	<b>2,386.72</b>	<b>9,087.03</b>	<b>79.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,473.75</b>	<b>1,900.00</b>	<b>9,573.75</b>	<b>83.44</b>

## INSPECTION

Date of Assignment: 08/01/2018

Date Inspected: 12/01/2018 Inspected At:

Hiap Lek Automobile Trading  
Blk 14 #01-19 Sector B, Sin Ming Industrial  
Est  
Singapore 575658

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2019)	
<b>Parts:</b> 143	HYUNDAI I30 1.6 FD C/W (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SJS4650D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	448.00 F	*-FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	56.00 F	*-FL
3	10		*REAR BUMPER CLIP	Not Necessary	35.00 F	*-FL
4	1		*REAR SHOCK ABSORBER RH	Not Necessary	220.00 F	*-FL
5	1		*REAR LOWER ARM RH	Not Necessary	261.80 F	*-FL
6	1		*REAR KNUCKLE ARM RH	Not Necessary	383.00 F	*-FL
7	1		*REAR KNUCKLE ASSIST ARM RH	Not Necessary	162.00 F	*-FL
8	1		*REAR TRAILING ARM RH	Not Necessary	166.80 F	*-FL
9	1		*REAR CONTROL ARM RH	Not Necessary	192.80 F	*-FL
10	1		*REAR STABILISER LINK RH	Not Necessary	75.80 F	*-FL
11	1		*REAR WHEEL HUB / BEARING RH	Not Necessary	349.00 F	*-FL
12	1		*REAR DOOR RH	Dented	1,412.20 F	*1,412.20 FL
13	1		*REAR DOOR FRAME STICKER RH	Necessary	27.00 F	*27.00 FL
14	2		*REAR DOOR FRAME STICKER RH	Necessary	54.00 F	*54.00 FL
15	1		*REAR DOOR GLASS OUTER MOULDING RH	Necessary	58.50 F	*58.50 FL
16	1		*REAR DOOR GLASS INNER MOULDING RH	Necessary	44.20 F	*44.20 FL
17	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	61.10 F	*-FL
18	1		*REAR DOOR OUTER HANDLE END CAP RH	Not Necessary	26.00 F	*-FL
19	2		*REAR DOOR HINGE RH	Not Necessary	114.40 F	*-FL
20	1		*REAR DOOR CHECK RH	Not Necessary	71.50 F	*-FL
21	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	133.00 F	*-FL
22	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	632.00 F	*-FL
23	1		*REAR DOOR WINDOW REGULATOR RH	Not Necessary	236.00 F	*-FL
24	1		*REAR DOOR WINDOW REGULATOR MOTOR RH	Not Necessary	229.00 F	*-FL
25	1		*REAR DOOR WINDOW GLASS CHANNEL RH	Not Necessary	38.00 F	*-FL
26	1		*REAR DOOR INNER LOCK RH	Not Necessary	246.00 F	*-FL
27	1		*FRONT DOOR RH	Repair	1,367.35 F	*-FL
28	1		*FRONT DOOR FRAME STICKER RH	Not Necessary	27.00 F	*-FL
29	2		*FRONT DOOR FRAME STICKER RH	Not Necessary	54.00 F	*-FL
30	1		*FRONT DOOR GLASS OUTER MOULDING RH	Not Necessary	57.20 F	*-FL
31	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	61.10 F	*-FL
32	1		*FRONT DOOR OUTER KEY CYLINDER LOCK RH	Not Necessary	78.00 F	*-FL
33	1		*FRONT DOOR OUTER KEY CYLINDER LOCK COVER RH	Not Necessary	26.00 F	*-FL
34	1		*REAR DOOR SPEAKER RH	Not Necessary	150.00 FS	*-FS
35	1		*REAR SPORT RIM RH	Repair	450.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$) 8,003.75 1,595.90

- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 319.18

Total Parts (\$\$) 8,003.75 1,276.72

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEATING REAR RH FENDER, RH DOOR CENTRE PILLAR AND RH FRAME MEMBERS. TO REMOVE AND REFIT ABOVE PARTS	New	840.00	300.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.	New	1,500.00	600.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	30.00
4	TO RUST PROOF AFFECTED AREAS	New	120.00	60.00
5	TO REMOVE, REFIT RH FRONT SPORT RIM / TYRE AND BALANCING	New	50.00	0.00
6	TO REMOVE AND REFIT REAR SUSPENSION SYSTEM	New	400.00	0.00
7	TO CONDUCT ELECTRONIC WHEEL ALIGNMENT TEST	New	180.00	60.00
8	TO REMOVE, TRANSFER AND REFIT RH REAR COMPONENTS	New	300.00	60.00
Gross Labour Cost (S\$)			3,470.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >