

ASS. REC. BY:

REF: CS/SMO 19008851 / 1/19/03ⁿ²

Special Instruction:

Surveyor: Kalvin

ASSIGNMENT (Office)

From (Person): Melvin Ye

of SMO

Date/Time: 16.5.19 / 11.47 p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 5264G

Insured: PA 8266C

at Workshop m/s Trans-city Auto

Tel: 62130998

of NO 2 Ame Street 67.

Policy No: DIBMTSC BU000674

Claim No: CMTD 1902344

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.5.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"w"

H.O.D. Endorsement:

Date/Time: 14.5.19 9:20 a.m.

Person Contacted: Randy

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 5264G - CC31 AXN 1703979 / KZN 392 D.O.A - 18/07/2017
	PA 8266C - CC6/AXN 4012793 / KSY 3W2 D.O.A - 10/09/2014
21/5/19 @ 8:08pm	revised to Melvin Ye via Maximen.

300000 Kolm

REF:

Estimate/Ref: _____
 OD/TP/RS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Sal or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lvm-Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
1/8/19	Chc 1145965.45/122 (Red 672558.91, 79%) SMO

RECEIVED 01 AUG 2019

DelatTime, File Pass to? ☐ : Prel. Report
 01/8 1145965.45 ☐ : Final Report
 Date/Time, File Return to?
 MER-TP
 5965.45

SHI/52646 19 Dec 2018
 Type: M.Car / M.Cycle / Bus / Van / Lorry / T/ Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius cc 1798
 Colour: M. Red/Lite A/C: Insu 6 / Std / Nil / NA
 Sp. Reading: 29284 T/Radio: Insu 6 / Std / Nil / NA
 Eng/No: _____
 Cl/No: JTP/KB3F4203078731
 Gen. Cond: Good / 6 / Poor / Burnt
 Steering: Inor 6 / Jammed / Leaked / Burnt or
 Brake: Inor 6 / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/T or
 Tyre Size: F: 195/65 R15
 R: 7
 BS / DUN / EXNOVA 6 / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 7 mm R/Bal: 7 mm
 L/Bal: 7 mm L/Bal: 7 mm
 D.O.A: 14/5/19 D.O.L: 17/5/19
 Survey held at: Transub
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 5
 Resurvey No. of Trip: 1
 Add Fee: ☐ : Site Insp (S)
☐ : Interview (S)
☐ : Test (S)
 Survey Fee:
 Transportation: 450
 S + RS: 11
 Phone: _____
 Other: _____
 TOTAL: 461

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melvin Ye

Date: 21 May 2019

Preliminary Advice

Insured Vehicle No	: PA8266C	Accident Date	: 14/05/2019
TP Vehicle No	: SHD5264G	Assignment Date	: 16/05/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 5.00
Date of Inspection	: 17/05/2019		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD NO 2 ANG MO KIO STREET 63 SINGAPORE 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,524.36
Revised Amount	:S\$	5,970.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,970.95

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2019		16 May 2019 16:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIBERTY RESOURCES PTE LTD, Co. Reg. No.: 200204300N								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD5264G	Date of Loss:	14/05/2019 08:00 - :59						
Claim Type:	TP / CMTD1902344	Policy/Cover Note No.:	D18MTSCBU000674 (Comprehensive)						
Vehicle Reg. No. (Insured):	PA8266C	Policy No. (Claimant):							
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Melvin Ye - 6322 4667]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/05/2019]								
Driver/Custodian (Insured):	TAY TIANG CHEW (), NRIC: S0201120D, Tel: +6598252218 Email:								
Adj Asg. Remarks:	WS: CANDY 62130998								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD5264G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B93863
Chassis No.:	JTDKB3FU203078731
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	19 Dec 2018
First Registration Date:	19 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2026
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	18 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,057.00
COE Rebate Amount:	\$17,645.00
Total Rebate Amount:	\$28,330.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2019 15:00
Date Of Accident	14/05/2019 08:45
Exact Location Of Accident	LORONG CHUAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5264G
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	NG TECK BEE
NRIC No	S1588652H
Date Of Birth	30/07/1963
Occupation	OUTDOOR
Date Of Driving Pass	24/10/1980
Driving Experience	38 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97589696
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	22D TEMBELING ROAD
Postcode	423567
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKONWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20190514/2078

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA8266C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NG TECK BEE

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHD5264G

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pus ~~is~~ attach police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190514/2078

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190514/2078

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/05/2019 13:35		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: NG TECK BEE			Address: APT BLK 22D TEMBELING ROAD SINGAPORE 423567		
ID Type / ID No.: NRIC NO / S1588652H			Contact No.: Home/Office: Mobile: 97589696		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 55	Date of Birth: 30/07/1963	Type of Informant: Driver		
Race:			Language:		Institution / School Name:
Occupation: OTHERS			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 14/05/2019 08:45	Type of Location: Straight Road
Location: Along Road 1 LORONG CHUAN INFRONT TRAFFIC JUNCTION				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD5264G	Car				Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190514/2078

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190514/2078

CONTINUATION OF REPORT

Driver			
Name	NG TECK BEE	ID No.	S1588652H
Related Vehicle	NIL	Contact No.	97589696
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	14/05/2019	Date Discharge	14/05/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE & LOCATION,

I WAS DRIVING MY TAXI ALONG THE STRAIGHT ROAD. I PASSED BY THE ZEBRA CROSSING AND WAS WAITING AFTER THE ZEBRA CROSSING TO TURN TO MY LEFT. SUDDENLY I FELT AN IMPACT FROM THE BACK OF MY TAXI.
I THEN REALISED THAT, A MINIBUS COLLIDED ON MY VEHICLE.

THE DRIVER APPROACHED ME AFTER THE ACCIDENT, BUT HE NEVER WAIT FOR THE AMBULANCE.

HE LEFT WITHOUT GIVING HIS PARTICULARS.
I SUSTAINED INJURY AND WAS BROUGHT OVER TO THE HOSPITAL.

MY TAXI WAS DAMAGED AND WAS TOWED TO TRAFFIC POLICE.

THATSA LL



**SINGAPORE
POLICE FORCE**



T/20190514/2078

3 of 3

Report No. T/20190514/2078

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
YOGENDRAN S/O RAJASAKARAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt NOR FAIZAL BIN YAHYA
Contact No.: 65476202

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
14/05/2019 13:35

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Signature:

Trans-cab Auto Services Pte Ltd

AAD1905-117

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5264G

PIP \$5965.75 / 56%

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5264G

JTDKB3FU203078731

TOYOTA

PRIUS

14.5.2019

Sumpo

19/12/2018

PART**LIST**

1	1 REAR BUMPER	— <i>Refund</i>	\$	458.60
2	1 REAR BUMPER RE-INFORCEMENT	— <i>RH</i>	\$	318.80
3	1 REAR BUMPER TOWING COVER	— <i>mainly</i>	\$	14.70
4	1 REAR BUMPER UNDER COVER (BLACK)	— <i>in</i>	\$	552.60
5	1 REAR BUMPER SIDE RETAINER LH	<i>X</i> <i>in</i>	\$	112.70
6	1 REAR BUMPER SIDE RETAINER RH	<i>X</i> <i>in</i>	\$	112.70
7	1 REAR TAILGATE	— <i>Reichold</i>	\$	1,547.27
8	1 REAR TAILGATE OUTER GARNISH	— <i>in</i>	\$	905.10
9	1 COVER, REAR COMBINATION LAMP, RH	<i>X</i> <i>in</i>	\$	54.70
10	1 COVER, REAR COMBINATION LAMP, RH	<i>X</i> <i>in</i>	\$	54.70
11	1 GARNISH, BACK DOOR SIDE, LH	<i>X</i> <i>in</i>	\$	93.60
12	1 GARNISH, BACK DOOR SIDE, RH	<i>X</i> <i>in</i>	\$	93.60
13	1 BOARD ASSY, BACK DOOR TRIM	<i>X</i> <i>in</i>	\$	254.40
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	<i>X</i> <i>in</i>	\$	51.20
15	1 REAR TAILGATE WEATHERSTRIP	<i>X</i> <i>in</i>	\$	365.20
16	1 REAR END PANEL	— <i>Reichold</i>	\$	602.10
17	1 TAILLAMP LOWER RH	<i>X</i> <i>in</i>	\$	548.40
18	1 TAILLAMP UPPER RH	<i>X</i> <i>in</i>	\$	557.90
19	1 REAR BUMPER SIDE RH	<i>X</i> <i>in</i>	\$	232.00
20	1 REAR BUMPER SIDE LH	<i>X</i> <i>in</i>	\$	232.00
21	1 TAILLAMP LOWER LH	<i>X</i> <i>in</i>	\$	548.40
22	1 TAILLAMP UPPER LH	<i>X</i> <i>in</i>	\$	557.90
23	1 PAN, REAR FLOOR	<i>X</i> <i>in</i>	\$	572.10
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	<i>X</i> <i>in</i>	\$	77.00
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	<i>X</i> <i>in</i>	\$	192.90
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	<i>X</i> <i>in</i>	\$	77.00
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	<i>X</i> <i>in</i>	\$	192.90
28	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	<i>X</i> <i>in</i>	\$	290.50

Trans-cab Auto Services Pte Ltd

AAD1905-117

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5264G

29	1 REAR FENDER LH	X <i>sv</i>	\$	817.50
30	1 REAR FENDER RH	X <i>sv</i>	\$	817.50

\$	11,305.97
----	------------------

25%	\$	2,826.49
-----	----	-----------------

\$	8,479.48
----	-----------------

Special Nett

1	1SET PARKING AID	<i>shld</i>	\$	700.00 <i>250</i>
2	1SET REAR BUMPER CLIP	<i>nc</i>	\$	22.00 <i>-25%</i>
3	2 REAR WINDSCREEN SELANT	<i>nc</i>	\$	80.00
4	1 WINDSCREEN MOULDING	X <i>nc</i>	\$	100.00
5	1 REAR WINDSCREEN INNER SPONGE SEAL	X <i>nc</i>	\$	100.00
6	1 REAR TAILGATE TOYOTA LOGO	<i>nc</i>	\$	47.00 <i>-25%</i>
7	1 REAR TAILGATE WORDING 'PRIUS'	<i>nc</i>	\$	52.90 <i>-25%</i>
8	1 REAR TAILGATE WORDING 'HYBRID'	<i>nc</i>	\$	53.50 <i>-25%</i>
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	<i>nc</i>	\$	80.00
10	1 REAR TAILGATE STICKER '6555-3333'	<i>nc</i>	\$	80.00
11	1 REAR BUMPER PROTECTOR	<i>nc</i>	\$	100.00 <i>50</i>

TOTAL	\$	1,415.40
--------------	----	-----------------

TOTAL PARTS	\$	9,894.88
--------------------	----	-----------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00 <i>800</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>800</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>50</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>40</i>

Trans-cab Auto Services Pte Ltd

AAD1905-117

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5264G

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00 50
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00 X 2
To repair and realign rear exhaust pipe.	\$	170.00 X 2
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X 1
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 50
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 120
To check steering geometry and computer wheel alignment	\$	220.00 X 2
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	170.00 X 1
TOTAL	\$	10,150.00

Over All Total \$ **28,524.36** 20044.88

(PART-BY-PART) Repair Days**20 DAYS**

Kalini 100kg
 17/5/19 1745h.
 5071.
 P/P
 Before Paint photo

WCS Auto Consultants hence notify the Repairer of the following:

- To be used in relation to any painting
- To be used in relation to any welding
- To be used in relation to any mechanical work
- To be used in relation to any electrical work
- To be used in relation to any other work
- To be used in relation to any other work
- To be used in relation to any other work
- To be used in relation to any other work

is acknowledged by the Repairer

Signature: _____

Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19008851/K1QD3N2

Date: 01/08/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTSCBU000674
Claimant Vehicle No :	SHD5264G	Insured Vehicle No :	PA8266C
Date of Loss:	14/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902344

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5264G	Engine No:	2ZR2B93863
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU203078731
Reg. Date:	19/12/2018 (Man. Year: 2018)	Odometer:	29284 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,894.88	4,055.45	5,839.43	59.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,150.00	1,910.00	8,240.00	81.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,044.88	5,965.45	14,079.43	70.24
+ GST 7.00/7.00% (S\$)	1,403.14	417.58	985.56	70.24
Nett Amount (S\$)	21,448.02	6,383.03	15,064.99	70.24

INSPECTION

Date of Assignment:	16/05/2019		
Date Inspected:	17/05/2019	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days		

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2019)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5264G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Bent	318.80 FL	*318.80 FL
3	1		*REAR BUMPER TOWING COVER	Missing	14.70 FL	*14.70 FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Cracked	552.60 FL	*552.60 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Cracked	112.70 FL	*112.70 FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*-FL
7	1		*REAR TAILGATE	Buckled	1,547.27 FL	*1,547.27 FL
8	1		*REAR TAILGATE OUTER GARNISH	Cracked	905.10 FL	*905.10 FL
9	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*-FL
10	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*-FL
11	1		*GARNISH,BACK DOOR SIDE,LH	Serviceable	93.60 FL	*-FL
12	1		*GARNISH,BACK DOOR SIDE,RH	Serviceable	93.60 FL	*-FL
13	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	254.40 FL	*-FL
14	1		*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	51.20 FL	*-FL
15	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*-FL
16	1		*REAR END PANEL	Buckled	602.10 FL	*602.10 FL
17	1		*TAILLAMP LOWER RH	Serviceable	548.40 FL	*-FL
18	1		*TAILLAMP UPPER RH	Serviceable	557.90 FL	*-FL
19	1		*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*-FL
20	1		*REAR BUMPER SIDE LH	Serviceable	232.00 FL	*-FL
21	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*-FL
22	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*-FL
23	1		*PAN,REAR FLOOR	Serviceable	572.10 FL	*-FL
24	1		*EXTENSION,REAR FLOOR SIDE PANEL,RH	Serviceable	77.00 FL	*-FL
25	1		*EXTENSION,REAR FLOOR PANL TO QUARTER PANEL,LH	Serviceable	192.90 FL	*-FL
26	1		*EXTENSION,REAR FLOOR SIDE PANEL,LH	Serviceable	77.00 FL	*-FL
27	1		*EXTENSION,REAR FLOOR PANL TO QUARTER PANEL,RH	Serviceable	192.90 FL	*-FL
28	1		*PANEL,QUARTER WHEEL HOUSE,OUTER LH	Serviceable	290.50 FL	*-FL
29	1		*REAR FENDER LH	Serviceable	817.50 FL	*-FL
30	1		*REAR FENDER RH	Serviceable	817.50 FL	*-FL
31	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*16.50 FS
32	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.00 FS	*35.25 FS
33	1		*REAR TAILGATE WORDING PRIUS	Necessary	52.90 FS	*39.68 FS
34	1		*REAR TAILGATE WORDING HYBRID	Necessary	53.50 FS	*40.12 FS
35	1		*SET PARKING AID	Shorted	700.00 FS	*250.00 FS
36	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
37	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
38	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
39	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*80.00 FS
40	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	12,721.37
					5,183.42	
					- List Item Discount on L Items 25.00/25.00% (S\$)	2,826.49
					1,127.97	
					Total Parts (S\$)	9,894.88
					4,055.45	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	800.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	800.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	50.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	40.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	50.00
6	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	50.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	120.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			10,150.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >