

22/03/2012

ASS. REC. BY:

REF: CS/SMO/90088591 K9 d3

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi

of

SMO

Date/Time: 21-5-19 11:30 a.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 1356A

Insured:

GBH 93019

at Workshop m/s Chuan Ho Auto

Tel:

9066 1925

of 160 Sin Ming Drive #07-09

Policy No: D19M7HCV6000175

Claim No: CMTD1902068

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 9/4/2019

CA / REV / REP. / REV 24 HRS

Date/Time: 21-5-19 11:46 a.m.

Person Contacted:

Shann

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 1356A - X
	GBH 93019 - X
26/6/19 @ 11.36 am	revised to Hwang Shiang Yi via Messenger.

ASSIGNMENT

From: Date: 25/6/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 1356A

at Workshop m/s: chuan Ho Auto

of 160 Simming Drive # 07-09

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1wp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKZ 1356A Yr Regn: 01, 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta 2013

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 79601 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVVW 888168 GM 009070

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 7 mm

L/Bal. 9 mm L/Bal. 7 mm

D.O.A. 9/16/19 D.O.I. 25/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/6 11:00 AM 8/1700 C. Sum (Red \$4041.60, 70%)

RECEIVED 28 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 28/6 11:00 AM

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Inve (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos:

Notes:

TOTAL

250
11

261

Report Format:

MEP-7P

Lump Sum / ME: 1700

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 26 Jun 2019

Preliminary Advice

Insured Vehicle No	: GBH9301G	Accident Date	: 09/04/2019
TP Vehicle No	: SKZ1356A	Assignment Date	: 21/05/2019
Make	: VOLKSWAGEN JETTA GP	Est. Duration of Repair	: 3.00
Date of Inspection	: 25/06/2019		
Inspection At	: CHUAN HO AUTO SERVICE (SIN MING) 160 SIN MING DRIVE, #07-09, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,741.60
Revised Amount	:S\$	2,134.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,134.25

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Apr 2019		21 May 2019 11:30 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	KWAN TUCK SING, ID: S1122544F		
Vehicle Reg. No.:	SKZ1356A	Date of Loss:	09/04/2019 18:00 - :59
Claim Type:	TP / CMTD1902068	Policy/Cover Note No.:	D19MTHCVE000175 (Third Party Only)
Vehicle Reg. No. (Insured):	GBH9301G	Policy No. (Claimant):	
		Excess:	
Repairer:	Chuan Ho Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity, 575722 Sin Ming - Tel: 91892365		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang YI - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/05/2019]		
Adj Asg. Remarks:	WS: SHARIN 9069 1985		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2544F
Vehicle Details	
Vehicle No.:	SKZ1356A
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T HL HID 1634G5
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	CAXF82920
Chassis No.:	WVWZZZ16ZGM009070
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$21,584.00
Original Registration Date:	11 Jan 2016
First Registration Date:	11 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$22,218.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2026
PARF Rebate Amount:	\$16,663.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,301.00
COE Rebate Amount:	\$35,514.00
Total Rebate Amount:	\$52,177.00

The information contained herein is correct as at 26 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/04/2019 23:07
Date Of Accident	09/04/2019 18:00
Exact Location Of Accident	TRAFFIC JUNC OF SOUTH BOUNA VISTA RD&LOWER KENT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ1356A
Insured/Policyholder	
Name Of Registered Owner	KWAN TUCK SING
NRIC No	S1122544F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91529872
Alternative Phone No	OFFICE-91529872
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	JETTA GP 1.4 TSI 90 A/T HL HID 1634G5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00001194
Cover Note Number	
Driver	
Name of Driver	KWAN HAN YANG
NRIC No	S9244030C
Date Of Birth	14/11/1992
Occupation	INDOOR
Date Of Driving Pass	08/08/2017
Driving Experience	1 YEAR AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91529872
Fax Number	
Contact Number	
EMail Address	TSKWAN5880@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was at traffic junction of South Bouna Vista Road and Lower Kent Ridge Road. I was on the middle lane of 3 lane road. Traffic light turned green and i started to moved off when vehicle GBH9301G from behind collided onto the rear of my car. Damages to my car were on the rear portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9301G
Vehicle Make/Model/Colour	TOYOTA HIACE VAN TURBO 5DR MT
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUHAMMAD EFFENDI BIN MOOHAMAD
NRIC/Passport Number	S9526298H
Contact Number	97709292
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at this centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


VERIFIED BY AJAX MARS
REPORTING OFFICER

Muhammad Faizal

Bin Pabla

Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement

ACCIDENT STATEMENT (2000 characters)

I was at traffic junction of South Bouna Vista Road and Lower Kent Ridge Road. I was on the middle lane of 3 lane road. Traffic light turned green and i started to moved off when vehicle GBH9301G from behind collided onto the rear of my car. Damages to my car were on the rear portion. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

10 April 2019 at 10:48 PM

Date/Time:

10 April 2019 at 10:48 PM

CHUAN HO AUTO SERVICE
 SIN MING AUTO CITY
 160 SIN MING DRIVE #07-09
 SINGAPORE 575722

ESTIMATE : SKZ 1356 A

Vehicle & Document Information

Date: 17/05/2019
 Vehicle No: SKZ 1356 A
 Make/Model: VOLKSWAGEN JETTA

S/N	Description	Qty	Repairer's Est	Revised Est
1	REAR BUMPER <i>1212-50</i>	1	\$ 1,456.00	\$ <i>Ben</i> 1,456.00 ✓
2	REAR LOWER BUMPER	1	\$ 755.00	\$ <i>Sh</i> 755.00 X
3	BOOTLID	1	\$ 1,900.00	\$ <i>1</i> 1,900.00 ✓
4	REAR BUMPER SENSOR SET <i>P17</i>	1	\$ <i>320</i> 466.00	\$ <i>Shed</i> 466.00 ✓
			Total :	\$ 4,577.00
			<i>10% -20%</i>	\$ 915.40
			Parts Total :	\$ 3,661.60

1	ANTIRUST PROOFING, GALVANISING SPOT WIELD	\$ <i>20</i> 200.00 ✓
1	TO CHECK LIGHTING, WIRING & FUSES	\$ <i>151</i> 280.00
1	LABOUR TO DISMANTLE, REPAIR AND REPLACE PARTS	\$ <i>300</i> 800.00
1	TO PUTTY, PRIMER, RE-SPRAY REAR BUMPER AND REAR BUMPER LOWER BUMPER	\$ <i>250</i> 800.00 <i>440</i>

Labour Total :	\$ 2,080.00
Parts Total :	\$ 3,661.60
Total :	\$ 5,741.60
-20%	\$ 1,148.32
Grand Total :	\$ 4,593.28
Lump Sum :	\$ 4,500.00

CHUAN HO AUTO SERVICE

Not withain 6199.30
L1 Day & 1700h
Resurvey After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19008859/KQD3N2

Date: 01/07/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTHCVE000175
Claimant Vehicle No :	SKZ1356A	Insured Vehicle No :	GBH9301G
Date of Loss:	09/04/2019	Nature of Claim:	TP
		Claim No:	CMTD1902068

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ1356A	Engine No:	CAXF82920
Make & Model:	VOLKSWAGEN JETTA GP, 1.4 TSI 90 HL HID 1634G5 (A)	Chassis No:	WVWZZZ16ZGM009070
Reg. Date:	11/01/2016 (Man. Year: 2015)	Odometer:	79601 km
Colour:	Metallic Grey		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,119.30	1,379.25	2,740.05	66.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	755.00	1,325.00	63.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,199.30	2,134.25	4,065.05	65.57
Approved Total (Overridden) (S\$)		1,700.00		
Nett Amount (S\$)	6,199.30	1,700.00	4,499.30	72.58

INSPECTION

Date of Assignment:	21/05/2019	
Date Inspected:	25/06/2019	Inspected At: Chuan Ho Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2019)
Parts: 143	VOLKSWAGEN JETTA GP 1.4 TSI 90 HL HID 1634G5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKZ1356A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,456.00 FL	*1,212.50 FL
2	1		*REAR LOWER BUMPER	Serviceable	755.00 FL	*- FL
3	1		*BOOTLID	Repair	1,900.00 FL	*- FL
4	1		*SET REAR BUMPER SENSOR	Shorted	466.00 FL	*320.00 FL
					Sub Total (S\$)	4,577.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	457.70
					Total Parts (S\$)	4,119.30
						1,379.25

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ANTIRUST PROOFING,GALVANISING SPOT WIELD	New	200.00	0.00
2	TO CHECK LIGHTING,WIRING & FUSES	New	280.00	15.00
3	LABOUR TO DISMANTLE,REPAIR AND REPLACE PARTS	New	800.00	300.00
4	TO PUTTY,PRIMER,RE-SPRAY REAR BUMPER AND REAR BUMPER LOWER BUMPER	New	800.00	440.00
Gross Labour Cost (\$\$)			2,080.00	755.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >