

22/03/2019

ASS. REC. BY:

REF: CS/CT119008847/ RIC d302

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping

of CT1

Date/Time: 21.5.19 10.34pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGP 5771H

Insured: GBF 1967Z

at Workshop m/s Ccf car rental

Tel: 9623 2256

of BIC 461 Pasir Ris Drive 4 # 04-461

Policy No: DMCVSN16504418022

Claim No: SVM19070219802

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/5/2019

22.5.19 3.00pm

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21.5.19 2.36pm

Person Contacted: Alicia Ng

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	(X) Inspection	176 sin ming Drive #05-05
	SGP 5771H - CC4/A1G17065990/Et 3392			D.O.A - 14/03/2017
	GBF 1967Z - VA/CT119003029/24			D.O.A - 16/02/2019
	Before paint: 23/5/2019			
	After paint: 27/5/2019			

(08/11/13)

ASS. REC. BY: Paul

REF C12

## ASSIGNMENT

From: \_\_\_\_\_

Date: 02.5.2019

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGP 5711Hat Workshop m/s Cck Car Rentalof 176 Sin Ming Drive #05-05

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 300p.m

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS exp

Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Veh No: SGP 5711HYr Regn: Sep / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 3C.C. 1496Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 55246

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 3M6B42A8G0317471Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 22/05/19Survey held at CAR RENTAL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range of repair (4K-6K) / 5 days

RECEIVED 07 JUN 2019

30/5/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )Survey Fee: 150

Transportation:

S + RS, SI

Photos

Others

TOTAL

150Report Format: PRS

Lump Sum / I.B.I: (\$ )

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 May 2019		21 May 2019 10:34 <a href="#">Assign</a>				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	HONG TAT ELECTRICAL CO LLP, Co. Reg. No.: T10LL1697H								
Main Claimant:	YEO ENG CHIN, ID: S0039716D								
Vehicle Reg. No.:	SGP5771H	Date of Loss:	13/05/2019 19:00 - :59 [43 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202188C02	Policy/Cover Note No.:	DMCVSN16509418022 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBF1967Z	Policy No. (Claimant):	P10017961R01						
		Excess:	S\$0.00						
Repairer:	Cck Car Rental () BLK 461 PASIR RIS DRIVE 4 #04-461, 510461 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	Auto & General Insurance (Singapore) Pte. Limited. (HQ) - Tel: 6540 2180								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/05/2019]								
Driver/Custodian (Insured):	KWEK SIAM NGUAN (62 / Male), NRIC: S1183090J Email:								
Adj Asg. Remarks:	to contact Alicia Ng at 9623 2256 to arrange for PRS. Workshop CCK Car Rental 176 Sin Ming Drive #05-05 Sin Ming AutoCare Singapore 575721 Thank you								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
● CHINA_TAIPING (21/05/2019): Cancellation of Assignment: SGP5771H									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SGP5771H		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	With Sun Roof		
Vehicle Scheme :	Normal		
Vehicle Make :	MAZDA		
Vehicle Model :	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT		
Chassis No. :	JM6BM42A8G0317471		
Propellant :	Petrol		
Engine No. :	P520313466		
Engine Capacity :	1496 cc		
Maximum Power Output :	88.0 kW ( 118 bhp )		
Maximum Laden Weight :	1835 kg		
Unladen Weight :	1321 kg		
Year Of Manufacture :	2015		
Original Registration Date :	25 Sep 2015		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$58,700.00		
COE Expiry Date :	24 Sep 2025		
Road Tax Expiry Date :	24 Sep 2019		
PARF Eligibility Expiry Date :	24 Sep 2025		
Inspection Due Date :	24 Sep 2020		
Intended Transfer Date :	06 Jun 2019		
CO2 Emission :	135.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$5,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9716D
<b>Vehicle Details</b>	
Vehicle No.:	SGP5771H
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	P520313466
Chassis No.:	JM6BM42A8G0317471
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,299.00
Original Registration Date:	25 Sep 2015
First Registration Date:	25 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$10,299.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2025
PARF Rebate Amount:	\$7,724.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,700.00
COE Rebate Amount:	\$36,981.00
<b>Total Rebate Amount:</b>	<b>\$44,705.00</b>

The information contained herein is correct as at 06 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 14/05/2019 16:59  
 Date Of Accident 13/05/2019 19:30  
 Exact Location Of Accident LORNIE ROAD  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SGP5771H  
**Insured/Policyholder**  
 Name Of Registered Owner YEO ENG CHIN  
 NRIC No S0039716D  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-96226233  
 Alternative Phone No Office-96226233

### Vehicle Particulars

Manufacturer MAZDA  
 Model 3

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number P10017961R01  
 Cover Note Number

### Driver

Name of Driver YEO ENG CHIN  
 NRIC No S0039716D  
 Date Of Birth 31/08/1949  
 Occupation INDOOR  
 Date Of Driving Pass 12/11/1974  
 Driving Experience 44 YEARS AND 6 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-96226233

## Fax Number

Contact Number	OFFICE-96226233
EMail Address	NOEMAIL
Address	20 CLOVER AVENUE
Postcode	579308
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

ON 13/05/2019 AROUND 7.30PM, I WAS DRIVING MY MAZDA 3 (SGP5771H) ALONG LORNIE ROAD TOWARDS BRADDELL ROAD. I WAS TRAVELLING VERY SLOWLY AS TRAFFIC WAS HEAVY. A LORRY (GBF1967Z) CUT INTO MY LANE AND THE BACK OF HIS LORRY HIT THE LEFT FRONT OF MY CAR. WE INSPECTED THE LORRY TOGETHER AND AGREED THERE'S NO DAMAGES TO THE LORRY. MR KWEK'S SON CALLED ME ABOUT AN HOUR LATER AND ASKED ME TO CLAIM FROM MY INSURANCE SINCE HIS LORRY NO DAMAGE AND CLOSE CASE. HE CLAIMED THAT HIS FATHER SIGNALLED. I WOULD LIKE TO CLAIM FROM THE LORRY'S INSURANCE SINCE HE TRIED TO OVERTAKE AND CUT INTO MY LANE.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	GBF1967Z
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KWEK SIAM NGUAN
NRIC/Passport Number	

6/6/2019

E-FILE

Contact Number 97513648  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)



## Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Sketch Plan #2



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/5/2019 around 7:30 pm, I was driving my Mazda 3 (SGP 5771H) along Lornie Rd towards Braddell Road. I was travelling very slowly as traffic was heavy. A lorry (Toyota Dyna GBF ~~19672~~ 19672 / Driver Kwek Siam Nguan mobile 97516348) cut into my lane and the back of his lorry hit the left front of my car.

We inspected the lorry together and agreed there was no damage to the lorry.

Mr Kwek's son called me about an hour later and asked me to claim from my insurance since his lorry was damaged, and close the case. He claimed that his father signalled.

I'd like to claim from the lorry's insurance since he ~~overtook~~ tried to overtake and cut into my lane.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #3




































## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 May 2019		21 May 2019 10:34 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>HONG TAT ELECTRICAL CO LLP</b> , Co. Reg. No.: T10LL1697H								
Main Claimant:	<b>YEO ENG CHIN</b> , ID: S0039716D								
Vehicle Reg. No.:	<b>SGP5771H</b>	Date of Loss:	13/05/2019 19:00 - :59 [43 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D202188C02</b>	Policy/Cover Note No.:	DMCVSN16509418022 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBF1967Z</b>	Policy No. (Claimant):	P10017961R01						
		Excess:	S\$0.00						
Repairer:	<b>Cck Car Rental ( )</b> BLK 461 PASIR RIS DRIVE 4 #04-461, 510461 Sin Ming - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Claimant's Insurer:	<b>Auto &amp; General Insurance (Singapore) Pte. Limited. (HQ)</b> - Tel: 6540 2180								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 30/05/2019]</b>								
Driver/Custodian (Insured):	KWEK SIAM NGUAN (62 / Male) , NRIC: S1183090J Email:								
Adj Asg. Remarks:	to contact Alicia Ng at 9623 2256 to arrange for PRS. Workshop CCK Car Rental 176 Sin Ming Drive #05-05 Sin Ming AutoCare Singapore 575721 Thank you								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• CHINA_TAIPING (21/05/2019): <b>Cancellation of Assignment: SGP5771H</b>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGP5771H (SNM19D202188C02)  
[GBF1967Z]  
TP  
YEO ENG CHIN  
May 13 2019 7:00PM  
[HONG TAT ELECTRICAL CO LLP]  
Cck Car Rental

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Assessment Reports								1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print						
1	14/05/19 17:47	Accident Statement		 Load HTM							
2	17/05/19 13:57	Addendum Sheet		 Load TIF							
3	17/05/19 13:57	Accident Statement Addm. #1		 Load HTM							
Photos/Images								3 per page	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
2	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
3	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
4	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
5	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
6	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
7	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
8	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
9	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
10	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
11	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
12	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
13	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
14	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
15	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
16	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
17	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
18	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
19	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
20	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
21	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
22	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
23	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
24	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
25	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
26	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
27	06/06/19 16:08	General View		 Load JPG	<input checked="" type="checkbox"/>						
28	06/06/19 16:08	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>						
29	06/06/19 16:08	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>						
30	06/06/19 16:08	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>						
31	06/06/19 16:08	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>						
32	06/06/19 16:08	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>						

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
33	06/06/19 16:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	06/06/19 16:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	06/06/19 16:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	06/06/19 16:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
37	06/06/19 16:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
38	06/06/19 16:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 16:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 16:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 16:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 16:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 16:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 16:09	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/05/19 10:33	INSD GBF1967Z GIA Report	Load PDF	

## Linked Accident Report Documents

Video			View <input type="button" value="View In Browser"/>	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	17/05/19 13:56	Video - Accident	Load MOV	
2	17/05/19 13:56	Video - Accident	Load MOV	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	14/05/19 17:47	Accident Statement	Load HTM	
2	17/05/19 13:57	Addendum Sheet	Load TIF	
3	17/05/19 13:57	Accident Statement Addm. #1	Load HTM	
4	22/05/19 16:54	Addendum Sheet Click here & type to add comment...	Load TIF	
5	22/05/19 16:54	Accident Statement Addm. #2	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	14/05/19 17:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	14/05/19 17:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	14/05/19 17:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	14/05/19 17:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	14/05/19 17:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	14/05/19 17:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	14/05/19 17:05	Sketch Plan	Load TIF	
2	14/05/19 17:05	Sketch Plan #2	Load TIF	
3	14/05/19 17:05	Sketch Plan #3	Load TIF	
4	14/05/19 17:05	Sketch Plan #4	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19008877/R1CD3E2

Date: 10/06/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN16509418022

Claimant Vehicle  
No: SGP5771HInsured Vehicle  
No: GBF1967Z

Date of Loss: 13/05/2019

Nature of Claim: TP

Claim  
No: SNM19D202188C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGP5771H

Make &amp; Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)

Engine No: P520313466

Reg. Date: 25/09/2015 (Man. Year: 2015)

Chassis No: JM6BM42A8G0317471

Colour: Red

Odometer: 55246 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 21/05/2019

Date Inspected: 22/05/2019 Inspected At:

Cck Car Rental  
BLK 461 PASIR RIS DRIVE 4 #04-461  
Singapore 510461

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$6,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2019)
<b>Parts:</b>	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGP5771H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >